Land Transport Authority	Division/Section: ITSO Division /ITSO OCC Traffic Operations	Rev No. 2 Effective Date: Xx Dec 2020
ITSO Division	Document No: ITSO/OCC/SOP/NOP02.004	
Monitoring & R	eporting of Equipment & Sy	ystem Faults
Monitoring & R	eporting of Equipment & Sy	ystem Faults
Monitoring & Ro	eporting of Equipment & Sy	ystem Faults
Monitoring & Ro	eporting of Equipment & Sy	ystem Faults
Monitoring & R	eporting of Equipment & Sy	ystem Faults

Doc No.	ITSO/OCC/SOP/NOP02.004	Page	1 of 35	
File	Monitoring & Reporting of Equipment & System Faults			

Monitoring & Reporting of Equipment & System Faults

Table of Contents

1	DESCRIPTION	5
	RESPONSIBLE PERSON	
3	ACTIONS	5
4	ABBREVIATIONS	6
5	REFERENCES & ATTACHMENTS7	-35

Doc No.	ITSO/OCC/SOP/NOP02.004	Page	2 of 35	
File	Monitoring & Reporting of Equipment & System Faults			

Monitoring & Reporting of Equipment & System Faults

DOCUMENT CONTROL

REV	DOCUMENT TITLE & COPY NUMBER	Date	Prepared by	Reviewed by	Approved by
0	Monitoring & Reporting of Equipment & System Faults Copyof	15 th December 2009	Benson Khoe (SOE)	Alfred Loh (SOE)	Soh Ling Tim (MOPN)
1	Monitoring & Reporting of Equipment & System Faults Copyof	XX October 2013	Chiam Zhi Wei (DysOE) Chua Teck Leong (AOM, ITSO OCC)	Ng Soon Han, Frankie (DOM, ITSO OCC)	Yeo Se Lay (SM,Ops)
2	Monitoring & Reporting of Equipment & System Faults Copyof	XX December 2020	Daniel Wu (AOM) Lye Keng Fatt (DM, ITSO OCC)	Ng Soon Han, Frankie (Mgr, ITSO OCC)	Yeo Se Lay (DDIT)

Doc No.	ITSO/OCC/SOP/NOP02.004	Page	3 of 35	
File	Monitoring & Reporting of Equipment & System Faults			

Monitoring & Reporting of Equipment & System Faults

AMENDMENT HISTORY RECORD

Rev. No.	Effective Date of	Section & Sub- Section Amended	Amendments/ References	Party Requesting for Change
	Change			S
1	XX Oct 2013	Whole Document	Due to organization change of division name from ITSC to ITSO.	DOM, ITSO OCC
2	XX Dec 2020	Whole Document	Due to change of Staff Designations in ITSO OCC. Delete SOE, insert DM Delete DySOE, insert DyAM	Mgr, ITSO OCC

Doc No.	ITSO/OCC/SOP/NOP02.004	Page	4 of 35	
File	Monitoring & Reporting of Equipment & System Faults			

Monitoring & Reporting of Equipment & System Faults

Section 1. Description

- 1.1.1 Describes in brief the monitoring of the various systems in ITSO OCC and the process of handling fault.
- 1.1.2 All system / equipment faults shall be reported to the Fault Coordinator except road furniture damage, which will be reported by the DM, DyAM or OE. FC will verify and report the fault respectively.
- 1.1.3 Whereas the monitoring of equipment status although the FC is mainly responsible but by virtue all ITSO OCC personnel uses these equipment, all ITSO OCC personnel shall assist in this area of fault monitoring.
- 1.1.4 FC shall monitor all equipments and systems failure, error and fault in ITSO OCC and issue corrective maintenance work orders to respective contractors
- 1.1.5 Depending on the severity of fault or failure that causes impact to ITSO OCC operations, FC shall inform the Duty DM and DyAM. At the same time FC shall inform the respective and relevant LTA maintenance officer in the order of correct escalations.
- 1.1.6 FC shall follow up with the fault and failure of the system or equipment until full rectification has been done.

Section 2. Personnel Involved

2.1.1 All OCC operations staff.

Section 3. Process

Sub-section 3.1 Systems & Equipment Fault Monitoring and Reporting

- 3.1.1 The details of the various equipment and systems used and monitored by ITSO OCC can found in ITSC/OCC/SOP/GEN01.003
- 3.1.2 When a fault is first detected, the person who first detected the fault shall report it to the FC.
- 3.1.3 FC shall determine the equipment or system having fault falls into which category (Refer to flow chart in Attachment 2 for details). Note for any traffic lights within Changi Airport boundary is under the charge of CAAS. Any faults involving these traffic lights to direct it to CAAS on contact number 6542 1122
- 3.1.4 The FC shall call contractor and send corrective maintenance work order (refer to ITSC/OCC/WM/SYS03.006), as for other category only a phone call would suffice (refer to Attachment 1).
- 3.1.5 Contractors shall acknowledge the fault work order and rectify the fault within the specified response and downtime.
- 3.1.6 Once fault has been fully rectified, FC shall verify the equipment serviceability status, acknowledge rectification completion and record down the rectified timing.

Doc No.	ITSO/OCC/SOP/NOP02.004	Page	5 of 35	
File	Monitoring & Reporting of Equipment & System Faults			

Monitoring & Reporting of Equipment & System Faults

3.1.7 In the event the failure or fault which caused severe impact to operations are not rectified within the specified response and downtime, FC shall inform DM and DyAM and inform the respective and relevant LTA maintenance officer in the order of correct escalations

Section 4. Abbreviations

FC Fault Coordinator

ITSO Intelligent Transport Systems

Operations

OCC Operations Control Center
OE Operations Executive
DM. Deputy Manager

DyAM Deputy Assistant Manager

Section 5. References & Attachments

1. Intelligent Transport Systems Center (Operations), Integrated Standard Operating Procedures

INTENTIONALLY LEFT BLANK

Doc No.	ITSO/OCC/SOP/NOP02.004	Page	6 of 35
File	Monitoring & Reporting of Equipment &	& System Fa	aults

Monitoring & Reporting of Equipment & System Faults


ATTACHMENT 1 - GLIDE REGIONAL COMPUTER (RC) CABIN LIST

Region	Location	CCT Ref No	Cabin Tel	Contact Numbers
RC1, RC2, RC4, RC17	ITS Centre 3 rd Storey Computer Room	0474261 (2 Mbps)		ATS Traffic Pte Ltd (RC3-RC19)
RC3	Jln Bt Merah / CTE Flyover	0474262 (64 kbps)	62703203	Contractors: YA Lim HP: 92285205
RC5	Braddell Rd / Lor 6 Toa Payoh F/O	0474269 (64 kbps)	62580369	Mansor HP: 81613117 Philip
RC6	Fort Rd / ECP F/O	0474271 (64 kbps)	63464996	HP: 96159898 TYCO Engineering
RC7	Braddell Rd / CTE F/O	0474276 (64 kbps)	62838781	(RC1-RC2) CM/VAX/Corba
RC8, RC16	Jurong Town Hall Rd / PIE F/O	0474278 (64 kbps)	65601634	Contractors: Leow HP: 93691751
RC9, RC10, RC15	Lentor Ave / SLE F/O	0474315 (128 kbps)	65528854	Ridzuan HP: 96195248
RC11, RC12	Loyang Ave / TPE F/O	0474317 (64 kbps)	67828517	LTA: Chong Shaw Feng HP: 96565106 Wai Keat
RC13, RC14	Mandai Rd / BKE F/O	0474321 (64 kbps)	63660264	HP: 91724641 Lincoln Wong HP: 93200430

Doc No.	ITSO/OCC/SOP/NOP02.004	Page	7 of 35	
File	Monitoring & Reporting of Equipment & System Faults			

Monitoring & Reporting of Equipment & System Faults

ATTACHMENT 2



Doc No.	ITSO/OCC/SOP/NOP02.004	Page	8 of 35
File	Monitoring & Reporting of Equipment &	System Fa	aults

Monitoring & Reporting of Equipment & System Faults

ATTACHMENT 3 - TECHNICAL ALARM LIST (i-TRANSPORT SYSTEM)

S/no	Equipment class	description	attributes
1	TID / TMD	graphic module defect	dsp
		module line 1 defect	ds1
		module line 2 defect	ds2
2	TED / TTD	module line 1 defect	ds1
		module line 2 defect	ds2
		module line 3 defect	ds3
3	TSD	graphics module defect	dsp
4	LUS	arrow bubble defect	daa
		amber cross bubble defect	dab
		red cross bubble defect	dac
5	VT900 (video track)	checksum failure	dac
		SSYFAIL on VME Module Slot	das
6	Video incident detector	detection zone failed	daz
	V	camera failed	dac
7	Video matrix	communication defect between FELS and Matrix	dsc
8	Jet fan	tripped	dst
		thermal overload	dso

Doc No.	ITSO/OCC/SOP/NOP02.004	Page	9 of 35
File	Monitoring & Reporting of Equipment &	& System Fa	aults

		running fault	dsr
		control fault	· dsc
		box fan capacity shortage	dsb
9	Tunnel section	box fan capacity shortage	dss
10	Carbon Monoxide Meter - internal	meter fault	dsm
11	Carbon Monoxide Meter - external	meter fault	dsm
12	Visibility Meter	meter fault	dsm
13	Fan Panel	emergency fan panel powered indicator	dsp
14	Split Aircon	control fault	dsf
		tripped	dst
15	Photometer and Boost Lighting Control	general fault	dsg
		light level indicator fault	dsl
16	Boost Lighting Switching Unit	control indicator fault	dsc
		boost light switch unit powered	dsp
17	Tunnel Main Pump	control fault	dsf
-		tripped	dst
		high bearing temperature	dsb
18	Tunnel Main Sump	main sump not powered	dsp
		level switch failure	dss
		level switch storage chamber main sump	dsc

Doc No.	ITSO/OCC/SOP/NOP02.004	Page	10 of 35
File	Monitoring & Reporting of Equipment &	& System Fa	aults

		circuit breaker undefined	dsc	-
			THE PERSONAL PROPERTY.	
		protection relay tripped and circuit breaker closed	dsb	
30	High Voltage Transformer Feeder	protection relay tripped	dst	
		circuit breaker undefined	dsc	and the same
		protection relay tripped and circuit breaker closed	dsb	
31	High Voltage DC Power Device	battery low alarm	dsb	
		battery charger failure	dsc	-
-		DC bus bar under-voltage	dsv	
32	LV MDB Incoming Feeder	protection relay tripped	dst	
		circuit breaker undefined	dsc	
-		protection relay tripped and circuit breaker closed	dsb	
33	LV MDB Outgoing Feeder	protection relay tripped	dst	
		circuit breaker undefined	dsc	
		protection relay tripped and circuit breaker closed	dsb	
-		control fault	dsf	
34	LV DC Power Device	battery low alarm	dsb	
		battery charger failure	dsc	
35	LV Diesel Generator	generator running	dsr	
		battery charger low	dsb	
_		protection relay tripped	dst	
-		circuit breaker undefined	dsu	
		generator fault	dsg	
		battery charger failure	dsc	
36	LV Automatic Transfer Switch	circuit breaker undefined	dsc	

Doc No.	ITSO/OCC/SOP/NOP02.004	Page	11 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

19	De-watering Pump	control fault	dsf
		tripped	dst
20	Cleaning Pump	control fault	dof
*****		tripped	dsf
		an pool	dst
21	Vehicle Door	vehicle door not closed	dsc
22	Pedestrian Door	pedestrian door not closed	dsc
23	Emergency Staircase	tunnel door opened	dst
		street door opened	dss
24	Pressurization Fan	control fault	dsc
		pressurization fan tripped	dsp
25	ES Normal Fan	normal fan tripped	dst
26	HV Public Utility Incoming Feeder Power and Breaker	HV incoming feeder protection relay tripped	dst
		HV PUB incoming feeder circuit breaker undefined	dsb
		protection relay tripped and circuit breaker closed	dsc
27	High Voltage Bus Coupler	all three circuit breakers are closed	dsa
-		circuit breaker undefined	dsc
28	High Voltage Outgoing Feeder	protection relay tripped	dst
		circuit breaker undefined	dsc
-		protection relay tripped and circuit breaker closed	dsb
29	High Voltage Incoming Feeder from other Building	protection relay tripped	dst

Doc No.	ITSO/OCC/SOP/NOP02.004	Page	12 of 35
File	Monitoring & Reporting of Equipment &	System Fa	aults


		circuit breaker undefined	dsa
43	LV Bus Coupler	alam	-
42	LV Annunciator Panel	Panel alarm	dsf
10			usu
41	LV UPS Maintenance Circuit Breaker	circuit breaker undefined	dsc
	TAVAIL DICUNCT	circuit breaker undefined	dsc
40	LV UPS Normal Circuit Breaker	Circuit brooks and fine	
		UPS room fan coil stopped	dss
		UPS charger failure	dsc
	-	UPS high temperature indicator	dst
39	LV UPS	UPS battery low	dsb
20	LVIIDE		dsb
		protection relay tripped and circuit breaker closed	
-		circuit breaker undefined	dsc
38	LV Emergency Panel Outgoing Feeder	protection relay tripped	dst
VI	- Timaliudi Hallolet SWITCH	circuit breaker undefined	dsc
37	LV Manual Transfer Switch		

Doc No.	ITSO/OCC/SOP/NOP02.004	Page	13 of 35
File	Monitoring & Reporting of Equipment &	& System Fa	aults

1	ANNEX A	4
2	ANNEX B	5
3	EMAS VMS FAULT FLOWCHART	6
4	EMAS FELS FAULT FLOWCHART	7
5	EMAS SURVEILLANCE FAULT FLOWCHART	8
6	FCT TUNNEL EQUIPMENT FAULT FLOWCHART	9
7	FCT TUNNEL SYSTEM FAULT FLOWCHART	10
8	GLIDE RC AND CM FAULT FLOWCHART	11
9	GLIDE CORBA SERVER FAULT FLOWCHART	12
10	GLIDE TRAFFIC LIGHT FAULT FLOWCHART	13
11	TRAFFIC SCAN FAULT FLOWCHART	14
12	I-TRANSPORT FAULT FLOWCHART	15
13	UMH FAULT FLOWCHART	16
14	PGS CMS AND VMS FAULT FLOWCHART	17
15	RCS FAULT FLOWCHART	18
16	EA RVMS CVMS AND SYSTEM FAULT FLOWCHART	19
17	JEYES AND ENDURA FAULT FLOWCHART	20
18	CTE TUNNEL FIRE ALARM FAULT FLOWCHART	21
19	CTE TUNNEL VENTILATION FAULT FLOWCHART	22
20	CTE TUNNEL LIGHTING FAULT FLOWCHART	23
21	CTE TUNNEL DRAINAGE FAULT FLOWCHART	24


Doc No.	ITSO/OCC/SOP/NOP02.004	Page	14 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	15 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	16 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	17 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	18 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	19 of 35
File	Monitoring & Reporting of Equipment &	& System Fa	aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	20 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	21 of 35
File	Monitoring & Reporting of Equipment &	System Fa	aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	22 of 35
File	Monitoring & Reporting of Equipment &	& System Fa	aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	23 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	24 of 35
File	Monitoring & Reporting of Equipment &	& System Fa	aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	25 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	26 of 35
File	Monitoring & Reporting of Equipment & System Faults		

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	27 of 35
File	Monitoring & Reporting of Equipment & System Faults		

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	28 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	29 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	30 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	31 of 35
File	Monitoring & Reporting of Equipment & System Faults		

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	32 of 35
File	Monitoring & Reporting of Equipment & System Faults		

Monitoring & Reporting of Equipment & System Faults




Doc No.	ITSO/OCC/SOP/NOP02.004	Page	33 of 35
File	Monitoring & Reporting of Equipment & System Faults		

Monitoring & Reporting of Equipment & System Faults



Doc No.	ITSO/OCC/SOP/NOP02.004	Page	34 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults

Monitoring & Reporting of Equipment & System Faults



Doc No.	ITSO/OCC/SOP/NOP02.004	Page	35 of 35
File	Monitoring & Reporting of Equipment & System Faults		aults