












PF1 ($R^2=0.996$)PF2 ($R^2=0.995$)PF3 ($R^2=0.993$)PF4 ($R^2=0.996$)PF5 ($R^2=0.995$)PF6 ($R^2=0.993$)PF7 ($R^2=0.992$)PF8 ($R^2=0.996$)PF11 ($R^2=0.999$)PF12 ($R^2=0.999$)PF13 ($R^2=0.996$)PF14 ($R^2=0.996$)