Dummy Examination Report

Transport Department Vehicle Examination Complex 運輸署車輛檢驗綜合大樓

XX, XX STREET, TSING YI 青衣XX街XX號

Telephone 電話: 275XXXXX

Exam. Report No. 檢驗報告編號

TY1F21Y000123

VEHICLE EXAMINATION REPORT AND REPAIR ORDER

車輛檢驗報告及修理通知令

Exam. Date & Time Lane No. Appointment No. 3-2-2020 10:35 AP0123456789OP 預約編號 驗車日期 及時間 驗車線號 Chassis No./VIN Vehicle Reg.Mark Make MGV1234 MGVM WDW456WZ345FGH888 底粉/車輛識別够碼 車輛登記號碼 廠名 Year of Manufacture Model Model Code 2019 MGVM wwwwwwwwoowwwwwww 製造年份 规键 型號編碼 Exam. Code Type Approval No. Class 01 012 WWWWWWWWWWWWWWW00 類型評定編號 檢驗期別 類別 Axle Weight(t) WT-1 (2.100) WT-2 (2.200) WT-3 (2.400) PGVW 認可車輛總重(t) 6.300 車軸重量(公噸) WT-4 (2.400) WT-5 (/) WT-6 (/) PGCW 認可組合式總重(t)

			ITE	м Л	目		RESULTS 結果	DEFECTS	缺點			
1) VISUAL I	NSPE	CTION	表面	檢驗								
Failed Items 不合格項目	1,2,3,4	,5							*PASS			
2) BRAKE T	EST #	動測詢	式									
Brake Force(N) 制助力(N)	5	Service 脳([r]	Secondary 種語				Parking 泊車]		
	N/S 左	O/S 右	Imbl. (%)	N/S 左	0/S 右	Imbl. (%)	N/S 左	O/S 右	Imbl. (%)]		
Axle 1 第一軸	0	0	0	1	/	/	1	/	/	1		
Axle 2 第二帕	2000	2000	0	1	- /	- /	- /	7	1	*PASS		
Axle 3 第三帕	2000	2000	0	2000	2000	0	2000	2000	0	1		
Axle 4 第四帕	2000	2000	0	2000	2000	0	2000	2000	0			
Axle 5 第五帕	- /	- /	- /	- /	- /	- /	- /	- /	- /]		
Axle 6 第六帕	- /	- /	- 7	- /	- /	- /	- /	- /	- /]		
Efficiency 效能 (%)		50			50			50				
3) EMISSION	N TES	T廢氣	測試		Horse Po	E機測試 wer 最大 〒=40 H	PASS					
4) SPEEDOM	1ЕТЕН	R TES	「速」	E 裁 測i	武		PASS					
5) HEAD LA	MP TI	EST 連	頭燈》	隵			PASS					
6) UNDER C	ARRI	AGE II	NSPC	TION J	医盤検	驗						
Failed Items 不合格項目												
OVERA	LL E	EXA	MIN	IATI	ON	EVA	LU	ATI	ON	整體測試	評估	PASS

Overall Length:12000 mm,	Overall Height: 4000 mm,	GVW:10000 kg,	P
Excess Length Permit Required;	Excess Height Permit Required;	Excess Weight Permit Required;	Reserve

Upon passing the Overall Examination Evaluation, this report is required for vehicle relicensing and is only valid for this purpose within 4

months from the date of issue. 當整體測試評估合格後,車幅續轉時需出示此報告表,以更換車幅轉撥,此報告在簽發日起計四個月內有效。

新金班面域以下各合价值、中间域间均为国历水区或分类。以是两项域域的,更保管化度对自由部门等的对外。 The above which having been examined in accordance with the Road Traffic Ordinance Cap 74 (Section 87 & 85) was found to have the defects listed above. You are hereby required to rectify these defects and produce the vehicle for a further inspection within one month from the date of this report.

根據香港法例第三七四章道路交通條例(第八十三條及第八十五條)之根定檢驗上述率轉後,發現有上述故障,謎讀 台灣將故障條果,後後在此報告查查目起計一個月內新該中交來覆據。
For descriptions of tiens numbers to Visual Inspection & Under Carriage Inspection, please refer to overleaf for details.

附注來身表面及底盤檢驗的數字代號註解,請轉看被頁。

Date of Issue 簽發日期 3-2-2020

输車主任 Chan Tai Man