Company: GsD / GroupGets Project: ButterStick r1.0

# Engineering Change Notice (ECN)

ECN Number 001

Origination Date Friday, 27th August, 2021

Originator of ChangeGregory DavillProject NameButterStick r1.0Type of ActionPart Substitution

Reason for Change Remove difficult to source component from design


## Detailed description of changes

### Replace BOM item U18

	Mfg	Part
Old	Texas Instruments	TPS2121RUXR
New	YAGEO	RC0603JR-130RL

#### Populate new part on PCB

Install U18 such that it shorts pins 1,2 and 7,8 of U18



Note CAD view is Top view (Through the PCB). Whereas render view is Bottom View.

## QC checks

Skew of U18 is acceptable, and expected.

Acceptance criteria on soldering is that it's successfully soldered across pins 1,2 and 7,8 of U18