- 1) Load Chip-8 Assembler-3 4 pages @ 0000
- 2) Flip up run switch -- screen blank
- 3) Enter Start Address -- 0200 for most Chip-8 programs -- press Key E to "Enter" this address and continue

4) PASS 1

- a) Press Key 1 -- play one source listing section
- b) Beeper signals ready for next section, or second pass

5) PASS 2

- a) Press Key 2 -- beeper signals ready
- b) Press Key 2 again play same source listing sections
- c) Beeper signals ready for next section, or begin output

6) TAPING

- a) Press Key F -- beeper signals ready to begin output. "F" is displayed in upper right corner
- b) Advance tape to clear spot
- c) Start record on tape machine
- d) Press Key F again tape output begins
- e) Automatic Tape Format:
 - 1) 6 pages Symbol and Link Tables
 - 2) 4 second pause
 - 3) 3 pages Object Program