the following step.

2) Change the byte at 0204 to D5. You have just
disabled the link function. If your program used it, it
will not now work. (What? You want to eat your cake
too? Really!)

Perform a first pass on the first group of your
source listings. After this, press Key 2. Now you must
enter the address of the next group as described above
(0500 probably if the first group started at 0200). Press
Key 1 to start the first pass for the second group.
Continue until all groups are done. As long as you never
exceed the 73 labels limit, you'll have no problems.

What you have done it to create a symbol table
that includes all the labels and addresses for all groups.

Flip the run switch down and call up the operating
system.

1) Change the byte at 0034 back to 7B -- don't
   worry about the other change if you made it.
2) In addition, change the byte at 0329 to 0D

You may now flip the run switch back up. The
symbol table you have created has been preserved by