II B. SECOND PASS

Back up the tape to the same spot where you began the first pass just before the first of the two sections of source listing recorded there. Press Key 2. The screen will remain on, the beeps will sound, and you once again are presented with two options:

- 1) Key 2 -- continue (or start) second pass
- 2) Key F -- begin taping

Every time you hear the quick series of beeps during the second pass, you have the above two options. (The only way to return to the first pass from here is to start over again.)

Playing in the second pass of your source listing is accomplished in the exact same manner as for the first, except that Key 2 now must be used to signal the computer to expect another section. Therefore, press Key 2, the screen goes blank; start the tape. When the display returns, the beeps will sound; press Key 2 again. Continue in this manner until all sections are completed. At the end of the last section, the display will be on. ONCE AGAIN -- DO NOT TOUCH THE RUN SWITCH.