電源 非常停止スイッチ 主電源スイッチ Conn to CircuitBoard Conn to Battery SW_SPST Conn_01x02_Female Conn_01x02_Female J1 Conn_01x02_Female H1 GND +12V 主電源スイッチ GND Conn_01x02_Female Conn_01x02_Female MountingHole_Pad BSS138 GND 保護回路・スイッチ Fuse J10 +12V F1 Conn_01x02_Female Conn_01x02_Female Fuse Q3 TJ60S04M3L TJ60S04M3L Conn_01x02_Female Conn_01x02_Female Relay 100k RAYEX-L90 D2 CUS10F30 J12 K1 Conn_01x02_Female Conn_01x02_Female TJ60S04M3L Voltmeter_DC GND J13 TJ60S04M3L Conn_01x02_Female Conn_01x02_Female GND ねじ穴 H3 H5 MountingHole MountingHole Sheet: / File: LargePW.kicad_sch H4 MountingHole H6 MountingHole Title: Size: A4 Date: Rev: KiCad E.D.A. kicad (6.0.11) ld: 1/1