電源 主電源スイッチ Conn to Battery 非常停止スイッチ Conn to CircuitBoard SW_SPST Conn_01x02_Female Conn_01x02_Female Conn_01x02_Female H1 GND +12V 10k 主電源スイッチ GND Q5 Conn_01x02_Female Conn_01x02_Female MountingHole_Pad BSS138 VDD 1 1 2 GND GND 保護回路・スイッチ Fuse J10 +12V F1 Conn_01x02_Female Conn_01x02_Female Fuse Q3 Q1 VDD __RelayIN TJ60S04M3L TJ60S04M3L GND RelayOUT_ Conn_01x02_Female Conn_01x02_Female 2 T T S Relay C2 VDD 1 10000uF 100k 510 K1 D2 CUS10F30 R4 510 日本 510 RAYEX-L90 J12 Conn_01x02_Female Conn_01x02_Female TJ60S04M3L 1uF Voltmeter_DC RelaySW Q2 C1 GND GND RelayIN J13 TJ60S04M3L Conn_01x02_Female Conn_01x02_Female _Relay0UT GND Sheet: / File: LargePW.kicad_sch Title: Size: A4 Date: Rev: KiCad E.D.A. kicad (6.0.11) ld: 1/1