





RS485/Device MAX3485_AB Conn c20 +3.3V 0.1uF GNDD 1 R25 2.2k 24V_IN 🚣 GNDD RS485_A RS485_A RS485_B JP1 RS485_X MainRX_RS485TXD RS485_Y R29 120 Jumper_2_Open RS485_B R23 10k GNDD R26 2.2k Conn_01x06_MountingPin MAX3485 GNDD GNDD 1 24V_0UT_<u></u> RS485_A RS485_B RS485_X MAX3485_XY RS485_Y +3.3V C19 0.1uF **~**68550 R27 GNDD 2.2k Conn_01x06_MountingPin RS485_X JP2 2 R30 120 Jumper_2_Open MainTX_RS485RXD-RS485_Y R24 20k 24V_conn R28 2.2k MAX3485 SolderJumper_2_Open JP3 GNDD Sheet: /RS485/ File: RS485.kicad_sch Title: Size: A4 Date: Rev: KiCad E.D.A. kicad 7.0.11 ld: 4/6

MotorDriver



