

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 1/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

GENERAL INFORMATION

// (COM-INFO) //

THA 00002/13 (31 JUL 26)

COM INFO:--All A350 and BOEING 787:
are now eligible and included in EUROCONTROL airspace CPDLC Logon list.
Action Required: Pilots are required to initiate CPDLC logon when entering European airspace.
(ISSUED 23MAR26/BKKPC2/UFN)

--IN CASE CANNOT BE CONTACTED BKKOC VIA TELEPHONE,
PILOTS MAY CONTACT VIA MS TEAMS CHANNEL: "OC.CENTER".
(ISSUED 30JUL24/BKKOC/UFN)

-- To improve CTOT for all flights both outbound from BKK and
inbound to BKK, pilots may contact TOCC when ready for departure to request an earlier CTOT
through any of the following channels:

- : MS Teams chat
- : LINE CLC-Pilot
- : CUT 129.325
- : Phone 02-137-1202

In addition to above contact channels, for DOMESTIC flight, pilots may also directly contact
ground staff to request earlier CTOT. (ISSUED 15FEB25/BKKOP/UFN)

--DELEGATED FUNCTIONS PHONE DIRECTORY (Direct Number)

1. OPEN BOARDING GATE : 02-137-1260
 2. BUS GATE - REMOTE BAY & DOMESTIC V.V. : 02-137-1260
 3. CREW BUS OPC-TERMINAL V.V. : 02-137-1019, 02-137-1020
 4. CONFIRM BOARDING GATE/BAY/BELT : 02-137-1263
 5. ZFW/WEIGHT & BALANCE/LOAD SHEET : 02-137-1291, 02-137-1292
 6. TG LOST & FOUND : 02-134-5454
 7. OTHER INQUIRIES/BKKOC : 02-137-1202
- (ISSUED 17JUL22/BKKOC-INFO/UFN)

--If expected divert due to weather or traffic congestion at any TG destination airports,
please kindly advise TOCC, via ACARS using OPERATIONS prompt or SITA address BKKOPTG,
the current fuel on board immediately to keep close monitoring of the flight.
(ISSUED 08MAY25/BKKOP/UFN)

--In case of pilot receives information from ground staff to delay departure due to connecting
passenger, please kindly confirm with TOCC via CUT channel.
(ISSUED 27NOV24/BKKOP/UFN)

--FOR FLIGHTS PLANNED NAVIGATING THROUGH KABUL FIR,
ONCE FINAL FL TO ENTER KABUL FIR IS AVAILABLE,
PLEASE ACARS DOWNLINK ETO/ENTRY WPT/FL TO BKKOPTG
(ISSUED 12DEC24/BKKOC/UFN)

--Please kindly consider and issue recommendation for route P500 G500 as soon as possible in
order to reduce operational risk.

1.Due to limitation of passenger oxygen chemical type (22 minutes).
If weather deviation is required, pilots shall deviate west of route only.

2.In an event of critical in-flight emergency, the aircraft should follow ICAO emergency
descent procedures, broadcast status and intentions on 125.2 MHZ and 121.5 MHZ. Thereafter,
proceed at the discretion of the PIC until clear Kabul FIR and in contact with the ATC
responsible for the airspace.
(ISSUED 31JUL24/D1/OC/UFN)

--Any flight operation by TG into the uncontrolled airspace and conflict zone,
the latest operational information " Closures and Warnings" issued by means of ICAO State
letters,
NOTAMs, AICs/AIPs, and EASA CZIB - TG are subject to strictly following the
guidance/directions
from their national authority as well as their own risk assessment.
(ISSUED 15APR24 CORR/TN003/22/OW/UFN)

--WEF 01AUG26,
SUBJ: SPECIAL SECURITY ARRANGEMENT:SSA008/2026
ATTN ALL CONCERNED

THE AVIATION SECURITY COMMITTEE (ASC) MTG ON 23JUL2026
AGREED TO ANNOUNCE SSA008/2026 AS FLWS:

AA PLS BE INFM THT THIS SSA WILL SUPERSEDE SSA007/2026
FROM 01AUG2026 UNTIL FURTHER TLX ADV

BB FR FLT DEP FRM STATION EUROPE: ARN AMS BRU CDG CPH FRA IST
LHR MUC MXP OSL ZRH

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 2/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

LEVEL: LOW CMA PERFORM SSA ACCORDING TO EU REQUIREMENTS
AS FLWS:
A1 - A/C PRE-FLIGHT SECURITY SEARCH CONDUCTED BY PIC CMA
CABIN CREW CMA ASM/SMT/DELEGATED PERSONNEL N GROUND/
STATION ENGINEER
A18-1 5% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
CONDUCTED BY CABIN CREW

CC FR FLT DEP FRM STATION: DAC ISB KHI LHE RGN

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW

DD FR DOM FLT DEP FRM STATION: HDY

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW

EE FR FLT DEP FRM MAINBASE STATION: BKK

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW
F2 - IDENTITY CHECK OF CREW MEMBERS BEFORE BOARDING AT
BOARDING GATE
P2 - SECONDARY CHECK AT GATE
(APPLY ONLY FLT FRM BKK TO MEL PER N SYD)

FF THE FLWG SSA SHALL BE IMPLEMENTED FR ALL ROUTE AS NORMAL PROC
P5 - INTENSIVELY PERFORM IDENTITY CHECK N VERIFICATION OF PAX
BEFORE BOARDING A/C BY
- COMPARING PAX WZ PHOTOGRAPH N PASSPORT/TVL DOCS TO
ENSURE PAX IS BONA FIDE N
- VERIFYING THE NAMES IN THE TICKETS CORRESPOND TO THOSE
ON THE IDENTITY DOCS
V1 - ALERT STAFF TO OBSERVE UNUSUAL BEHAVIOR OF PAX N ALL
PERSONNEL INVOLVED N ANY SUSPICIOUS ITEM IN THE
OPERATING AREA

GG THOSE STN NOT ON THE LIST ABOVE ARE LOW LEVEL STP
APPLY NORMAL SECURITY PROC AS MENTIONED IN OPERATION MANUAL

ADDITIONAL INSTRUCTION.

FR FLT OPS TO BLR MAA N CCU PLS IMPLEMENT THE FLW MEASURES AT THE
CHK-IN COUNTERS;
1. PROV DEDICATED CHK-IN COUNTERS FR FLT TO BLR MAA N CCU
2. DISPLAY WARNING N INFO SIGNAGE AT:
-CHK-IN COUNTERS
-B/D GATE
-FLT INFO DISPLAY SYSTEM (FIDS) AT CHK-IN COUNTERS
3. CONDUCT RANDOM X-RAY SCREENING OF SUSPICIOUS BAG AT CHK-IN
COUNTERS
4. CONDUCT RANDOM SCREENING BY USING SNIFFER DOGS IN THE CHK-IN AREA.

IN CASE OF THREAT SITU N EXTRA MEASURES ARE REQ CMA
STN MONITORING TEAM/SMT MAY RAISE UP MEASURES AS APPROPRIATE

ANY SECURITY INCIDENTS MAY OCCUR SHALL INFO MANAGEMENT CONCERNED
N BKKD1 ACCLY STP

REMARK

A18-1 5% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
WILL BE REVISED IN SPM NEXT REVISION

PLS ACK N CFM ACTUAL PERFORM TO OFC BKKD1-B
BRGDS/CAPT. CHINGCHEEP B./BKKD1 ASC CHAIRMAN

Company Fuel Guidelines

THA 00195/26 (16 JUL 26)

COM INFO:--WEF 17JUL26,
Company Fuel Guidelines:
1) Flight Outbound from VTBS:
1.1) 15 mins:
-TG319
-ETA within TEMPO ±1 hr with adverse weather condition

1.2) 5 mins:

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 3/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

-BLR (ONLY WHEN SINGLE RWY OPS)
-TG317, TG407, TG409

2) Flight Inbound to VTBS:

2.1) 20 mins:

ETA within TEMPO ± 2 hrs with adverse weather condition*

2.2) 5 mins:

*ETA 1400-1600 (BKK local time)

3) European Flights:

3.1) Outbound flight to European: CF 3 PERCENT (Except TG916/CF5)

3.2) Inbound flight to VTBS: RCFP*

4) Flight Level Plan for VTUK,

-Outbound from VTBS: FL250

-Inbound to VTBS: FL240

5) Planning for Arrival WADD:

To improve flight planning accuracy, for WADD arrivals, after waypoint KOLTA, flights shall plan to DOBMA and then follow DOBMA## STAR.

6) TG649: Flight level shall not be planned above FL380.

7) TG900: When ETA falls within TEMPO ± 2 hrs and adverse weather conditions, LTAC shall be designated as the destination alternate.

8) Destination VTUD:

Remove altitude restrictions and use the optimum altitude for planning.

Remark:

1) Pilot Management Department (PA)

1.1) Destinations ZBAA and ZSPD:

Flights shall be planned as Economic Tankage without company fuel, with the following conditions:

-Widebody aircraft shall be planned with far alternates (RKSI, RJFF).

-Narrowbody aircraft shall be planned with ZBTJ as the alternate; however, ZFW shall be restricted to ensure the carriage of at least 30 minutes of extra fuel.

1.2) Destination YPPH: ALTN YGEL (+05MINS EXTRA FUEL)

YGEL shall be used as ALTN airport effective 25 Apr 2026 following revision of OM-A section 8.3.26 (Operations at Uncontrolled Aerodromes)

2) Everything else regarding fuel planning policy remains the same as last month.

3) Adverse weather conditions*:

RA, TS or TSRA and visibility 5000m or less

(REVISED NO.1/REF EMAIL Summary of Fuel Initiatives Meeting - 13JUL26
For Fuel Committee member/BKKPC)

Minima for flight planning

THA 00136/26 (29 MAY 26)

COM INFO: Application of planning minima for flight planning

Due to limited space in the OFP fuel planning box, any display of "BASIC FUEL SCHEME" shall be interpreted as "BASIC FUEL SCHEME WITH VARIATION."

All THAI flights are planned using Basic Fuel Scheme with Variation, unless otherwise specified by Flight Dispatcher.

Alternate planning minima shall be applied in accordance with OMA 8.1.7.5.2.
Display format will be reviewed and updated following stakeholder discussion.

OFP - TCAR format

THA 00093/26 (18 MAY 26)

COM INFO: SFP/OFP change format according to OM-A (TCAR version)

Due to identified limitations in the current OFP template, the following temporary procedures shall apply with immediate effect:

1. RVSM - Standby Altimeter

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 4/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

The current OFP does not provide a dedicated line for Standby Altimeter recording as required by OMA 14.4.4.

Action: Record the Standby Altimeter value adjacent to the existing record row.

This procedure is mandatory to ensure compliance with OMA 14.4.4.

2. RAIM Information

RAIM shown in the OFP is for terminal operations only.

Action: For flights requiring NPA, crew shall verify RAIM availability separately using an approved RAIM Forecast Report.

3. RCFP - MINF at DP

the displayed MINF at DP may be incorrect.

Action: Disregard the displayed value and refer to the minimum fuel at DP provided in the eOFP application to maintain information consistency.

These instructions are mandatory until corrected in the next OFP version.

FLIGHT LEG INFORMATION

RJAAVTBS

## AIC NR 011/26 ##	THA 00211/26 (31 JUL 26)
// (SEE ATTCH) //	
## AIC 012/26 ##	THA 00364/25 (31 JUL 26)
// (SEE ATTCH) //	
## AIP SUP NR 165/26 ##	THA 00014/26 (08 JUL 26)
// (SEE ATTCH) //	
## NRT-HAZARD MAP ##	THA 00172/26 (26 JUN 26)
// (SEE ATTCH) //	
## REF AIC 051/19 ##	THA 00630/19 (28 JAN 26)
// (SEE ATTCH) //	
## AIP SUP 224/25 ##	THA 00362/25 (09 MAY 26)
// (SEE ATTCH) //	
## AIC NR 018/24 ##	THA 00231/24 (18 APR 26)
// (SEE ATTCH) //	

AERODROME INFORMATION

RJAA / NRT

// (COM-INFO) //	THA 00211/13 (05 AUG 26)
COM INFO:--CURFEW TIME BETWEEN 1400-2100 UTC (ISSUED 17APR/OW-INFO)	
	RJAAA1193/26 (05 AUG 26)
RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT.	
	RJAAA1179/26 (05 AUG 26)
GROOVING FOR RWY 16R/34L PARTLY ERASED DUE TO CONST LEN: 25.0M (BTN 241.15M AND 266.15M FM RWY 16R THR) WID: 6.0M (BTN 2.0M AND 8.0M ON THE WEST SIDE OF RCL)	
	RJAAA1167/26 (05 AUG 26)
"TWY-CL-LGT FOR TWY Q5(INT OF Q),Q5,Q6(BTN SPOT 11 AND SPOT 16) U/S DUE TO CONST"	
	RJAAA1158/26 (05 AUG 26)
"TWY-CL-LGT FOR TWY D1(BTN M AND M1-GWY),D1(INT OF M),D3(FM M TO N1) U/S DUE TO TROUBLE"	
	RJAAA1131/26 (05 AUG 26)
1510-2030 "TWY K(BTN E1 AND K1-HOLD),C(INT OF E1),C(BTN E1 AND P1),E1 CLSD	

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 5/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

DUE
TO MAINT"

RJAAA1129/26 (05 AUG 26)

1410-2030
"TWY B,B1 THRU B9,F(BTN F1 AND F3),F(BTN F4 AND F5),F1 THRU F5,
K(BTN B AND B6),C(BTN B AND E1),L(BTN B9 AND U5) CLSD DUE TO MAINT"

RJAAA1128/26 (05 AUG 26)

1510-2030
"TWY A,A1 THRU A10 CLSD DUE TO MAINT
1.EXC ACFT IN AIC 051/19 ITEM 3
2.EXC EMERG ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

*RJAAA1127/26 (05 AUG 26)

1510-2030
RWY 16R/34L CLSD DUE TO MAINT
1.EXC ACFT IN AIC051/19 ITEM3
2.EXC EMERG ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR

*RJAAA1126/26 (05 AUG 26)

1410-2030
RWY 16L/34R CLSD DUE TO MAINT

RJAAA1095/26 (20 JUL 26)

STOP-BAR-LGT FOR TWY B1 THRU B9 U/S
RMK: (1)REF AIP SUP 165/26 ITEM TWY:5
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAA1093/26 (20 JUL 26)

"TWY-CL-LGT FOR TWY A,A2 U/S
RMK: (1)REF AIP SUP 165/26 ITEM TWY:2
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER"

RJAAA1091/26 (20 JUL 26)

"FLW LGT U/S
PALS FOR RWY 16L
SEQUENCED-FLG-LGT FOR RWY 16L
RMK: (1)REF AIP SUP 165/26 ITEM RWY:1,2
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER
NOTAM"

RJAAA1049/26 (20 JUL 26)

"TWY-CL-LGT FOR TWY N2,D1(INT OF M),M(BTN D2 AND H1) U/S DUE TO
CONST"
30 JUN 26 20:00 UNTIL 29 SEP 26 15:00 ESTIMATED

RJAAA0892/26 (20 JUL 26)

TRIGGER NOTAM-PERM AIRAC AIP AMDT NR8/2026
WEF 06 AUG 2026
UPDATE OF ILS(RWY 34L) AND ABOLISHMENT OF IM(RWY 16R

RJAAA0722/26 (04 JUN 26)

"VISUAL-DOCKING-GUIDANCE-SYSTEM FOR SPOT 61,66,71,84,85,88,97-U/S
DUE TO CONST"

VTBS / BKK

// (COM-INFO)//

THA 00064/25 (09 AUG 26)

VTBS:--REF AIP SUP A53/25:
RETIls U/S:
RWY 01/19: TWYs B3, B5, B7, B8, B10 and B11
RWY 02R/20L: TWYs E5, E7, E9, E12, E13, E15.

--REF AIP SUP A13/25:
1) The Visual Docking Guidance System (VDGS) at
the ACFT stands 101 - 114 are U/S. (14 ACFT stands).
2) Airlines or Ground service providers shall provide a License Mechanic
performed as Marshaller to guide the aircraft from taxilane to the
parking position.
3) The ACFT are strongly advised to strictly follow the Marshaller's signal.

--REF AIP SUP A54/24:
DVOR/DME (SVB) (133932.5N 1004353.2E) (111.4 MHZ, CH51X) temporary suspended

from 28 November 2024 at 0001 UTC to 02 October 2026 at 0949 UTC.

--REF AIP SUP A01/25:
Taxiway C between Taxilane T1 and Taxilane T2, Taxiway C1 closed.

OB Company Safety NOTAM-BKK##

THA 00161/26 (09 AUG 26)

// (SEE ATTCH)//

VTBDC4473/26 (07 AUG 26)

ADVANCED VISUAL DOCKING GUIDANCE SYSTEM (A-VDGS)
ACFT STAND NR 119 505 AND 520 U/S DUE TO MAINT
RMK: ACFT HAVE TO FLW MARSHALLING SIGNALS STRICTLY

VTBDC4316/26 (05 AUG 26)

TWY CLSD DUE TO WIP DETAIL AS FLW:
-TWY E BTN TWY D1 AND TWY D2
-TWY D1
-TWY D BEHIND ACFT STAND NR 516-525

VTBDC4026/26 (20 JUL 26)

ADVANCED VISUAL DOCKING GUIDANCE SYSTEM (A-VDGS)
ACFT STAND NR 501 U/S DUE TO MAINT
RMK: ACFT HAVE TO FLW MARSHALLING SIGNALS STRICTLY

VTBDC3521/26 (11 JUL 26)

TRIGGER NOTAM-PERM AIRAC AIP AMDT 08/26 WEF 06 AUG 2026.
AD 2-VTBS-1 AD 2.4 HANDLING SER AND FAC
AD 2.20 LCA AD REGULATIONS

VTBU / UTP

VTBDC4363/26 (03 AUG 26)

ILS RWY 18 U/S DUE TO MAINT

VTBDC4088/26 (20 JUL 26)

TWY EDGE LGT U/S DUE TO MAINT DETAIL AS FLW:
-TWY B
-TWY E BTN TWY B AND TWY F

// (COM-INFO)//

THA 00176/26 (15 JUL 26)

VTBU:--(NEW)+++Due to the unavailability of LAE at UTP Station.
In the event of a diversion to UTP, flight crews shall perform aircraft refueling in accordance with the applicable refueling procedures specified in the respective Fleet FCOM.
(ISSUED 02JUL26/BKKOC/UFN)

*VTBDC3302/26 (03 JUL 26)

PALS CAT 1 RWY 18 AND SALS RWY 36 U/S DUE TO MAINT

VTBDC3240/26 (03 JUL 26)

OBST MOBILE CRANE HGT 98.425FT AGL ERECTED DETAIL AS FLW:
PSN 1: 123937.98N1010027.35E
DIST 346.47M BFR THR RWY 36 AND 455.00M RIGHT SIDE OF RCL
PSN 2: 124005.68N1010029.64E
DIST 507.53M BEYOND THR RWY 36 AND 454.95M RIGHT SIDE OF RCL

*VTBDC2844/26 (07 JUN 26)

AD CATEGORY FOR FIRE FIGHTING AND RESCUE SERVICES
DOWNGRADED TO CAT 9.

VTBDC0333/23 (06 APR 24)

"IAC-ICAO-NDB RWY 36 CHANGED AS FLW:
-OCA/H : STRAIGHT-IN APPROACH
: READ 790(766)FT INSTEAD OF 750(726)FT
-OCA/H : CIRCLING APPROACH CAT A, B
: READ 1200(1141)FT INSTEAD OF 750(726)FT, 1190(1166)FT
-OCA/H : CIRCLING APPROACH CAT C, D
: READ 1450(1391)FT INSTEAD OF 1290(1266)FT, 1445(1421)FT
REF AIP VTBU AD 2.24, AD 2-VTBU-8-1"

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 7/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

ADDITIONAL INFORMATION

VTBD / DMK

VTBDC4440/26 (06 AUG 26)

2230-0400
"ILS RWY 21L ON TEST, DO NOT USE"

VTBDJ6039/26 (06 AUG 26)

DAILY 2300-0300
ILS RWY 21L FLTICK WILL TAKE PLACE RADIUS 15NM
CENTRE 135451.74N1003620.49E
RMK: DEP/ARR ACFT WILL BE DLA DURING THIS PERIOD
F) GND
G) 3500FT AMSL

// (COM-INFO) //

THA 00435/14 (04 AUG 26)

COM INFO:-- DMK TG LINE MAINTENANCE WILL PROVIDE RAMP HANDLING SERVICE ON
TG FLIGHTS DIVERTED TO DMK, WHILE PIC MUST PERFORM REDUCE LINE CHECK
TO RELEASE AIRCRAFT. PRIOR TO FLIGHT DIVERSION TO DMK PLS INFORM
TOCC COMMAND CENTER (OC) VIA CUT FREQUENCY 129.325 MHZ
TO COORDINATE WITH DMK TG LINE MAINTENANCE IN ADVANCE FOR SMOOTH
HANDLING UPON ARRIVAL AT DMK
CONTACT POINTS FOR DMK LINE MAINTENANCE IN (24hrs)
AT DMK ARE AS FLW
1. TEL: 02-563-8178 (66-8178, 9999)
2. Email dmkjcb@thaiairways.com
(ISSUED 12DEC24/OP/UFN)

// (COM-INFO) //

THA 00214/26 (04 AUG 26)

VTBD:--REF AIP SUP A25/26:
1 INTRODUCTION
With effect from 24 July 2026 at 0000 UTC, the purpose of this AIP Supplement is to inform
pilots and operators concerning the unserviceability
of Rapid Exit Taxiway Indicator Lights (RETILs) of runway 21R at Don Mueang International
Airport.
2 DETAILS
RETILs for rapid exit taxiway O will be unserviceable.
3 CONTACT
Unit: Aeronautical Information Service Sub-Division, Airside Operations Division (VTBD)
Tel: +662 535 1782, +662 535 1793
Email: aisvtbd@airportthai.co.th
4 VALIDITY
This AIP Supplement supersedes NOTAM C3646/26, A2407/26 and will remain current until further
advised. Any changes to this AIP Supplement
will be notified through NOTAM.

*VTBDC4399/26 (04 AUG 26)

04 AUG 2026 16:00-10 AUG 2026 22:00
04 06 07 08 10 1600-2200
RWY 03L/21R CLSD DUE TO WIP

VTBDJ5310/26 (04 AUG 26)

"TEMPO RESTRICTED AREA ACT RADIUS 0.5NM CENTRE
135526.22N1003713.11E APPROVAL SHALL BE MADE BEFORE ENTERING,
EXCEPT DEP AND ARR ACFT AT VTBD PILOT IN COMMAND SHALL STRICTLY
COMPLY WITH ATC INSTRUCTION"
F) GND
G) 3000FT AGL

VTBDC3519/26 (04 AUG 26)

TRIGGER NOTAM-PERM AIRAC AIP AMDT 08/26 WEF 06 AUG 2026.
AD 2-VTBD-1 AD 2.22 FLT PROC

VTUU / UBP

VTBDJ5964/26 (03 AUG 26)

DAILY 0100-1100
GUN FRNG WILL TAKE PLACE WI AREA
151219N1045456E-151204N1045548E-151132N1045519E-
151207N1045448E-151219N1045456E

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 8/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

F) GND
G) 1000FT AGL

VTBDC4321/26 (31 JUL 26)

ROAD CONSTRUCTION FROM FIRE STATION TO RUNWAY 05/23
AT UBON RATCHATHANI AIRPORT. EXTD TO 31 OCT 2026 AT 1500UTC.
REF AIRAC AIP SUP B06/26

*VTBDC4257/26 (28 JUL 26)

"AD OPR HR ATS AND ARO HR SER CHANGED AS FLW:
JUL 28 1307-1415, 28-SEP 27 2300-1400"

VTBDC3533/26 (27 JUN 26)

TRIGGER NOTAM-PERM AIRAC AIP AMDT 08/26 WEF 06 AUG 2026.
AD 2-VTUU-1 AD 2.2 AD GEOGRAPHICAL AND ADMINISTRATIVE DATA
AD 2.24 CHARTS RELATED TO AN AD
AD 2-VTUU-2 ADC-ICAO
ACFT PRKG/DCKG CHART-ICAO
AD GND MOV CHART-ICAO
AD 2-VTUU-6 SID-ICAO RNAV RWY 23

VTBDC3445/26 (24 JUN 26)

STRIP RWY 05/23 WIP FM THR RWY 05 TO DIST 442M
ON BOTH SIDES OF RWY 05

VTBDC3444/26 (24 JUN 26)

STRIP RWY 05/23 WIP FM THR RWY 23 TO DIST 442M
ON BOTH SIDES OF RWY 23

VTCC / CNX

VTBDC4510/26 (09 AUG 26)

TWY Q BTN TWY F AND ACFT STAND NR 20R CLSD
DUE TO TEMPO ACFT PRKG.

// (COM-INFO)//

THA 00444/15 (09 AUG 26)

VTCC:--REF AIP SUP A19/25:
1 INTRODUCTION
With effect from 17 April 2025 at 1000 UTC,
the purpose of this AIP Supplement is to inform all concerned regarding the Aircraft stand
number 1 closed at Chiang Mai International Airport.
2 DETAILS
Aircraft stand number 1 closed for improvements to enhance aircraft parking compatibility.

VTBDC4503/26 (09 AUG 26)

ACFT STAND NR 6 CLSD DUE TO WIP

VTBDC4502/26 (09 AUG 26)

ACFT STAND NR 5 CLSD DUE TO WIP

VTBDJ5911/26 (05 AUG 26)

DAILY 0200-0500 0600-0900
UNMANNED AIRCRAFT WILL TAKE PLACE RADIUS 1.3NM CENTRE
184820.07N0985736.03E
F) GND
G) 150FT AGL

VTBDC4220/26 (05 AUG 26)

RVR RWY 36 U/S

VTBDC4059/26 (20 JUL 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS) ACFT STAND NR 3 U/S

VTBDC3965/26 (09 AUG 26)

OBST TOWER CRANE HGT 230FT AGL ERECTED AT
184725.38N0985815.11E DIST 1038M BFR THR
RWY 18 AND 854M LEFT SIDE OF EXTD RCL

VTBDC3956/26 (09 AUG 26)

"JUL 15 0210-1100, JUL 16-SEP 30 0100-1100"
OBST MOBILE CRANE HGT 82FT AGL ERECTED AT
184704.31N0985757.46E DIST 390M BFR THR
RWY 18 AND 328M LEFT SIDE OF EXTD RCL

VTBDC3306/26 (03 JUL 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS)
ACFT STAND NR 7 AND NR 8 U/S

VTBDJ4315/26 (07 JUN 26)

TEMPO RESTRICTED AREA ACT RADIUS 0.5NM CENTRE 184626N0985806E
(EXCLUDING LDG AND TKOF RWY 18/36)
F) GND
G) 3000FT AGL

ENROUTE INFORMATION

ASP / ASIA/PACIFIC
N I L

JPN / JAPAN OCEANIC AREA
N I L

RJJJ / FUKUOKA FIR

RJAAQ1892/26 (09 AUG 26)

10 AUG 2026 07:00-10 AUG 2026 21:00
"EASTBOUND PACOTS TRACKS BETWEEN SOUTHEAST ASIA AND NORTH AMERICA,
TRACK 14.
FLEX ROUTE : EMRON 40N160E 43N170E 44N180E 44N170W 43N160W
42N150W 40N140W 38N130W ALLBE
RCTP/VHHH ROUTE : MOLKA M750 MUKEP Y891 OVSUN Y893 IGMIS Y57 POROT
OTR11 AVBET OTR9 EMRON
NAR ROUTE : ACFT LDG KSFO--ALLBE PIRAT OSI KSFO
ACFT LDG KLAX--ALLBE PIRAT BURGL IRNMN KLAX
RMK : TRK 15 NOT AVAILABLE
ATM CENTER TEL:81-92-608-8870"

RJAAQ1891/26 (09 AUG 26)

10 AUG 2026 10:00-10 AUG 2026 21:00
"EASTBOUND PACOTS TRACKS BETWEEN JAPAN AND HAWAII,
TRACK 11.
FLEX ROUTE : SEALS 35N150E 34N160E 33N170E 30N180E 27N170W DANNO
JAPAN ROUTE : LAPIL OTR13 SEALS
PHNL ROUTE : DANNO BOOKE PHNL
RMK : TRK 11 NOT AVAILABLE IF CROSSING DANNO AFTER 1830Z.
TRACK 12.
FLEX ROUTE : SEALS 35N150E 34N160E 33N170E 30N180E 27N170W SYVAD
JAPAN ROUTE : LAPIL OTR13 SEALS
PHNL ROUTE : SYVAD BOOKE PHNL
RMK : ATM CENTER TEL:81-92-608-8870"

RJAAQ1890/26 (09 AUG 26)

10 AUG 2026 07:00-10 AUG 2026 21:00
"EASTBOUND PACOTS TRACKS BETWEEN JAPAN AND NORTH AMERICA,
TRACK 1.
FLEX ROUTE : OMOTO R580 OPHET PLADO CHIKI 51N170W 51N160W 50N150W
49N140W PRETY
JAPAN ROUTE : MAKMU R580 OMOTO
NAR ROUTE : ACFT LDG KSEA/KPDX--PRETY TOU KSEA/KPDX
ACFT LDG CYVR--PRETY GOVAD CYVR
RMK : ACFT LDG OTHER DEST--PRETY UPR TO DEST
TRACK 2.
FLEX ROUTE : ADGOR AGEDI AKISU ASPIN LYYLE 50N180E 49N170W 48N160W
47N150W 45N140W 42N130W VESPA
JAPAN ROUTE : ADNAP R591 ADGOR
NAR ROUTE : ACFT LDG KSFO--VESPA AMAKR BGGLO KSFO
ACFT LDG KLAX--VESPA ENI OAK BURGL IRNMN KLAX
TRACK 3.
FLEX ROUTE : EMRON 42N160E 44N170E 45N180E 45N170W 44N160W 43N150W
41N140W 39N130W DACEM
JAPAN ROUTE : AVBET OTR9 EMRON
NAR ROUTE : ACFT LDG KLAX--DACEM PAINT PIRAT BURGL IRNMN KLAX
ACFT LDG KSFO--DACEM PAINT PIRAT OSI KSFO
RMK : ATM CENTER TEL:81-92-608-8870"

RJAAY0896/26 (09 AUG 26)

09 AUG 2026 14:59-10 AUG 2026 16:00
"FLOW CTL AS FLWS,

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 10/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

AREA: ATS RTE A593/Y592
PROC: EXP DEP CLR TIME WILL BE ISSUED TO ACFT WB VIA ONIKU DETOURING
AROUND TYPHOON DOLPHIN
RMK: REF AIP ENR1.9-1"

RJAAZ1321/26 (09 AUG 26)

09 AUG 2026 14:36-10 AUG 2026 16:00
"FLOW CTL AT FIR BDRY AS FLWS,
RTE: B576/Y742
ACFT: SB FOR MANILA FIR VIA KABAM DEP FM KOREA
PROC: (1) 12MIN INTERVAL REGARDLESS OF ALT WILL BE APPLIED AT ATOTI OR
MUGUS
(2) ATOTI OR MUGUS ONLY AVBL DEP FM KOREA
RMK: REF AIP ENR1.9-1"

*RJAAQ1889/26 (09 AUG 26)

"CDR ARE ESTABLISHED AS FLW,
RTE PERIOD MNM APPLICABLE ALT
1) L512 2608101200/2608102200 MEA
2) Z13 2608101200/2608102200 MEA
3) Z14 2608101200/2608102200 MEA
4) Z25 2608101330/2608101910 MEA
5) Z26 2608101330/2608101910 MEA
6) Z27 2608101330/2608101910 MEA
7) Z40 2608092200/2608102200 MEA
8) Z41 2608092200/2608101910 MEA
9) Z262 2608101330/2608102200 MEA
RMK: REF AIP ENR3.3"

*RJAAQ1888/26 (09 AUG 26)

"CDR ARE ESTABLISHED AS FLW,
RTE PERIOD MNM APPLICABLE ALT
1) Z16 2608101300/2608102100 MEA
2) Z17 2608092100/2608092200 MEA
Z17 2608101300/2608102100 MEA
3) Z18 2608092100/2608092200 MEA
Z18 2608101300/2608102100 MEA
4) Z21 2608092100/2608092200 MEA
Z21 2608101200/2608102100 MEA
5) Z101 2608101300/2608102100 MEA
6) Z102 2608101300/2608102100 MEA
7) Z162 2608092100/2608092200 MEA
Z162 2608101300/2608102100 MEA
8) Z171 2608092100/2608092200 MEA
Z171 2608101200/2608102100 MEA
9) Z182 2608092100/2608092200 MEA
Z182 2608101200/2608102100 MEA
RMK: REF AIP ENR3.3"

RJAAY0895/26 (09 AUG 26)

09 AUG 2026 09:55-10 AUG 2026 16:00
FLOW CTL AS FLWS :
AREA : ATS RTE A1/G581/Y26/Y52
PROC : EXP DEP CLR TIME WILL BE ISSUED TO ACFT VIA KABAM N892
RMK : REF AIP ENR 1.9-1.

*RJAAP3916/26 (09 AUG 26)

"ROCKET H3(QZS-7) WILL BE LAUNCHED
LAUNCHING DATE AND TIME : BTN 2608101923 AND 2608102023
RMK: REF AIP SUP 104/26 ITEM 1,2,3"
F) SFC
G) UNL
09 AUG 26 09:11 UNTIL 10 AUG 26 20:56 ESTIMATED

RJAAZ1311/26 (09 AUG 26)

09 AUG 2026 00:44-10 AUG 2026 16:00
"FLOW CTL AT FIR BDRY AS FLWS,
RTE: A593/Y592
ACFT: WB FOR DETOURING TYPHOON DEP FM JAPAN
PROC: 60MIN INTERVAL REGARDLESS OF ALT WILL BE APPLIED AT ONIKU."

RJAAQ1887/26 (09 AUG 26)

"CDR ARE ESTABLISHED AS FLW,
RTE PERIOD MNM APPLICABLE ALT
1) Z29 2608101500/2608102100 MEA
2) Z31 2608101500/2608102100 MEA
3) Z32 2608101500/2608102100 MEA

4) Z34 2608101500/2608102100 MEA
RMK: REF AIP ENR3.3"

// (COM-INFO) //

THA 00046/20 (08 AUG 26)

COM INFO:--FOR DATA LINK COST-EFFICIENT OPERATIONS:
1) PREFLIGHT:
VERIFY BOTH HF SET TO VOICE MODE
DISREGARD MEMO MESSAGE ABOUT HF DATALINK
NOTE: HF SHALL BE SET TO DATA IF BOTH VHF (DATA) AND SAT (DATA) ARE LOST
2) IN FLIGHT PROCEDURE:
WHEN ENTERING JAPANS FIR .. SET ACARS VHF TO VOICE
WHEN EXITING JAPANS FIR .. SET ACARS VHF TO DATA

IF SATCOM DATA IS UNSERVICEABLE,
SET VHF3 BACK TO DATA TO RECOVER DATALINK CAPABILITY.
(ISSUED 02JAN25/TN001/25/OP/UFN)

--AWY A593 (ONIKU-NIRAT-SADLI-LAMEN) (FUKUOKA FIR-INCHEON FIR-SHANGHAI FIR)
FOLLOWING ALTITUDE ARE USED BY FUKUOKA ACC:
WESTBOUND: FL240, FL280 OR FL300, FL400,
EASTBOUND: FL250, FL290 OR FL310, FL390
(ISSUED 27JUN/REF AIP REPUBLIC OF KOREA/OW/UFN)

*RJAAP3876/26 (08 AUG 26)

09 AUG 2026 22:00-10 AUG 2026 13:30
"IWAKUNI TEMPO RESERVED AIRSPACE ACT AS FLW,
NAME/ID ALT PERIOD
ITRA-E SFC/FL250 2608092200/2608101330
ITRA-N1 SFC/FL180 2608092200/2608101330
ITRA-N2 SFC/FL600 2608092200/2608101330
ITRA-N3 SFC/FL240 2608092200/2608101330
ITRA-S10 SFC/FL600 2608092200/2608101330
ITRA-S11 SFC/FL600 2608092200/2608101330
ITRA-S12 SFC/FL600 2608092200/2608101330
ITRA-S13 SFC/FL600 2608092200/2608101330
ITRA-S14 SFC/FL600 2608092200/2608101330
ITRA-S15 SFC/FL600 2608092200/2608101330
ITRA-S16 SFC/FL600 2608092200/2608101330
ITRA-S20 SFC/FL450 2608092200/2608101330
ITRA-S21 SFC/FL450 2608092200/2608101330
ITRA-S22 SFC/FL450 2608092200/2608101330
ITRA-S23 SFC/FL450 2608092200/2608101330
ITRA-S24 SFC/FL450 2608092200/2608101330
ITRA-S25 SFC/FL450 2608092200/2608101330
ITRA-S30 SFC/FL250 2608092200/2608101330
ITRA-S31 SFC/FL250 2608092200/2608101330
ITRA-S32 SFC/FL250 2608092200/2608101330
ITRA-S33 SFC/FL250 2608092200/2608101330
RMK:REF AIP SUP 023/26"
F) SFC
G) FL600

RJAAQ1861/26 (06 AUG 26)

CHICHIJIMA TACAN/CIT-U/S DUE TO POWER OUTAGE
RMK:EXC ACFT WITH PRIOR PERMISSION
SOURCE/JSDF-M(RJAO

RJAAQ1816/26 (08 AUG 26)

"REF AIP SUP 107/26(CHANGE TO READ)
HEAVY BALLOON RELEASING(HAPS)
CHANGE TO READ
NAME OF BALLOON
HBAL804
HBAL805
SSR CODE
HBAL804,CODE:2572
HBAL805,CODE:2573
ESTIMATED PERIOD OF RELEASE
FROM 24 MAY 2026 TO 30 OCT 2026
PERIOD OF STAY AT FUKUOKA FIR
UP TO APRX 120DAYS
REMARKS
TEL:080-8534-4642(FIRST PRIORITY)
080-8316-8142(SECOND PRIORITY)
THIS NOTAM WILL BE INCORPORATED IN SUP"

RJAAQ1773/26 (08 AUG 26)

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 12/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

TIL 23 DEC 2026
UNSERVICEABILITY AND ALTERNATE PROCEDURES OF SENDAI VOR/DME (SDE)
TEMPORARY ESTABLISHMENT OF REPORTING POINT
TEMPORARY CHANGE OF REPORTING POINTS
TEMPORARY ESTABLISHMENT OF DIRECT ROUTES

RJAAQ1772/26 (08 AUG 26)

TRIGGER NOTAM-AIRAC AIP SUP NR172/26
WEF 03 SEP 2026 TIL 17 FEB 2027
UNSERVICEABILITY AND ALTERNATE PROCEDURES OF ISHIGAKIJIMA VOR/DME (IGE)
TEMPORARY ESTABLISHMENT OF REPORTING POINT
TEMPORARY CHANGE OF REPORTING POINTS
TEMPORARY ESTABLISHMENT OF DIRECT ROUTES
TEMPORARY CHANGE OF EN-ROUTE HOLDING

RJAAQ1578/26 (08 JUL 26)

"TRIGGER NOTAM-PERM AIRAC AIP AMDT NR9/2026
WEF 06 AUG 2026
CHANGE OF WX OBS TIME
ESTABLISHMENT OF REPORTING POINT, ETC
LED CONVERSION OF ABN AT HANAMAKI AP/RJSI"

RJAAQ1524/26 (08 JUL 26)

"REF AIP PAGE GEN 3.6-7
APPLICABLE AIRCRAFT TEMPO CHANGE AS FLW
CHANGE TO READ
3.4.1 APPLICABLE AIRCRAFT
AIRPLANES USED FOR AIR TRANSPORT SERVICES WHOSE MAXIMUM
CERTIFICATED TAKE-OFF MASS IS OVER 27,000 KG AND TO WHICH THE
CERTIFICATE OF AIRWORTHINESS WAS FIRST ISSUED ON OR AFTER 1 JANUARY
2024(EXCEPT FOR B777F)."
30 JUN 26 15:00 UNTIL 29 SEP 26 14:59 ESTIMATED

RJAAZ0810/26 (25 JUN 26)

1910-2200
"FLOW CTL AT FIR BDRY AS FLWS,
RTE: B576/Y741/Y743
ACFT: NB ENTERING INCHEON FIR
PROC: FL390 NOT AVBL AT SALMI AND LIPLO
RMK: REF AIP ENR1.9-1"

RJAAQ1348/26 (25 JUN 26)

"TRIGGER NOTAM-PERM AIRAC AIP AMDT NR8/2026
WEF 06 AUG 2026
UPDATE OF KOCHI VOR/DME
REVISION OF AWY
REVISION OF RNAV ROUTES
ESTABLISHMENT AND ABOLISHMENT OF DCT ROUTES
ESTABLISHMENT OF REPORTING POINT, ETC."

RJAAQ1173/26 (22 MAY 26)

OPERATORS OF AIRCRAFT REGISTERED IN JAPAN ARE ADVISED NOT TO ENTER
MINSK(UMMV) FIR DUE TO SERIOUS SAFETY AND SECURITY CONCERNS TO
COMMERCIAL AVIATION.
19 MAY 26 00:54 UNTIL 18 AUG 26 14:59 ESTIMATED

RJAAP2331/26 (18 MAY 26)

"ALL ACFT INTENDING TO FLY WI FUKUOKA FIR ARE ADVISED TO PAY
SPECIAL ATTENTION TO THE FOLLOWING INFORMATION.
IN ACCORDANCE WITH ARTICLE 82-3 OF JAPAN SELF DEFENSE FORCE LAW,
ANTIBALLISTIC MISSILES MAY BE LAUNCHED FOR THE DESTRUCTION OF THE
ROCKET EXPECTED TO BE LAUNCHED FROM NORTH KOREA.
THE ANTIBALLISTIC MISSILES ARE DEPLOYED AT POSITIONS BLW,
(1)NAHA-SHI : 261219N1273929E
(2)MIYAKOJIMA : 244602N1251930E
(3)ISHIGAKIJIMA : 242404N1241121E
(4)YONAGUNIJIMA : 242638N1225716E"
F) SFC
G) UNL
18 MAY 26 08:35 UNTIL 17 AUG 26 15:00 ESTIMATED

TWN / TAIWAN
N I L

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 13/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

RCAA / TAIPEI FIR

RCTPA2792/26 (09 AUG 26)

09 AUG 2026 10:35-10 AUG 2026 16:00
"CONSEQUENT TO FLOW CTL IMPOSED BY MANILA ACC, FLOW CTL AT FIR
BDRY AS FLW:
ACFT DEP FM KOREA/JAPAN OVERFLYING TAIPEI FIR ENTERING MANILA FIR
VIA KABAM IS SUBJECT TO THE FLW RESTRICTIONS:
(1) 10 MIN INTERVAL REGARDLESS OF ALT AT SALMI
(2) 15 MIN INTERVAL REGARDLESS OF ALT AT BULAN
(3) 12 MIN INTERVAL REGARDLESS OF ALT AT IGURU
(DEP FM KOREA VIA SALMI ONLY)
(DEP FM JAPAN VIA BULAN/IGURU ONLY)"

RCTPA2731/26 (06 AUG 26)

AUG 07 08 10-14 0120-0300
"REF AIP SUP 15/26, AIRSPACE BLOCKED DUE TO FLIGHT TESTING AND
RELATED ALTERNATE ROUTES AND MEASURES.
BLOCKED AREA B(SFC-FL450) DRG
AUG 07 08 10-14 0200-0300 SUSPENDED,
RELATED ALTERNATE ROUTES AND MEASURES DRG
AUG 07 08 10-14 0120-0300 SUSPENDED."

RCTPA2089/26 (25 JUN 26)

"TRIGGER NOTAM-PERM AIRAC AIP AMDT 03/26,
WEF 06 AUG 2026, 0000UTC.
AREA FOUR IS REVISED AS AREA FOUR (A) AND AREA FOUR (B)."

RCTPA2088/26 (25 JUN 26)

"TRIGGER NOTAM-PERM AIRAC AIP AMDT 03/26,
WEF 06 AUG 2026, 0000UTC.
THE TABLE OF MET OBSERVATIONS AND REPORTS IS UPDATED."

*RCTPA1859/26 (25 JUN 26)

"AIP SUP 15/26 WEF 01 JUL 2026 TIL 30 SEP 2026, ALTERNATE
ROUTES AND MEASURES FOR AIRSPACE BLOCKED DUE TO FLIGHT TESTING
(JUL TO SEP 2026)."

*RCTPA1725/26 (07 JUN 26)

1800-2100
FLOW CTL AT FIR BDRY AS FLW:
1.RTE: M750
2.ACFT: NB FOR ENTERING RKRR
3.PROC: FL390 NOT AVBL AT ENVAR

RCTPA0600/26 (11 MAR 26)

"REF AIP SUP 06/26, AIR TRAFFIC FLOW MANAGEMENT (ATFM),
TAIPEI AIR TRAFFIC FLOW MANAGEMENT UNIT (ATFMU)
BEGINS OPERATIONS AT 16 MAR 2026, 0000 UTC.
RMK: FOR QUERY, CONTACT TAIPEI ATFMU
TEL +886-3-3841090, +886-3-3841091, +886-3-3841092."
16 MAR 26 00:00 UNTIL 31 MAR 27 23:59 ESTIMATED

RCTPA0135/25 (28 JAN 25)

"REF AIP SUP 06/24 UNSERVICEABILITY OF LUDAO VOR GID,
END DATE OF THIS SUP REVISED AS 31 DEC 2026.
THE REST NC."
17 JAN 25 02:00 UNTIL 31 DEC 26 23:59 ESTIMATED

HKG / HONG KONG

N I L

VHHK / HONG KONG FIR

VHHHA1785/26 (06 AUG 26)

NIL AIRAC PUBLICTAION FOR EFFECTIVE DATE 06 AUG 2026.

VHHHA1636/26 (24 JUL 26)

03 05 06 10 12 13 17 19 20 24 26 27 2315-0600
"DUE TO SURVEILLANCE EQUIPMENT CAPABILITY, IFR FLT WITHOUT
OPERABLE
ADS-B OUT EQUIPAGE ARE NOT PERMITTED TO OPERATE WI VHHK,
IRRESPECTIVE OF LEVELS.

EXEMPTION MAY BE GRANTED WITH PRIOR COOR VIA HONG KONG ATS WATCH SUPERVISOR.
REFER TO AIP HK GEN 1.5 PARAGRAPH 3.7.6 FOR REQUIREMENTS FOR ADS-B OUT EQUIPAGE."

VHHHA1584/26 (16 JUL 26)

1600-2030
"FOR TRAFFIC OVERFLYING HONG KONG FIR VIA ATS ROUTE A1 OR PBN ROUTE
P901 TO ENVAR M750 DESTINED FOR INCHEON FIR. DUE TO DOWNSTREAM ACC'S REQUIREMENT, 5 MINUTES CONSTANT OR INCREASING LONGITUDINAL SEPARATION BETWEEN FLIGHTS AT THE SAME LEVEL SHALL BE PROVIDED AT IKELA.
RMK: RESTRICTION MAY BE ADJUSTED SUBJECT TO SITUATION AND DISCRETION OF HONG KONG ATS FLOW MANAGER."
16 JUL 26 16:00 UNTIL 16 OCT 26 20:30 ESTIMATED

VHHHA1501/26 (09 JUL 26)

NIL AIRAC PUBLICATION FOR EFFECTIVE DATE 06 AUG 2026.

*VHHHA1163/26 (02 JUN 26)

DAILY 1700-2030
"DUE TO RESTRICTION FROM TAIPEI ACC (REFER TO NOTAM RCAA A1725/26),
OVERFLYING ACFT ENTERING HONG KONG FIR VIA IKELA EXITING ENVAR ENTERING RKRR, FL390 NOT AVBL AT IKELA.
(RMK: RESTRICTION MAY BE ADJUSTED SUBJECT TO SITUATION AND DISCRETION OF HONG KONG ATS FLOW MANAGER.)"

** A1048/26 **

VHHHA1048/26 (25 MAY 26)

"REF AIP HK ENR 1.8 PARA 8C, FLAS BTN HONG KONG FIR AND SANYA FIR/CONTROL AREA FOR ROUTES A202 AND R339, CHANGES AS FLW:
HONG KONG FIR TO SANYA CONTROL AREA:
1) FLAS FOR A202, POINTS BEYOND ASSAD:
S0840 (SUBJ COOR), S1040, S1160, S1220
2) FLAS FOR R339, POINTS BEYOND NANNING:
S0840 (SUBJ COOR), S0980, S1040, S1100, S1160, S1220"

CHN / CHINA
N I L

CH2 / CHINA SANYA
N I L

ZJSA / SANYA FIR

ZBBBA0783/26 (08 AUG 26)

"SANYA FIR(ZJSA)EXECUTE OCS(ONE CTOT SOLUTION)PROCEDURE,ALL ACFT OVERFLYING SANYA FIR(ZJSA) SHALL OPERATE CTOT (CALCULATED TAKE OFF TIME).
EXECUTION BY CTOT(CALCULATED TAKE OFF TIME)."

VNM / VIETNAM
N I L

VVHM / HO CHI MINH FIR

*VVVVA2677/26 (03 AUG 26)

04-06 12 0000-0400
"DUE TO FRNG ACT, DO NOT USE ATS RTE SEGMENT AND EN-ROUTE HLDG FOR FLT OPERATIONS EQUAL TO, OR BELOW FL110 AS FLW:
- W2: AC - VEPMA
- EN-ROUTE HLDG: AC
(SEE NOTAM VVVV A2657/26).
FROM GND TO FL110"

VVVVA2345/26 (10 JUL 26)

"RADIO CHECK ON THE FOLLOWING FREQ DRG PERIODS OF LOW AIR TFC DENSITY, NO ADVERSE WX PHENOMENA:
- SECTOR 1: 134.050 MHZ (PRI), 125.375 MHZ (SRY)
- SECTOR 2: 120.100 MHZ (PRI), 128.775 MHZ (SRY)
- SECTOR 3: 120.900 MHZ (PRI), 133.850 MHZ (SRY)
- SECTOR 4: 133.050 MHZ (PRI), 119.350 MHZ (SRY)
- SECTOR 5: 120.700 MHZ (PRI), 133.150 MHZ (SRY)
- SECTOR 6: 132.350 MHZ (PRI), 128.775 MHZ (SRY)

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

- SECTOR 7: 128.175 MHZ (PRI), 133.850 MHZ (SRY)
- EMERG: 121.500 MHZ
- TAN SON NHAT TMC: 125.500 MHZ (PRI), 124.075 MHZ (SRY)
- TAN SON NHAT ARR: 126.350 MHZ (PRI), 127.725 MHZ (SRY)
- HF ACC HO CHI MINH: 11297/11396/13300/5655/8942 KHZ."

LAO / LAOS
N I L

VLVT / VIENTIANE FIR
N I L

THA / THAILAND
N I L

VTBB / BANGKOK FIR

VTBDC4513/26 (09 AUG 26)

CDR Y5 (RNAV 2) AVBL FOR FLIGHT PLANNING AS FLW:
PERIOD : MEA LOWER/UPPER LIMITS
0000-0229 FL130/FL460
0230-0500 FL270/FL460
0501-0559 FL130/FL460
0600-0730 FL270/FL460
0731-2359 FL130/FL460

VTBDJ5859/26 (28 JUL 26)

"TEMPO RESTRICTED AREA ACT RADIUS 10NM CENTRE 182802N0972620E
(MAE SARIANG DISTRICT MAE HONG SON PROVINCE,
EXCLUDING YANGON FIR)
RMK: ACFT MAY FILE FPL ON THE AFFECTED RTE BUT EXP RADAR
VECTORED BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC"
F) GND
G) UNL

*VTBDJ5792/26 (25 JUL 26)

TRIGGER NOTAM NON-AIRAC AIP SUP A28/26 WEF 10 AUG 2026
JOINT MIL AIR EXER IN BANGKOK FIR FALCON STRIKE 2026
F) GND
G) UNL

VTBDC4027/26 (17 JUL 26)

"DUE TO VT D41A ACT FPL PROC FOR ACFT OPR FM/TO VTCC DETAIL AS FLW:
1. PERIOD MON-FRI 0000-1100
DEP/OVERFLY DEST/OVERFLY RTE
VTCC VTCT W12 IKISU W22
VTCC PONUK R207 IKISU W22 CTR A581
VTCT VTCC W22 IKISU W12
PONUK VTCC Y27 DUBEN Y28 CRIST R207 (FOR RNAV)
PONUK VTCC A581 CTR W22 IKISU R207 (FOR NON-RNAV)
2. PERIOD MON-FRI 1101-2359, SAT SUN H24
DEP/OVERFLY DEST/OVERFLY RTE
VTCC VTCT W20
VTCC PONUK A581
VTCT VTCC W20
PONUK VTCC A581"

VTBDJ5614/26 (16 JUL 26)

DAILY 0100-0230 0600-1100
"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA 3NM EITHER SIDE OF
A LINE: 143000.00N1022800.00E-143107.26N1051100.12E
(SI SAKET, UBON RATCHATHANI, BURIRAM, SURIN AND
NAKHON RATCHASIMA PROVINCE)
RMK: ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR VECTORED
BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC"
F) FL200
G) FL250

VTBDJ5613/26 (16 JUL 26)

DAILY 0100-0230 0600-1100
"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA 3NM EITHER SIDE OF
A LINE:151638.34N1001745.12E-145407.02N1004920.52E-
143000.00N1022800.00E
(CHAINAT, NAKHON SAWAN, SARABURI, LOP BURI, BURI RAM
AND NAKHON RATCHASIMA PROVINCE)
RMK: ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR VECTORED

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 16/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC"
F) FL150
G) FL200

VTBDJ5304/26 (29 JUN 26)

"JUN 29 0815-2359, JUN 30 0000-1659 2200-2359, JUL 01 2200-SEP 30 1659"
"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA
144705N1033019E-143541N1051246E-142051N1051232E-
141826N1030616E-142521N1030558E-144705N1033019E
(SI SAKET, UBON RATCHATHANI, BURIRAM AND SURIN PROVINCE
EXCLUDING PHNOM PENH FIR)
RMK: ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR VECTORED BY
ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC"
F) 8000FT AMSL
G) FL170

VTBDC3518/26 (27 JUN 26)

TRIGGER NOTAM-PERM AIRAC AIP AMDT 08/26 WEF 06 AUG 2026.
GEN 0.4 CHECKLIST OF AIP PAGES
GEN 3.2 ANC
GEN 4.1 AD/HLP CHARGES
ENR 1.8 REGIONAL SUPPLEMENTARY PROC
ENR 1.9 ATFM AND AIRSPACE MANAGEMENT

VTBDC2855/26 (26 MAY 26)

"AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM
THE DEMOCRATIC REPUBLIC OF THE CONGO AND THE REPUBLIC OF UGANDA
1. PURSUANT TO THE RESOLUTION OF THE NATIONAL COMMUNICABLE DISEASE
COMMITTEE, EFFECTIVE FROM 27 MAY 2026 AT 1800 HOURS (LOCAL TIME)
ONWARDS, PASSENGERS AND CREW MEMBERS DEPARTING FROM THE DEMOCRATIC
REPUBLIC OF THE CONGO (DR CONGO) AND THE REPUBLIC OF UGANDA SHALL BE
PERMITTED TO ENTER THE KINGDOM OF THAILAND ONLY VIA SUVARNABHUMI
AIRPORT AND SHALL BE SUBJECT TO A MANDATORY QUARANTINE PERIOD OF
TWENTY-ONE (21) DAYS, CALCULATED FROM THE DATE OF DEPARTURE FROM
THE AFFECTED AREAS, IN ACCORDANCE WITH THE PRESCRIBED PUBLIC
HEALTH PROCEDURES.
2. ALL AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM
THE ABOVE-MENTIONED AREAS ARE REQUESTED TO COMPLY WITH AND IMPLEMENT
THE PRESCRIBED MEASURES ACCORDINGLY."

// (COM-INFO) //

THA 00126/26 (14 MAY 26)

COM INFO:--REF AIP SUP A19/26;
1
INTRODUCTION
With effect from 14 May 2026 at 0001 UTC to 31 December 2026 at 0001 UTC, the purpose of this
AIRAC AIP Supplement is to inform all
concerned regarding Temporary suspension of SURAT THANI DVOR/DME (STN) due to relocation
details are as follows.
2
THE PERIOD OF TEMPORARY SUSPENSION
STN DVOR/DME will be temporarily suspension from 14 May 2026 at 0001 UTC to 31 December 2026
at 0001 UTC.
3
FLIGHT PROCEDURE
A temporary reporting point name SAPUD (090746.24N 0990805.09E) will be established at the
same coordinates of SURAT THANI DVOR/
DME (STN) for ATS routes G458, W17, W24, W28, W32 and Y8 and a portion of ATS route G458
between STN and MENEX will be suspended
until STN normal operations resume.
4
FLIGHT PLANNING PROCEDURES
Reference to the AIP-THAILAND part ENR 1.10 item 4.1.1.1, 4.1.1.2 a, 4.1.1.2 b, 4.1.1.3 a,
4.1.1.3 b non-RNAV2 approved aircraft. To maintain
efficiency of ATS during SURAT THANI DVOR/DME (STN) relocation, non-RNAV approved aircraft
that intend to operate on G458 between
SAPUD and MENEX shall file flight plan, depending on ACFT capability.
5
CONTACT
Unit: Air Traffic Navigation Systems Engineering Department, Aeronautical Radio of Thailand
Ltd.
Email: pariwat.ch@aerorhai.co.th
6
VALIDITY
This AIRAC AIP Supplement will remain current until 31 December 2026 at 0001 UTC. Any changes
to this AIRAC AIP Supplement will be
notified by NOTAM.

AEROPLANE INFORMATION

AIRCRAFT CATEGORY = D
N I L

AIRCRAFT TYPE = B777
N I L

AIRCRAFT SUBTYPE = B773E
N I L

AIRCRAFT REGISTRATION = HSTTA
N I L

ADDITIONAL INFORMATION

RJTT / HND

RJAAE4243/26 (08 AUG 26)

09-10 12 15-16 19 22-23 26 29-30 1430-2100
"TWY A3,A6,A9,A11,A14,L3,L6,L9,L11,L13,L14 CLSD DUE TO MAINT"

RJAAJ1686/26 (04 AUG 26)

06-07 11 13-14 18 20-21 25 27-28 1530-2130
"ILS-LOC,GP,DME,IM FOR RWY 34R U/S DUE TO CONST"

RJAAJ1687/26 (04 AUG 26)

06-07 11 13-14 18 20-21 25 27-28 1530-2130
"ILS-LOC,GP,DME FOR RWY 16L U/S DUE TO CONST"

*RJAAJ1682/26 (04 AUG 26)

06-07 11 13-14 18 20-21 25 27-28 1530-2130
RWY 16L/34R CLSD DUE TO MAINT
RMK: SEE AIP RJTT AD2.23

RJAAE4176/26 (04 AUG 26)

06-07 11 13-14 18 20-21 25 27-28 1530-2130
TWY C1 THRU C14 CLSD DUE TO MAINT

RJAAJ1678/26 (04 AUG 26)

RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT.

RJAAE4138/26 (03 AUG 26)

10 AUG 2026 14:30-10 AUG 2026 21:00
"TWY B5,B9,B10,B11,B14,T5,T9,T11,T14,A16,L16,Q CLSD DUE TO MAINT"

RJAAE4129/26 (02 AUG 26)

10 AUG 2026 17:30-10 AUG 2026 20:00
"TWY W(BTN SPOT 30 AND SPOT 41),W(BEHIND SPOT 41),W13 CLSD DUE TO CONST"

RJAAE4126/26 (02 AUG 26)

10 AUG 2026 15:00-10 AUG 2026 17:30
"TWY E(BTN E12 AND SPOT 501),E(BEHIND SPOT 501) CLSD DUE TO CONST"

RJAAE4128/26 (02 AUG 26)

10 AUG 2026 17:30-10 AUG 2026 21:00
"TWY J(BTN A AND W),W(BTN K AND SPOT 41) CLSD DUE TO CONST"

RJAAE4127/26 (02 AUG 26)

10 AUG 2026 15:00-10 AUG 2026 21:00
"TWY J(BTN R AND W),J1(BTN J AND K),J2(BTN J AND K) CLSD DUE TO CONST"

RJAAE4125/26 (02 AUG 26)

10 AUG 2026 15:00-10 AUG 2026 21:00
"TWY J(BTN C AND R),E(BTN K AND SPOT 501),R(BTN K AND SPOT 501) CLSD DUE TO CONST"

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 18/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

RJAAE4124/26 (02 AUG 26)

10 AUG 2026 15:00-10 AUG 2026 21:00
"TWY L(BTN L3 AND L4),L(INT OF L3),P(BTN P3 AND P8),P(INT OF P3),
P3,P4 CLSD DUE TO CONST"

RJAAE4122/26 (02 AUG 26)

10 AUG 2026 15:00-10 AUG 2026 21:00
"TWY N(BTN N2 AND N5),N(INT OF F) CLSD DUE TO CONST"

RJAAE4123/26 (02 AUG 26)

10 AUG 2026 15:00-10 AUG 2026 21:00
"TWY N(BTN N5 AND N7),N(INT OF N5),N(INT OF N7),N5,N7 RESTRICTED
DUE TO CONST
NOT AVBL FOR ACFT WITH WINGSPAN MORE THAN 52M"

RJAAE4121/26 (02 AUG 26)

10 AUG 2026 15:00-10 AUG 2026 21:00
TWY W(BTN W13 AND K) RESTRICTED DUE TO CONST
NOT AVBL FOR ACFT WITH WINGSPAN MORE THAN 65.0M

RJAAJ1661/26 (31 JUL 26)

"ACFT-STAND-ID-SIGN FOR SPOT 47 U/S
VISUAL-DOCKING-GUIDANCE-SYSTEM FOR SPOT 47 U/S
APN-FLOOD-LGT FOR SPOT 401 PARTLY U/S
APN-FLOOD-LGT FOR SPOT 909 PARTLY U/S
RMK : (1) REF AIP SUP 187/26 ITEM APRON : 3, 8, 9, 11
(2) THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED
BY FURTHER NOTAM."

RJAAJ1660/26 (31 JUL 26)

TWY-EDGE-LGT FOR J(BTN R AND J1) PARTLY TEMPO INSTALLED
RMK: (1)REF AIP SUP 187/26 ITEM TWY:46
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAJ1659/26 (31 JUL 26)

"TAXIING-GUIDANCE-SIGN FOR T12, T14, Q, Q1, Q2 U/S
RAPID-EXIT-TWY-INDICATOR-LGT FOR C10 U/S
RMK : (1) REF AIP SUP 187/26 ITEM TWY : 13, 43
(2) THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED
BY FURTHER NOTAM."

RJAAJ1658/26 (31 JUL 26)

"TWY CL LGT FOR R1, W11(BTN W AND R1) U/S
TWY CL LGT FOR K(BTN C AND R),E(INT OF K) U/S
TWY CL LGT FOR A16 U/S
TWY CL LGT FOR T12, T14, Q, Q1, Q2 U/S
TWY CL LGT FOR C(INT OF C3), C(INT OF C5) U/S
TWY CL LGT FOR C7,C8,C9 U/S
TWY CL LGT FOR J(BTN R AND W), J1(BTN J AND K), J2(BTN J AND K) U/S
TWY CL LGT FOR M1 U/S
RMK: (1)REF AIP SUP 187/26 ITEM TWY:2,4,6,12,33,44,45,50
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

*RJAAJ1656/26 (31 JUL 26)

"RWY-THR-ID-LGT FOR RWY 16L U/S
SEQUENCED-FLG-LGT FOR RWY 34L U/S
REDL FOR RWY 16L/34R PARTLY U/S
APCH-GUIDANCE-LGT FOR RWY 16R/16L(NR.4) U/S
APCH-GUIDANCE-LGT FOR RWY 16R/16L(NR.6,NR.8) PARTLY U/S
LIGHTING SYSTEM CAT-2,3 FOR RWY 34R DOWNGRADED TO CAT-1
RMK: (1)REF AIP SUP 187/26 ITEM RWY:30,49,52,54,55,56
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

*RJAAJ1657/26 (31 JUL 26)

RCLL FOR RWY 16L/34R U/S
RMK: (1)REF AIP SUP 187/26 ITEM RWY:51
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAJ1655/26 (31 JUL 26)

"REF AIP PAGE RJTT AD2-4 (CHANGE TO READ)
RJTT AD 2.8 APRONS, TAXIWAYS AND CHECK LOCATIONS DATA
5. INS CHECKPOINTS
CHANGE TO READ
SPOT NR

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 19/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

(DELETE)
25 : 353314.45N/1394647.60E
INSTEAD OF
SPOT NR
31 : 353313.19N/1394648.39E
32 : 353314.60N/1394647.42E
CHANGE TO READ
SPOT NR
26, 27, 28, 29
INSTEAD OF
SPOT NR
33, 34, 35, 36"

RJAAJ1653/26 (31 JUL 26)

REF AIP SUP 187/26 ITEM APRON:B (CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL

RJAAJ1646/26 (31 JUL 26)

10 AUG 2026 00:30-10 AUG 2026 07:30
FLW APCH-GUIDANCE-LGT U/S DUE TO MAINT
NR1-1 THRU NR1-5 FOR RWY 16R/16L
NR2 FOR RWY 16R/16L

// (COM-INFO) //

THA 00207/26 (31 JUL 26)

RJTT:--SUBJ: GATE/SPOT ASSIGNMENT AT HND DURING 01AUG26-31AUG26

AA.. DATE: 01AUG26-31AUG26

TG682 ARR AT GATE/SPOT 141 (TOWING OUT 132)
TG683 DEP AT GATE/SPOT 145

BB.. DATE: 01AUG26-31AUG26

TG660 ARR AT GATE/SPOT 105P
TG661 DEP AT GATE/SPOT 105P

PLS NOTE THAT THE ABOVE DATES ARE LOCAL DATES

RJAAJ1636/26 (30 JUL 26)

02-04 06-07 09-11 13-14 16-18 20-21 23-25 27-28 30-31 1430-2100
"ILS-LOC,GP,DME FOR RWY 22 U/S DUE TO CONST"

RJAAJ1634/26 (30 JUL 26)

01 05 08 12 15 19 22 26 29 1430-2100
GBAS NOT AVBL DUE TO CONST

RJAAJ1633/26 (30 JUL 26)

01 05 08 12 15 19 22 26 29 1430-2100
"ILS-LOC,GP,DME FOR RWY 23 U/S DUE TO CONST"

RJAAJ1629/26 (30 JUL 26)

01-03 05 08-10 12 15-17 19 22-24 26 29-31 1430-2100
"ILS-LOC,GP,DME FOR RWY 34L U/S DUE TO CONST"

RJAAJ1628/26 (30 JUL 26)

01-03 05 08-10 12 15-17 19 22-24 26 29-31 1430-2100
"ILS-LOC,GP,DME FOR RWY 16R U/S DUE TO CONST"

RJAAJ1623/26 (29 JUL 26)

GROOVING FOR RWY 16L/34R PARTLY ERASED DUE TO MAINT
1.LEN: 98.0M (BTN 1004.8M AND 1102.8M FM RWY 34R THR)
WID: 11.0M (BTN 1.0M AND 12.0M ON THE EAST SIDE OF RCL)
2.LEN: 98.0M (BTN 1004.8M AND 1102.8M FM RWY 34R THR)
WID: 11.0M (BTN 1.0M AND 12.0M ON THE WEST SIDE OF RCL)

RJAAE4030/26 (29 JUL 26)

02 09 16 23 30 1430-2100
"TWY B5,B9,B10,B11,T5,T9,T11,A16,L16,Q CLSD DUE TO MAINT"

RJAAE4025/26 (29 JUL 26)

01 05 08 12 15 19 22 26 29 1430-2100
"TWY D1 THRU D7,D,S,S1,S2,S3,E(BTN A AND D),R(BTN A AND D) CLSD DUE
TO MAINT"

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 20/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

*RJAAJ1622/26 (29 JUL 26)

01 05 08 12 15 19 22 26 29 1430-2100
RWY 05/23 CLSD DUE TO MAINT
RMK: SEE AIP RJTT AD2.23

RJAAE4023/26 (29 JUL 26)

02-04 06-07 09-11 13-14 16-18 20-21 23-25 27-28 30-31 1430-2100
"TWY B3,B4,B6,B8,B13,T3,T4,T6,T8 CLSD DUE TO MAINT"

*RJAAJ1620/26 (29 JUL 26)

02-04 06-07 09-11 13-14 16-18 20-21 23-25 27-28 30-31 1430-2100
RWY 04/22 CLSD DUE TO MAINT
RMK: AVBL CROSS RWY 04/22 VIA TWY OTHER THAN CLSD TWY
SEE AIP RJTT AD2.23

RJAAE4022/26 (29 JUL 26)

01-03 05 08-10 12 15-17 19 22-24 26 29-31 1430-2100
"TWY A1,A2,A5,A7,A8,A10,A12,A13,L5,L10,L12 CLSD DUE TO MAINT"

*RJAAJ1619/26 (29 JUL 26)

01-03 05 08-10 12 15-17 19 22-24 26 29-31 1430-2100
RWY 16R/34L CLSD DUE TO MAINT
RMK: AVBL CROSS RWY 16R/34L VIA TWY OTHER THAN CLSD TWY
SEE AIP RJTT AD2.23

RJAAJ1604/26 (27 JUL 26)

"SURFACE PAINTED DIRECTION SIGN FOR N(INT OF N2) ERASED
TWY SIDE STRIPE MARKING FOR F ERASED
RMK: (1)REF AIP SUP 187/26 ITEM TWY:16,49
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAJ1608/26 (27 JUL 26)

"SPOT 401 RELOCATED
SPOT 47 RELOCATED
RMK: (1)REF AIP SUP 187/26 ITEM APRON:5,7
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAJ1607/26 (27 JUL 26)

"SPOT 402 CLSD
SPOT 23 CLSD
RMK: (1)REF AIP SUP 187/26 ITEM APRON:D,E
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAJ1606/26 (27 JUL 26)

COMPASS AREA CLSD
RMK: (1)REF AIP SUP 187/26 ITEM APRON:C
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAJ1609/26 (27 JUL 26)

MARKING FOR COMPASS AREA ERASED
RMK: (1)REF AIP SUP 187/26 ITEM APRON:10
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAJ1603/26 (27 JUL 26)

"TWY CL MARKING FOR N2 PARTLY ERASED
TWY CL MARKING FOR F,T(INT OF F),N(INT OF F) PARTLY ERASED
SURFACE PAINTED DIRECTION SIGN FOR F,T(INT OF F),N(INT OF F),
N5(BEHIND SPOT 941) PARTLY ERASED
RMK: (1)REF AIP SUP 187/26 ITEM TWY:15,47,48
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAE3974/26 (27 JUL 26)

"TWY M1(BEHIND SPOT 23) CLSD
TWY N2(BTN N AND SPOT 935) CLSD
TWY F CLSD
RMK: (1)REF AIP SUP 187/26 ITEM TWY:A,B,D
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAJ1602/26 (27 JUL 26)

"GROOVING FOR RWY 16L/34R PARTLY,GRADUALLY ERASED OR INSTALLED
RMK: (1)REF AIP SUP 187/26 ITEM RWY:53,58
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 21/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

RJAAJ1594/26 (24 JUL 26)

0000-0700
UNMANNED ACFT:
AREA: BOUNDED BY FLW POINTS
353943N1394557E - 353945N1394559E - 353943N1394601E - 353939N1394608E
- 353937N1394605E - 353943N1394557E
(CHUO-KU IN TOKYO)
WT: 0.9KG
F) SFC
G) 601FT AMSL

RJAAJ1582/26 (22 JUL 26)

OBST DAY MARKING ERASED
TYPE: CHIMNEY
PSN: 353046.7N1394420.4E ELEV: 245FT AMSL
(KAWASAKI-SHI IN KANAGAWA)

RJAAJ1541/26 (17 JUL 26)

GROOVING FOR RWY 16L/34R PARTLY ERASED DUE TO MAINT
LEN: 22.0M (BTN 726.8M AND 748.8M FM RWY 34R DISPLACED THR)
WID: 3.5M (BTN 2.0M AND 5.5M ON THE EAST SIDE OF RCL)

RJAAJ1529/26 (17 JUL 26)

TWY-CL-LGT FOR TWY B (BTN B9 AND B10) U/S DUE TO TROUBLE
RMK: THIS NOTAM WILL BE INCORPORATED IN SUP

RJAAJ1531/26 (17 JUL 26)

TWY-CL-LGT FOR TWY R (BTN A AND SPOT 709) U/S DUE TO TROUBLE
RMK: THIS NOTAM WILL BE INCORPORATED IN SUP

RJAAJ1530/26 (17 JUL 26)

TWY-CL-LGT FOR TWY E (FM SPOT 808 TO SPOT 809) U/S DUE TO TROUBLE
RMK: THIS NOTAM WILL BE INCORPORATED IN SUP

RJAAJ1526/26 (17 JUL 26)

TWY-CL-LGT FOR TWY W (INT OF W9) U/S DUE TO TROUBLE
RMK: THIS NOTAM WILL BE INCORPORATED IN SUP

RJAAJ1528/26 (17 JUL 26)

TWY-CL-LGT FOR TWY E3 (BTN E AND R) U/S DUE TO TROUBLE
RMK: THIS NOTAM WILL BE INCORPORATED IN SUP

RJAAJ1527/26 (17 JUL 26)

TWY-CL-LGT FOR TWY A (BEHIND SPOT 201) U/S DUE TO TROUBLE
RMK: THIS NOTAM WILL BE INCORPORATED IN SUP

RJAAJ1525/26 (17 JUL 26)

TWY-CL-LGT FOR TWY W (INT OF W11) U/S DUE TO TROUBLE
RMK: THIS NOTAM WILL BE INCORPORATED IN SUP

RJAAJ1524/26 (17 JUL 26)

TWY-CL-LGT FOR TWY J1 (BTN J AND K) U/S DUE TO TROUBLE
RMK: THIS NOTAM WILL BE INCORPORATED IN SUP

RJAAJ1523/26 (17 JUL 26)

TWY-CL-LGT FOR TWY C (INT OF C14) U/S DUE TO TROUBLE
RMK: THIS NOTAM WILL BE INCORPORATED IN SUP

RJAAJ1505/26 (17 JUL 26)

"REF AIP PAGE RJTT AD2-4 (CHANGE TO READ)
RJTT AD 2.8 APRONS, TAXIWAYS AND CHECK LOCATIONS DATA
5. INS CHECKPOINTS
CHANGE TO READ
30 : 353324.01N/1394640.31E
INSTEAD OF
37 : 353324.18N/1394639.92E"

RJAAJ1459/26 (17 JUL 26)

VISUAL-DOCKING-GUIDANCE-SYSTEM FOR SPOT 59 THRU 65 U/S DUE TO
CONST

RJAAJ1092/26 (18 JUN 26)

DISPLAY OF TARGET START UP APPROVAL TIME(TSAT) ON
VISUAL-DOCKING-GUIDANCE-SYSTEM FOR SPOT 18 THRU 23 U/S DUE TO TROUBLE
RMK:REF AIP RJTT AD 2.20

RJBB / KIX

RJAAB2091/26 (07 AUG 26)

10 AUG 2026 14:00-10 AUG 2026 21:00
"TWY-EDGE-LGT FOR TWY Y(BTN B6 AND J4),B6,B7,J3(BTN Y AND
S1),S1(BTN
J4 AND U),S2,S4(BTN J3 AND J4),S4(BTN J3 AND T),S6(BTN J3 AND
J4),S6(BTN J3 AND T),Z(BTN J3 AND J4),Z(BTN J3 AND W8),W9,T(FM SPOT
91 TO SPOT 99) U/S DUE TO MAINT"

RJAAB2090/26 (07 AUG 26)

10 AUG 2026 14:00-10 AUG 2026 21:00
TWY J3(BTN S4 AND S6) CLSD DUE TO MAINT

*RJAAB2078/26 (07 AUG 26)

10 AUG 2026 14:00-31 AUG 2026 23:30
10 13 17 20 22-24 27 29-31 1400-2330
RWY 06L/24R CLSD DUE TO MAINT

RJAAB2079/26 (07 AUG 26)

10 AUG 2026 14:00-31 AUG 2026 23:30
10 13 17 20 22-24 27 29-31 1400-2330
"TWY B1,B3,B5,B6,B7,B8,B9,B10,B12,B14,Y,J3(BTN Y AND Z),J4(BTN Y
AND
Z),W6(BTN Y AND Z),W8(BTN Y AND Z) CLSD DUE TO MAINT"

RJAAB2057/26 (05 AUG 26)

10 AUG 2026 16:00-13 AUG 2026 20:30
10 13 1600-2030
"TWY S1(BTN J4 AND U),S1(INT OF U),U(BTN R AND S1),R(INT OF
S1),R(INT OF U),J3(BTN S1 AND S2) CLSD DUE TO MAINT"

RJAAB2043/26 (04 AUG 26)

RWY INCURSION WARNING OPERATION SUSPENDE DUE TO MAINT

RJAAB2006/26 (31 JUL 26)

"TWY-CL-LGT FOR TWY J4 (BTN L AND S1),
S1 (BTN J3 AND J4) U/S DUE TO MAINT."

RJAAB2004/26 (31 JUL 26)

TWY-CL-LGT FOR TWY B12 U/S DUE TO MAINT

RJAAB2003/26 (31 JUL 26)

TWY-CL-LGT FOR TWY B10 U/S DUE TO MAINT.

RJAAB2005/26 (31 JUL 26)

TWY-CL-LGT FOR TWY B14 U/S DUE TO MAINT

RJAAB2002/26 (31 JUL 26)

TWY-CL-LGT FOR TWY Y(BTN B9 AND B14) U/S DUE TO MAINT

RJAAB1980/26 (30 JUL 26)

10 AUG 2026 17:30-10 AUG 2026 20:30
"TWY Z(BTN W6 AND W8),W6(BTN Z AND T),Z(INT OF W6),W7 CLSD DUE TO
MAINT"

RJAAB1913/22 (21 JUL 26)

"REF AIP PAGE RJBB AD2.24-STAR-29,30,31,AD2.24-IAC-12,
AD2.24-OTHER-2,3 (CHANGE TO READ)
ALISA ECHO ARRIVAL
BECKY ECHO ARRIVAL
BERTH ECHO ARRIVAL
CANDY ECHO ARRIVAL
RNP RWY06R
RNAV HLDG PATTERN
(HLDG PATTERN AT AKASI)
CHANGE TO READ

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 23/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

MHA 4000
INSTEAD OF
MHA 5000"

RJAAB1440/26 (08 JUN 26)

"TRIGGER NOTAM-PERM AIRAC AIP AMDT NR8/2026
WEF 06 AUG 2026
ESTABLISHMENT OF FLT PROC, ETC. DUE TO RELOCATION OF KOCHI VOR/DME"

RJGG / NGO

RJAAG1916/26 (06 AUG 26)

10 AUG 2026 15:00-10 AUG 2026 21:00
"ACFT STAND TXL D,D5 THRU D7,N CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

RJAAG1915/26 (06 AUG 26)

10 AUG 2026 15:00-10 AUG 2026 20:10
"ACFT STAND TXL E,E2 THRU E6,P,J,K3 CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1.5HR BFR"

RJAAG1914/26 (06 AUG 26)

10 AUG 2026 17:50-10 AUG 2026 20:10
"TWY A(INT OF B1),A(FM B5 TO B6),A(INT OF B10),A1,A5,A6,A10,
B,B1,B5,B6,B10,C,C7 THRU C10 CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

*RJAAG1913/26 (06 AUG 26)

10 AUG 2026 17:50-10 AUG 2026 20:10
RWY 18/36 CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR

RJAAG1903/26 (04 AUG 26)

RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT

// (COM-INFO) //

THA 00104/12 (31 JUL 26)

COM INFO:--REGARDING GPU AND ACU USING AT NGO AIRPORT,
KINDLY REMIND AND INFO AS FOLLOWS:
AA. WHEN AIRCRAFT PARK AT REMOTE BAY, PLEASE KINDLY USE APU ON ARR.
BB. WHEN AIRCRAFT PARK AT SPOT WITH PASSENGER BOARDING BRIDGE,
KINDLY USE GPU AND ACU DUE TO FUEL MANAGEMENT POLICY
AND AIRPORT AUTHORITY REQUESTED. (ISSUE/16DEC/NGOKKTG/INFO)

RJAAG1863/26 (31 JUL 26)

"05 1500-2200, 06-08 10-11 17-22 24-29 31 1330-2200"
"TWY-CL-LGT FOR TWY A3,A5,A6,A8 U/S
RMK: (1)REF AIP SUP 182/26 ITEM TWY:5
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAG1862/26 (31 JUL 26)

"05 1500-2200, 06-08 10-11 17-22 24-29 31 1330-2200"
"TWY A(INT OF B3),A3S,A3,B3,A(INT OF B8),A8,A8N,B8 CLSD
RMK: (1)REF AIP SUP 182/26 ITEM TWY:D
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAG1861/26 (31 JUL 26)

"TWY-SIDE-STRIPE-MARKING FOR A1,A3S,A3,A8,A8N,A10,B1,B3,B8,B10
TEMPO
INSTL
RMK: (1)REF AIP SUP 182/26 ITEM TWY:8
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAG1860/26 (31 JUL 26)

"TWY-EDGE-LGT FOR A3S,A3,A8,A8N,B3,B8 TEMPO INSTL
RMK: (1)REF AIP SUP 182/26 ITEM TWY:7
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM)"

RJAAG1859/26 (31 JUL 26)

"TWY-CL-MARKING FOR A,A1 THRU A10,B1 THRU B10,C7,C9,E4 PARTLY
ERASED
RMK: (1)REF AIP SUP 182/26 ITEM TWY:6
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 24/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

RJAAG1858/26 (31 JUL 26)

"TWY-CL-LGT FOR A,A1 THRU A4,A6 THRU A10,B2 THRU B10,C7,C9,E4 U/S
RMK: (1)REF AIP SUP 182/26 ITEM TWY:4
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAG1857/26 (31 JUL 26)

STOP-BAR-LGT FOR A1 THRU A10 U/S
RMK: (1)REF AIP SUP 182/26 ITEM TWY:3
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAG1856/26 (31 JUL 26)

"TWY A(BTN B1 AND B3),A2,B2,A(BTN B3 AND B5),A4,B4,A(BTN B6 AND B8),A7,B6N,B7,A(BTN B8 AND B10),A9,B9 CLSD
RMK: (1)REF AIP SUP 182/26 ITEM TWY:C
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAG1855/26 (31 JUL 26)

RWY-SIDE-STRIPE-MARKING FOR RWY 18/36 TEMPO INSTL
RMK: (1)REF AIP SUP 182/26 ITEM RWY:2
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAG1815/26 (24 JUL 26)

09 23 30 1330-2200
"TWY-CL-LGT FOR TWY A3,A5,A6,A8 U/S DUE TO CONST
RMK: UNSERVICEABLE AREA INCLUDE AIP SUP 182/26"

RJAAG1806/26 (24 JUL 26)

AUG 09 23 30 1330-2200
"TWY A (INT OF B3), A (INT OF B8), A3, A3S, A8, A8N, B3, B8
CLSD DUE TO CONST."

RJ00 / ITM

RJAAK2041/26 (05 AUG 26)

REF AIP SUP 084/26 ITEM TWY:12(CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL

RJAAK2042/26 (05 AUG 26)

REF AIP SUP 084/26 ITEM TWY:13(CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL

RJAAK2040/26 (05 AUG 26)

REF AIP SUP 084/26 ITEM TWY:11(CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL

RJAAK2019/26 (04 AUG 26)

REF AIP SUP 084/26 ITEM TWY:10(CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL

RJAAK2017/26 (04 AUG 26)

REF AIP SUP 170/26 ITEM 26(CHANGE TO READ)
NO LONGER IN FORCE
CONST POSTPONED

RJAAK2013/26 (04 AUG 26)

RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT

RJAAK2010/26 (03 AUG 26)

REF AIP SUP 155/26 (CHANGE TO READ)
TEMPORARY CHANGE OF INSTRUMENT APPROACH PROCEDURES:
3.(1) ILS RWY32L
CHANGE TO READ
REFER TO AIP SUP NR154/26
AND SEE NOTAM RJAAANYX K2007/26
3.(2) VOR A
CIRCLING MDA(H)
TOTAL AREA
CAT B

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 25/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

CHANGE TO READ
590(551)
3.(3) RNP RWY32L
CIRCLING MDA(H)
TOTAL AREA
CAT B
CHANGE TO READ
590(551)

RJAAK2007/26 (03 AUG 26)

REF AIP SUP 154/26(CHANGE TO READ)
UNSERVICEABILITY AND ALTERNATE PROCEDURES OF OSAKA ILS-LOC32L(ISK)
ILS RWY32L
CIRCLING MDA(H)
TOTAL AREA
CAT B
CHANGE TO READ
590(551)

RJAAK1999/26 (31 JUL 26)

"REF AIP SUP 084/26 ITEM RWY:9,11,12 (CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL"

RJAAK1973/26 (30 JUL 26)

REF AIP SUP 084/26 ITEM RWY:7 (CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL

RJAAK1946/26 (28 JUL 26)

REF AIP SUP 084/26 ITEM RWY:8 (CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL

RJAAK1910/26 (23 JUL 26)

REF AIP SUP 084/26 ITEM RWY:13 (CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL

RJAAK1890/26 (21 JUL 26)

REF AIP SUP 084/26 ITEM RWY:10 (CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL

RJAAK1848/26 (14 JUL 26)

REF AIP SUP 084/26 ITEM TWY:8 (CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL

RJAAK1847/26 (14 JUL 26)

REF AIP SUP 084/26 ITEM RWY:14 (CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL

RJAAK1759/26 (05 JUL 26)

TRIGGER NOTAM-AIRAC AIP SUP 154/26
WEF 06 AUG 2026 TIL 25 NOV 2026
UNSERVICEABILITY AND ALTERNATE PROCEDURES OF OSAKA ILS-LOC32L (ISK)

RJAAK1758/26 (05 JUL 26)

"TRIGGER NOTAM-PERM AIRAC AIP AMDT NR9/2026
WEF 06 AUG 2026
REVISION OF FLT PROC, ETC"

RJAAK1711/26 (25 JUN 26)

RLLS NR.7 FOR RWY 14R U/S DUE TO TROUBLE

RJAAK1692/26 (23 JUN 26)

"REF AIP SUP 084/26 ITEM TWY:6 (CHANGE TO READ)
RWY-ENTRANCE-LGT FOR B4,C1,W6,W7 U/S
END OF VALIDITY
CHANGE TO READ
AUG 2026"

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 26/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

RJAAK1687/26 (23 JUN 26)

"FLW LGT U/S
RWY-ENTRANCE-LGT FOR C6,W10
INTERMEDIATE-HLDG-PSN-LGT FOR TWY A1
RMK: (1)REF AIP SUP 084/26 ITEM TWY:7,9
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAK1685/26 (23 JUN 26)

"TWY-CL-LGT FOR TWY A1,B4,C1,C2,C6,E1,W2,W5,W9 U/S
RMK: (1)REF AIP SUP 084/26 ITEM TWY:1,2,3,4,5
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

*RJAAK1682/26 (23 JUN 26)

RCLL FOR RWY 14L/32R U/S
RMK: (1)REF AIP SUP 084/26 ITEM RWY:2
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAK1683/26 (23 JUN 26)

"FLW LGT U/S
TKOF-HOLD-LGT FOR RWY 14L/32R
OVERRUN-AREA-EDGE-LGT ON RWY 32R SIDE
RMK: (1)REF AIP SUP 084/26 ITEM RWY:3,4
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAK1580/26 (02 JUN 26)

"TDZ MARKING FOR RWY 14L/32R PARTLY,GURADUALLY ERASED OR INSTALLED
RMK:REF AIP SUP 084/26 ITEM RWY:9"

RJAAK1573/26 (02 JUN 26)

"REF AIP SUP 084/26 ITEM RWY:7,8,9,11,12,13
(CHANGE TO READ)
RWY THR MARKING FOR RWY 14L/32R GURADUALLY ERASED OR INSTALLED
RWY DESIGNATION MARKING FOR RWY 14L/32R GURADUALLY ERASED OR
INSTALLED
TDZ MARKING FOR RWY 14L/32R PARTLY,GURADUALLY ERASED OR INSTALLED
RWY SIDE STRIPE MARKING FOR RWY 14L/32R PARTLY,GURADUALLY ERASED OR
INSTALLED
GROOVING FOR RWY 14L PARTLY,GURADUALLY ERASED OR INSTALLED
GROOVING FOR RWY 32R PARTLY,GURADUALLY ERASED OR INSTALLED
START OF VALIDITY
CHANGE TO READ
JUN 2026"

RJAAK1535/26 (28 MAY 26)

OBST DAY MARKING ERASED
TYPE: POWER LINE TOWER
PSN: 344450.0N1352315.0E ELEV: 241FT AMSL
(AMAGASAKI-SHI IN HYOGO

// (COM-INFO) //

THA 00188/15 (24 MAY 25)

COM INFO:--TAKE OFF AND LANDING NOT PERMITTED BETWEEN 1200-2200,
EXCEPT IN EMERGENCY (OW-INFO)

RJFF / FUK

RJAAF0835/26 (07 AUG 26)

10 AUG 2026 05:00-10 AUG 2026 08:00
UNMANNED ACFT:
(1)AREA: BOUNDED BY FLW POINTS
333926N1303335E - 333917N1303320E - 333910N1303317E - 333904N1303306E
- 333857N1303301E - 333851N1303305E - 333839N1303306E -
333838N1303310E - 333901N1303325E - 333901N1303340E - 333906N1303339E
- 333908N1303329E - 333919N1303330E - 333924N1303338E -
333926N1303335E
(2)AREA: BOUNDED BY FLW POINTS
333502N1303215E - 333501N1303216E - 333459N1303215E - 333457N1303210E
- 333458N1303211E - 333502N1303215E
(3)AREA: BOUNDED BY FLW POINTS
333458N1303155E - 333500N1303148E - 333506N1303148E - 333506N1303153E
- 333503N1303158E - 333459N1303156E - 333458N1303155E
(4)AREA: BOUNDED BY FLW POINTS
333500N1303244E - 333503N1303243E - 333500N1303225E - 333454N1303219E
- 333443N1303211E - 333441N1303211E - 333440N1303214E -
333445N1303216E - 333447N1303220E - 333443N1303224E - 333439N1303232E

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 27/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

- 333441N1303240E - 333443N1303239E - 333445N1303230E -
333449N1303225E - 333453N1303229E - 333454N1303236E - 333500N1303244E
(5)AREA: BOUNDED BY FLW POINTS
333300N1303048E - 333300N1303049E - 333257N1303052E - 333253N1303054E
- 333248N1303054E - 333251N1303051E - 333254N1303047E -
333256N1303046E - 333300N1303048E
(KASUYA-GUN IN FUKUOKA)
WT: 21.2KG
NUMBER: 2
F) SFC
G) 1326FT AMSL

*RJAAF0829/26 (06 AUG 26)

07-16 19-25 27-31 1330-2130
RWY 16L/34R CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR

RJAAF0816/26 (04 AUG 26)

RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT.

RJAAF0801/26 (29 JUL 26)

01-03 06-16 19-31 1400-2130
"TWY A(FM K1 TO E8),ACFT STAND TXL K1 THRU K7,Y CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

RJAAF0795/26 (29 JUL 26)

01-03 06-31 1330-2130
"TWY A(BTN E8 AND E13),E1 THRU E13,C1 THRU C9,W1 THRU W10,J1 THRU
J5,B,ACFT STAND TXL U CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

*RJAAF0778/26 (28 JUL 26)

01-25 27-31 1330-2130
RWY 16R/34L CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR

RJAAF0687/26 (08 JUL 26)

TWY-CL-LGT FOR TWY C6 U/S
RMK: (1)REF AIP SUP 161/26 ITEM TWY:1
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAF0683/26 (07 JUL 26)

"ACFT-STAND-ID-SIGN FOR SPOT 56,57,58 U/S
RMK: (1)REF AIP SUP 161/26 ITEM APRON:1
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAF0682/26 (07 JUL 26)

TWY-EDGE-LGT FOR WEST APN U/S
RMK: (1)REF AIP SUP 161/26 ITEM TWY:2
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAF0681/26 (07 JUL 26)

SEQUENCED-FLG-LGT FOR RWY 16L U/S
RMK: (1)REF AIP SUP 161/26 ITEM RWY:1
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

*RJAAF0671/26 (02 JUL 26)

PALS FOR RWY 16L PARTLY U/S DUE TO CONST
RMK: AVBL APCH LGT LEN 427M

RJFK / KOJ

RJAAK2055/26 (08 AUG 26)

0000-0800
UNMANNED ACFT:
AREA: BOUNDED BY FLW POINTS
315756N1304026E - 315753N1304027E - 315753N1304029E - 315752N1304030E
- 315751N1304032E - 315751N1304034E - 315752N1304035E -
315752N1304036E - 315751N1304038E - 315746N1304037E - 315743N1304038E
- 315742N1304034E - 315740N1304034E - 315740N1304029E -
315740N1304024E - 315741N1304023E - 315742N1304019E - 315744N1304019E
- 315746N1304021E - 315748N1304022E - 315750N1304022E -
315751N1304023E - 315752N1304026E - 315757N1304025E - 315756N1304026E
(AIRA-GUN IN KAGOSHIMA)

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 28/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

WT: 1.5KG
F) SFC
G) 3249FT AMSL

RJAAK1674/26 (19 JUN 26)

ALL STOP-BAR-LGT U/S DUE TO CONST

// (COM-INFO) //

THA 00557/16 (05 DEC 24)

RJFK:--ATS OPERATION HOURS (2230-1230)
(REF AIP RJFK AD 2.3)

ROAH / OKA

RJAAH2969/26 (04 AUG 26)

RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT

RJAAH2914/26 (31 JUL 26)

"TWY-CL-LGT FOR TWY D3,E7,N3 U/S DUE TO MAINT"

RJAAH2912/26 (31 JUL 26)

TWY-CL-LGT FOR TWY E10 U/S
RMK: REF AIP SUP 147/26 ITEM TWY:2

RJAAH2911/26 (31 JUL 26)

REF AIP SUP 147/26 ITEM TWY:2 (CHANGE TO READ)
TWY-CL-LGT FOR E10 FOR E10 U/S
END OF VALIDITY
CHANGE TO READ
JUL 2027

RJAAH2903/26 (31 JUL 26)

REF AIP SUP 147/26 ITEM TWY:3 (CHANGE TO READ)
RWY-ENTRANCE-LGT FOR E10 U/S
END OF VALIDITY
CHANGE TO READ
AUG 2026

RJAAH2866/26 (28 JUL 26)

03 05 07 10 12 14 17 19 21 24 26 28 31 1400-2130
"TWY E1,E2,E4(BTN RWY 18L/36R AND E4C),E5 THRU E10,A4(BTN SPOT 15
AND A5),A5 THRU A9,W1(BTN RWY 18L/36R AND W2),W3(BTN RWY 18L/36R AND
W3C),W4,W5,B(BTN J2 AND W5) CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

*RJAAH2867/26 (28 JUL 26)

03-07 10-14 17-21 24-28 31 1400-2130
RWY 18L/36R CLSD DUE TO MAINT
(1)AVBL CROSS RWY18L/36R VIA OTHER THAN CLSD TWY
(2)EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR

RJAAH2865/26 (28 JUL 26)

03-07 10-14 17-18 1530-2030
"TWY A1,A2,A3,A4(FM E4C TO SPOT 15),C1,C2,D1,D2,D3,N1,N2,N3 CLSD
DUE
TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

RJAAH2862/26 (28 JUL 26)

04 06 11 13 18 20 25 27 1400-2130
"TWY E3 THRU E10,A4(BTN SPOT 15 AND A5),A5 THRU A9,W2 THRU W5,B(BTN
J2 AND W5) CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

RJAAH2861/26 (28 JUL 26)

01-02 08-09 15-16 22-23 29-30 1400-2130
"TWY T1 THRU T9,C,J1,J2,R,B(FM W1 TO J2),W1(FM W2 TO B),W2,W3,W3C
CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

*RJAAH2860/26 (28 JUL 26)

01-02 08-09 15-16 22-23 29-30 1400-2130
RWY 18R/36L CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR

RJAAH2854/26 (28 JUL 26)

REF AIP PAGE ROAH AD2-27 (CHANGE TO READ)
ROAH AD 2.19 RADIO NAVIGATION AND LANDING AIDS
ILS-LOC 36R(IOK) REMARKS
ADD IN TEXT
LOC UNUSABLE : BETWEEN 0.5NM FM RWY THR AND RWY THR
RMK: THIS NOTAM WILL INCORPORATED IN AMDT ON 01 OCT 2026

RJAAH2788/26 (23 JUL 26)

03-07 10-11 17-21 24-26 31 1400-2100
"ILS-LOC,GP,DME FOR RWY 36R U/S DUE TO CONST"

RJAAH2789/26 (23 JUL 26)

01-02 16 22-23 29-30 1400-2100
"ILS-LOC,GP,DME FOR RWY 36L U/S DUE TO CONST"

RJAAH2790/26 (23 JUL 26)

01-02 16 22-23 29-30 1400-2100
"ILS-LOC,GP,DME FOR RWY 18R U/S DUE TO CONST"

RJAAH2760/26 (22 JUL 26)

04 19 1430-1930
FLW FREQ U/S DUE TO MAINT
RMK: ALTN FREQ AVBL AS FLW

	FREQ	ALTN FREQ
NAHA APPROACH/	119.1MHZ	125.55MHZ
NAHA DEPARTURE	335.8MHZ	310.0MHZ
	126.5MHZ	122.45MHZ
	258.3MHZ	321.5MHZ
KADENA ARRIVAL	135.9MHZ	121.1MHZ
	255.8MHZ	285.4MHZ
NAHA RADAR	290.3MHZ	363.8MHZ
	257.5MHZ	NONE
	297.2MHZ	NONE
	317.8MHZ	NONE

RKSI / ICN

// (COM-INFO) //THA 00219/26 (06 AUG 26)

COM INFO:+++ (NEW) --RKSI/ICN RWY34L/34R:
DUE TO AN ERROR IN THE EOSID PUBLISHED IN THE LIDO ROUTE MANUAL FOR RWY 34L AND RWY 34R, THE PUBLISHED EOSID SHALL NOT BE USED. IN THE EVENT OF AN ENGINE FAILURE DURING TAKEOFF FROM RWY 34L OR RWY 34R, FLIGHT CREWS SHALL DISREGARD THE ENGINE-OUT PROCEDURE CONTAINED IN THE ROUTE MANUAL AND APPLY THE FOLLOWING PROCEDURE:

-RWY 34L:
Climb on RWY Track. At 7 DME 'WNG' 112.9 LT to 'PY985' [N3723.3 E12605.9] (090 INBD,RT)

-RWY 34R:
Climb on RWY Track. At 7 DME 'WNG' 112.9 LT to 'PY985' [N3723.3 E12605.9] (090 INBD,RT)

Validity Period: 06AUG26 -UFN

(ISSUED 06AUG26/BKKPC/UFN)

RKRR1073/26 (31 JUL 26)

"TXL R23, R24 AVBL FOR ACFT UP TO ICAO CODE E WHEN TAXIING TO STAND
208R, 290R"

// (COM-INFO) //THA 00037/25 (11 JUL 26)

COM INFO:--Extra Charge 25% by Ground Handling
When Aircraft On Block Before 0600LT (2100Z).
(UPDATE 14SEP25/SMT/OP/INFO/UFN)

RKRRZ0444/26 (11 JUL 26)

"TRIGGER NOTAM - PERM AIRAC AIP AMDT 7/26 WEF 1600 UTC 5 AUG 2026
- INFORMATION OF WEBSITE ADDRESS.
- INFORMATION OF STOP-BAR LIGHTS, RWY HOLDING POSITION AND HOT SPOT SYMBOL."

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 30/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

RKPC / CJU

*RKRA1100/26 (06 AUG 26)

1400-2100
RWY 07/25 CLSD DUE TO WIP
RMK:
1. RWY 07/25 CLSD START TIMES MAY BE ADJUSTED AFTER THE END OF
SKED FLT OPS
2. 60MIN PN FOR NML OPS

RKRA1060/26 (28 JUL 26)

31 JUL 2026 14:00-10 AUG 2026 21:00
1400-2100
ACFT STAND NR 13 AND 18 CLSD DUE TO WIP

RKRRZ0446/26 (25 JUN 26)

TRIGGER NOTAM - AIRAC AIP SUP 56/26 WEF 1600 UTC 5 AUG 2026 TIL
1600 UTC 14 APR 2027
- THE ILS/DME FOR RWY 07 AT JEJU INTL AIRPORT WILL BE UNSERVICEABLE
DUE TO REPLACEMENT.

// (COM-INFO) //

THA 00357/17 (05 DEC 24)

COM-INFO:--RKPC AERODROME IS CLASSIFIED AS GROUP B. (REF SAI)

ZSPD / PVG

ZBBBF3220/26 (07 AUG 26)

"PUDONG AIRPORT VISUAL APPROACH REGULAR OPERATION:
1. IMPLEMENTATION WEATHER CONDITIONS PREVAILING VISIBILITY : MORE
THAN 5,000M,CEILING: 700M AND ABOVE.
2. INSTRUCTIONS FOR PILOTS
2.1 THE VISUAL APPROACH SHALL BE INITIATED BY EITHER PILOT OR ATC
UPON MUTUAL APPROVAL. ATC WILL INFORM THE CREW OF THE EXPECTED
VISUAL APPROACH WHEN ISSUING THE ARRIVAL METHOD, , THE PILOT MUST
INFORM THE ATC IF CANNOT ACCEPT THE VISUAL APPROACH.
2.2 THE ATC MAY ISSUE VISUAL APPROACH INSTRUCTION AFTER PILOT
REPORT THE LANDING RUNWAY OR THE PRECEDING AIRCRAFT IS IN SIGHT.
2.3 AFTER RECEIVING THE VISUAL APPROACH CLEARANCE,THE ALTITUDE AND
HEADING SHALL BE AT THE PILOT'S OWN DISCRETION.FLYING TOWARD THE
LANDING AIRPORT OR FOLLOW THE PRECEDING AIRCRAFT FOR VISUAL
APPROACH, THE PILOT IS RESPONSIBLE FOR MAINTAINING SAFETY
SEPARATION BETWEEN PRECEDING AIRCRAFT AND GROUND OBSTACLES.
2.4 PUDONG AIRPORT WILL BROADCAST THE VISUAL APPROACH INFORMATION
ON THE ATIS.
3. TERMINATION OF VISUAL APPROACH
3.1 DURING THE VISUAL APPROACH, THE CONTROLLER WILL ACTIVELY
TERMINATE THE VISUAL APPROACH IN ANY OF THE FOLLOWING SITUATIONS:
3.1.1 THE PILOT REPORTS THAT IT IS UNABLE TO CONTINUE AND COMPLETE
THE VISUAL APPROACH DUE TO WEATHER CONDITIONS OR OTHER REASONS
3.1.2 THE CONTROLLER FINDS THAT THE WEATHER CONDITIONS ARE BELOW
THE
METEOROLOGICAL CONDITIONS FOR THE VISUAL APPROACH
3.1.3 THE CONTROLLER DISCOVERS PHENOMENA THAT MAY AFFECT FLIGHT
SAFETY DURING THE VISUAL APPROACH OF THE ACFT.
3.2 THERE IS NO NEED TO SET A MISSED APPROACH SEGMENT FOR A VISUAL
APPROACH. WHEN AN ACFT CANNOT COMPLETE THE VISUAL APPROACH, IT
WILL BE CONVERTED TO AN INSTRUMENT APPROACH OR THE APPROACH WILL
BE
TERMINATED. THE CONTROLLER WILL PROVIDE NECESSARY ASSISTANCE AND
ALLOCATE THE ACFT WITH THE SEPARATION IN ACCORDANCE WITH THE
REGULATIONS.
3.3 WHEN THE CONTROLLER DEEMS THAT THE CONTINUED IMPLEMENTATION OF
THE VISUAL APPROACH BY THE ACFT MAY CAUSE SUBSEQUENT SAFETY
HAZARDS, THE CONTROLLER WILL INSTRUCT THE ACFT TO TERMINATE THE
VISUAL APPROACH AND ALLOCATE THE ACFT WITH THE SPECIFIED RADAR
SEPARATION.
3.4 AFTER TERMINATING THE VISUAL APPROACH, THE CONTROLLER WILL
ISSUE CONTROL INSTRUCTIONS SUCH AS HEADING AND ALTITUDE TO THE
ACFT TO ESTABLISH THE CORRESPONDING SAFE SEPARATION ASAP.)"

ZBBBF3215/26 (07 AUG 26)

10 AUG 2026 05:00-10 AUG 2026 09:00
"TWY B CLSD BTN TWY B8 AND TWY B7,INTERSECTION CLSD BTN TWY B8
AND TWY B,BTN TWY B7 AND TWY B."

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 31/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

ZBBBBF3209/26 (07 AUG 26)

10 AUG 2026 18:00-10 AUG 2026 22:15
"FLW TWY CLSD:
1. TWY E5 BTN TWY L08 AND TWY L09.INTERSECTION CLSD BTN TWY L08 AND TWY E5.
2. TWY T2 BTN TWY B AND TWY E.
3. TWY L17.
4. TWY L08 BTN TWY R6 AND TWY R5.
5. TWY L17A BTN PARKING STAND NR.451 AND NR.452.INTERSECTION CLSD BTN TWY L17A AND PARKING STAND NR.451,BTN TWY L17A AND PARKING STAND NR.452."

ZBBBBF3211/26 (07 AUG 26)

10 AUG 2026 17:30-10 AUG 2026 22:15
"FLW TWY CLSD:
1. TWY P1,P4 CLSD BTN TWY D AND TWY B.
2. TWY A BTN TWY B8 AND TWY P1.INTERSECTION CLSD BTN TWY P1 AND TWY A. ACFT SHALL CROSS TWY A VIA TWY P2,P3,P6,P5."

*ZBBBBF3213/26 (07 AUG 26)

10 AUG 2026 17:30-10 AUG 2026 22:15
"RWY17L/35R CLSD. ACFT SHALL CROSS RWY17L/35R VIA TWY P2,P3,P5,P6."

*ZBBBBF3207/26 (07 AUG 26)

08 AUG 2026 17:30-10 AUG 2026 22:15
08 10 1730-2215
RWY16L/34R CLSD.

ZBBBBF3208/26 (07 AUG 26)

08 AUG 2026 17:30-10 AUG 2026 22:15
08 10 1730-2215
"FLW TWY CLSD:
1,TWY G,H.
2.TWY R1 BTN TWY G AND TWY H, INTERSECTION CLSD BTN TWY G AND TWY R1, BTN TWY H AND TWY R1.
3.TWY R6 BTN TWY G AND TWY H, INTERSECTION CLSD BTN TWY G AND TWY R6, BTN TWY H AND TWY R6."

ZBBBBF3193/26 (06 AUG 26)

"IMPLEMENT THE LID(LANDING INFORMATION DELIVER) OPERATION TRIAL.THE BASIC LID PROCEDURE AS FOLLOW:
1.SHANGHAI APPROACH WILL ISSUE THE LID MESSAGE BY DATA-LINK TO ARRIVAL FLIGHTS TO ZSPD 50 MINUTES BEFORE LANDING
2.THE LID INFORMATION WILL INCLUDE EXPECTED ARRIVAL PROCEDURE, TRANSITION(ON REQUIRED), LANDING RUNWAY, AND PARKING STAND
3.PILOT CAN DIRECTLY USE THE LID INFORMATION FOR FMS PREPARATION DURING CRUISE PHASE WITHOUT RADIO CONFIRMATION BY ACC.PRKG STAND INFORMATION FOR REFERENCE ONLY,BASED ON AD ALLOCATION,DO NOT CONTACT ATC FOR PRKG STAND INFORMATION IN AIR.
4.ON INITIAL CONTACT SHANGHAI APPROACH,PILOT SHOULD ADVISE YOUR LID INFORMATION INCLUDING EXPECTED ARRIVAL PROCEDURE,TRANSITION(IF ANY), AND LANDING RUNWAY
5.SHANGHAI APPROACH WILL CONFIRM OR MODIFY FROM PILOT LID REPORT:
6.AFTER ESTABLISH RADIO COMMUNICATION WITH SHANGHAI APPROACH, ALL CHANGE FOR THE LANDING INFORMATION SHOULD BE JUST FOLLOWED THE INSTRUCTION BY CONTROLLER .
7.IF PILOT DO NOT RECEIVE THE LID INFORMATION, PILOT SHOULD FOLLOW THE CURRENT PROCEDURE
8.FOR BETTER IMPROVE THE LID SERVICE, PLEASE FEEL FREE TO TELL US YOUR SUGGESTION AND COMMENTS TO EMAIL:
SUNY1(A)ATMB.NET.CN"
06 AUG 26 07:37 UNTIL 31 DEC 26 15:59 ESTIMATED

ZBBBBF2931/26 (22 JUL 26)

"FLW PARKING STAND CNL FOLLOW-ME VEHICLE (EXCEPT ACFT TYPE A380) WHEN ACFT TAXI IN:PARKING STAND NR.102-108,182-188."

ZBBBBF2442/26 (11 JUL 26)

LIUZAO VOR/DME 'PDL' 109.4MHZ/CH31X U/S BTN RADIAL 209DEG-213DEG CLOCKWISE.

ZBBBBF2231/26 (11 JUL 26)

"REFER TO AIP ZSPD 3P-12(2026-5-1), RWY 16L/16R SID DESIGNATION

IS LAMEN-5(BY ATC) .
OTHERS REMAIN."

ZBBBBF2232/26 (11 JUL 26)

"REFER TO AIP ZSPD 3V-1(2026-5-1), SID DESIGNATTION ON
'D22.0HSH-HSH' SECTION ARE ODULO-E/ ODULO-F/ ODULO-G (BY
ATC)/ODULO-H(BY ATC)/PIKAS-G(BY ATC)/ PIKAS-H(BY ATC) .
OTHERS REMAIN."

ZBBBBF2230/26 (11 JUL 26)

"REFER TO AIP ZSPD 3P-3(2026-5-1), RWY16L/16R SID RWY TRANSITION
PROCEDURE DESIGNATION ARE PIKAS-3(BY ATC) AND PIKAS-5, RWY17L/17R
SID RWY TRANSITION PROCEDURE DESIGNATION IS PIKAS-3(BY ATC) .
OTHERS REMAIN."

ZBBBBF2079/26 (11 JUL 26)

"ACTIVITIES OF BIRD FLOCKS WILL TAKE PLACE AROUND AD:
AREA 1:PRIMARY ACTIVITY AREA INCLUDE THE NORTHERN END OF
AIRPORT,EASTERN OF CHONGMING ISLAND TO SEA OF CHANGXING ISLAND,
AND AREAS WI A 6KM RADIUS OF THE SOUTHERN OF WETLAND,FARMLAND AND
COASTAL REGION.
ALT:0M-200M,MIGRATORY FLIGHT ALT 300M-2,000M AT AUG AND SEP.
TIME:DAY AND NIGHT,
AERODROME AUTHORITY RESORTS TO DISPERSAL METHODS TO REDUCE BIRD
ACTIVITIES.
EXERCISE CAUTION WHILE LANDING AND TAKE-OFF."

ZBBBBF1826/26 (11 JUL 26)

TWY T5(BTN TWY S1 AND TWY S2) ONLY AVBL FOR ACFT WITH WINGSPAN
LESS THAN 36M.
14 MAY 26 03:23 UNTIL 13 AUG 26 15:59 ESTIMATED

RCTP / TPE

*RCTPA2785/26 (08 AUG 26)

0400-0430
RWY 05R/23L CLSD DUE TO INSPECTION.
10 AUG 26 04:00 UNTIL 27 SEP 26 04:30 ESTIMATED

*RCTPA2783/26 (08 AUG 26)

0300-0330
RWY 05L/23R CLSD DUE TO INSPECTION.
10 AUG 26 03:00 UNTIL 27 SEP 26 03:30 ESTIMATED

// (COM-INFO) //THA 00202/26 (03 AUG 26)

COM INFO:+++ (NEW) --TPE/RCTP:
TAKEOFF AND LANDING PERFORMANCE CALCULATION
SHALL BE BASED ON TEMPORARY RUNWAY WHEN OPERATING ON 05R.

Runway 05R
Validity Period: 01JUL2026 - 30SEP27

(REVISED 03AUG26/BKKPC/TILL 30SEP27)

RCTPA2638/26 (03 AUG 26)

"AIP SUP 19/26 WEF 03 AUG 2026 TIL 31 DEC 2027,
GROUND MANEUVERING RESTRICTIONS FOR AERODROME REFERENCE
CODE F AIRCRAFT AT TAIPEI/TAIWAN TAOYUAN INTERNATIONAL AIRPORT.
THIS AIP SUP REPLACES AIP SUP 14/22."

RCTPA2549/26 (28 JUL 26)

"BIRD CONCENTRATION DRG 2100-1100:
1.IN THE VCY OF THE AP, AND AT AP
IN THE APPROACH PATH OF RWY 23L,
HGT: 0-1500FT, BIRD WT: 370 GRAMS.
2.IN THE VCY OF THE AP AND AT AP
IN THE APPROACH PATH OF RWY 05L/23R AND RWY 05R/23L,
HGT: 0-300FT, BIRD WT: 750-1500 GRAMS.
3.IN THE NORTH OF RWY 05L/23R AND IN THE SOUTH OF RWY 05R/23L,
HGT: 0-300FT, BIRD WT: 87 GRAMS."

RCTPA2436/26 (19 JUL 26)

"PORTION OF TWY L BEHIND PRKG BAY 525 CLSD
FOR ACFT PRKG AND TOWING.
RMK: DEP ACFT IN PRKG BAY 524 PUSH BACK TO FACE EAST

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 33/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

UNTIL ABEAM PRKG BAY 520, THEN TAX."
19 JUL 26 13:41 UNTIL 16 OCT 26 08:00 ESTIMATED

RCTPA2166/26 (09 JUL 26)

0330-0400
"SCHEDULED CLOSURE OF RWY 05R/23L SUSPENDED.
REF AIP RCTP AD 2.20.1, ITEM 4."
30 JUN 26 03:30 UNTIL 27 SEP 26 04:00 ESTIMATED

RCTPA2164/26 (09 JUL 26)

0230-0300
"SCHEDULED CLOSURE OF RWY 05L/23R SUSPENDED.
REF AIP RCTP AD 2.20.1, ITEM 4."
30 JUN 26 02:30 UNTIL 27 SEP 26 03:00 ESTIMATED

RCTPA2069/26 (25 JUN 26)

"PORTION OF TWY E BTN TWY P (EXCLUDED) AND TWY Q (EXCLUDED) ONLY
AVBL FOR ACFT WITH CODE LETTER A, B, C, D, E.
(REF ICAO ANNEX 14 AERODROMES, TABLE 1-1 AERODROME REFERENCE CODE)
RMK: ACFT TYPE B748 TOWING IS PERMITTED."
23 JUN 26 22:20 UNTIL 31 AUG 26 09:00 ESTIMATED

RCTPA1648/26 (07 JUN 26)

PORTION OF TWY R BTN TWY R1 (INCLUDED) AND TWY R3 (EXCLUDED)
CLSD FOR ACFT PRKG.
29 MAY 26 00:37 UNTIL 25 AUG 26 08:00 ESTIMATED

RCTPA2908/25 (08 SEP 25)

"REF AIP SUP 14/22, GROUND MANEUVERING RESTRICTIONS FOR AD
REFERENCE
CODE F ACFT AT TAIPEI/TAIWAN TAOYUAN INTL AP, END DATE REVISED AS
31 AUG 2028, 1559UTC. THE REST NC."

RCKH / KHH

// (COM-INFO) //

THA 00220/26 (07 AUG 26)

RCKH:--AIP SUP 16/26:
-CONSTRUCTION WORK AT KAOHSIUNG INTL AIRPORT

1. This AIP SUP replaces AIP SUP 27/25 (Phase 2, Phase 8 and Phase 9 deleted).
2. To avoid jet blast hazard, pilots shall use minimum breakaway thrust/power setting near construction areas.
3. Airport operations are limited to aircraft with a wingspan up to but not including 65M (up to and including aerodrome reference code E).
4. Estimated construction period is through JUL 2027. The following construction phase will be activated by NOTAM.

-Phase 1 (during curfew 1601-2230 UTC)
1. RWY 09/27 closed.
2. All Taxiways closed.
3. The airport, under the above conditions,
is only available for emergency medical service helicopter TKOF/LDG at designated area.
4. The airport is not to be used for technical landing or not
to be requested as an alternate for flight planning

RCTPA2744/26 (06 AUG 26)

"TWY CENTER LINE LGT OF TWY B, TWY C, TWY D,
TWY E, TWY F, TWY G, TWY H AND TWY S U/S DUE TO WIP."
06 AUG 26 22:30 UNTIL 05 NOV 26 22:30 ESTIMATED

RCTPA2697/26 (05 AUG 26)

TWY H CLSD DUE TO WIP.

RCTPU1899/26 (04 AUG 26)

"UNMANNED ACFT WILL BE RELEASED:
1. CASE NR: AB260626002201
2. LCA: XIAOGANG DISTRICT, KAOHSIUNG CITY
3. THE AREA OVERLAPS PART OF VFR CORRIDOR C9 AND C15,
ACFT ARE CTN ADZ.
4. COOR TEL: 0923-125168, 0972-323695
5. AREA AS FLW :
223409N 1201922E - 223436N 1201954E - 223344N 1202036E -
223317N 1201959E - 223409N 1201922E"
F) SFC
G) 500FT AMSL

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 34/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

RCTPA2611/26 (31 JUL 26)

TWY G CLSD DUE TO WIP.

RCTPA2609/26 (31 JUL 26)

TWY B CLSD DUE TO WIP.

RCTPA2610/26 (31 JUL 26)

TWY C CLSD DUE TO WIP.

RCTPU1848/26 (30 JUL 26)

"UNMANNED ACFT WILL BE RELEASED:
1.CASE NR:AB260616003701
2.LCA:XIAOGANG DISTRICT, KAOHSIUNG CITY
3.THE AREA OVERLAPS PART OF HELIPORT OF KAOHSIUNG
EMERGENCY OPERATION CENTER, PART OF VFR CORRIDOR C9
AND C15, ACFT ARE CTN ADZ.
4.COOR TEL:0910-551384, 0965-454118
5.AREA AS FLW:
223520N 1201847E
223552N 1201942E
223421N 1202024E
223421N 1202116E
223303N 1202219E
223305N 1202051E
223520N 1201847E"
F) SFC
G) 600FT AMSL

RCTPA2556/26 (29 JUL 26)

TWY F CLSD DUE TO WIP.

RCTPA2555/26 (29 JUL 26)

TWY D CLSD DUE TO WIP.

RCTPA2442/26 (20 JUL 26)

"REF AIRAC AIP AMDT 03/26 RCKH AD 2.13 DECLARED DISTANCES,
INTERSECTION TAKE-OFF OF RWY 27, CHANGE TWY F TO READ TWY G.
THIS NOTAM WILL BE INCORPORATED IN AIRAC AIP AMDT 04/26
WEF 01 OCT 2026."

*RCTPA2408/26 (17 JUL 26)

1601-2230
"REF AIP SUP 16/26 DATED 17 JUL 2026 AND NOTAM A2405/26, CONST
WORK AT KAOHSIUNG INTL AIRPORT, PHASE 1 (DURING CURFEW) ACT.
RWY 09/27 AND ALL TWY CLSD."

RCTPA2405/26 (17 JUL 26)

"AIP SUP 16/26, CONST WORK AT KAOHSIUNG INTL AIRPORT.
REPLACES AIP SUP 27/25.
THE DATE AND TIME OF CONST PHASE ACTIVATION WILL BE NOTIFIED BY
NOTAM."
17 JUL 26 02:35 UNTIL 31 JUL 27 23:59 ESTIMATED

RCTPA2096/26 (25 JUN 26)

"TRIGGER NOTAM-PERM AIRAC AIP AMDT 03/26,
WEF 06 AUG 2026, 2230UTC.
1. STAND 515 IS WITHDRAWN.
2. NEW RAPID EXIT TWY D, F ARE INSTALLED.
3. EXISTING TWY ARE RE-DESIGNATED AS B, C, E, G, H, J.
4. TWY C, E, G, H, J, S CENTERLINE LIGHTS ARE INSTALLED.
5. HOT SPOTS ARE UPDATED.
6. ADC IS REVISED ACCORDINGLY."

// (COM-INFO)//

THA 00352/17 (10 JUN 26)

COM-INFO:--1) ATS HRS (2200-1600)
2) DUE TO NOISE ABATEMENT, TAKE OFF/LDG IS PROHIBITED
DURING THE PERIOD FM 1601-2230 UTC EXCEPT EMERGENCY.
(REF AIP TAIPEI AD 2-RCKH)

RPLL / MNL

RPLLB4034/26 (09 AUG 26)

"TWY EDGE LGT ON THE FLW AREAS: TWY C (BTN TWY G6 AND G4),

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 35/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

TWY G7, G8, K, L AND RAPID EXIT TWY R3 U/S.

RMK: EXER CTN WHEN TAX."

RPLLB4033/26 (09 AUG 26)

"EXER CTN WHEN TAX TWY F1, F2, F3, F4, F5, G3, H3, H4 AND H5 DUE
RWY 13/31 GUARD LGT U/S."

RPLLB4026/26 (09 AUG 26)

EXER CTN WHEN TAX PORTION OF TWY D (BTN TWY G12 AND G15) DUE
PRESENCE OF POTHOLES AND UNEVEN PAVEMENT SFC.

RPLLB4025/26 (09 AUG 26)

EXER CTN WHEN TAX PORTION OF TWY Y (AT COORD: 143054.33N
1210059.41E AND 143103.11N 1210101.55E) DUE PRESENCE OF RUTTING
PAVEMENT.

RPLLB3994/26 (07 AUG 26)

EXER CTN WHEN OPR REMOTE PRKG APN T2 (RPA T2) BAY NR 26 DUE
PRESENCE OF SOFTSPOT.

RPLLB3995/26 (07 AUG 26)

11 AUG 2026 00:00-16 AUG 2026 09:00
0000-0900
TERMINAL 3 APN PRKG BAY NR 107 WIP
(DEMOLITION AND EXCAVATION WORKS FOR THE NOSE LOADER
FOUNDATION OF PAX BOARDING BRIDGE).

RMK: EXER CTN WHEN OPR DUE PRESENCE OF MEN AND EQPT
(TWO (2) BACKHOES WITH HGT APRX 9.85FT).

RPLLB3938/26 (04 AUG 26)

EXER CTN WHEN OPR REMOTE PRKG APN T2 (RPA T2) BAY NR 25
DUE PRESENCE OF POTHOLE AND CRACKED PAVEMENT.

RPLLB3927/26 (03 AUG 26)

"EXER CTN WHEN TAX PORTION OF TWY L (ABM TERMINAL 1 STARTING POINT
S4, S5 AND S6) DUE PRESENCE OF SOFT SPOT AND UNEVEN PAVEMENT SFC."

RPLLB3881/26 (31 JUL 26)

ILS CAT I RWY 24 U/S.

RPLLB3865/26 (30 JUL 26)

"STOP BAR LGT TWY C, G3, E1, E2, E4, E5, H1, H2, RAPID EXIT TWY
R2, R3 AND R4 WIP (SYSTEM TESTING)."

RPLLB3857/26 (30 JUL 26)

EXER CTN WHEN OPR 5J RAMP 1 APN DUE WIP (LOADING AND UNLOADING OF
EQPT) AT COORD: 143046N 1210113E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 92FT).

RPLLB3807/26 (28 JUL 26)

EXER CTN WHEN OPR GA MOV AREA DUE PRESENCE OF POTHOLES
AT COORD: 143135.40N 1210010.07E.

RPLLB3806/26 (28 JUL 26)

EXER CTN WHEN OPR RPA GA DUE WIP (LOADING AND
UNLOADING OF EQPT) AT COORD: 143130.64N 1210004.70E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 26FT).

RPLLB3798/26 (28 JUL 26)

"EXER CTN WHEN TAX TWY F1, G11 AND PORTION OF TWY N (ABM RPA T3
PRKG BAY NR 123, 124, 125 AND 126) DUE WIP (CONST OF TWY AT COORD:
143120.24N 1210026.09E)

RMK: PRESENCE OF MEN AND EQPT.
ALL ARRIVING ACFT TAX PORTION OF TWY N (ABM RPA T3 PRKG BAY
NR 123, 124, 125 AND 126) AND TWY G11 SHALL FLW DIVERTED TWY CL
MARKINGS AND MNM TAX PWR.
TERMINAL 3 APN STARTING POINT S13 REPOSITIONED TEMPO DIVERTED CL
MARKINGS ABM RPA T3 PRKG BAY NR 124."

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 36/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

RPLLB3795/26 (28 JUL 26)

EXER CTN WHEN TAX PORTION OF TWY D (BTN TWY G11 AND G12) AND F1
DUE WIP (CONST OF TWY AT COORD: 143120.24N 1210026.09E).

RMK: ALLOWED FOR ACFT CODE C TOWING OPS ONLY.
ACFT CODE B AND BLW ALLOWED FOR TAX PWR.

RPLLB3794/26 (28 JUL 26)

EXER CTN WHEN OPR TERMINAL 3 APN STARTING POINT S13 DUE WIP
(CONST OF TWY AT COORD: 143120.24N 1210026.09E)

RMK: PRESENCE OF MEN AND EQPT.

RPLLB3775/26 (27 JUL 26)

"EXER CTN WHEN OPR TERMINAL 1 APN PRKG BAY NR 2, 5, 14 AND 15 DUE
PRESENCE OF DAMAGED PAVEMENT."

RPLLB3774/26 (27 JUL 26)

EXER CTN WHEN OPR RPA GA APN PRKG BAY NR 71 DUE WIP (LOADING AND
UNLOADING OF ACFT PARTS) AT COORD: 143122N 1210006E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 36FT).

RPLLB3776/26 (27 JUL 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (LOADING AND UNLOADING
OF ACFT PARTS) AT COORD: 143109N 1210008E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 115FT).

RPLLB3773/26 (27 JUL 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (LOADING AND UNLOADING
OF EQPT) AT COORD: 143116.06N 1210015.07E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 16FT).

RPLLB3772/26 (27 JUL 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (LOADING AND UNLOADING
OF ACFT PARTS) AT COORD: 143113N 1210008E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 100FT).

RPLLB3770/26 (27 JUL 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (DEMOLITION OF HANGAR)
AT COORD: 143059.65N 1210011.23E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 148FT).

RPLLB3771/26 (27 JUL 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (DEMOLITION OF HANGAR)
AT COORD: 143137.84N 1210013.11E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 36FT).

RPLLB3769/26 (27 JUL 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (LOADING AND UNLOADING
OF EQPT) AT COORD: 143110N 1210016E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 53FT).

RPLLB3762/26 (27 JUL 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (LOADING AND UNLOADING OF
EQPT) AT COORD: 143138.94N 1210016.90E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 25M).

RPLLB3683/26 (23 JUL 26)

EXER CTN WHEN TAX PORTION OF TWY C (ABM TWY G9)
DUE PRESENCE OF UNEVEN PAVEMENT SFC.

RPLLB3671/26 (22 JUL 26)

EXER CTN WHEN TAX TWY H5 DUE WIP (RELOCATION OF AWOS).

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 37/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

RMK: PRESENCE OF MEN AND EQPT.

RPLLB3319/26 (10 JUL 26)

APN CTL THREE PRI FREQ 121.35MHZ U/S DUE TO TECHNICAL ISSUE.

RMK: ALL ACFT CTC APN CTL THREE ON SRY FREQ 121.55MHZ.

RPLLB3172/26 (10 JUL 26)

0000-2359 EXC JUL 04 06

EXER CTN WHEN OPR GA MOV AREA DUE WIP (HANGAR CONST) AT
COORD: 143111.43N 1210004.54E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 115FT).

RPLLB3169/26 (10 JUL 26)

0000-2359 EXC JUL 04 06

"EXER CTN WHEN OPR GA MOV AREA DUE PRESENCE OF POTHOLES AT COORD:
143132.09N 1210025.14E, 143132.43N 1210028.21E AND 143106.71N
1210023.79E."

RPLLB3064/26 (10 JUL 26)

TERMINAL 3 APN PRKG BAY NR 120 CLSD DUE WIP (INSTL OF NEW PAX
BOARDING BRIDGE).

RMK: EXER CTN WHEN PSG THE AREA DUE PRESENCE OF MEN AND EQPT WITH
BOOM HGT APRX 75.46FT.

RPLLB3063/26 (10 JUL 26)

TERMINAL 3 APN PRKG BAY NR 101 CLSD DUE WIP (DISMANTLING AND
INSTL OF NEW PAX BOARDING BRIDGE).

RMK: EXER CTN WHEN PSG THE AREA DUE PRESENCE OF MEN AND EQPT WITH
BOOM HGT APRX 75.46FT.

RPLLB2938/26 (10 JUL 26)

EXER CTN DRG LDG/TKOF RWY 06/24 DUE WIP (GRADING OF RWY STRIP) FM
COORD 142948.01N 1210000.15E TO 143048.41N 1210149.59E.

RMK: PRESENCE OF MEN AND EQPT.

RPLLB2160/26 (10 JUN 26)

TERMINAL 2 APN PRKG BAY NR 49 LTD TO CODE C AND LOWER CAT ACFT
DUE WIP (CONST OF NEW TERMINAL 5 APN).

*RPLLB2161/26 (10 JUN 26)

"RWY 13/31 HR OF OPS:

TUE, WED, FRI, SUN: H24

MON, THU, SAT: 0000-1400, 2000-2359."

RPLLB2162/26 (10 JUN 26)

MON THU SAT 1400-2000

TWY J AND P CLSD DUE WIP (CONST OF TWY).

RPLLB2159/26 (10 JUN 26)

EXER CTN WHEN TAX PORTION OF TWY K (FM COORD 143045.25N
1210047.50E TO 143057.77N 1210034.83E) DUE WIP (CONST OF TWY).

RPLLB2158/26 (10 JUN 26)

TWY F1B CLSD DUE WIP (CONST OF TWY FM COORD 143124N 1210011E TO
143046N 1210050E).

RMK: PRESENCE OF MEN AND EQPT.

RPLLB2156/26 (10 JUN 26)

EXER CTN WHEN TAX ABM TWY H3 DUE WIP (CONST OF TWY).

RPLLB2157/26 (10 JUN 26)

EXER CTN WHEN TAX TWY P DUE PRESENCE OF OPEN TRENCH
AT COORD: 143045N 1210049E.

RPLLB2155/26 (10 JUN 26)

EXER CTN WHEN TAX PORTION OF TWY K AT COORD: 143044N 1210048E DUE

WIP (CONST OF TWY) .

RPLLB2154/26 (10 JUN 26)

EXER CTN DRG LDG/TKOF RWY 06/24 DUE RANDOM LASER LGT EMITTING FM UNIDENTIFIED SOURCES.

ZGGG / CAN

ZBBBG3445/26 (29 JUL 26)

TWY B1 CLSD EAST OF TWY Y.

ZBBBG3330/26 (23 JUL 26)

FLW TWY ONLY AVBL FOR ACFT WITH WING SPAN NOT MORE THAN 65M:
1.TWY Q15 NORTH OF TWY Q10.
2.TWY Q16.

ZBBBG3241/26 (20 JUL 26)

PARKING STAND FX14 CLSD DUE TO MAINT.
22 JUL 26 04:00 UNTIL 30 SEP 26 15:59 ESTIMATED

ZBBBG3201/26 (17 JUL 26)

"DUE TO OPERATIONAL REQUIREMENTS, TWY B EASTBOUND, TURN RIGHT TO TWY T1 ONLY AVBL FOR ACFT WITH WINGSPAN NOT MORE THAN 36M(ACFT TYPE C AND BELOW)."
17 JUL 26 07:19 UNTIL 16 OCT 26 15:59 ESTIMATED

ZBBBG3200/26 (17 JUL 26)

TWY Q11 CLSD BTN TWY Q AND TWY Q15.
17 JUL 26 07:18 UNTIL 16 OCT 26 15:59 ESTIMATED

ZBBBG3050/26 (11 JUL 26)

PARKING STAND FX09 CLSD.DUE TO MAINT.

ZBBBG3021/26 (10 JUL 26)

"AD ADD LIMITATION AS FLW,DUE TO WIP:
1.WHEN TAXI IN TWY E,ACFT ARE FORBIDDEN TO TURN LEFT TO TWY J1.
2.WHEN TAXI IN TWY J1,ACFT ARE FORBIDDEN TO TURN RIGHT TO TWY E."
10 JUL 26 07:56 UNTIL 30 SEP 26 15:59 ESTIMATED

ZBBBG2963/26 (08 JUL 26)

"PRKG STAND GY07,GY08,GY09,GY10 CLSD DUE TO WIP."
08 JUL 26 07:40 UNTIL 30 SEP 26 15:59 ESTIMATED

ZBBBG2703/26 (30 JUN 26)

"DUE TO PINGZHOU VOR/DME 'POU' U/S,FLW SID PROCEDURE U/S:
1.SID RWY01L/01R(ZGGG-3V-5):SAREX-1.
2.SID RWY01L/01R(ZGGG-3V-7):VIBOS-1."
30 JUN 26 03:02 UNTIL 30 SEP 26 15:59 ESTIMATED

ZBBBG2695/26 (30 JUN 26)

"REF AIP AD2.20 USE OF APRONS AND PARKING STANDS ITEM 3.2
CHANGED AS FLW:
ACFT SHALL BE GUIDED BY FOLLOW-ME VEHICLE TO ENTER INTO THE WHOLE STANDS,
CHINA SOUTHERN AIRLINES AND CHONGQING AIRLINES NOT NEED TO FOLLOW THE FOLLOW-ME VEHICLE TO ENTER INTO THE PARKING STANDS
NR.101-133,134L,134-137,144-149,149L,149R,201-235,236,238,238L,238R ,240,240L,240R,251-254,254L,254R,255,255L,255R,301-308,329,330,401-419, 401L,401R,402L,402R,403L,403R,404L,404R,405L,405R,406L,406R,GY01-GY05."
30 JUN 26 22:00 UNTIL 30 SEP 26 15:59 ESTIMATED

ZBBBG2675/26 (29 JUN 26)

"TWY N CLSD BTN TWY T12 AND TWY T13,DUE TO OPERATION REQUIREMENT."
29 JUN 26 06:01 UNTIL 30 SEP 26 15:59 ESTIMATED

ZBBBG2328/26 (12 JUN 26)

LONGMEN VOR/DME 'LMN' 116.3MHZ/CH110X U/S DUE TO MAINT.
12 JUN 26 07:17 UNTIL 31 DEC 26 15:59 ESTIMATED

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 39/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

// (COM-INFO)//

THA 00290/17 (10 JUN 26)

COMP INFO:--RE GROUND POWER UNIT UTILIZATION AT
GUANGZHOU BAIYUN INTL A/P AS NOTIFICATION TO AIRMAN-NOTAM STP
INFO FROM CANKKTG:
" GPU N ACU WLBE CONNECTED TO A/C AFTER PARKING BRIDGE HAS BEEN
CONNECTED- REPEAT -ALL EXTERNAL POWER WLBE CONNECTED AFTER A/C
BLOCKED ON N BRIDGE CONNECTION IS COMPLETED STP"
(UPDATE 02JAN26/CANKK-INFO/UFN)

ZBBBG1489/26 (10 JUN 26)

TWY S1 CLSD.
21 APR 26 02:18 UNTIL 03 SEP 26 15:59 ESTIMATED

VHHH / HKG

VHHHA1811/26 (07 AUG 26)

10 AUG 2026 18:01-10 AUG 2026 22:45
"THE FLW TWY CLSD DUE WIP:
TWY B BTN TWY S AND TWY V
TWY T ABM STAND D202, STAND D204 AND STAND D206"

VHHHA1810/26 (07 AUG 26)

10 AUG 2026 18:01-10 AUG 2026 23:30
THE FLW TWY CLSD DUE WIP:
TWY A10 NORTH OF TWY A
TWY F BTN TWY F6 AND TWY F7
TWY B12
TWY B BTN TWY V AND TXL B7
TWY W BTN TWY B AND TXL W1
TWY V1

*VHHHA1804/26 (07 AUG 26)

10 AUG 2026 18:00-10 AUG 2026 23:59
"DUE TO WIP, AIP SUP 27/25 IS SUSPENDED. RWY AVBL AS FLW:
AUG 10 1800-2259
NORTH RWY (RWY 07L/25R) AVBL
CENTRE RWY (RWY 07C/25C) CLSD FOR MAINT
SOUTH RWY (RWY 07R/25L) CLSD ON STBY
AUG 10 2300-2359
NORTH RWY (RWY 07L/25R) AVBL
CENTRE RWY (RWY 07C/25C) CLSD FOR MAINT
SOUTH RWY (RWY 07R/25L) AVBL"

*VHHHA1803/26 (07 AUG 26)

10 AUG 2026 08:00-14 AUG 2026 14:00
DAILY 0800-1400
CENTRE RWY (RWY07C/RWY25C) CLSD ON STANDBY DUE WIP

VHHHA1802/26 (07 AUG 26)

10 AUG 2026 08:00-14 AUG 2026 14:00
DAILY 0800-1400
THE FLW TWY CLSD DUE WIP:
TWY F BTN TWY E2 AND TWY D

VHHHA1779/26 (05 AUG 26)

10 13 0200-0700
SIU MO TO DVOR/DME 'SMT' 114.80 MHZ/CH95X NOT AVBL DUE MAINT.

VHHHA1716/26 (31 JUL 26)

TWY D BTN TXL D10 AND TWY E CLSD DUE WIP

VHHHA1514/26 (13 JUL 26)

10 JUL 2026 07:47-10 AUG 2026 23:59
"REF AIP AMDT 7/26, RNAV1(DME/DME/IRU) CONTINGENCY PROCEDURE TAKES
EFFECT FROM 9 JULY 2026. RNAV TRANSITION FOR ILS RWY25R AVBL FOR
BOTH RNP1 AND RNAV1(DME/DME/IRU) CAPABLE ACFT. THIS NOTAM SUPPLEMENT
THE INFORMATION ON AIC 30/24 PARA.3.1"
10 JUL 26 07:47 UNTIL 10 AUG 26 23:59 ESTIMATED

// (COM-INFO)//

THA 00281/17 (17 MAY 26)

VHHH:--REF AIP SUP 27/25:
1 Introduction
1.1 This AIP SUP promulgates the runway closure programme and associated closure period.

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 40/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

2 Runway Closure Programme

2.1 RWY 07L/25R (North Runway) will be closed for 5 nights per week, either on Standby or Maintenance.

2.2 RWY 07C/25C (Centre Runway) will be closed for 2 nights per week, on Maintenance only.

2.3 RWY 07R/25L (South Runway) will be closed for 7 nights per week, either on Standby or Maintenance

-Runway RWY 07L/25R(North Runway)

Closure Mode Standby:

Closure Period (UTC) 1800-2259

Days of Closure (UTC)

Every Monday, Wednesday and Saturday

Closure Mode Maintenance:

Closure Period (UTC) 1800-2359

Days of Closure (UTC)

Every Tuesday and Thursday

-Runway RWY 07C/25C(Centre Runway)

Closure Mode Maintenance:

Closure Period (UTC) 1800-2359

Days of Closure (UTC)

Every Sunday and Friday

-Runway RWY 07R/25L(South Runway)

Closure Mode Standby:

Closure Period (UTC) 1800-2259

Days of Closure (UTC)

Every Sunday, Tuesday, Thursday and Friday

Closure Mode Maintenance:

Closure Period (UTC) 1800-2359

Days of Closure (UTC)

Every Monday, Wednesday and Saturday

3 Runway Availability During Closure Periods

3.1 In the event that the operational runway becomes unavailable, the closed runway on Standby will be available within

20 minutes. Dependent on the work being carried out at the time, it may take up to 2 hours for a closed runway on

Maintenance to return to services.

4 Revisions to Runway Closure Programme

4.1 The runway closure schedule may be revised in the event of forecast or actual adverse weather conditions or other extenuating circumstances.

4.2 Any revision to the runway closure programme will be promulgated by NOTAM.

// (COM-INFO)//

THA 00072/26 (17 MAY 26)

VHHH:+++ (NEW) --Effective from 23 Mar 26 until further notice, applicable to all Airbus* aircraft types as follows:

Please modify altitude constraint at waypoint VH515 from "At or above 4 300 ft" to "At 4 500 ft" to reduce the probability of missed altitude constraints along the ILS approach to runway 25R.

This modification will create a pseudo continuous descent path starting at VH515 and will reduce the number of vertical transitions.
(ISSUED 23MAR26/BKKDP/UFN)

VMMC / MFM

VMMCA0272/26 (09 AUG 26)

10 AUG 2026 16:00-14 AUG 2026 23:59

MON WED FRI 1600-2359

TWY C1 CLOSED DUE TO WIP. SINGLE TWY OPERATION IMPLEMENTED. ALL ARRIVING AND DEPARTING AIRCRAFT WILL PROCEED TO/FROM APRON VIA TWY H.

VMMCA0271/26 (09 AUG 26)

10 AUG 2026 16:00-14 AUG 2026 23:59

MON WED FRI 1600-2359

ILS CAT II RWY 34 NOT AVAILABLE DUE TO WIP.

Official Pilot Briefing

THA677 10AUG26 HSTTA B773E RJAA 0825 VTBS 1455

Page 41/42
Trans ID: 5097641
Creation Time: 09.08.2026 23:09UTC

VMMCA0257/26 (31 JUL 26)

"REFERRING TO AIP GEN 3.6.1, TABLE 3.6.3, AND AD 2.6,
3 BOATS USED FOR RESCUE AND FIRE FIGHTING IN THE VICINITY OF
AIRPORT ARE AVAILABLE, EACH BOAT EQUIPPED WITH 2 LIFE RAFTS
WITH A CAPACITY OF 38 PERSONS PER EACH RAFT.
SAR VESSELS OF MARINE AND WATER BUREAU AVAILABLE AT 2212.25N
11332.24E WITH 1 LIFE RAFT FOR 15 PERSONS. AT 2212.55N 11332.41E,
ONE BOAT WITH CAPACITY 43 PERSONS PLUS 4 LIFE RAFTS FOR 50 PERSONS
PER EACH RAFT AND ONE BOAT WITH 4 LIFE RAFTS FOR 100 PERSONS PER
EACH RAFT."

31 JUL 26 12:59 UNTIL 31 AUG 26 23:59 ESTIMATED

*VMMCA0256/26 (27 JUL 26)

TUE THU SUN 2000-2200
RWY 16/34 CLOSED DUE TO MAINTENANCE.

VMMCA0255/26 (27 JUL 26)

"ADVANCED-VISUAL DOCKING GUIDANCE SYSTEM (AVDGS) ON AIRCRAFT STAND
A6 IS NOT AVAILABLE, MARSHALLING SERVICE WILL BE PROVIDED."

VMMCA0245/26 (23 JUL 26)

"UNLESS SPECIFIED BY MACAU ATC, IN CASE OF RWY34 MISSED APPROACH,
ALL TRAFFIC SHALL INITIALLY CLIMB TO 4000FT AND MAINTAIN. EXPECT
FURTHER CLIMB BY ZHUHAI ATC."

VVDN / DAD

VVVVA2652/26 (01 AUG 26)

DOPPLER WX RADAR SYSTEM (METEOR 60DX10-S) U/S FOR REPAIR
RMK: LOW-LEVEL WS ALERT SYSTEM (LLWAS) NML OPS.
01 AUG 26 12:39 UNTIL 31 OCT 26 23:59 ESTIMATED

VVVVA2511/26 (24 JUL 26)

"ESTABLISHMENT OF TWY E OPR PROCEDURES DURING ACFT TKOF/LDG
ON RWY 17L/35R:
- IN CASE OF ACFT CODE D/E TKOF/LDG ON RWY 17L/35R, ACFT UP
TO CODE C ARE PERMITTED TO USE TWY E
- IN CASE OF ACFT CODE C TKOF/LDG ON RWY 17L/35R, ACFT UP TO
CODE E ARE PERMITTED TO USE TWY E
REF AIP VIET NAM, ITEM VVDN AD 2.23-8."

VVVVA2510/26 (24 JUL 26)

"ADDN OF GP HOLD POSITIONS:
- POSITIONS:
+ GP HOLD 1: ON TWY E (654M FM CL OF TWY E2 TO THE SOUTH,
176M FM CL OF TWY E1 TO THE NORTH)
+ GP HOLD 2: ON TWY E (72M FM CL OF TWY E1 TO THE SOUTH)
- OPS PROC:
+ GP HOLD 1: USED FOR ACFT UP TO CODE E
+ GP HOLD 2: USED FOR ACFT UP TO CODE C
REF AIP VIET NAM, ITEM VVDN AD 2.9."

VVVVA2335/26 (10 JUL 26)

CLEANING ON RWY 35L/17R WHEN THERE ARE NO FLT OPS OR DRG
INTERMITTENT TIME BTN FLTS.

VVVVA1937/26 (17 JUN 26)

"REF AIP SUP 12/26 WEF 04 MAR 2026,
FREE OF CHARGE FOLLOW-ME CAR IS PROVIDED TO GUIDE ACFT TAX
IN/OUT STANDS WI CONST AREA DURING CONST PERIOD."

VVVVA1328/22 (17 OCT 23)

THE ADJUSTMENT OF STOP LINE OF ACFT FOR STANDS 1-9 AS FLW:
114.7 M FM TAXILANE D TO THE EAST.

VVVVA1209/22 (17 OCT 23)

"VISUAL DOCKING GUIDANCE SYSTEM (VDGS) IS SAFEDOCK TYPE T1
(T-TYPES),
AVBL AT ACFT STANDS 21, 23, 25
- REF AIP VIET NAM ITEM VVDN AD 2.9 PAGE AD 2.VVDN-7 DATED 30 JUL
2021."

VVNB / HAN

*VVVVA2707/26 (06 AUG 26)

10 AUG 2026 19:00-11 AUG 2026 23:00
DAILY 1900-2300
RWY 11L/29R NOT AVBL FOR TKOF AND LDG DUE TO MAINT
RMK: THE WORKING AREA WILL BE STOPPED WHEN THERE ARE VIP FLT
OPS OR VIS LESS THAN 2000M.

VVVVA2697/26 (05 AUG 26)

"WIP ON AREA, DETAILS AS FLW:
- THE WESTERN: 44.5M FM CL OF TWY V9
- THE NORTHERN: 80.48M FM CL OF TWY S
RMK: THE WORKING AREA WILL BE STOPPED WHEN THERE ARE MIL FLT,
VIP FLT OPS OR VIS LESS THAN 2000M."

VVVVA2696/26 (05 AUG 26)

"WIP ON AREA DRG INTERMITTENT TIME BTN FLTS, DETAILS AS FLW:
- THE WESTERN: ADJACENT TO THE EDGE OF APN 2, 29.5M FM CL OF
TWY V9
- THE NORTHERN: 80.48M FM CL OF TWY S
RMKS:
- ALL WORKMEN AND EQPT MUST VACATE THE WORKSITE WI 10 MIN
WHEN A CODE E WIDE-BODY ACFT
OR A LARGER EQUIVALENT IS TAXIING VIA TWY V9, TAXILANES
W13/W14
- THE WORKING AREA WILL BE STOPPED WHEN THERE ARE MIL FLT,
VIP FLT OPS OR VIS LESS THAN 2000M."

VVVVA2461/26 (20 JUL 26)

"WIP ON MIL APN (FM STANDS QS1A TO QS11) DRG
INTERMITTENT TIME BTN FLIGHTS
RMK: THE WORKING AREA WILL BE STOPPED WHEN THERE ARE VIP FLT
OPS, VIS LESS THAN 2000M OR BAD WX CONDITIONS."

VVVVA2462/26 (20 JUL 26)

"WIP ON TAXIWAYS N, N1, N2, N3, N4, N5 DRG
INTERMITTENT TIME BTN FLIGHTS
RMK: THE WORKING AREA WILL BE STOPPED WHEN THERE ARE VIP FLT
OPS, VIS LESS THAN 2000M OR BAD WX CONDITIONS."

VVVVA2425/26 (16 JUL 26)

"WIP ON AREAS, DETAILS AS FLW:
- AREA 1:
+ THE NORTHERN: 265M FM CL OF TWY V, 33.5M FM CL OF TXL
INTO STAND 52, 27M FM CL OF TXL INTO STAND 55A
+ THE WESTERN: 62M FM EXTENDED CL OF TXL W5
+ THE EASTERN: 33M FM EXTENDED CL OF TXL W7
- AREA 2:
+ THE NORTHERN: 248M FM CL OF TWY V, 54M FM THE SAFETY
LIMIT LINE AT STAND 74
+ THE WESTERN: ADJ TO VAECO FENCE."

THA677 10AUG26/0825 RJAA/VTBS
N I L