

Official Pilot Briefing

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Page 1/21
Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

GENERAL INFORMATION

// (COM-INFO) //

THA 00002/13 (21 AUG 26)

COM INFO:+++ (NEW)--A320/A321neo/A330/A350 fleet:

Do not use loadsheet application in Flysmart+.
To calculate stab setting, use data in loadsheet from ground staff.
Effective date: 21AUG26
End date: Until further notice
(ISSUED 21AUG/26/BKKPC/UFN)

--All A350 and BOEING 787:
are now eligible and included in EUROCONTROL airspace CPDLC Logon list.
Action Required: Pilots are required to initiate CPDLC logon when entering European airspace.
(ISSUED 23MAR26/BKKPC2/UFN)

--IN CASE CANNOT BE CONTACTED BKKOC VIA TELEPHONE,
PILOTS MAY CONTACT VIA MS TEAMS CHANNEL: "OC.CENTER".
(ISSUED 30JUL24/BKKOC/UFN)

-- To improve CTOT for all flights both outbound from BKK and
inbound to BKK, pilots may contact TOCC when ready for departure to request an earlier CTOT
through any of the following channels:
: MS Teams chat
: LINE CLC-Pilot
: CUT 129.325
: Phone 02-137-1202

In addition to above contact channels, for DOMESTIC flight, pilots may also directly contact
ground staff to request earlier CTOT. (ISSUED 15FEB25/BKKOP/UFN)

--DELEGATED FUNCTIONS PHONE DIRECTORY (Direct Number)
1. OPEN BOARDING GATE : 02-137-1260
2. BUS GATE - REMOTE BAY & DOMESTIC V.V. : 02-137-1260
3. CREW BUS OPC-TERMINAL V.V. : 02-137-1019, 02-137-1020
4. CONFIRM BOARDING GATE/BAY/BELT : 02-137-1263
5. ZFW/WEIGHT & BALANCE/LOAD SHEET : 02-137-1291, 02-137-1292
6. TG LOST & FOUND : 02-134-5454
7. OTHER INQUIRIES/BKKOC : 02-137-1202
(ISSUED 17JUL22/BKKOC-INFO/UFN)

--If expected divert due to weather or traffic congestion at any TG destination airports,
please kindly advise TOCC, via ACARS using OPERATIONS prompt or SITA address BKKOPTG,
the current fuel on board immediately to keep close monitoring of the flight.
(ISSUED 08MAY25/BKKOP/UFN)

--In case of pilot receives information from ground staff to delay departure due to connecting
passenger, please kindly confirm with TOCC via CUT channel.
(ISSUED 27NOV24/BKKOP/UFN)

--FOR FLIGHTS PLANNED NAVIGATING THROUGH KABUL FIR,
ONCE FINAL FL TO ENTER KABUL FIR IS AVAILABLE,
PLEASE ACARS DOWNLINK ETO/ENTRY WPT/FL TO BKKOPTG
(ISSUED 12DEC24/BKKOC/UFN)

--Please kindly consider and issue recommendation for route P500 G500 as soon as possible in
order to reduce operational risk.
1. Due to limitation of passenger oxygen chemical type (22 minutes).
If weather deviation is required, pilots shall deviate west of route only.

2. In an event of critical in-flight emergency, the aircraft should follow ICAO emergency
descent procedures, broadcast status and intentions on 125.2 MHZ and 121.5 MHZ. Thereafter,
proceed at the discretion of the PIC until clear Kabul FIR and in contact with the ATC
responsible for the airspace.
(ISSUED 31JUL24/D1/OC/UFN)

--Any flight operation by TG into the uncontrolled airspace and conflict zone,
the latest operational information "Closures and Warnings" issued by means of ICAO State
letters,
NOTAMs, AICs/AIPs, and EASA CZIB - TG are subject to strictly following the
guidance/directions
from their national authority as well as their own risk assessment.
(ISSUED 15APR24 CORR/TN003/22/OW/UFN)

--WEF 01AUG26,
SUBJ: SPECIAL SECURITY ARRANGEMENT:SSA008/2026
ATTN ALL CONCERNED

Official Pilot Briefing

Page 2/21

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

THE AVIATION SECURITY COMMITTEE (ASC) MTG ON 23JUL2026
AGREED TO ANNOUNCE SSA008/2026 AS FLWS:

- AA PLS BE INFM THT THIS SSA WILL SUPERSEDE SSA007/2026
FROM 01AUG2026 UNTIL FURTHER TLX ADV
- BB FR FLT DEP FRM STATION EUROPE: ARN AMS BRU CDG CPH FRA IST
LHR MUC MXP OSL ZRH

LEVEL: LOW CMA PERFORM SSA ACCORDING TO EU REQUIREMENTS
AS FLWS:
A1 - A/C PRE-FLIGHT SECURITY SEARCH CONDUCTED BY PIC CMA
CABIN CREW CMA ASM/SMT/DELEGATED PERSONNEL N GROUND/
STATION ENGINEER
A18-1 5% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
CONDUCTED BY CABIN CREW
- CC FR FLT DEP FRM STATION: DAC ISB KHI LHE RGN

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW
- DD FR DOM FLT DEP FRM STATION: HDY

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW
- EE FR FLT DEP FRM MAINBASE STATION: BKK

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW
F2 - IDENTITY CHECK OF CREW MEMBERS BEFORE BOARDING AT
BOARDING GATE
P2 - SECONDARY CHECK AT GATE
(APPLY ONLY FLT FRM BKK TO MEL PER N SYD)
- FF THE FLWG SSA SHALL BE IMPLEMENTED FR ALL ROUTE AS NORMAL PROC
P5 - INTENSIVELY PERFORM IDENTITY CHECK N VERIFICATION OF PAX
BEFORE BOARDING A/C BY
- COMPARING PAX WZ PHOTOGRAPH N PASSPORT/TVL DOCS TO
ENSURE PAX IS BONA FIDE N
- VERIFYING THE NAMES IN THE TICKETS CORRESPOND TO THOSE
ON THE IDENTITY DOCS
V1 - ALERT STAFF TO OBSERVE UNUSUAL BEHAVIOR OF PAX N ALL
PERSONNEL INVOLVED N ANY SUSPICIOUS ITEM IN THE
OPERATING AREA
- GG THOSE STN NOT ON THE LIST ABOVE ARE LOW LEVEL STP
APPLY NORMAL SECURITY PROC AS MENTIONED IN OPERATION MANUAL

ADDITIONAL INSTRUCTION.

- FR FLT OPS TO BLR MAA N CCU PLS IMPLEMENT THE FLW MEASURES AT THE
CHK-IN COUNTERS;
1. PROV DEDICATED CHK-IN COUNTERS FR FLT TO BLR MAA N CCU
 2. DISPLAY WARNING N INFO SIGNAGE AT:
-CHK-IN COUNTERS
-B/D GATE
-FLT INFO DISPLAY SYSTEM (FIDS) AT CHK-IN COUNTERS
 3. CONDUCT RANDOM X-RAY SCREENING OF SUSPICIOUS BAG AT CHK-IN
COUNTERS
 4. CONDUCT RANDOM SCREENING BY USING SNIFFER DOGS IN THE CHK-IN AREA.

IN CASE OF THREAT SITU N EXTRA MEASURES ARE REQ CMA
STN MONITORING TEAM/SMT MAY RAISE UP MEASURES AS APPROPRIATE

ANY SECURITY INCIDENTS MAY OCCUR SHALL INFO MANAGEMENT CONCERNED
N BKKD1 ACCLY STP

REMARK

A18-1 5% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
WILL BE REVISED IN SPM NEXT REVISION

PLS ACK N CFM ACTUAL PERFORM TO OFC BKKD1-B
BRGDS/CAPT. CHINGCHEEP B./BKKD1 ASC CHAIRMAN

Official Pilot Briefing

Page 3/21

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

Company Fuel Guidelines

THA 00228/26 (17 AUG 26)

COM INFO:--WEF 14AUG26,

Company Fuel Guidelines:

1) Flight Outbound from VTBS:

1.1) 15 mins:

-TG319

-ETA within TEMPO ± 1 hr with adverse weather condition

1.2) 5 mins:

-BLR (ONLY WHEN SINGLE RWY OPS)

-TG317, TG407, TG409

2) Flight Inbound to VTBS:

2.1) 20 mins:

ETA within TEMPO ± 2 hrs with adverse weather condition

2.2) 5 mins:

ETA 1400-1600 and 1730-2130* (BKK local time)

3) European Flights:

3.1) *All Outbound flight to European: CF 3 PERCENT*

3.2) Inbound flight to VTBS: RCFP + 05MINS*

4) Flight Level Plan for VTUK,

-Outbound from VTBS: FL250

-Inbound to VTBS: FL240

5) Planning for Arrival WADD:

To improve flight planning accuracy, for WADD arrivals, after waypoint KOLTA, flights shall plan to DOBMA and then follow DOBMA## STAR.

6) TG649: Flight level shall not be planned above FL380.

7) TG900: When ETA falls within TEMPO ± 2 hrs and adverse weather conditions, LTAC shall be designated as the destination alternate.

8) Destination VTUD:

Remove altitude restrictions and use the optimum altitude for planning.

Remark:

1) Pilot Management Department (PA)

1.1) Destinations ZBAA and ZSPD:

Flights shall be planned as Economic Tankage without company fuel, with the following conditions:

-Widebody aircraft shall be planned with far alternates (RKSI, RJFF).

-Narrowbody aircraft shall be planned with ZBTJ as the alternate; however, ZFW shall be restricted to ensure the carriage of at least 30 minutes of extra fuel.

1.2) Destination YPPH: ALTN YGEL

(*THE 05MINS OF EXTRA FUEL IS REMOVED*)

YGEL shall be used as ALTN airport effective 25 Apr 2026 following revision of OM-A section 8.3.26 (Operations at Uncontrolled Aerodromes)

2) Everything else regarding fuel planning policy remains the same as last month.

3) Adverse weather conditions*:

RA, TS or TSRA and visibility 5000M or less

(ISSUED 10AUG26/EMAIL Summary of Fuel Initiatives Meeting - AUG26
For Fuel Committee member/BKKPC)

Minima for flight planning

THA 00136/26 (29 MAY 26)

COM INFO: Application of planning minima for flight planning

Due to limited space in the OFP fuel planning box, any display of "BASIC FUEL SCHEME" shall be interpreted as "BASIC FUEL SCHEME WITH VARIATION."

Official Pilot Briefing

Page 4/21

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

All THAI flights are planned using Basic Fuel Scheme with Variation, unless otherwise specified by Flight Dispatcher.

Alternate planning minima shall be applied in accordance with OMA 8.1.7.5.2.
Display format will be reviewed and updated following stakeholder discussion.

FLIGHT LEG INFORMATION

VTBSVHHH

## AIC NR 06/26 ##	THA 00099/26 (16 MAY 26)
// (SEE ATTCH) //	
## AIC NR 01/26 ##	THA 00065/26 (16 MAY 26)
// (SEE ATTCH) //	
## AIP SUP 27/25 ##	THA 00143/25 (10 JUL 26)
// (SEE ATTCH) //	
## AIP SUP 26/25 ##	THA 00366/25 (10 JUL 26)
// (SEE ATTCH) //	

VHHHVTBS

## AIC NR 06/26 ##	THA 00099/26 (16 MAY 26)
// (SEE ATTCH) //	
## AIC NR 01/26 ##	THA 00065/26 (16 MAY 26)
// (SEE ATTCH) //	
## AIP SUP 27/25 ##	THA 00143/25 (10 JUL 26)
// (SEE ATTCH) //	
## AIP SUP 26/25 ##	THA 00366/25 (10 JUL 26)
// (SEE ATTCH) //	

AERODROME INFORMATION

VTBS / BKK

	VTBDC4857/26 (25 AUG 26)
26 AUG 2026 02:00-26 AUG 2026 09:00 ACFT STAND NR D5 AND D6 CLSD DUE TO WIP	
	VTBDC4845/26 (24 AUG 26)
25 AUG 2026 17:00-26 AUG 2026 23:30 DAILY 1700-2330 TWY CLSD DUE TO WIP DETAIL AS FLW: -TWY F -TWY F1 TO TWY F12 -TWY F15 -TWY W -TWY Y -TWY Z	
	*VTBDC4842/26 (24 AUG 26)
26 AUG 2026 20:30-29 AUG 2026 21:45 26 29 2030-2145 RWY 01/19 CLSD DUE TO WIP	
	*VTBDC4841/26 (24 AUG 26)
25 AUG 2026 17:00-26 AUG 2026 23:30 DAILY 1700-2330 RWY 02L/20R CLSD DUE TO WIP	
	*VTBDC4824/26 (24 AUG 26)
AUG 24 27 1900-2330 RWY 01/19 CLSD DUE TO WIP	

VTBDC4779/26 (22 AUG 26)

ADVANCED VISUAL DOCKING GUIDANCE SYSTEM (A-VDGS)
ACFT STAND NR 512 U/S DUE TO MAINT
RMK: ACFT HAVE TO FLW MARSHALLING SIGNALS STRICTLY

THA 00064/25 (09 AUG 26)

// (COM-INFO)//

VTBS:--REF AIP SUP A53/25:
RETIls U/S:
RWY 01/19: TWYs B3, B5, B7, B8, B10 and B11
RWY 02R/20L: TWYs E5, E7, E9, E12, E13, E15.

--REF AIP SUP A13/25:
1) The Visual Docking Guidance System (VDGS) at the ACFT stands 101 - 114 are U/S. (14 ACFT stands).
2) Airlines or Ground service providers shall provide a License Mechanic performed as Marshaller to guide the aircraft from taxilane to the parking position.
3) The ACFT are strongly advised to strictly follow the Marshaller's signal.

--REF AIP SUP A54/24:
DVOR/DME (SVB) (133932.5N 1004353.2E) (111.4 MHZ, CH51X) temporary suspended from 28 November 2024 at 0001 UTC to 02 October 2026 at 0949 UTC.

--REF AIP SUP A01/25:
Taxiway C between Taxilane T1 and Taxilane T2, Taxiway C1 closed.

OB Company Safety NOTAM-BKK## THA 00161/26 (09 AUG 26)

// (SEE ATTCH)//

VTBDC4473/26 (07 AUG 26)

ADVANCED VISUAL DOCKING GUIDANCE SYSTEM (A-VDGS)
ACFT STAND NR 119 505 AND 520 U/S DUE TO MAINT
RMK: ACFT HAVE TO FLW MARSHALLING SIGNALS STRICTLY

VTBDC4316/26 (05 AUG 26)

TWY CLSD DUE TO WIP DETAIL AS FLW:
-TWY E BTN TWY D1 AND TWY D2
-TWY D1
-TWY D BEHIND ACFT STAND NR 516-525

VTBDC4026/26 (20 JUL 26)

ADVANCED VISUAL DOCKING GUIDANCE SYSTEM (A-VDGS)
ACFT STAND NR 501 U/S DUE TO MAINT
RMK: ACFT HAVE TO FLW MARSHALLING SIGNALS STRICTLY

VHHH / HKG

VHHHA1962/26 (24 AUG 26)

26 AUG 2026 18:01-26 AUG 2026 20:00
TWY K BTN TWY Q2 AND TWY K4 CLSD DUE WIP

VHHHA1961/26 (24 AUG 26)

26 AUG 2026 17:00-26 AUG 2026 22:45
THE FLW TWY AND TXL CLSD DUE WIP
TWY Y BTN TWY Z3 AND TWY E
TWY D BTN TWY D8 AND TWY E
TWY E BTN TXL E4 AND TWY F6
TXL H8 ABM STAND S107

VHHHA1963/26 (24 AUG 26)

26 AUG 2026 18:01-26 AUG 2026 23:30
TWY K6 NORTH OF TWY K CLSD DUE WIP

VHHHA1943/26 (21 AUG 26)

TWY C BTN TWY D8 AND TWY E CLSD DUE WIP

*VHHHA1938/26 (21 AUG 26)

DAILY 0800-1400
CENTRE RWY (RMY 07C/25C) CLSD ON STBY DUE WIP

VHHHA1937/26 (21 AUG 26)

DAILY 0800-1400

Official Pilot Briefing

Page 6/21

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

TWY F BTN TWY E2 AND TWY D CLSD DUE WIP

VHHHA1868/26 (14 AUG 26)

TWY E BTN TWY F5 AND TWY F6 DOWNGRADED TO CODE E DUE WIP

VHHHA1851/26 (10 AUG 26)

"REF AIP HK GEN 3.3 PARA 1.1 AND GEN 3.4 PARA 1.1, TEL NR OF ASSISTANT DIRECTOR-GENERAL OF CIVIL AVIATION (AIR TRAFFIC MANAGEMENT) CHANGED TO 2910 6988."

VHHHA1847/26 (10 AUG 26)

"REF AIP AMDT 7/26, RNAV1(DME/DME/IRU) CONTINGENCY PROCEDURE TAKES EFFECT FROM 9 JULY 2026. RNAV TRANSITION FOR ILS RWY25R AVBL FOR BOTH RNP1 AND RNAV1(DME/DME/IRU) CAPABLE ACFT. THIS NOTAM SUPPLEMENT THE INFORMATION ON AIC 30/24 PARA.3.1"
10 AUG 26 03:57 UNTIL 09 SEP 26 23:59 ESTIMATED

// (COM-INFO)//

THA 00281/17 (17 MAY 26)

VHHH:--REF AIP SUP 27/25:

1 Introduction

1.1 This AIP SUP promulgates the runway closure programme and associated closure period.

2 Runway Closure Programme

2.1 RWY 07L/25R (North Runway) will be closed for 5 nights per week, either on Standby or Maintenance.

2.2 RWY 07C/25C (Centre Runway) will be closed for 2 nights per week, on Maintenance only.

2.3 RWY 07R/25L (South Runway) will be closed for 7 nights per week, either on Standby or Maintenance

-Runway RWY 07L/25R(North Runway)

Closure Mode Standby:

Closure Period (UTC) 1800-2259

Days of Closure (UTC)

Every Monday, Wednesday and Saturday

Closure Mode Maintenance:

Closure Period (UTC) 1800-2359

Days of Closure (UTC)

Every Tuesday and Thursday

-Runway RWY 07C/25C(Centre Runway)

Closure Mode Maintenance:

Closure Period (UTC) 1800-2359

Days of Closure (UTC)

Every Sunday and Friday

-Runway RWY 07R/25L(South Runway)

Closure Mode Standby:

Closure Period (UTC) 1800-2259

Days of Closure (UTC)

Every Sunday, Tuesday, Thursday and Friday

Closure Mode Maintenance:

Closure Period (UTC) 1800-2359

Days of Closure (UTC)

Every Monday, Wednesday and Saturday

3 Runway Availability During Closure Periods

3.1 In the event that the operational runway becomes unavailable, the closed runway on Standby will be available within 20 minutes. Dependent on the work being carried out at the time, it may take up to 2 hours for a closed runway on

Maintenance to return to services.

4 Revisions to Runway Closure Programme

4.1 The runway closure schedule may be revised in the event of forecast or actual adverse weather conditions or other extenuating circumstances.

4.2 Any revision to the runway closure programme will be promulgated by NOTAM.

Official Pilot Briefing

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Page 7/21
Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

// (COM-INFO)//

THA 00072/26 (17 MAY 26)

VHHH:+++ (NEW) --Effective from 23 Mar 26 until further notice,
applicable to all Airbus* aircraft types as follows:

Please modify altitude constraint at waypoint VH515 from "At or above 4 300 ft" to "At 4 500 ft" to reduce the probability of missed altitude constraints along the ILS approach to runway 25R.

This modification will create a pseudo continuous descent path
starting at VH515 and will reduce the number of vertical transitions.
(ISSUED 23MAR26/BKKDP/UFN)

VMMC / MFM

VMMCA0295/26 (23 AUG 26)

MON WED FRI 1600-2359
TWY C1 CLOSED DUE TO WIP. SINGLE TWY OPERATION IMPLEMENTED. ALL
ARRIVING AND DEPARTING AIRCRAFT WILL PROCEED TO/FROM APRON VIA TWY H.

VMMCA0294/26 (23 AUG 26)

MON WED FRI 1600-2359
ILS CAT II RWY34 NOT AVAILABLE DUE TO WIP.

VMMCA0290/26 (21 AUG 26)

DAILY 1000-2200
"REFER TO HONG KONG NOTAM CONCERNING SPECIAL ACTIVITY AT SOUTH OF
MACAO ATZ, BOUNDED BY:
220826N 1135307E
215634N 1141115E
213104N 1133833E
214423N 1132132E
HELICOPTER ROUTES JULIET AND LIMA SUSPENDED."

VMMCA0289/26 (20 AUG 26)

"ADVANCED-VISUAL DOCKING GUIDANCE SYSTEM (AVDGS) ON AIRCRAFT STAND
A6 IS NOT AVAILABLE, MARSHALLING SERVICE WILL BE PROVIDED."

VMMCA0288/26 (20 AUG 26)

DAILY 1000-2200
"REFER TO HONG KONG NOTAM CONCERNING SPECIAL ACTIVITY AT SOUTH OF
MACAO ATZ, BOUNDED BY:
220826N 1135307E
215634N 1141115E
213104N 1133833E
214423N 1132132E
ALL RWY16 DEPARTURES SHALL CROSS PAPA/MC501/MCU RADIAL 164 DEGREE
DISTANCE 8.5NM AT 3000FT OR ABOVE. FOR RWY16 MISSED APCH, AIRCRAFT
SHALL CROSS MC513/MCU RADIAL 171 DEGREE DISTANCE 7.4NM/ZUH RADIAL
148 DEGREE DISTANCE 15.0NM/ZAO RADIAL 181 DEGREE DISTANCE 13.8NM AT
3000FT OR ABOVE."

VMMCA0281/26 (17 AUG 26)

"REFERRING TO AIP GEN 3.6.1, TABLE 3.6.3, AND AD 2.6, 3 BOATS USED
FOR RESCUE AND FIRE FIGHTING IN THE VICINITY OF AIRPORT ARE
AVAILABLE, EACH BOAT EQUIPPED WITH 2 LIFE RAFTS WITH A CAPACITY OF 38
PERSONS PER EACH RAFT.
SAR VESSELS OF MARINE AND WATER BUREAU AVAILABLE AT 2212.25N
11332.24E OR 2209.98N 11334.45E WITH 1 LIFE RAFT FOR 15 PERSONS.
AT 2212.55N 11332.41E, ONE BOAT WITH 1 LIFE RAFT FOR 15 PERSONS, TWO
BOATS WITH EACH CAPACITY 43 PERSONS PLUS EACH BOAT EQUIPPED WITH 4
LIFE RAFTS FOR 50 PERSONS PER EACH RAFT."
17 AUG 26 10:15 UNTIL 31 AUG 26 23:59 ESTIMATED

*VMMCA0256/26 (27 JUL 26)

TUE THU SUN 2000-2200
RWY 16/34 CLOSED DUE TO MAINTENANCE.

VMMCA0245/26 (23 JUL 26)

"UNLESS SPECIFIED BY MACAU ATC, IN CASE OF RWY34 MISSED APPROACH,
ALL TRAFFIC SHALL INITIALLY CLIMB TO 4000FT AND MAINTAIN. EXPECT
FURTHER CLIMB BY ZHUHAI ATC."

Official Pilot Briefing

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Page 8/21
Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

VTBU / UTP

VTBDJ6288/26 (21 AUG 26)

25 AUG 2026 08:00-26 AUG 2026 10:00
"25 0800-1200, 26 0230-1000"
ILS FLTCK WILL TAKE PLACE RADIUS 20NM
CENTRE 124047N1010018E
RMK: DEP/ARR ACFT WILL BE DLA DURING THIS PERIOD
F) GND
G) 3000FT AMSL

VTBDC4363/26 (03 AUG 26)

ILS RWY 18 U/S DUE TO MAINT

VTBDC4088/26 (20 JUL 26)

TWY EDGE LGT U/S DUE TO MAINT DETAIL AS FLW:
-TWY B
-TWY E BTN TWY B AND TWY F

// (COM-INFO)//

THA 00176/26 (15 JUL 26)

VTBU:--(NEW)+++Due to the unavailability of LAE at UTP Station.
In the event of a diversion to UTP, flight crews shall perform aircraft refueling in
accordance with the applicable refueling procedures specified in the respective Fleet FCOM.
(ISSUED 02JUL26/BKKOC/UFN)

*VTBDC3302/26 (03 JUL 26)

PALS CAT 1 RWY 18 AND SALS RWY 36 U/S DUE TO MAINT

VTBDC3240/26 (03 JUL 26)

OBST MOBILE CRANE HGT 98.425FT AGL ERECTED DETAIL AS FLW:
PSN 1: 123937.98N1010027.35E
DIST 346.47M BFR THR RWY 36 AND 455.00M RIGHT SIDE OF RCL
PSN 2: 124005.68N1010029.64E
DIST 507.53M BEYOND THR RWY 36 AND 454.95M RIGHT SIDE
OF RCL

VTBDC0333/23 (06 APR 24)

"IAC-ICAO-NDB RWY 36 CHANGED AS FLW:
-OCA/H : STRAIGHT-IN APPROACH
: READ 790(766)FT INSTEAD OF 750(726)FT
-OCA/H : CIRCLING APPROACH CAT A, B
: READ 1200(1141)FT INSTEAD OF 750(726)FT, 1190(1166)FT
-OCA/H : CIRCLING APPROACH CAT C, D
: READ 1450(1391)FT INSTEAD OF 1290(1266)FT, 1445(1421)FT
REF AIP VTBU AD 2.24, AD 2-VTBU-8-1"

ADDITIONAL INFORMATION

RCKH / KHH

RCTPA2897/26 (17 AUG 26)

TWY S BTN TWY B (INCLUDED) AND TWY C (EXCLUDED) CLSD DUE TO
WIP.

// (COM-INFO) //

THA 00220/26 (07 AUG 26)

RCKH:--AIP SUP 16/26:
-CONSTRUCTION WORK AT KAOHSIUNG INTL AIRPORT

1. This AIP SUP replaces AIP SUP 27/25 (Phase 2, Phase 8 and Phase 9 deleted).
2. To avoid jet blast hazard, pilots shall use minimum breakaway thrust/power setting near construction areas.
3. Airport operations are limited to aircraft with a wingspan up to but not including 65M (up to and including aerodrome reference code E).
4. Estimated construction period is through JUL 2027. The following construction phase will be activated by NOTAM.

-Phase 1 (during curfew 1601-2230 UTC)
1. RWY 09/27 closed.
2. All Taxiways closed.
3. The airport, under the above conditions,
is only available for emergency medical service helicopter TKOF/LDG at designated area.
4. The airport is not to be used for technical landing or not

Official Pilot Briefing

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Page 9/21
Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

to be requested as an alternate forflight planning

RCTPA2744/26 (10 AUG 26)

"TWY CENTER LINE LGT OF TWY B, TWY C, TWY D,
TWY E, TWY F, TWY G, TWY H AND TWY S U/S DUE TO WIP."
06 AUG 26 22:30 UNTIL 05 NOV 26 22:30 ESTIMATED

RCTPA2697/26 (10 AUG 26)

TWY H CLSD DUE TO WIP.

RCTPA2611/26 (10 AUG 26)

TWY G CLSD DUE TO WIP.

RCTPA2609/26 (10 AUG 26)

TWY B CLSD DUE TO WIP.

RCTPA2556/26 (10 AUG 26)

TWY F CLSD DUE TO WIP.

RCTPA2555/26 (10 AUG 26)

TWY D CLSD DUE TO WIP.

RCTPA2442/26 (10 AUG 26)

"REF AIRAC AIP AMDT 03/26 RCKH AD 2.13 DECLARED DISTANCES,
INTERSECTION TAKE-OFF OF RWY 27, CHANGE TWY F TO READ TWY G.
THIS NOTAM WILL BE INCORPORATED IN AIRAC AIP AMDT 04/26
WEF 01 OCT 2026."

*RCTPA2408/26 (10 AUG 26)

1601-2230

"REF AIP SUP 16/26 DATED 17 JUL 2026 AND NOTAM A2405/26, CONST
WORK AT KAOHSIUNG INTL AIRPORT, PHASE 1 (DURING CURFEW) ACT.
RWY 09/27 AND ALL TWY CLSD."

RCTPA2405/26 (10 AUG 26)

"AIP SUP 16/26, CONST WORK AT KAOHSIUNG INTL AIRPORT.
REPLACES AIP SUP 27/25.
THE DATE AND TIME OF CONST PHASE ACTIVATION WILL BE NOTIFIED BY
NOTAM."
17 JUL 26 02:35 UNTIL 31 JUL 27 23:59 ESTIMATED

// (COM-INFO)//

THA 00352/17 (10 JUN 26)

COM-INFO:--1) ATS HRS (2200-1600)
2) DUE TO NOISE ABATEMENT, TAKE OFF/LDG IS PROHIBITED
DURING THE PERIOD FM 1601-2230 UTC EXCEPT EMERGENCY.
(REF AIP TAIPEI AD 2-RCKH)

RCTP / TPE

RCTPA3042/26 (25 AUG 26)

PORTION OF TWY R BTN TWY R1 (INCLUDED) AND TWY R3 (EXCLUDED)
CLSD FOR ACFT PRKG.
25 AUG 26 01:33 UNTIL 24 NOV 26 08:00 ESTIMATED

*RCTPA3022/26 (24 AUG 26)

0400-0430

RWY 05R/23L CLSD DUE TO INSPECTION.

RCTPU2074/26 (20 AUG 26)

"UNMANNED ACFT WILL BE RELEASED:
1.CASE NR:AB260706002404
2.LCA:DAYUAN DISTRICT, TAOYUAN CITY
3.COOR TEL:0939-114657, 0919-502656
4.AREA AS FLW:
250330N 1211625E
250350N 1211542E
250355N 1211550E
250332N 1211637E
250330N 1211625E"
F) SFC
G) 600FT AMSL

Official Pilot Briefing

Page 10/21

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

RCTPU2073/26 (20 AUG 26)

"UNMANNED ACFT WILL BE RELEASED:
1.CASE NR:AB260706002403
2.LCA:DAYUAN DISTRICT, TAOYUAN CITY
3.COOR TEL:0939-114657, 0919-502656
4.AREA AS FLW:
250446N 1211529E
250513N 1211552E
250509N 1211600E
250444N 1211538E
250355N 1211550E
250350N 1211542E
250446N 1211529E"
F) SFC
G) 600FT AMSL

RCTPA2859/26 (14 AUG 26)

"PORTION OF TWY E BTN TWY P(EXCLUDED) AND TWY Q(EXCLUDED) ONLY
AVBL FOR ACFT WITH CODE LETTER A, B, C, D, E.
(REF ICAO ANNEX 14 AERODROMES, TABLE 1-1 AERODROME REFERENCE CODE)
RMK: ACFT TYPE B748 TOWING IS PERMITTED."
14 AUG 26 08:35 UNTIL 31 OCT 26 09:00 ESTIMATED

RCTPA2820/26 (14 AUG 26)

FLW TWY CLSD DUE TO WIP:
1.TWY Q4 BTN TWY Q(EXCLUDED) AND TWY S(EXCLUDED)
2.PORTION OF TWY R BTN TWY Q2(EXCLUDED) AND TWY Q4(EXCLUDED)

*RCTPA2812/26 (14 AUG 26)

0300-0330
RWY 05L/23R CLSD DUE TO INSPECTION.

RCTPA2798/26 (10 AUG 26)

"AUG 19 0030-0200, AUG 31 SEP 02 0935-1035"
"AIR EXER WILL TAKE PLACE:
1.LIAISON OFFICER AT TAIPEI APP,
TFC CONCERNED KEEP CLOSE CTC WITH TAIPEI APP.
2.TFC OF RCTP MAY BE DELAYED DUE TO AIR EXER.
3.THE AREA OVERLAPS VFR HEL RTE H2 AND VFR CORRIDOR C1,
ACFT ARE CTN ADZ.
4.OPR TEL: 03-4792111, 03-4802749,
0985-553770, 0963-809885
5.AREA AS FLW:
250116N 1211309E
245917N 1211412E
245609N 1211123E
245959N 1210944E
250116N 1211309E"
F) SFC
G) 600FT AMSL

// (COM-INFO) //

THA 00202/26 (03 AUG 26)

COM INFO:+++ (NEW) --TPE/RCTP:
TAKEOFF AND LANDING PERFORMANCE CALCULATION
SHALL BE BASED ON TEMPORARY RUNWAY WHEN OPERATING ON 05R.

Runway 05R
Validity Period: 01JUL2026 - 30SEP27

(REVISED 03AUG26/BKKPC/TILL 30SEP27)

RCTPA2638/26 (10 AUG 26)

"AIP SUP 19/26 WEF 03 AUG 2026 TIL 31 DEC 2027,
GROUND MANEUVERING RESTRICTIONS FOR AERODROME REFERENCE
CODE F AIRCRAFT AT TAIPEI/TAIWAN TAOYUAN INTERNATIONAL AIRPORT.
THIS AIP SUP REPLACES AIP SUP 14/22."

RCTPA2549/26 (10 AUG 26)

"BIRD CONCENTRATION DRG 2100-1100:
1.IN THE VCY OF THE AP, AND AT AP
IN THE APPROACH PATH OF RWY 23L,
HGT: 0-1500FT, BIRD WT: 370 GRAMS.
2.IN THE VCY OF THE AP AND AT AP
IN THE APPROACH PATH OF RWY 05L/23R AND RWY 05R/23L,

HGT: 0-300FT, BIRD WT: 750-1500 GRAMS.
3.IN THE NORTH OF RWY 05L/23R AND IN THE SOUTH OF RWY 05R/23L,
HGT: 0-300FT, BIRD WT: 87 GRAMS."

RCTPA2436/26 (10 AUG 26)

"PORTION OF TWY L BEHIND PRKG BAY 525 CLSD
FOR ACFT PRKG AND TOWING.
RMK: DEP ACFT IN PRKG BAY 524 PUSH BACK TO FACE EAST
UNTIL ABEAM PRKG BAY 520, THEN TAX."
19 JUL 26 13:41 UNTIL 16 OCT 26 08:00 ESTIMATED

RCTPA2166/26 (09 JUL 26)

0330-0400
"SCHEDULED CLOSURE OF RWY 05R/23L SUSPENDED.
REF AIP RCTP AD 2.20.1, ITEM 4."
30 JUN 26 03:30 UNTIL 27 SEP 26 04:00 ESTIMATED

RCTPA2164/26 (09 JUL 26)

0230-0300
"SCHEDULED CLOSURE OF RWY 05L/23R SUSPENDED.
REF AIP RCTP AD 2.20.1, ITEM 4."
30 JUN 26 02:30 UNTIL 27 SEP 26 03:00 ESTIMATED

RCTPA2908/25 (08 SEP 25)

"REF AIP SUP 14/22, GROUND MANEUVERING RESTRICTIONS FOR AD
REFERENCE
CODE F ACFT AT TAIPEI/TAIWAN TAOYUAN INTL AP, END DATE REVISED AS
31 AUG 2028, 1559UTC. THE REST NC."

VVNB / HAN

VVWA2869/26 (24 AUG 26)

DAILY 1800-2300
"WIP ON AREA DRG INTERMITTENT TIME BTN FLTS, DETAILS AS FLW:
- THE NORTHERN: 46M FM CL OF TWY S
- THE SOUTHERN: 45,5M FM CL OF TWY V
- THE EASTERN: 315M FM CL OF TWY V5
- THE WESTERN: 78M FM CL OF TWY V4
RMK: THE WORKING AREA WILL BE STOPPED WHEN THERE ARE VIP FLT
OPS OR BAD WX CONDITIONS."

VVWA2866/26 (24 AUG 26)

DAILY 0400-1000
"DUE TO ROCKET FRNG ACT, DO NOT USE THE PBN PROCEDURES
AS FLW:
- HLDG PATTERN: BIVIM (STAR RNAV RWY 11L/R: BIVIM 1A
TRANSITION, STAR RNAV RWY 29L/R: BIVIM 1B TRANSITION)
(SEE NOTAM VVVV A2849/26)."

*VVWA2839/26 (21 AUG 26)

25 AUG 2026 19:00-26 AUG 2026 23:00
DAILY 1900-2300
RWY 11L/29R NOT AVBL FOR TKOF AND LDG DUE TO MAINT
RMK: THE WORKING AREA WILL BE STOPPED WHEN THERE ARE VIP FLT
OPS OR VIS LESS THAN 2000M.

VVWA2697/26 (05 AUG 26)

"WIP ON AREA, DETAILS AS FLW:
- THE WESTERN: 44.5M FM CL OF TWY V9
- THE NORTHERN: 80.48M FM CL OF TWY S
RMK: THE WORKING AREA WILL BE STOPPED WHEN THERE ARE MIL FLT,
VIP FLT OPS OR VIS LESS THAN 2000M."

VVWA2696/26 (05 AUG 26)

"WIP ON AREA DRG INTERMITTENT TIME BTN FLTS, DETAILS AS FLW:
- THE WESTERN: ADJACENT TO THE EDGE OF APN 2, 29.5M FM CL OF
TWY V9
- THE NORTHERN: 80.48M FM CL OF TWY S
RMKS:
- ALL WORKMEN AND EQPT MUST VACATE THE WORKSITE WI 10 MIN
WHEN A CODE E WIDE-BODY ACFT
OR A LARGER EQUIVALENT IS TAXIING VIA TWY V9, TAXILANES
W13/W14
- THE WORKING AREA WILL BE STOPPED WHEN THERE ARE MIL FLT,

Official Pilot Briefing

Page 12/21

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

VIP FLT OPS OR VIS LESS THAN 2000M."

VTBD / DMK

*VTBDC4858/26 (25 AUG 26)

25 27 28 29 31 1600-2200
RWY 03L/21R CLSD DUE TO WIP

*VTBDC4735/26 (20 AUG 26)

"21 1500-1600, 23 26 30 1600-2200"
RWY 03R/21L CLSD DUE TO WIP

// (COM-INFO) //

THA 00435/14 (04 AUG 26)

COM INFO:-- DMK TG LINE MAINTENANCE WILL PROVIDE RAMP HANDLING SERVICE ON
TG FLIGHTS DIVERTED TO DMK, WHILE PIC MUST PERFORM REDUCE LINE CHECK
TO RELEASE AIRCRAFT. PRIOR TO FLIGHT DIVERSION TO DMK PLS INFORM
TOCC COMMAND CENTER (OC) VIA CUT FREQUENCY 129.325 MHZ
TO COORDINATE WITH DMK TG LINE MAINTENANCE IN ADVANCE FOR SMOOTH
HANDLING UPON ARRIVAL AT DMK
CONTACT POINTS FOR DMK LINE MAINTENANCE IN (24hrs)
AT DMK ARE AS FLW
1. TEL: 02-563-8178 (66-8178, 9999)
2. Email dmkjcb@thaiairways.com
(ISSUED 12DEC24/OP/UFN)

// (COM-INFO) //

THA 00214/26 (04 AUG 26)

VTBD:--REF AIP SUP A25/26:
1 INTRODUCTION
With effect from 24 July 2026 at 0000 UTC, the purpose of this AIP Supplement is to inform
pilots and operators concerning the unserviceability
of Rapid Exit Taxiway Indicator Lights (RETILs) of runway 21R at Don Mueang International
Airport.

2 DETAILS
RETILs for rapid exit taxiway 0 will be unserviceable.

3 CONTACT
Unit: Aeronautical Information Service Sub-Division, Airside Operations Division (VTBD)
Tel: +662 535 1782, +662 535 1793
Email: aisvtbd@airportthai.co.th

4 VALIDITY
This AIP Supplement supersedes NOTAM C3646/26, A2407/26 and will remain current until further
advised. Any changes to this AIP Supplement
will be notified through NOTAM.

VTBDJ5310/26 (04 AUG 26)

"TEMPO RESTRICTED AREA ACT RADIUS 0.5NM CENTRE
135526.22N1003713.11E APPROVAL SHALL BE MADE BEFORE ENTERING,
EXCEPT DEP AND ARR ACFT AT VTBD PILOT IN COMMAND SHALL STRICTLY
COMPLY WITH ATC INSTRUCTION"
F) GND
G) 3000FT AGL

VTUU / UBP

*VTBDC4867/26 (25 AUG 26)

"AD OPR HR ATS AND ARO HR SER CHANGED AS FLW:
AUG 25 1205-1430 2300-2359,
AUG 26-SEP 27 0000-1400 2300-2359,
SEP 28 0000-1400"

VTBDC4836/26 (24 AUG 26)

TEMPO PAPI RWY 05 INSTL ON LEFT SIDE AT DIST 342M FM DTHR

VTBDC4756/26 (21 AUG 26)

RWY 05/23 CLSD DIST 500M FM THR RWY 05 DUE TO WIP.
DECLARED DIST AS FLW:
RWY TORA(M) TODA(M) ASDA(M) LDA(M)
05 2500 2500 2560 2500
23 2500 2500 2500 2500
RMK: RWY 05 THE TORA WHEN ENTERING RWY FM TWY A IS 1950M AND
ASDA IS 2010M

Official Pilot Briefing

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Page 13/21
Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

// (COM-INFO) //

THA 00221/26 (11 AUG 26)

COM INFO:+++ (NEW) --UBP/VTUU:
TAKEOFF AND LANDING PERFORMANCE CALCULATION SHALL BE BASED ON TEMPORARY RUNWAY WHEN OPERATING
ON 05 and 23.

-Runway 05
Validity Period: 10AUG2026 - 09OCT2026

-Runway 23
Validity Period: 10AUG2026 - 09OCT2026

(ISSUE 11AUG26/BKKPC/TIL 09OCT26)

VTBDC4321/26 (31 JUL 26)

ROAD CONSTRUCTION FROM FIRE STATION TO RUNWAY 05/23
AT UBON RATCHATHANI AIRPORT. EXTD TO 31 OCT 2026 AT 1500UTC.
REF AIRAC AIP SUP B06/26

VTCC / CNX

VTBDC4738/26 (25 AUG 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS) ACFT STAND
NR 5 AND NR 6 U/S

VTBDJ6200/26 (25 AUG 26)

TEMPO RESTRICTED AREA ACT RADIUS 0.5NM CENTRE 184626N0985806E
(EXCLUDING LDG AND TKOF RWY 18/36)
F) GND
G) 3000FT AGL

// (COM-INFO) //

THA 00444/15 (09 AUG 26)

VTCC:--REF AIP SUP A19/25:
1 INTRODUCTION
With effect from 17 April 2025 at 1000 UTC,
the purpose of this AIP Supplement is to inform all concerned regarding the Aircraft stand
number 1 closed at Chiang Mai International Airport.
2 DETAILS
Aircraft stand number 1 closed for improvements to enhance aircraft parking compatibility.

VTBDC4059/26 (20 JUL 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS) ACFT STAND NR 3 U/S

VTBDC3965/26 (25 AUG 26)

OBST TOWER CRANE HGT 230FT AGL ERECTED AT
184725.38N0985815.11E DIST 1038M BFR THR
RWY 18 AND 854M LEFT SIDE OF EXTD RCL

VTBDC3956/26 (25 AUG 26)

"JUL 15 0210-1100, JUL 16-SEP 30 0100-1100"
OBST MOBILE CRANE HGT 82FT AGL ERECTED AT
184704.31N0985757.46E DIST 390M BFR THR
RWY 18 AND 328M LEFT SIDE OF EXTD RCL

VTBDC3306/26 (03 JUL 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS)
ACFT STAND NR 7 AND NR 8 U/S

ENROUTE INFORMATION

ASP / ASIA/PACIFIC

N I L

THA / THAILAND

N I L

VTBB / BANGKOK FIR

VTBDC4866/26 (25 AUG 26)

CDR Y5 (RNAV 2) AVBL FOR FLIGHT PLANNING AS FLW:
PERIOD : MEA LOWER/UPPER LIMITS
0000-0229 FL130/FL460

0230-0330 FL370/FL460
0331-2359 FL130/FL460

VTBDJ6270/26 (19 AUG 26)

20 25 27 0200-0500
GUN FRNG WILL TAKE PLACE WI AREA
124000N1005200E-124000N1005600E-123700N1005600E-
123700N1005800E-122000N1005800E-122000N1004800E-
123700N1004800E-124000N1005200E
(SATTAHIP DISTRICT CHON BURI PROVINCE AND GULF OF THAILAND)
RMK: ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR VECTORED
BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC
F) SFC
G) 15000FT AGL

// (COM-INFO)//

THA 00126/26 (10 AUG 26)

COM INFO:--REF AIP SUP A19/26;
1
INTRODUCTION
With effect from 14 May 2026 at 0001 UTC to 31 December 2026 at 0001 UTC, the purpose of this
AIRAC AIP Supplement is to inform all
concerned regarding Temporary suspension of SURAT THANI DVOR/DME (STN) due to relocation
details are as follows.
2
THE PERIOD OF TEMPORARY SUSPENSION
STN DVOR/DME will be temporarily suspension from 14 May 2026 at 0001 UTC to 31 December 2026
at 0001 UTC.
3
FLIGHT PROCEDURE
A temporary reporting point name SAPUD (090746.24N 0990805.09E) will be established at the
same coordinates of SURAT THANI DVOR/
DME (STN) for ATS routes G458, W17, W24, W28, W32 and Y8 and a portion of ATS route G458
between STN and MENEX will be suspended
until STN normal operations resume.
4
FLIGHT PLANNING PROCEDURES
Reference to the AIP-THAILAND part ENR 1.10 item 4.1.1.1, 4.1.1.2 a, 4.1.1.2 b, 4.1.1.3 a,
4.1.1.3 b non-RNAV2 approved aircraft. To maintain
efficiency of ATS during SURAT THANI DVOR/DME (STN) relocation, non-RNAV approved aircraft
that intend to operate on G458 between
SAPUD and MENEX shall file flight plan, depending on ACFT capability.
5
CONTACT
Unit: Air Traffic Navigation Systems Engineering Department, Aeronautical Radio of Thailand
Ltd.
Email: pariwat.ch@aerothai.co.th
6
VALIDITY
This AIRAC AIP Supplement will remain current until 31 December 2026 at 0001 UTC. Any changes
to this AIRAC AIP Supplement will be
notified by NOTAM.

VTBDJ5859/26 (10 AUG 26)

"TEMPO RESTRICTED AREA ACT RADIUS 10NM CENTRE 182802N0972620E
(MAE SARIANG DISTRICT MAE HONG SON PROVINCE,
EXCLUDING YANGON FIR)
RMK: ACFT MAY FILE FPL ON THE AFFECTED RTE BUT EXP RADAR
VECTORED BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC"
F) GND
G) UNL

VTBDC4027/26 (10 AUG 26)

"DUE TO VT D41A ACT FPL PROC FOR ACFT OPR FM/TO VTCC DETAIL AS FLW:
1. PERIOD MON-FRI 0000-1100
DEP/OVERFLY DEST/OVERFLY RTE
VTCC VTCT W12 IKISU W22
VTCC PONUK R207 IKISU W22 CTR A581
VTCT VTCC W22 IKISU W12
PONUK VTCC Y27 DUBEN Y28 CRIST R207 (FOR RNAV)
PONUK VTCC A581 CTR W22 IKISU R207 (FOR NON-RNAV)
2. PERIOD MON-FRI 1101-2359, SAT SUN H24
DEP/OVERFLY DEST/OVERFLY RTE
VTCC VTCT W20
VTCC PONUK A581
VTCT VTCC W20
PONUK VTCC A581"

Official Pilot Briefing

Page 15/21

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

VTBDJ5614/26 (10 AUG 26)

DAILY 0100-0230 0600-1100

"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA 3NM EITHER SIDE OF
A LINE: 143000.00N1022800.00E-143107.26N1051100.12E
(SI SAKET, UBON RATCHATHANI, BURIRAM, SURIN AND
NAKHON RATCHASIMA PROVINCE)
RMK: ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR VECTORED
BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC"

F) FL200
G) FL250

VTBDJ5613/26 (10 AUG 26)

DAILY 0100-0230 0600-1100

"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA 3NM EITHER SIDE OF
A LINE: 151638.34N1001745.12E-145407.02N1004920.52E-
143000.00N1022800.00E
(CHAINAT, NAKHON SAWAN, SARABURI, LOP BURI, BURI RAM
AND NAKHON RATCHASIMA PROVINCE)
RMK: ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR VECTORED
BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC"

F) FL150
G) FL200

VTBDJ5304/26 (10 AUG 26)

"JUN 29 0815-2359, JUN 30 0000-1659 2200-2359, JUL 01 2200-SEP 30
1659"

"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA
144705N1033019E-143541N1051246E-142051N1051232E-
141826N1030616E-142521N1030558E-144705N1033019E
(SI SAKET, UBON RATCHATHANI, BURIRAM AND SURIN PROVINCE
EXCLUDING PHNOM PENH FIR)
RMK: ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR VECTORED BY
ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC"

F) 8000FT AMSL
G) FL170

VTBDC2855/26 (10 AUG 26)

"AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM
THE DEMOCRATIC REPUBLIC OF THE CONGO AND THE REPUBLIC OF UGANDA
1. PURSUANT TO THE RESOLUTION OF THE NATIONAL COMMUNICABLE DISEASE
COMMITTEE, EFFECTIVE FROM 27 MAY 2026 AT 1800 HOURS (LOCAL TIME)
ONWARDS, PASSENGERS AND CREW MEMBERS DEPARTING FROM THE DEMOCRATIC
REPUBLIC OF THE CONGO (DR CONGO) AND THE REPUBLIC OF UGANDA SHALL BE
PERMITTED TO ENTER THE KINGDOM OF THAILAND ONLY VIA SUVARNABHUMI
AIRPORT AND SHALL BE SUBJECT TO A MANDATORY QUARANTINE PERIOD OF
TWENTY-ONE (21) DAYS, CALCULATED FROM THE DATE OF DEPARTURE FROM
THE AFFECTED AREAS, IN ACCORDANCE WITH THE PRESCRIBED PUBLIC
HEALTH PROCEDURES.
2. ALL AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM
THE ABOVE-MENTIONED AREAS ARE REQUESTED TO COMPLY WITH AND IMPLEMENT
THE PRESCRIBED MEASURES ACCORDINGLY."

LAO / LAOS

N I L

VLVT / VIENTIANE FIR

N I L

VNM / VIETNAM

N I L

VVHN / HANOI FIR

VVVVA2868/26 (24 AUG 26)

DAILY 0400-1000

"DUE TO ROCKET FRNG ACT, ATS RTE SEGMENTS MENTIONED BELOW
SHALL BE OPERATED AS FLW:

- ARR FLT TO NOI BAI AD VIA ATS ROUTE Q2: Q2 - NIVEN -
185727N1052018E - BISON
- ARR FLT TO NOI BAI AD VIA ATS ROUTE N639: N639 - VILAO -
185727N1052018E - BISON
- ARR FLT TO CAT BI AD VIA ATS ROUTE N639: N639 - VILAO -
185727N1052018E - NAH
- ARR FLT TO THO XUAN AD VIA ATS ROUTE W2 - VIN - W24:

Official Pilot Briefing

Page 16/21

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

W2 - DONGI - 185727N1052018E - HARON
- DEP FLT FM DONG HOI AD TO NOI BAI AD VIA ATS ROUTES W2/Q2:
VVDH - 185727N1052018E - BISON
- DEP FLT FM NOI BAI AD, CAT BI AD VIA ATS ROUTES W2/N639:
NAH - VIDAD - VILAO/DONGI
- OVERFLIGHT VIA ATS ROUTE A206: OFFSET 10NM SOUTH OF ATS
ROUTE
- OVERFLIGHT VIA ATS ROUTE N639:
+ SOUTHBOUND FLT (FM SECTOR 2 TO SECTOR 3): NAH - VIDAD -
VILAO
+ NORTHBOUND FLT (FM SECTOR 3 TO SECTOR 2): N639 - VILAO -
185727N1052018E - NAH
- NORTHBOUND OVERFLIGHT VIA ATS ROUTE Q2: Q2 - NIVEN -
185727N1052018E - NAH
(SEE NOTAMS VVVV A2849/26)."

VVVVA2867/26 (24 AUG 26)

DAILY 0400-1000
"DUE TO ROCKET FRNG ACT, DO NOT USE ATS ROUTE/SEGMENTS AND
EN-ROUTE HLDG FOR FLT OPERATIONS AS FLW:
- W24
- A206: VIN - BUVAN
- N639: KAMSU - BIVIM
- W2: NAH - VIN
- Q2: BUVAN - BIVIM
- EN-ROUTE HLDG: BIVIM, VIN
(SEE NOTAMS VVVV A2849/26)."

*VVVVA2849/26 (23 AUG 26)

DAILY 0400-1000
ROCKET FRNG WILL TAKE PLACE WI:
190742N1054358E - 191829N1055228E - 191828N1060440E -
190634N1061938E - 184641N1061938E - 184642N1060410E -
185113N1055150E - 185915N1054338E - 190643N1054341E -
190742N1054358E
BRG: 117 DEG - 146 DEG
- ALL FLIGHTS ARE PROHIBITED WITHIN THIS AREA.
F) GND
G) 30000M AGL

VVVVA1196/22 (13 JUL 24)

AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) LOCATED AT VAN
DON
TWR OPS WITH CHARACTERISTICS AS FLW:
- COVERAGE: 463KM
- COORD: 210707.44N-1072510.42E (WGS-84)
- HR OF SERVICE: H24.

CHN / CHINA
N I L

ZGZU / GUANGZHOU FIR

ZBBBA3939/26 (25 AUG 26)

26 AUG 2026 07:00-26 AUG 2026 13:00
"ATS RTE V107 AVBL.FLIGHTS ALONG R343 LAOLIANGCANG VOR
'LLC'-GOSMA ADJUSTED TO ATS RTE V107,W45. ATS RTE V107,W45 TWO WAY
AVAILABLE, ALL ACFT FLW ATC INSTRUCTION.
1. LAOLIANGCANG VOR 'LLC' TO ZHHH:
LAOLIANGCANG VOR 'LLC'-W194-CHANGDE NDB 'CD'-W45-LINLI VOR
'LIN'-W207-TIKME-W208- TIANMEN VOR 'WTM'-ZHHH.
2. AVLEN AND BEYOND TO LAOLIANGCANG VOR 'LLC':
AVLEN-W37-DUBAS-R343-TIANHE VOR 'WHA'-A581-VIBUB-V107-LAOLIANGCANG
VOR 'LLC' AND BEYOND.
3. LAOLIANGCANG VOR 'LLC' TO VEXAN AND BEYOND: LAOLIANGCANG VOR
'LLC'-V107-VIBUB-A581-IDPOG-W56-VEXAN AND BEYOND.
4. XISHUI VOR 'XSH' AND BEYOND TO LAOLIANGCANG VOR 'LLC': XISHUI
VOR 'XSH'-W80-IDGAG-A581-VIBUB-V107-LAOLIANGCANG VOR 'LLC' AND
BEYOND.
5. LAOLIANGCANG VOR 'LLC' TO TIANHE VOR 'WHA' AND BEYOND:
LAOLIANGCANG VOR 'LLC'-V107-VIBUB-A581-TIANHE VOR 'WHA' AND BEYOND."

ZBBBA3951/26 (25 AUG 26)

26 AUG 2026 11:45-26 AUG 2026 14:35
"SEGMENT OSNOV-ALGAG OF ATS RTE G586 NOT AVBL DUE TO TECHNICAL
REASON, SCHEDULED FLIGHTS ALONG G586 OSNOV-ALGAG ADJUSTED TO ATS

RTE V147,V148, ALL ACFT FLW ATC INSTRUCTION.
1. MOLSO AND BEYOND TO MAMSI AND BEYOND: MOLSO-OPIXU-UGRIG-MAMSI AND BEYOND.
2. MOLSO AND BEYOND TO ZGKL: MOLSO-OPIXU-UGRIG-MAMSI-ZGKL.
3. MAMSI AND BEYOND TO MOLSO AND BEYOND: MAMSI-UGRIG-OPIXU-MOLSO AND BEYOND.
4. ZGKL TO MOLSO AND BEYOND: MAMSI-UGRIG-OPIXU-MOLSO AND BEYOND.
5. AGVIL AND BEYOND TO MAMSI AND BEYOND:
AGVIL-OSNOV-OPIXU-UGRIG-MAMSI AND BEYOND.
6. AGVIL AND BEYOND TO ZGKL: AGVIL-OSNOV-OPIXU-UGRIG-MAMSI-ZGKL."

*ZBBBA3937/26 (25 AUG 26)

25 AUG 2026 23:30-26 AUG 2026 12:30
2330-0350 1110-1230
SEGMENT NANNING VOR 'WUY'-RUNEG OF ATS RTE W169 CLSD.

*ZBBBA3936/26 (25 AUG 26)

25 AUG 2026 23:30-26 AUG 2026 12:30
2330-0350 1110-1230
"SEGMENT NANNING VOR 'WUY'-ALEKI OF ATS RTE R339 NOT AVBL DUE TO TECHNICAL REASON,ALL AFFECTED FLIGHTS SHALL BE ADJUSTED.ALL ACFT FOLLOW ATC INSTRUCTIONS:
SCHEDULED FLIGHTS ALONG R339 NANNING VOR 'WUY'-ALEKI ADJUSTED TO NANNING VOR 'WUY'-V153-ALEKI."

ZBBBA3892/26 (24 AUG 26)

26 AUG 2026 01:30-26 AUG 2026 08:30
JIUZHOU VOR/DME 'ZAO' FREQ 117.2MHZ/CH119X U/S DUE TO MAINT.

ZBBBA2645/26 (08 JUL 26)

LAOLIANGCANG NDB 'GJ' 245KHZ U/S DUE TO MAINT.
09 JUL 26 16:01 UNTIL 07 OCT 26 15:59 ESTIMATED

ZBBBA2472/26 (29 JUN 26)

NANXIONG VOR/DME 'NNX' 115.6MHZ/CH103X U/S DUE TO MAINT.
29 JUN 26 08:10 UNTIL 30 SEP 26 15:59 ESTIMATED

CH2 / CHINA SANYA
N I L

ZJSA / SANYA FIR

ZBBBA0783/26 (08 AUG 26)

"SANYA FIR(ZJSA)EXECUTE OCS(ONE CTOT SOLUTION)PROCEDURE,ALL ACFT OVERFLYING SANYA FIR(ZJSA) SHALL OPERATE CTOT (CALCULATED TAKE OFF TIME).
EXECUTION BY CTOT(CALCULATED TAKE OFF TIME)."

MAC / MACAU
N I L

HKG / HONG KONG
N I L

VHHK / HONG KONG FIR

VHHHA1846/26 (10 AUG 26)

17 19 20 24 26 27 2315-0600
"DUE TO SURVEILLANCE EQUIPMENT CAPABILITY, IFR FLT WITHOUT OPERABLE ADS-B OUT EQUIPAGE ARE NOT PERMITTED TO OPERATE WI VHHK, IRRESPECTIVE OF LEVELS.
EXEMPTION MAY BE GRANTED WITH PRIOR COOR VIA HONG KONG ATS WATCH SUPERVISOR.
REFER TO AIP HK GEN 1.5 PARAGRAPH 3.7.6 FOR REQUIREMENTS FOR ADS-B OUT EQUIPAGE."

VHHHA1584/26 (16 JUL 26)

1600-2030
"FOR TRAFFIC OVERFLYING HONG KONG FIR VIA ATS ROUTE A1 OR PBN ROUTE
P901 TO ENVAR M750 DESTINED FOR INCHEON FIR. DUE TO DOWNSTREAM ACC'S REQUIREMENT, 5 MINUTES CONSTANT OR INCREASING LONGITUDINAL SEPARATION BETWEEN FLIGHTS AT THE SAME LEVEL SHALL BE PROVIDED AT

IKELA.
RMK: RESTRICTION MAY BE ADJUSTED SUBJECT TO SITUATION AND DISCRETION
OF HONG KONG ATS FLOW MANAGER."
16 JUL 26 16:00 UNTIL 16 OCT 26 20:30 ESTIMATED

*VHHHA1163/26 (02 JUN 26)

DAILY 1700-2030
"DUE TO RESTRICTION FROM TAIPEI ACC (REFER TO NOTAM RCAA
A1725/26),
OVERFLYING ACFT ENTERING HONG KONG FIR VIA IKELA EXITING ENVAR
ENTERING RKRR, FL390 NOT AVBL AT IKELA.
(RMK: RESTRICTION MAY BE ADJUSTED SUBJECT TO SITUATION AND
DISCRETION OF HONG KONG ATS FLOW MANAGER.)"

**** A1048/26 **** VHHHA1048/26 (25 MAY 26)

"REF AIP HK ENR 1.8 PARA 8C, FLAS BTN HONG KONG FIR AND SANYA
FIR/CONTROL AREA FOR ROUTES A202 AND R339, CHANGES AS FLW:
HONG KONG FIR TO SANYA CONTROL AREA:
1) FLAS FOR A202, POINTS BEYOND ASSAD:
S0840 (SUBJ COOR), S1040, S1160, S1220
2) FLAS FOR R339, POINTS BEYOND NANNING:
S0840 (SUBJ COOR), S0980, S1040, S1100, S1160, S1220"

AEROPLANE INFORMATION

AIRCRAFT CATEGORY = D
N I L

AIRCRAFT TYPE = B777
N I L

AIRCRAFT SUBTYPE = B773E
N I L

AIRCRAFT REGISTRATION = HSTKQ
N I L

ADDITIONAL INFORMATION

ZGGG / CAN

ZBBBG3798/26 (25 AUG 26)

"ADD NEW VISUAL DOCKING GUIDANCE SYSTEM FOR PARKING
STAND
NR.144-173,815,816,816L,816R,818,819,819L,819R,821,822,822L,822R,82
4-838,
910-914,916,916L,916R,917,919,919L,919R,920,922,922L,922R,923-939
."

ZBBBG3445/26 (29 JUL 26)

TWY B1 CLSD EAST OF TWY Y.

ZBBBG3330/26 (23 JUL 26)

FLW TWY ONLY AVBL FOR ACFT WITH WING SPAN NOT MORE THAN 65M:
1.TWY Q15 NORTH OF TWY Q10.
2.TWY Q16.

ZBBBG3241/26 (20 JUL 26)

PARKING STAND FX14 CLSD DUE TO MAINT.
22 JUL 26 04:00 UNTIL 30 SEP 26 15:59 ESTIMATED

ZBBBG3201/26 (17 JUL 26)

"DUE TO OPERATIONAL REQUIREMENTS, TWY B EASTBOUND, TURN RIGHT TO
TWY T1 ONLY AVBL FOR ACFT WITH WINGSPAN NOT MORE THAN 36M(ACFT
TYPE C AND BELOW)."
17 JUL 26 07:19 UNTIL 16 OCT 26 15:59 ESTIMATED

ZBBBG3200/26 (17 JUL 26)

TWY Q11 CLSD BTN TWY Q AND TWY Q15.
17 JUL 26 07:18 UNTIL 16 OCT 26 15:59 ESTIMATED

Official Pilot Briefing

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Page 19/21
Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

ZBBBBG3050/26 (11 JUL 26)

PARKING STAND FX09 CLSD.DUE TO MAINT.

ZBBBBG3021/26 (10 JUL 26)

"AD ADD LIMITATION AS FLW,DUE TO WIP:
1.WHEN TAXI IN TWY E,ACFT ARE FORBIDDEN TO TURN LEFT TO TWY J1.
2.WHEN TAXI IN TWY J1,ACFT ARE FORBIDDEN TO TURN RIGHT TO TWY E."
10 JUL 26 07:56 UNTIL 30 SEP 26 15:59 ESTIMATED

ZBBBBG2963/26 (08 JUL 26)

"PRKG STAND GY07,GY08,GY09,GY10 CLSD DUE TO WIP."
08 JUL 26 07:40 UNTIL 30 SEP 26 15:59 ESTIMATED

ZBBBBG2703/26 (30 JUN 26)

"DUE TO PINGZHOU VOR/DME 'POU' U/S,FLW SID PROCEDURE U/S:
1.SID RWY01L/01R(ZGGG-3V-5):SAREX-1.
2.SID RWY01L/01R(ZGGG-3V-7):VIBOS-1."
30 JUN 26 03:02 UNTIL 30 SEP 26 15:59 ESTIMATED

ZBBBBG2695/26 (30 JUN 26)

"REF AIP AD2.20 USE OF APRONS AND PARKING STANDS ITEM 3.2
CHANGED AS FLW:
ACFT SHALL BE GUIDED BY FOLLOW-ME VEHICLE TO ENTER INTO THE WHOLE
STANDS,
CHINA SOUTHERN AIRLINES AND CHONGQING AIRLINES NOT NEED TO FOLLOW
THE FOLLOW-ME VEHICLE TO ENTER INTO THE PARKING STANDS
NR.101-133,134L,134-137,144-149,149L,149R,201-235,236,238,238L,238R
,240,240L,240R,251-254,254L,254R,255,255L,255R,301-308,329,330,401-
419,
401L,401R,402L,402R,403L,403R,404L,404R,405L,405R,406L,406R,GY01-GY
05."
30 JUN 26 22:00 UNTIL 30 SEP 26 15:59 ESTIMATED

ZBBBBG2675/26 (29 JUN 26)

"TWY N CLSD BTN TWY T12 AND TWY T13,DUE TO OPERATION
REQUIREMENT."
29 JUN 26 06:01 UNTIL 30 SEP 26 15:59 ESTIMATED

ZBBBBG2328/26 (12 JUN 26)

LONGMEN VOR/DME 'LMN' 116.3MHZ/CH110X U/S DUE TO MAINT.
12 JUN 26 07:17 UNTIL 31 DEC 26 15:59 ESTIMATED

// (COM-INFO)//

THA 00290/17 (10 JUN 26)

COMP INFO:--RE GROUND POWER UNIT UTILIZATION AT
GUANGZHOU BAIYUN INTL A/P AS NOTIFICATION TO AIRMAN-NOTAM STP
INFO FROM CANKKTG:
" GPU N ACU WLBE CONNECTED TO A/C AFTER PARKING BRIDGE HAS BEEN
CONNECTED- REPEAT -ALL EXTERNAL POWER WLBE CONNECTED AFTER A/C
BLOCKED ON N BRIDGE CONNECTION IS COMPLETED STP"
(UPDATE 02JAN26/CANKK-INFO/UFN)

ZBBBBG1489/26 (10 JUN 26)

TWY S1 CLSD.
21 APR 26 02:18 UNTIL 03 SEP 26 15:59 ESTIMATED

VVDN / DAD

VVVVA2885/26 (25 AUG 26)

27 AUG 2026 00:00-14 SEP 2026 23:59
STANDS 19 AND 20A TEMPO CLSD.

VVVVA2879/26 (25 AUG 26)

DAILY 1900-2230
"WIP ON AREAS, WHEN THERE ARE NO FLT OPS OR DRG INTERMITTENT
TIME BTN FLTS, DETAILS AS FLW:
- AREA 1: ON CONNECTING TWY G1 (73M FM RCL 35R/17L
TO THE WEST, 140M FM RCL 35L/17R TO THE EAST)
- AREA 2: ON CONNECTING TWY G2 (73M FM RCL 35R/17L
TO THE WEST, 140M FM RCL 35L/17R TO THE EAST)
- AREA 3: ON CONNECTING TWY G4 (73M FM RCL 35R/17L
TO THE WEST, 140M FM RCL 35L/17R TO THE EAST)
- AREA 4: BTN RWY 35R/17L AND 35L/17R (122M FM RCL 35R/17L

Official Pilot Briefing

Page 20/21

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

TO THE WEST, 91M FM RCL 35L/17R TO THE EAST, 430M FM CL OF
TWY G4 TO THE NORTH, 510M FM CL OF TWY G6 TO THE SOUTH)
- AREA 5: BTN RWY 35R/17L AND 35L/17R (87M FM RCL 35R/17L
TO THE WEST, 126M FM RCL 35L/17R TO THE EAST, 490M FM CL
OF TWY G4 TO THE NORTH, 450M FM CL OF TWY G6 TO THE SOUTH)
- AREA 6: BTN RWY 35R/17L AND 35L/17R (53M FM RCL 35R/17L
TO THE WEST, 160M FM RCL 35L/17R TO THE EAST, 550M FM CL OF
TWY G4 TO THE NORTH, 390M FM CL OF TWY G6 TO THE SOUTH)
- AREA 7: ON CONNECTING TWY G6 (73M FM RCL 35R/17L TO
THE WEST, 140M FM RCL 35L/17R TO THE EAST)
- AREA 8: BTN RWY 35R/17L AND 35L/17R (121M FM RCL 35R/17L
TO THE WEST, 92M FM RCL 35L/17R TO THE EAST, 131M FM CL OF
TWY G6 TO THE NORTH)
- AREA 9: BTN RWY 35R/17L AND 35L/17R (86M FM RCL 35R/17L
TO THE WEST, 127M FM RCL 35L/17R TO THE EAST, 192M FM CL OF
TWY G6 TO THE NORTH)
- AREA 10: BTN RWY 35R/17L AND PARALLEL TWY E (80M FM RCL
35R/17L TO THE EAST, 70M FM CL OF PARALLEL TWY E TO THE
WEST, 604M FM CL OF CONNECTING TWY E4 TO THE NORTH,
336M FM CL OF CONNECTING TWY E6 TO THE SOUTH)."

*VVVA2815/26 (15 AUG 26)

ALS ON RWY 17R/35L U/S.
15 AUG 26 07:28 UNTIL 14 OCT 26 10:00 ESTIMATED

VVVA2814/26 (15 AUG 26)

LGT SYSTEM ON RWY 17R/35L U/S.
15 AUG 26 07:27 UNTIL 14 OCT 26 10:00 ESTIMATED

*VVVA2810/26 (15 AUG 26)

RWY 17R/35L TEMPO CLSD.

VVVA2811/26 (15 AUG 26)

"TAXIWAYS G1, G2, G4, G6, W1, W2, W4, W5, W6 TEMPO CLSD."

VVVA2813/26 (15 AUG 26)

PAPI RWY 17R/35L U/S.
15 AUG 26 07:25 UNTIL 14 OCT 26 10:00 ESTIMATED

VVVA2812/26 (15 AUG 26)

"ILS-LOC, GP, DME FOR RWY 35L U/S."
15 AUG 26 07:24 UNTIL 14 OCT 26 10:00 ESTIMATED

VVVA2745/26 (10 AUG 26)

CLEANING ON RWY 35R/17L WHEN THERE ARE NO FLT OPS OR DRG
INTERMITTENT TIME BTN FLTS.

VVVA2652/26 (01 AUG 26)

DOPPLER WX RADAR SYSTEM (METEOR 60DX10-S) U/S FOR REPAIR
RMK: LOW-LEVEL WS ALERT SYSTEM (LLWAS) NML OPS.
01 AUG 26 12:39 UNTIL 31 OCT 26 23:59 ESTIMATED

VVVA2511/26 (24 JUL 26)

"ESTABLISHMENT OF TWY E OPR PROCEDURES DURING ACFT TKOF/LDG
ON RWY 17L/35R:
- IN CASE OF ACFT CODE D/E TKOF/LDG ON RWY 17L/35R, ACFT UP
TO CODE C ARE PERMITTED TO USE TWY E
- IN CASE OF ACFT CODE C TKOF/LDG ON RWY 17L/35R, ACFT UP TO
CODE E ARE PERMITTED TO USE TWY E
REF AIP VIET NAM, ITEM VVDN AD 2.23-8."

VVVA2510/26 (24 JUL 26)

"ADDN OF GP HOLD POSITIONS:
- POSITIONS:
+ GP HOLD 1: ON TWY E (654M FM CL OF TWY E2 TO THE SOUTH,
176M FM CL OF TWY E1 TO THE NORTH)
+ GP HOLD 2: ON TWY E (72M FM CL OF TWY E1 TO THE SOUTH)
- OPS PROC:
+ GP HOLD 1: USED FOR ACFT UP TO CODE E
+ GP HOLD 2: USED FOR ACFT UP TO CODE C
REF AIP VIET NAM, ITEM VVDN AD 2.9."

Official Pilot Briefing

THA638 26AUG26 HSTKQ B773E VTBS 0700 VHHH 0945
THA639 26AUG26 HSTKQ B773E VHHH 1105 VTBS 1345

Page 21/21
Trans ID: 5118670
Creation Time: 25.08.2026 23:23UTC

VWVA1937/26 (17 JUN 26)

"REF AIP SUP 12/26 WEF 04 MAR 2026,
FREE OF CHARGE FOLLOW-ME CAR IS PROVIDED TO GUIDE ACFT TAX
IN/OUT STANDS WI CONST AREA DURING CONST PERIOD."

VWVA1328/22 (17 OCT 23)

THE ADJUSTMENT OF STOP LINE OF ACFT FOR STANDS 1-9 AS FLW:
114.7 M FM TAXILANE D TO THE EAST.

VWVA1209/22 (17 OCT 23)

"VISUAL DOCKING GUIDANCE SYSTEM (VDGS) IS SAFEDOCK TYPE T1
(T-TYPES),
AVBL AT ACFT STANDS 21, 23, 25
- REF AIP VIET NAM ITEM VVDN AD 2.9 PAGE AD 2.VVDN-7 DATED 30 JUL
2021."

THA638 26AUG26/0700 VTBS/VHHH
N I L

THA639 26AUG26/1105 VHHH/VTBS
N I L