

GENERAL INFORMATION**## Company Fuel Guidelines ##**

THA 00159/26 (18 JUN 26)

OM INFO:--WEF 19JUN26,
Company Fuel Guidelines:
1) Flight Outbound from VTBS:
1.1) 15 mins:
-TG319
-ETA within TEMPO ±1 hr with adverse weather condition

1.2) 5 mins:
-BLR (ONLY WHEN SINGLE RWY OPS)
-TG317, TG407, TG409*

2) Flight Inbound to VTBS:
2.1) 20 mins:
ETA within TEMPO ±2 hrs with adverse weather condition*

2.2) 5 mins:
ETA 22:00-24:00 (BKK local time)

3) European Flights:
3.1) Outbound flight to European: CF 3 PERCENT (Except TG916/CF5)

3.2) Inbound flight to VTBS: RCFP + 05MINS

4) Flight Level Plan for VTUK,
-Outbound from VTBS: FL250
-Inbound to VTBS: FL240

5) Planning for Arrival WADD:
To improve flight planning accuracy, for WADD arrivals,
after waypoint KOLTA, flights shall plan to DOBMA
and then follow DOBMA## STAR.

6) TG649: Flight level shall not be planned above FL380.

7) TG900: When ETA falls within TEMPO ±2 hrs and adverse weather conditions, LTAC shall be
designated as the destination alternate.

8) Destination VTUD*:

Remove altitude restrictions and use the optimum altitude for planning.

Remark:
1) Pilot Management Department (PA)

1.1) Destinations ZBAA and ZSPD:

Flights shall be planned as Economic Tankage without company fuel, with the following
conditions:

-Widebody aircraft shall be planned with far alternates (RKSI, RJFF).

-Narrowbody aircraft shall be planned with ZBTJ as the alternate; however, ZFW shall be
restricted to ensure the carriage of at least 30 minutes of extra fuel.

1.2) Destination YPPH: ALTN YGEL (+05MINS EXTRA FUEL)*

YGEL shall be used as ALTN airport effective 25 Apr 2026 following revision of OM-A section
8.3.26 (Operations at Uncontrolled Aerodromes)

2) Everything else regarding fuel planning policy remains the same as last month.

3) Adverse weather conditions*:
RA, TS or TSRA and visibility 5000m or less

(REVISED NO.1/REF EMAIL Summary of Fuel Initiatives Meeting - 08JUN26
For Fuel Committee member/BKKPC)

// (COM-INFO) //

THA 00002/13 (31 MAY 26)

COM INFO:--All A350 and BOEING 787:
are now eligible and included in EUROCONTROL airspace CPDLC Logon list.
Action Required: Pilots are required to initiate CPDLC logon when entering European airspace.

Official Pilot Briefing

THA201 27JUN26 HSTXB A320 VTBS 0030 VTSP 0200

Page 2/9
Trans ID: 5039479
Creation Time: 26.06.2026 16:45UTC

(ISSUED 23MAR26/BKKPC2/UFN)

--IN CASE CANNOT BE CONTACTED BKKOC VIA TELEPHONE,
PILOTS MAY CONTACT VIA MS TEAMS CHANNEL: "OC.CENTER".
(ISSUED 30JUL24/BKKOC/UFN)

-- To improve CTOT for all flights both outbound from BKK and inbound to BKK, pilots may contact TOCC when ready for departure to request an earlier CTOT through any of the following channels:

: MS Teams chat
: LINE CLC-Pilot
: CUT 129.325
: Phone 02-137-1202

In addition to above contact channels, for DOMESTIC flight, pilots may also directly contact ground staff to request earlier CTOT. (ISSUED 15FEB25/BKKOP/UFN)

--DELEGATED FUNCTIONS PHONE DIRECTORY (Direct Number)

1. OPEN BOARDING GATE : 02-137-1260
2. BUS GATE - REMOTE BAY & DOMESTIC V.V. : 02-137-1260
3. CREW BUS OPC-TERMINAL V.V. : 02-137-1019, 02-137-1020
4. CONFIRM BOARDING GATE/BAY/BELT : 02-137-1263
5. ZFW/WEIGHT & BALANCE/LOAD SHEET : 02-137-1291, 02-137-1292
6. TG LOST & FOUND : 02-134-5454
7. OTHER INQUIRIES/BKKOC : 02-137-1202

(ISSUED 17JUL22/BKKOC-INFO/UFN)

--If expected divert due to weather or traffic congestion at any TG destination airports, please kindly advise TOCC, via ACARS using OPERATIONS prompt or SITA address BKKOPTG, the current fuel on board immediately to keep close monitoring of the flight.
(ISSUED 08MAY25/BKKOP/UFN)

--In case of pilot receives information from ground staff to delay departure due to connecting passenger, please kindly confirm with TOCC via CUT channel.
(ISSUED 27NOV24/BKKOP/UFN)

--FOR FLIGHTS PLANNED NAVIGATING THROUGH KABUL FIR,
ONCE FINAL FL TO ENTER KABUL FIR IS AVAILABLE,
PLEASE ACARS DOWNLINK ETO/ENTRY WPT/FL TO BKKOPTG
(ISSUED 12DEC24/BKKOC/UFN)

--Please kindly consider and issue recommendation for route P500 G500 as soon as possible in order to reduce operational risk.

1. Due to limitation of passenger oxygen chemical type (22 minutes).
If weather deviation is required, pilots shall deviate west of route only.

2. In an event of critical in-flight emergency, the aircraft should follow ICAO emergency descent procedures, broadcast status and intentions on 125.2 MHZ and 121.5 MHZ. Thereafter, proceed at the discretion of the PIC until clear Kabul FIR and in contact with the ATC responsible for the airspace.
(ISSUED 31JUL24/D1/OC/UFN)

--Any flight operation by TG into the uncontrolled airspace and conflict zone, the latest operational information " Closures and Warnings" issued by means of ICAO State letters,
NOTAMs, AICs/AIPs, and EASA CZIB - TG are subject to strictly following the guidance/directions from their national authority as well as their own risk assessment.
(ISSUED 15APR24 CORR/TN003/22/OW/UFN)

--WEF 01JUN26,
SUBJ: SPECIAL SECURITY ARRANGEMENT:SSA006/2026
ATTN ALL CONCERNED

THE AVIATION SECURITY COMMITTEE (ASC) MTG ON 21MAY2026
AGREED TO ANNOUNCE SSA006/2026 AS FLWS:

AA PLS BE INFM THT THIS SSA WILL SUPERSEDE SSA005/2026
FROM 01JUN2026 UNTIL FURTHER TLX ADV

BB FR FLT DEP FRM STATION EUROPE: ARN BRU CDG CPH FRA IST LHR MUC
MXP OSL ZRH

LEVEL: LOW CMA PERFORM SSA ACCORDING TO EU REQUIREMENTS
AS FLWS:

A1 - A/C PRE-FLIGHT SECURITY SEARCH CONDUCTED BY PIC CMA
CABIN CREW CMA ASM/SMT/DELEGATED PERSONNEL N GROUND/
STATION ENGINEER

A18-1 5% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
CONDUCTED BY CABIN CREW

CC FR FLT DEP FRM STATION: DAC KHI KTI ISB LHE RGN SAI

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW

DD FR DOM FLT DEP FRM STATION: HDY HKT UBP

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW

EE FR FLT DEP FRM MAINBASE STATION: BKK

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW
F2 - IDENTITY CHECK OF CREW MEMBERS BEFORE BOARDING AT
BOARDING GATE
P2 - SECONDARY CHECK AT GATE
(APPLY ONLY FLT FRM BKK TO MEL PER N SYD)

FF THE FLWG SSA SHALL BE IMPLEMENTED FR ALL ROUTE AS NORMAL PROC
P5 - INTENSIVELY PERFORM IDENTITY CHECK N VERIFICATION OF PAX
BEFORE BOARDING A/C BY
- COMPARING PAX WZ PHOTOGRAPH N PASSPORT/TVL DOCS TO
ENSURE PAX IS BONA FIDE N
- VERIFYING THE NAMES IN THE TICKETS CORRESPOND TO THOSE
ON THE IDENTITY DOCS
V1 - ALERT STAFF TO OBSERVE UNUSUAL BEHAVIOR OF PAX N ALL
PERSONNEL INVOLVED N ANY SUSPICIOUS ITEM IN THE
OPERATING AREA

GG THOSE STN NOT ON THE LIST ABOVE ARE LOW LEVEL STP
APPLY NORMAL SECURITY PROC AS MENTIONED IN OPERATION MANUAL

ADDITIONAL INSTRUCTION.

FR FLT OPS TO BLR MAA N CCU PLS IMPLEMENT THE FLW MEASURES AT THE
CHK-IN COUNTERS;

1. PROV DEDICATED CHK-IN COUNTERS FR FLT TO BLR MAA N CCU
2. DISPLAY WARNING N INFO SIGNAGE AT:
-CHK-IN COUNTERS
-B/D GATE
-FLT INFO DISPLAY SYSTEM (FIDS) AT CHK-IN COUNTERS
3. CONDUCT RANDOM X-RAY SCREENING OF SUSPICIOUS BAG AT CHK-IN
COUNTERS
4. CONDUCT RANDOM SCREENING BY USING SNIFFER DOGS IN THE CHK-IN AREA.

IN CASE OF THREAT SITU N EXTRA MEASURES ARE REQ CMA
STN MONITORING TEAM/SMT MAY RAISE UP MEASURES AS APPROPRIATE

ANY SECURITY INCIDENTS MAY OCCUR SHALL INFO MANAGEMENT CONCERNED
N BKKD1 ACCLY STP

REMARK

A18-1 5% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
WILL BE REVISED IN SPM NEXT REVISION

PLS ACK N CFM ACTUAL PERFORM TO OFC BKKD1-B
BRGDS/CAPT. CHINGCHEEP B./BKKD1 ASC CHAIRMAN

Minima for flight planning

THA 00136/26 (29 MAY 26)

COM INFO: Application of planning minima for flight planning

Due to limited space in the OFP fuel planning box, any display of "BASIC FUEL SCHEME" shall be interpreted as "BASIC FUEL SCHEME WITH VARIATION."

All THAI flights are planned using Basic Fuel Scheme with Variation, unless otherwise specified by Flight Dispatcher.

Alternate planning minima shall be applied in accordance with OMA 8.1.7.5.2.
Display format will be reviewed and updated following stakeholder discussion.

OFP - TCAR format

THA 00093/26 (18 MAY 26)

COM INFO: SFP/OFP change format according to OM-A (TCAR version)

Due to identified limitations in the current OFP template,
the following temporary procedures shall apply with immediate effect:

1. RVSM - Standby Altimeter

Official Pilot Briefing

THA201 27JUN26 HSTXB A320 VTBS 0030 VTSP 0200

Page 4/9
Trans ID: 5039479
Creation Time: 26.06.2026 16:45UTC

The current OFP does not provide a dedicated line for Standby Altimeter recording as required by OMA 14.4.4.

Action: Record the Standby Altimeter value adjacent to the existing record row.

This procedure is mandatory to ensure compliance with OMA 14.4.4.

2. RAIM Information

RAIM shown in the OFP is for terminal operations only.

Action: For flights requiring NPA, crew shall verify RAIM availability separately using an approved RAIM Forecast Report.

3. RCFP - MINF at DP

the displayed MINF at DP may be incorrect.

Action: Disregard the displayed value and refer to the minimum fuel at DP provided in the eOFP application to maintain information consistency.

These instructions are mandatory until corrected in the next OFP version.

FLIGHT LEG INFORMATION

VTBSVTSP

## AIP SUP A16/26 ##	THA 00054/26 (18 APR 26)
(SEE ATTCH) //	
## AIP SUP A02/26 ##	THA 00007/26 (18 APR 26)
// (SEE ATTCH) //	
## AIP SUP A45/25 ##	THA 00295/25 (18 APR 26)
// (SEE ATTCH) //	

AERODROME INFORMATION

VTBS / BKK

	VTBDC3502/26 (26 JUN 26)
26 JUN 2026 10:15-27 JUN 2026 19:00 ACFT STAND NR E5 CLSD DUE TO WIP	
	VTBDC3497/26 (26 JUN 26)
26 JUN 2026 19:00-26 JUN 2026 23:15 TWY CLSD DUE TO WIP DETAIL AS FLW: -TWY E BTN TWY D1 AND TWY D3 -TWY D1 -TWY D2 -TWY E1	
	VTBDC3498/26 (26 JUN 26)
27 JUN 2026 19:00-27 JUN 2026 23:00 TXL CLSD DUE TO WIP DETAIL AS FLW: -TXL T11 BEHIND ACFT STAND NR E1 E3 E5 E7 E9 -TXL T12 BEHIND ACFT STAND NR D7 D8	
	VTBDC3496/26 (26 JUN 26)
26 JUN 2026 19:30-26 JUN 2026 23:00 TWY CLSD DUE TO WIP DETAIL AS FLW: -TWY G BTN TWY D AND TWY H2 -TWY H1 -TXL T13 BEHIND ACFT STAND NR E10 403	
	VTBDC3495/26 (26 JUN 26)
26 JUN 2026 19:00-26 JUN 2026 23:00 TWY CLSD DUE TO WIP DETAIL AS FLW: -TWY E BTN TWY D11 AND TWY E21 -TWY E15 -TWY E17 -TWY E19 -TWY E21	
	VTBDC3491/26 (26 JUN 26)

BANGKOK / SUVARNABHUMI INTERNATIONAL AIRPORT PSR U/S

Official Pilot Briefing

THA201 27JUN26 HSTXB A320 VTBS 0030 VTSP 0200

Page 5/9
Trans ID: 5039479
Creation Time: 26.06.2026 16:45UTC

*VTBDC3478/26 (25 JUN 26)

27 JUN 2026 20:30-27 JUN 2026 21:45
RWY 01/19 CLSD DUE TO WIP

VTBDC3476/26 (25 JUN 26)

26 JUN 2026 17:00-27 JUN 2026 23:30
"26 1700-2315, 27 1700-2330"
TWY CLSD DUE TO WIP DETAIL AS FLW:
-TWY F
-TWY F1 TO TWY F12
-TWY F15
-TWY W
-TWY Y
-TWY Z

*VTBDC3477/26 (25 JUN 26)

26 JUN 2026 23:15-27 JUN 2026 04:00
RWY 02R/20L CLSD EXC FOR CROSSING OPS
RMK/CROSSING OPS WILL BE ESTABLISHED AT ONE OF THE FLW LOCATIONS:
-NORTHERN INT: CROSS RWY 02R/20L BTN TWY W AND TWY E3
-SOUTHERN INT: CROSS RWY 02R/20L BTN TWY Z AND TWY E17

*VTBDC3474/26 (25 JUN 26)

26 JUN 2026 17:00-27 JUN 2026 23:30
"26 1700-2315, 27 1700-2330"
RWY 02L/20R CLSD DUE TO WIP

*VTBDC3473/26 (25 JUN 26)

26 JUN 2026 19:00-26 JUN 2026 23:15
RWY 02R/20L CLSD DUE TO WIP

OB Company Safety NOTAM-BKK

THA 00161/26 (22 JUN 26)

// (SEE ATTCH) //

// (COM-INFO) //

THA 00029/26 (18 JUN 26)

COM INFO:--WEF 16FEB26 04:00LT
The operation of opening aircraft doors from outside for all arriving flight
by ground staff at BKK station will be fully implemented.
(refer IOC GB/SS/005-26 date 30JAN 26/UFN)

// (COM-INFO) //

THA 00064/25 (18 JUN 26)

COM INFO:--REF AIP SUP A53/25:
RETIls U/S:
RWY 01/19: TWYs B3, B5, B7, B8, B10 and B11
RWY 02R/20L: TWYs E5, E7, E9, E12, E13, E15.

--1) The Visual Docking Guidance System (VDGS) at
the ACFT stands 101 - 114 are U/S. (14 ACFT stands).
2) Airlines or Ground service providers shall provide a License Mechanic
performed as Marshaller to guide the aircraft from taxilane to the
parking position.
3) The ACFT are strongly advised to strictly follow the Marshaller's signal.
(REF AIP SUP A13/25*)

--Suvarnabhumi:
DVOR/DME (SVB) (133932.5N 1004353.2E) (111.4 MHZ, CH51X) temporary suspended
from 28 November 2024 at 0001 UTC to 02 October 2026 at 0949 UTC.
(REF AIP SUP A54/24*)

--Taxiway C between Taxilane T1 and Taxilane T2, Taxiway C1 closed.
(REF AIP SUP A01/25*)

VTBDC2661/26 (07 JUN 26)

"AD 2.24 CHARTS RELATED TO AN AD,
IAC-ICAO CHANGED ALT AT IF AS FLW:
AD2-VTBS 8-9 ILS OR LOC Z RWY 19 CAT II
:READ ALT2500 (2496) INSTEAD OF ALT3000
AD2-VTBS 8-13 ILS OR LOC Z RWY 20L CAT II
:READ ALT3500 (3496) INSTEAD OF ALT4000
AD2-VTBS 8-23 RNP RWY 19 :READ ALT2500 (2496) INSTEAD OF ALT3000
AD2-VTBS 8-25 RNP RWY 20L :READ ALT3500 (3496) INSTEAD OF ALT4000
AD2-VTBS 8-27 RNP RWY 20R :READ ALT3500 (3492) INSTEAD OF ALT4000
REF AIRAC AIP AMDT AD2-VTBS-8-9, AD2-VTBS-8-13, AD2-VTBS-8-23,
AD2-VTBS-8-25, AD2-VTBS-8-27"

VTBDC2039/26 (19 APR 26)

ADVANCED VISUAL DOCKING GUIDANCE SYSTEM (A-VDGS)
ACFT STAND NR 119 308 516 AND 520 U/S DUE TO MAINT
RMK: ACFT HAVE TO FLW MARSHALLING SIGNALS STRICTLY

VTSP / HKT

VTBDC3381/26 (22 JUN 26)

ACFT STAND NR 9 CLSD DUE TO WIP

VTBDC3380/26 (22 JUN 26)

ACFT STAND NR 10 CLSD DUE TO WIP

VTBDJ5144/26 (19 JUN 26)

DAILY 0100-1000
UNMANNED AIRCRAFT WILL TAKE PLACE
RADIUS 1.3NM CENTRE 080510.87N 0982201.96E.
F) GND
G) 295FT AGL

// (COM-INFO)//THA 00094/26 (04 JUN 26)

VTSP:--REF AIP SUP A18/26:
1 INTRODUCTION
With effect from 5 May 2026 at 0101 UTC. The purpose of this AIP Supplement is to inform pilots and operators concerning the Visual Docking Guidance System (VDGS) of aircraft stand number 31 at Phuket International Airport (VTSP).
2 DETAILS
2.1 The Visual Docking Guidance System (VDGS) of aircraft stand number 31 is unserviceable.
2.2 The aircraft are strongly advised to strictly follow the Marshaller's signal.

VTBDC2995/26 (04 JUN 26)

RVR RWY 09/27 U/S

VTBDC2924/26 (04 JUN 26)

RWY CLOSURE FOR MAINT WORKS AT PHUKET INTERNATIONAL AIRPORT (VTSP) (MARCH-OCTOBER 2026)
ITEM 2. CLOSURE AREAS AND PERIODS OF RWY PREVENTIVE MAINT AMEND AS FLW:
MONTH DATES PERIOD OF CLOSURE
MAY 31 1730-2330
JUN 01-09 23 1730-2330
JUL 07 21 1815-2330
AUG 04 1815-2330
REF AIRAC AIP SUP A14/26

VTSG / KBV
N I L

ADDITIONAL INFORMATION

VTSB / URT

VTBDC2370/26 (30 APR 26)

"RWY 04/22 OVERLAY, PARL TWY CONST AND AIRFIELD LGT SYSTEM
REVISION AT VTSB
EXTD TO 30 JUL 2026 AT 1659UTC
REF AIRAC AIP SUP A51/25"

VTSS / HDY

VTBDC3464/26 (25 JUN 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS) ACFT STAND NR 5 U/S

VTBDC3112/26 (08 JUN 26)

"TACAN HTY 115.70MHZ/CH104X ON TEST, DO NOT USE"

VTBDC2126/26 (16 APR 26)

TWY EDGE LGT U/S DETAIL AS FLW:
-TWY J
-TWY K
-TWY L

Official Pilot Briefing

THA201 27JUN26 HSTXB A320 VTBS 0030 VTSP 0200

Page 7/9
Trans ID: 5039479
Creation Time: 26.06.2026 16:45UTC

-TWY M

VTBDC2077/26 (09 APR 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS) ACFT STAND NR 4 U/S

ENROUTE INFORMATION

ASP / ASIA/PACIFIC

N I L

THA / THAILAND

N I L

VTBB / BANGKOK FIR

VTBDC3483/26 (25 JUN 26)

26 JUN 2026 00:00-26 JUN 2026 23:59
CDR Y5 (RNAV 2) AVBL FOR FLIGHT PLANNING AS FLW:
PERIOD : MEA LOWER/UPPER LIMITS
0000-2359 FL130/FL460

VTBDC3430/26 (23 JUN 26)

"ALL ACFT VIA RTE B346, R474, W21 AND G473 ADVICE CTC
BANGKOK ACC PRI FREQ 126.500MHZ AND SRY FREQ 122.00MHZ
DUE TO RADIO FREQ INTERFERENCE"

*VTBDJ5085/26 (16 JUN 26)

27 JUN 2026 01:00-27 JUN 2026 11:00
"ROCKET (BANGFAI) FRNG WILL TAKE PLACE RADIUS 5NM CENTRE
160502.4N1035900.7E (SELAPHUM DISTRICT ROI ET PROVINCE)
RMK: COOR CTC TEL +668 7431 4322, +669 5691 0426"
F) GND
G) 19000FT AGL

VTBDC2855/26 (26 MAY 26)

"AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM
THE DEMOCRATIC REPUBLIC OF THE CONGO AND THE REPUBLIC OF UGANDA
1. PURSUANT TO THE RESOLUTION OF THE NATIONAL COMMUNICABLE DISEASE
COMMITTEE, EFFECTIVE FROM 27 MAY 2026 AT 1800 HOURS (LOCAL TIME)
ONWARDS, PASSENGERS AND CREW MEMBERS DEPARTING FROM THE DEMOCRATIC
REPUBLIC OF THE CONGO (DR CONGO) AND THE REPUBLIC OF UGANDA SHALL BE
PERMITTED TO ENTER THE KINGDOM OF THAILAND ONLY VIA SUVARNABHUMI
AIRPORT AND SHALL BE SUBJECT TO A MANDATORY QUARANTINE PERIOD OF
TWENTY-ONE (21) DAYS, CALCULATED FROM THE DATE OF DEPARTURE FROM
THE AFFECTED AREAS, IN ACCORDANCE WITH THE PRESCRIBED PUBLIC
HEALTH PROCEDURES.
2. ALL AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM
THE ABOVE-MENTIONED AREAS ARE REQUESTED TO COMPLY WITH AND IMPLEMENT
THE PRESCRIBED MEASURES ACCORDINGLY."

// (COM-INFO) //

THA 00126/26 (14 MAY 26)

COM INFO:--REF AIP SUP A19/26;

1

INTRODUCTION

With effect from 14 May 2026 at 0001 UTC to 31 December 2026 at 0001 UTC, the purpose of this
AIRAC AIP Supplement is to inform all
concerned regarding Temporary suspension of SURAT THANI DVOR/DME (STN) due to relocation
details are as follows.

2

THE PERIOD OF TEMPORARY SUSPENSION

STN DVOR/DME will be temporarily suspension from 14 May 2026 at 0001 UTC to 31 December 2026
at 0001 UTC.

3

FLIGHT PROCEDURE

A temporary reporting point name SAPUD (090746.24N 0990805.09E) will be established at the
same coordinates of SURAT THANI DVOR/
DME (STN) for ATS routes G458, W17, W24, W28, W32 and Y8 and a portion of ATS route G458
between STN and MENEX will be suspended
until STN normal operations resume.

4

FLIGHT PLANNING PROCEDURES

Reference to the AIP-THAILAND part ENR 1.10 item 4.1.1.1, 4.1.1.2 a, 4.1.1.2 b, 4.1.1.3 a,
4.1.1.3 b non-RNAV2 approved aircraft. To maintain
efficiency of ATS during SURAT THANI DVOR/DME (STN) relocation, non-RNAV approved aircraft
that intend to operate on G458 between

Official Pilot Briefing

THA201 27JUN26 HSTXB A320 VTBS 0030 VTSP 0200

Page 8/9
Trans ID: 5039479
Creation Time: 26.06.2026 16:45UTC

SAPUD and MENEX shall file flight plan, depending on ACFT capability.

5

CONTACT

Unit: Air Traffic Navigation Systems Engineering Department, Aeronautical Radio of Thailand Ltd.

Email: pariwat.ch@aerothai.co.th

6

VALIDITY

This AIRAC AIP Supplement will remain current until 31 December 2026 at 0001 UTC. Any changes to this AIRAC AIP Supplement will be notified by NOTAM.

VTBDJ3551/26 (14 MAY 26)

DAILY 0100-0230 0600-1130

"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA 5NM EITHER SIDE OF

A LINE:151638.34N1001745.12E-145407.02N1004920.52E-

143000.00N1022800.00E-143107.26N1051100.12E

(CHAINAT, NAKHON SAWAN, LOP BURI, SURIN, SI SA KET,

UBON RATCHATHANI, BURI RAM AND NAKHON RATCHASIMA PROVINCE)

RMK: ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR VECTORED

BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC"

F) FL150

G) FL200

VTBDC2184/26 (20 APR 26)

"DUE TO VT D41A ACT FPL PROC FOR ACFT OPR FM/TO VTCC DETAIL AS FLW:

1. PERIOD MON-FRI 0000-1100

DEP/OVERFLY	DEST/OVERFLY	RTE
-------------	--------------	-----

VTCC	VTCT	W12 IKISU W22
------	------	---------------

VTCC	PONUK	R207 IKISU W22 CTR A581
------	-------	-------------------------

VTCT	VTCC	W22 IKISU W12
------	------	---------------

PONUK	VTCC	Y27 DUBEN Y28 CRIST R207 (FOR RNAV)
-------	------	-------------------------------------

PONUK	VTCC	A581 CTR W22 IKISU R207 (FOR NON-RNAV)
-------	------	--

2. PERIOD MON-FRI 1101-2359, SAT SUN H24

DEP/OVERFLY	DEST/OVERFLY	RTE
-------------	--------------	-----

VTCC	VTCT	W20
------	------	-----

VTCC	PONUK	A581
------	-------	------

VTCT	VTCC	W20
------	------	-----

PONUK	VTCC	A581"
-------	------	-------

VTBDJ2001/26 (05 APR 26)

"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA :

144705N1033019E - 143541N1051246E - 142051N1051232E -

141826N1030616E - 142521N1030558E - 144705N1033019E

(SI SAKET, UBON RATCHATHANI, BURIRAM AND SURIN PROVINCE

EXCLUDING PHNOM PENH FIR)

RMK : ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR

VECTORED BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC."

F) 8000FT AMSL

G) FL170

AEROPLANE INFORMATION

AIRCRAFT CATEGORY = C

N I L

AIRCRAFT TYPE = A320

N I L

AIRCRAFT SUBTYPE = A320

N I L

AIRCRAFT REGISTRATION = HSTXB

N I L

ADDITIONAL INFORMATION

VTBU / UTP

*VTBDC3302/26 (18 JUN 26)

PALS CAT 1 RWY 18 AND SALS RWY 36 U/S DUE TO MAINT

C3100/26

VTBDC3100/26 (07 JUN 26)

ILS RWY 18 U/S DUE TO MAINT

Official Pilot Briefing

THA201 27JUN26 HSTXB A320 VTBS 0030 VTSP 0200

Page 9/9
Trans ID: 5039479
Creation Time: 26.06.2026 16:45UTC

*VTBDC2844/26 (07 JUN 26)

AD CATEGORY FOR FIRE FIGHTING AND RESCUE SERVICES
DOWNGRADED TO CAT 9.

VTBDC2193/26 (07 JUN 26)

TWY EDGE LGT U/S DUE TO MAINT DETAIL AS FLW:
-TWY B
-TWY E BTN TWY B AND TWY F

VTBDC0333/23 (06 APR 24)

"IAC-ICAO-NDB RWY 36 CHANGED AS FLW:
-OCA/H : STRAIGHT-IN APPROACH
: READ 790(766)FT INSTEAD OF 750(726)FT
-OCA/H : CIRCLING APPROACH CAT A, B
: READ 1200(1141)FT INSTEAD OF 750(726)FT, 1190(1166)FT
-OCA/H : CIRCLING APPROACH CAT C, D
: READ 1450(1391)FT INSTEAD OF 1290(1266)FT, 1445(1421)FT
REF AIP VTBU AD 2.24, AD 2-VTBU-8-1"

VTBD / DMK

*VTBDC3446/26 (24 JUN 26)

"24 1600-2200, 26 1500-1600, 27 28 1600-2200"
RWY 03R/21L CLSD DUE TO WIP

*VTBDC3440/26 (24 JUN 26)

25 26 29 1600-2200
RWY 03L/21R CLSD DUE TO WIP

VTBDC1938/26 (19 APR 26)

RAPID EXIT TWY INDICATOR LGT RWY 21R TOWARD RAPID EXIT TWY O U/S

VTBDJ1987/26 (19 APR 26)

"TEMPO RESTRICTED AREA ACT WI 0.5NM CENTRE OF 135526.22N1003713.11E
APPROVAL SHALL BE MADE BEFORE ENTERING, EXCEPT DEP AND ARR ACFT AT
VTBD PILOT IN COMMAND SHALL STRICTLY COMPLY WITH ATC INSTRUCTION"
F) GND
G) 3000FT AGL

// (COM-INFO)//

THA 00435/14 (16 DEC 24)

COM INFO:-- DMK TG LINE MAINTENANCE WILL PROVIDE RAMP HANDLING SERVICE ON
TG FLIGHTS DIVERTED TO DMK, WHILE PIC MUST PERFORM REDUCE LINE CHECK
TO RELEASE AIRCRAFT. PRIOR TO FLIGHT DIVERSION TO DMK PLS INFORM
TOCC COMMAND CENTER (OC) VIA CUT FREQUENCY 129.325 MHZ
TO COORDINATE WITH DMK TG LINE MAINTENANCE IN ADVANCE FOR SMOOTH
HANDLING UPON ARRIVAL AT DMK
CONTACT POINTS FOR DMK LINE MAINTENANCE IN (24hrs)
AT DMK ARE AS FLW
1. TEL: 02-563-8178 (66-8178, 9999)
2. Email dmkjcb@thaiairways.com
(ISSUED 12DEC24/OP/UFN)

THA201 27JUN26/0030 VTBS/VTSP

N I L