

GENERAL INFORMATION**## Company Fuel Guidelines ##**

THA 00159/26 (18 JUN 26)

OM INFO:--WEF 19JUN26,
Company Fuel Guidelines:
1) Flight Outbound from VTBS:
1.1) 15 mins:
-TG319
-ETA within TEMPO ±1 hr with adverse weather condition

1.2) 5 mins:
-BLR (ONLY WHEN SINGLE RWY OPS)
-TG317, TG407, TG409*

2) Flight Inbound to VTBS:
2.1) 20 mins:
ETA within TEMPO ±2 hrs with adverse weather condition*

2.2) 5 mins:
ETA 22:00-24:00 (BKK local time)

3) European Flights:
3.1) Outbound flight to European: CF 3 PERCENT (Except TG916/CF5)

3.2) Inbound flight to VTBS: RCFP + 05MINS

4) Flight Level Plan for VTUK,
-Outbound from VTBS: FL250
-Inbound to VTBS: FL240

5) Planning for Arrival WADD:
To improve flight planning accuracy, for WADD arrivals,
after waypoint KOLTA, flights shall plan to DOBMA
and then follow DOBMA## STAR.

6) TG649: Flight level shall not be planned above FL380.

7) TG900: When ETA falls within TEMPO ±2 hrs and adverse weather conditions, LTAC shall be
designated as the destination alternate.

8) Destination VTUD*:

Remove altitude restrictions and use the optimum altitude for planning.

Remark:
1) Pilot Management Department (PA)

1.1) Destinations ZBAA and ZSPD:

Flights shall be planned as Economic Tankage without company fuel, with the following
conditions:

-Widebody aircraft shall be planned with far alternates (RKSI, RJFF).

-Narrowbody aircraft shall be planned with ZBTJ as the alternate; however, ZFW shall be
restricted to ensure the carriage of at least 30 minutes of extra fuel.

1.2) Destination YPPH: ALTN YGEL (+05MINS EXTRA FUEL)*

YGEL shall be used as ALTN airport effective 25 Apr 2026 following revision of OM-A section
8.3.26 (Operations at Uncontrolled Aerodromes)

2) Everything else regarding fuel planning policy remains the same as last month.

3) Adverse weather conditions*:
RA, TS or TSRA and visibility 5000m or less

(REVISED NO.1/REF EMAIL Summary of Fuel Initiatives Meeting - 08JUN26
For Fuel Committee member/BKKPC)

// (COM-INFO) //

THA 00002/13 (31 MAY 26)

COM INFO:--All A350 and BOEING 787:
are now eligible and included in EUROCONTROL airspace CPDLC Logon list.
Action Required: Pilots are required to initiate CPDLC logon when entering European airspace.

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 2/34

Trans ID: 5041390

Creation Time: 28.06.2026 01:50UTC

(ISSUED 23MAR26/BKKPC2/UFN)

--IN CASE CANNOT BE CONTACTED BKKOC VIA TELEPHONE,
PILOTS MAY CONTACT VIA MS TEAMS CHANNEL: "OC.CENTER".
(ISSUED 30JUL24/BKKOC/UFN)

-- To improve CTOT for all flights both outbound from BKK and inbound to BKK, pilots may contact TOCC when ready for departure to request an earlier CTOT through any of the following channels:

: MS Teams chat
: LINE CLC-Pilot
: CUT 129.325
: Phone 02-137-1202

In addition to above contact channels, for DOMESTIC flight, pilots may also directly contact ground staff to request earlier CTOT. (ISSUED 15FEB25/BKKOP/UFN)

--DELEGATED FUNCTIONS PHONE DIRECTORY (Direct Number)

1. OPEN BOARDING GATE : 02-137-1260
2. BUS GATE - REMOTE BAY & DOMESTIC V.V. : 02-137-1260
3. CREW BUS OPC-TERMINAL V.V. : 02-137-1019, 02-137-1020
4. CONFIRM BOARDING GATE/BAY/BELT : 02-137-1263
5. ZFW/WEIGHT & BALANCE/LOAD SHEET : 02-137-1291, 02-137-1292
6. TG LOST & FOUND : 02-134-5454
7. OTHER INQUIRIES/BKKOC : 02-137-1202

(ISSUED 17JUL22/BKKOC-INFO/UFN)

--If expected divert due to weather or traffic congestion at any TG destination airports, please kindly advise TOCC, via ACARS using OPERATIONS prompt or SITA address BKKOPTG, the current fuel on board immediately to keep close monitoring of the flight.
(ISSUED 08MAY25/BKKOP/UFN)

--In case of pilot receives information from ground staff to delay departure due to connecting passenger, please kindly confirm with TOCC via CUT channel.
(ISSUED 27NOV24/BKKOP/UFN)

--FOR FLIGHTS PLANNED NAVIGATING THROUGH KABUL FIR,
ONCE FINAL FL TO ENTER KABUL FIR IS AVAILABLE,
PLEASE ACARS DOWNLINK ETO/ENTRY WPT/FL TO BKKOPTG
(ISSUED 12DEC24/BKKOC/UFN)

--Please kindly consider and issue recommendation for route P500 G500 as soon as possible in order to reduce operational risk.

1. Due to limitation of passenger oxygen chemical type (22 minutes).

If weather deviation is required, pilots shall deviate west of route only.

2. In an event of critical in-flight emergency, the aircraft should follow ICAO emergency descent procedures, broadcast status and intentions on 125.2 MHZ and 121.5 MHZ. Thereafter, proceed at the discretion of the PIC until clear Kabul FIR and in contact with the ATC responsible for the airspace.

(ISSUED 31JUL24/D1/OC/UFN)

--Any flight operation by TG into the uncontrolled airspace and conflict zone, the latest operational information "Closures and Warnings" issued by means of ICAO State letters,

NOTAMs, AICs/AIPs, and EASA CZIB - TG are subject to strictly following the guidance/directions

from their national authority as well as their own risk assessment.

(ISSUED 15APR24 CORR/TN003/22/OW/UFN)

--WEF 01JUN26,

SUBJ: SPECIAL SECURITY ARRANGEMENT:SSA006/2026

ATTN ALL CONCERNED

THE AVIATION SECURITY COMMITTEE (ASC) MTG ON 21MAY2026
AGREED TO ANNOUNCE SSA006/2026 AS FLWS:

AA PLS BE INFM THT THIS SSA WILL SUPERSEDE SSA005/2026
FROM 01JUN2026 UNTIL FURTHER TLX ADV

BB FR FLT DEP FRM STATION EUROPE: ARN BRU CDG CPH FRA IST LHR MUC
MXP OSL ZRH

LEVEL: LOW CMA PERFORM SSA ACCORDING TO EU REQUIREMENTS
AS FLWS:

A1 - A/C PRE-FLIGHT SECURITY SEARCH CONDUCTED BY PIC CMA
CABIN CREW CMA ASM/SMT/DELEGATED PERSONNEL N GROUND/
STATION ENGINEER

A18-1 5% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
CONDUCTED BY CABIN CREW

CC FR FLT DEP FRM STATION: DAC KHI KTI ISB LHE RGN SAI

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW

DD FR DOM FLT DEP FRM STATION: HDY HKT UBP

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW

EE FR FLT DEP FRM MAINBASE STATION: BKK

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW
F2 - IDENTITY CHECK OF CREW MEMBERS BEFORE BOARDING AT
BOARDING GATE
P2 - SECONDARY CHECK AT GATE
(APPLY ONLY FLT FRM BKK TO MEL PER N SYD)

FF THE FLWG SSA SHALL BE IMPLEMENTED FR ALL ROUTE AS NORMAL PROC
P5 - INTENSIVELY PERFORM IDENTITY CHECK N VERIFICATION OF PAX
BEFORE BOARDING A/C BY
- COMPARING PAX WZ PHOTOGRAPH N PASSPORT/TVL DOCS TO
ENSURE PAX IS BONA FIDE N
- VERIFYING THE NAMES IN THE TICKETS CORRESPOND TO THOSE
ON THE IDENTITY DOCS
V1 - ALERT STAFF TO OBSERVE UNUSUAL BEHAVIOR OF PAX N ALL
PERSONNEL INVOLVED N ANY SUSPICIOUS ITEM IN THE
OPERATING AREA

GG THOSE STN NOT ON THE LIST ABOVE ARE LOW LEVEL STP
APPLY NORMAL SECURITY PROC AS MENTIONED IN OPERATION MANUAL

ADDITIONAL INSTRUCTION.

FR FLT OPS TO BLR MAA N CCU PLS IMPLEMENT THE FLW MEASURES AT THE
CHK-IN COUNTERS;

1. PROV DEDICATED CHK-IN COUNTERS FR FLT TO BLR MAA N CCU
2. DISPLAY WARNING N INFO SIGNAGE AT:
-CHK-IN COUNTERS
-B/D GATE
-FLT INFO DISPLAY SYSTEM (FIDS) AT CHK-IN COUNTERS
3. CONDUCT RANDOM X-RAY SCREENING OF SUSPICIOUS BAG AT CHK-IN
COUNTERS
4. CONDUCT RANDOM SCREENING BY USING SNIFFER DOGS IN THE CHK-IN AREA.

IN CASE OF THREAT SITU N EXTRA MEASURES ARE REQ CMA
STN MONITORING TEAM/SMT MAY RAISE UP MEASURES AS APPROPRIATE

ANY SECURITY INCIDENTS MAY OCCUR SHALL INFO MANAGEMENT CONCERNED
N BKKD1 ACCLY STP

REMARK

A18-1 5% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
WILL BE REVISED IN SPM NEXT REVISION

PLS ACK N CFM ACTUAL PERFORM TO OFC BKKD1-B
BRGDS/CAPT. CHINGCHEEP B./BKKD1 ASC CHAIRMAN

Minima for flight planning

THA 00136/26 (29 MAY 26)

COM INFO: Application of planning minima for flight planning

Due to limited space in the OFP fuel planning box, any display of "BASIC FUEL SCHEME" shall be interpreted as "BASIC FUEL SCHEME WITH VARIATION."

All THAI flights are planned using Basic Fuel Scheme with Variation, unless otherwise specified by Flight Dispatcher.

Alternate planning minima shall be applied in accordance with OMA 8.1.7.5.2.
Display format will be reviewed and updated following stakeholder discussion.

OFP - TCAR format

THA 00093/26 (18 MAY 26)

COM INFO: SFP/OFP change format according to OM-A (TCAR version)

Due to identified limitations in the current OFP template,
the following temporary procedures shall apply with immediate effect:

1. RVSM - Standby Altimeter

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 4/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

The current OFP does not provide a dedicated line for Standby Altimeter recording as required by OMA 14.4.4.

Action: Record the Standby Altimeter value adjacent to the existing record row.

This procedure is mandatory to ensure compliance with OMA 14.4.4.

2. RAIM Information

RAIM shown in the OFP is for terminal operations only.

Action: For flights requiring NPA, crew shall verify RAIM availability separately using an approved RAIM Forecast Report.

3. RCFP - MINF at DP

the displayed MINF at DP may be incorrect.

Action: Disregard the displayed value and refer to the minimum fuel at DP provided in the eOFP application to maintain information consistency.

These instructions are mandatory until corrected in the next OFP version.

FLIGHT LEG INFORMATION

RJAAVTBS

## NRT-HAZARD MAP ##	THA 00172/26 (26 JUN 26)
// (SEE ATTCH) //	
## AIP SUP NR 063/26 ##	THA 00014/26 (09 MAY 26)
// (SEE ATTCH) //	
## REF AIC 051/19 ##	THA 00630/19 (28 JAN 26)
// (SEE ATTCH) //	
## AIC 025/25 ##	THA 00364/25 (28 JAN 26)
// (SEE ATTCH) //	
## AIP SUP 224/25 ##	THA 00362/25 (09 MAY 26)
// (SEE ATTCH) //	
## AIC NR 018/24 ##	THA 00231/24 (18 APR 26)
// (SEE ATTCH) //	

AERODROME INFORMATION

RJAA / NRT

	RJAAA0998/26 (22 JUN 26)
GROOVING FOR RWY 16R/34L PARTLY ERASED DUE TO CONST LEN: 47.5M (BTN 102.0M AND 149.5M FM RWY 16R THR) WID: 38.0M (BTN 0M AND 15.0M ON THE EAST SIDE OF RCL AND BTN 0M AND 23.0M ON THE WEST SIDE OF RCL	
	*RJAAA0982/26 (19 JUN 26)
RCLL FOR RWY 16R/34L PARTLY U/S DUE TO CONST RMK: AVBL FOR TKOF/LDG 19 JUN 26 20:00 UNTIL 03 JUL 26 20:00 ESTIMATED	
	RJAAA0954/26 (17 JUN 26)
SPOT 92 CLSD DUE TO CONST EXC ACFT WITH PRIOR PERMISSION	
	RJAAA0920/26 (10 JUN 26)
STOP-BAR-LGT FOR TWY B1 THRU B9 U/S RMK: REF AIP SUP 063/26 ITEM TWY:5	
	RJAAA0922/26 (10 JUN 26)
"FLW LGT-PARTLY U/S PALS FOR RWY 16L SEQUENCED-FLG-LGT FOR RWY 16L RMK: (1) REF AIP SUP 063/26 ITEM RWY:1,2 (2) THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"	

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 5/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

RJAAA0921/26 (10 JUN 26)

"TWY-CL-LGT FOR A,A2 PARTLY U/S
RMK: REF AIP SUP 063/26 ITEM TWY:2"

// (COM-INFO) //

THA 00211/13 (04 JUN 26)

COM INFO:--CURFEW TIME BETWEEN 1400-2100 UTC (ISSUED 17APR/OW-INFO)

// (COM-INFO)//

THA 00060/26 (04 JUN 26)

RJAA:+++ (NEW)--Temporary Runway shall be used when performing takeoff and landing operations on Runways 16L and 16R.
Runway 16L
Validity Period: 09 MAR 2026 - 10 APR 2026
Runway 16R
Validity Period: 19 MAR 2026 - 30 JUN 2026
(ISSUED 30MAR26/BKKPC/30JUN26)

*RJAAA0850/26 (04 JUN 26)

1510-2030
RWY 16R/34L CLSD DUE TO MAINT.
1.EXC ACFT IN AIC 051/19 ITEM 3
2.EXC EMERG ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR.

*RJAAA0773/26 (04 JUN 26)

1410-2030
RWY 16L/34R CLSD DUE TO MAINT

RJAAA0770/26 (04 JUN 26)

1510-2030
"TWY K (BTN E1 AND K1-HOLD),C (INT OF E1),C (BTN E1 AND P1),E1 CLSD
DUE TO MAINT"

RJAAA0767/26 (04 JUN 26)

REF AIP PAGE RJAA AD2-58 (CHANGE TO READ)
RJAA AD 2.22 FLIGHT PROCEDURES
(V)ATC PROCEDURES
(2)DEPARTURE
(B)INTERSECTION DEPARTURE
REMAINING RUNWAY LENGTH
CHANGE TO READ
RWY / TWY / REMAINING RUNWAY LENGTH
34L A9 3620M(11890FT)
16L B2 2020M(6640FT)
16L B3 2150M(7060FT)
(3)ARRIVAL
(B)SPEEDY TURN-OFF PROCEDURE (B)
DISTANCE FROM THRESHOLD (M/FT)
CHANGE TO READ
RWY / TWY / DISTANCE FROM THRESHOLD (M/FT)
34R B4 1740M(5710FT)
34R B2 2020M(6640FT)
RMK:THIS NOTAM WILL INCORPORATED IN AMDT ON 09 JUL 2026

RJAAA0765/26 (04 JUN 26)

1410-2030
"TWY B,B1 THRU B9,F (BTN F1 AND F3),F (BTN F4 AND F5),F1 THRU F5,
K (BTN B AND B6),C (BTN B AND E1),L (BTN B9 AND U5) CLSD DUE TO MAINT"

RJAAA0764/26 (04 JUN 26)

1510-2030
"TWY A,A1 THRU A10 CLSD DUE TO MAINT
1.EXC ACFT IN AIC 051/19 ITEM 3
2.EXC EMERG ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

RJAAA0722/26 (04 JUN 26)

"VISUAL-DOCKING-GUIDANCE-SYSTEM FOR SPOT 61,66,71,84,85,88,97-U/S
DUE TO CONST"

RJAAA0687/26 (04 JUN 26)

RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT

RJAAA0648/26 (30 APR 26)

"TWY-CL-LGT FOR TWY K (BTN B7 AND E6),L (BTN K AND U5),E2,
E3 (BTN C AND K),C (BTN E5 AND S5),E6 (BTN K AND P),

E7(BTN K AND P),E8,S6(BTN K AND S),S7(BTN K AND T),
T(BTN S7 AND T10),E5(BTN C AND K) U/S DUE TO CONST"

RJAAA0646/26 (30 APR 26)

INTERMEDIATE-HLDG-PSN-LGT FOR TWY K(BTN E2 AND E3) U/S DUE TO
CONST

RJAAA0620/26 (30 APR 26)

SPOT 204 CLSD DUE TO CONST

VTBS / BKK

*VTBDC3500/26 (26 JUN 26)

28 JUN 2026 19:00-28 JUN 2026 23:00
RWY 01/19 CLSD DUE TO WIP

VTBDC3499/26 (26 JUN 26)

28 JUN 2026 19:00-28 JUN 2026 22:30
TXL CLSD DUE TO WIP DETAIL AS FLW:
-TXL T13 BEHIND ACFT STAND NR E2 E4 E6 E8 E10 401 402 403
-TXL T14 BEHIND ACFT STAND NR F1 F3 F5

VTBDC3491/26 (26 JUN 26)

BANGKOK / SUVARNABHUMI INTERNATIONAL AIRPORT PSR U/S

OB Company Safety NOTAM-BKK ##THA 00161/26 (22 JUN 26)

// (SEE ATTCH) //

// (COM-INFO) //THA 00029/26 (18 JUN 26)

COM INFO:--WEF 16FEB26 04:00LT
The operation of opening aircraft doors from outside for all arriving flight
by ground staff at BKK station will be fully implemented.
(refer IOC GB/SS/005-26 date 30JAN 26/UFN)

// (COM-INFO) //THA 00064/25 (18 JUN 26)

COM INFO:--REF AIP SUP A53/25:
RETILs U/S:
RWY 01/19: TWYs B3, B5, B7, B8, B10 and B11
RWY 02R/20L: TWYs E5, E7, E9, E12, E13, E15.

- 1) The Visual Docking Guidance System (VDGS) at the ACFT stands 101 - 114 are U/S. (14 ACFT stands).
- 2) Airlines or Ground service providers shall provide a License Mechanic performed as Marshaller to guide the aircraft from taxilane to the parking position.
- 3) The ACFT are strongly advised to strictly follow the Marshaller's signal. (REF AIP SUP A13/25*)

--Suvarnabhumi:
DVOR/DME (SVB) (133932.5N 1004353.2E) (111.4 MHZ, CH51X) temporary suspended from 28 November 2024 at 0001 UTC to 02 October 2026 at 0949 UTC.
(REF AIP SUP A54/24*)

--Taxiway C between Taxilane T1 and Taxilane T2, Taxiway C1 closed.
(REF AIP SUP A01/25*)

VTBDC2661/26 (07 JUN 26)

"AD 2.24 CHARTS RELATED TO AN AD,
IAC-ICAO CHANGED ALT AT IF AS FLW:
AD2-VTBS 8-9 ILS OR LOC Z RWY 19 CAT II
:READ ALT2500 (2496) INSTEAD OF ALT3000
AD2-VTBS 8-13 ILS OR LOC Z RWY 20L CAT II
:READ ALT3500 (3496) INSTEAD OF ALT4000
AD2-VTBS 8-23 RNP RWY 19 :READ ALT2500 (2496) INSTEAD OF ALT3000
AD2-VTBS 8-25 RNP RWY 20L :READ ALT3500 (3496) INSTEAD OF ALT4000
AD2-VTBS 8-27 RNP RWY 20R :READ ALT3500 (3492) INSTEAD OF ALT4000
REF AIRAC AIP AMDT AD2-VTBS-8-9, AD2-VTBS-8-13, AD2-VTBS-8-23,
AD2-VTBS-8-25, AD2-VTBS-8-27"

VTBDC2039/26 (19 APR 26)

ADVANCED VISUAL DOCKING GUIDANCE SYSTEM (A-VDGS)
ACFT STAND NR 119 308 516 AND 520 U/S DUE TO MAINT
RMK: ACFT HAVE TO FLW MARSHALLING SIGNALS STRICTLY

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 7/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

VTBU / UTP

*VTBDC3302/26 (18 JUN 26)

PALS CAT 1 RWY 18 AND SALS RWY 36 U/S DUE TO MAINT

c3100/26

VTBDC3100/26 (07 JUN 26)

ILS RWY 18 U/S DUE TO MAINT

*VTBDC2844/26 (07 JUN 26)

AD CATEGORY FOR FIRE FIGHTING AND RESCUE SERVICES
DOWNGRADED TO CAT 9.

VTBDC2193/26 (07 JUN 26)

TWY EDGE LGT U/S DUE TO MAINT DETAIL AS FLW:

-TWY B

-TWY E BTN TWY B AND TWY F

VTBDC0333/23 (06 APR 24)

"IAC-ICAO-NDB RWY 36 CHANGED AS FLW:

-OCA/H : STRAIGHT-IN APPROACH

: READ 790(766)FT INSTEAD OF 750(726)FT

-OCA/H : CIRCLING APPROACH CAT A, B

: READ 1200(1141)FT INSTEAD OF 750(726)FT, 1190(1166)FT

-OCA/H : CIRCLING APPROACH CAT C, D

: READ 1450(1391)FT INSTEAD OF 1290(1266)FT, 1445(1421)FT

REF AIP VTBU AD 2.24, AD 2-VTBU-8-1"

ADDITIONAL INFORMATION

VTBD / DMK

*VTBDC3446/26 (24 JUN 26)

24 JUN 2026 16:00-28 JUN 2026 22:00

"24 1600-2200, 26 1500-1600, 27 28 1600-2200"

RWY 03R/21L CLSD DUE TO WIP

*VTBDC3440/26 (24 JUN 26)

25 26 29 1600-2200

RWY 03L/21R CLSD DUE TO WIP

VTBDC1938/26 (19 APR 26)

RAPID EXIT TWY INDICATOR LGT RWY 21R TOWARD RAPID EXIT TWY O U/S

VTBDJ1987/26 (19 APR 26)

"TEMPO RESTRICTED AREA ACT WI 0.5NM CENTRE OF 135526.22N1003713.11E

APPROVAL SHALL BE MADE BEFORE ENTERING, EXCEPT DEP AND ARR ACFT AT

VTBD PILOT IN COMMAND SHALL STRICTLY COMPLY WITH ATC INSTRUCTION"

F) GND

G) 3000FT AGL

// (COM-INFO)//

THA 00435/14 (16 DEC 24)

COM INFO:-- DMK TG LINE MAINTENANCE WILL PROVIDE RAMP HANDLING SERVICE ON

TG FLIGHTS DIVERTED TO DMK, WHILE PIC MUST PERFORM REDUCE LINE CHECK

TO RELEASE AIRCRAFT. PRIOR TO FLIGHT DIVERSION TO DMK PLS INFORM

TOCC COMMAND CENTER (OC) VIA CUT FREQUENCY 129.325 MHZ

TO COORDINATE WITH DMK TG LINE MAINTENANCE IN ADVANCE FOR SMOOTH

HANDLING UPON ARRIVAL AT DMK

CONTACT POINTS FOR DMK LINE MAINTENANCE IN (24hrs)

AT DMK ARE AS FLW

1. TEL: 02-563-8178 (66-8178, 9999)

2. Email dmkjcb@thaiairways.com

(ISSUED 12DEC24/OP/UFN)

VTUU / UBP

VTBDC3445/26 (24 JUN 26)

STRIP RWY 05/23 WIP FM THR RWY 05 TO DIST 442M
ON BOTH SIDES OF RWY 05

VTBDC3444/26 (24 JUN 26)

STRIP RWY 05/23 WIP FM THR RWY 23 TO DIST 442M

ON BOTH SIDES OF RWY 23

*VTBDC3428/26 (23 JUN 26)

"AD OPR HR ATS AND ARO HR SER CHANGED AS FLW:
JUN 23 1320-1415, 24-JUL 07 2300-1400"

VTCC / CNX

VTBDC3516/26 (27 JUN 26)

27 JUN 2026 02:00-28 JUN 2026 16:59
TWY Q BTN TWY F AND ACFT STAND NR 20R CLSD
DUE TO TEMPO ACFT PRKG

VTBDC3490/26 (26 JUN 26)

RVR RWY 36 U/S

VTBDC3385/26 (22 JUN 26)

ACFT STAND NR 5 CLSD DUE TO WIP

VTBDC3386/26 (22 JUN 26)

ACFT STAND NR 6 CLSD DUE TO WIP

VTBDC3333/26 (19 JUN 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS) ACFT STAND NR 3 U/S

VTBDC3306/26 (18 JUN 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS)
ACFT STAND NR 7 AND NR 8 U/S

// (COM-INFO) //THA 00444/15 (17 JUN 26)

VTCC:--REF AIP SUP A19/25:
1 INTRODUCTION
With effect from 17 April 2025 at 1000 UTC,
the purpose of this AIP Supplement is to inform all concerned regarding the Aircraft stand
number 1 closed at Chiang Mai International Airport.
2 DETAILS
Aircraft stand number 1 closed for improvements to enhance aircraft parking compatibility.

VTBDJ4851/26 (07 JUN 26)

"05 0842-1000, 06-30 0130-1000"
UNMANNED AIRCRAFT WILL TAKE PLACE RADIUS 1NM CENTRE
184625.67N0990008.84E
F) GND
G) 300FT AGL

VTBDJ4315/26 (07 JUN 26)

TEMPO RESTRICTED AREA ACT RADIUS 0.5NM CENTRE 184626N0985806E
(EXCLUDING LDG AND TKOF RWY 18/36)
F) GND
G) 3000FT AGL

VTBDC2648/26 (17 JUN 26)

"MAY 15 0412-0800, MAY 16-JUN 30 0200-0800"
OBST MOBILE CRANE HGT 65FT AGL ERECTED AT 184623.96N0985757.21E
DIST 815M BEYOND THR RWY 18 AND 320M LEFT SIDE OF RCL

VTBDC2132/26 (17 JUN 26)

DAILY 0100-1100
OBST MOBILE CRANE HGT 82FT AGL ERECTED AT
184704.31N0985757.46E DIST 390M BFR THR
RWY 18 AND 328M LEFT SIDE OF EXTD RCL

ENROUTE INFORMATION

ASP / ASIA/PACIFIC
N I L

JPN / JAPAN OCEANIC AREA
N I L

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 9/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

RJJJ / FUKUOKA FIR

*RJAAZ0968/26 (28 JUN 26)

28 JUN 2026 01:10-28 JUN 2026 14:00
"FLOW CTL AT FIR BDRY AS FLWS,
RTE: B576/Y742
ACFT: SB FOR RCTP,RCSS,RCMQ AND RCKH DEP FM KOREA
PROC: FL370 OR ABV NOT AVBL AT ATOTI AND MUGUS
RMK: REF AIP ENR1.9-1"

RJAAQ1508/26 (27 JUN 26)

28 JUN 2026 07:00-28 JUN 2026 21:00
"EASTBOUND PACOTS TRACKS BETWEEN SOUTHEAST ASIA AND NORTH AMERICA,
TRACK 14.
FLEX ROUTE : LEPKI 40N160E 43N170E 45N180E 45N170W 45N160W
45N150W 42N140W 38N130W ALLBE
RCTP/VHHH ROUTE : MOLKA M750 MUKEP Y891 OVSUN Y893 IGMIS Y57 POROT
Y809 AVBET OTR11 LEPKI
NAR ROUTE : ACFT LDG KSFO--ALLBE PIRAT OSI KSFO
ACFT LDG KLAX--ALLBE PIRAT BURGL IRNMN KLAX
RMK : TRK 15 NOT AVAILABLE
ATM CENTER TEL:81-92-608-8870"

RJAAQ1507/26 (27 JUN 26)

28 JUN 2026 10:00-28 JUN 2026 21:00
"EASTBOUND PACOTS TRACKS BETWEEN JAPAN AND HAWAII,
TRACK 11.
FLEX ROUTE : SEALS 36N150E 36N160E 33N170E 30N180E 26N170W DOGIF
CANON
JAPAN ROUTE : LAPIL OTR13 SEALS
PHNL ROUTE : CANON BOOKE PHNL
RMK : TRK 12 NOT AVAILABLE
ATM CENTER TEL:81-92-608-8870"

RJAAQ1506/26 (27 JUN 26)

28 JUN 2026 07:00-28 JUN 2026 21:00
"EASTBOUND PACOTS TRACKS BETWEEN JAPAN AND NORTH AMERICA,
TRACK 1.
FLEX ROUTE : KALNA 43N160E 46N170E 49N180E 50N170W 51N160W 52N150W
51N140W ORNAI
JAPAN ROUTE : ADNAP OTR5 KALNA
NAR ROUTE : ACFT LDG KSEA/KPDX--ORNAI TOU KSEA/KPDX
RMK : ACFT LDG CYVR--52N150W 52N140W MANJO POWOL CYVR
ACFT LDG OTHER DEST--ORNAI UPR TO DEST
TRACK 2.
FLEX ROUTE : EMRON 42N160E 45N170E 47N180E 48N170W 48N160W 48N150W
46N140W 42N130W VESPA
JAPAN ROUTE : ADNAP OTR7 EMRON
NAR ROUTE : ACFT LDG KSFO--VESPA AMAKR BGGLO KSFO
ACFT LDG KLAX--VESPA ENI OAK BURGL IRNMN KLAX
TRACK 3.
FLEX ROUTE : LEPKI 41N160E 44N170E 46N180E 47N170W 47N160W 47N150W
44N140W 40N130W DACEM
JAPAN ROUTE : AVBET OTR11 LEPKI
NAR ROUTE : ACFT LDG KLAX--DACEM PAINT PIRAT BURGL IRNMN KLAX
ACFT LDG KSFO--DACEM PAINT PIRAT OSI KSFO
RMK : ATM CENTER TEL:81-92-608-8870"

RJAAY0656/26 (27 JUN 26)

27 JUN 2026 11:32-28 JUN 2026 16:00
"FLOW CTL AS FLWS,
AREA: ATS RTE A1/G581/Y26/Y52
PROC: EXP DEP CLR TIME WILL BE ISSUED TO ACFT FOR MANILA FIR AND
BEYOND VIA KABAM
RMK: REF AIP ENR1.9-1"

RJAAZ0964/26 (27 JUN 26)

27 JUN 2026 11:30-28 JUN 2026 16:00
"FLOW CTL AT FIR BDRY AS FLWS,
RTE: B576/Y742
ACFT: SB FOR MANILA FIR AND BEYOND VIA KABAM FM KOREA
PROC:(1) 12 MIN INTERVAL REGARDLESS OF ALT WILL BE APPLIED AT
ATOTI,MUGUS
(2) ATOTI,MUGUS ONLY FM KOREA
RMK: REF AIP ENR1.9-1"

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 10/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

*RJAAQ1505/26 (27 JUN 26)

"CDR ARE ESTABLISHED AS FLW,
RTE PERIOD MNM APPLICABLE ALT
1) L512 2606281200/2606282200 MEA
2) Z13 2606272200/2606282200 MEA
3) Z14 2606272200/2606282200 MEA
4) Z25 2606272200/2606282200 MEA
5) Z26 2606272200/2606282200 MEA
6) Z27 2606272200/2606282200 MEA
7) Z40 2606272200/2606282200 MEA
8) Z41 2606272200/2606282200 MEA
9) Z262 2606272200/2606282200 MEA
RMK: REF AIP ENR3.3"

*RJAAQ1504/26 (27 JUN 26)

"CDR ARE ESTABLISHED AS FLW,
RTE PERIOD MNM APPLICABLE ALT
1) Z16 2606272100/2606272200 MEA
Z16 2606281200/2606282100 MEA
2) Z17 2606272100/2606272200 MEA
Z17 2606281200/2606282100 MEA
3) Z18 2606272100/2606272200 MEA
Z18 2606281200/2606282100 MEA
4) Z21 2606272100/2606272200 MEA
Z21 2606281200/2606282100 MEA
5) Z101 2606272100/2606282100 MEA
6) Z102 2606272100/2606282100 MEA
7) Z162 2606272100/2606272200 MEA
Z162 2606281200/2606282100 MEA
8) Z171 2606272100/2606272200 MEA
Z171 2606281200/2606282100 MEA
9) Z182 2606272100/2606272200 MEA
Z182 2606281200/2606282100 MEA
RMK: REF AIP ENR3.3"

*RJAAQ1503/26 (27 JUN 26)

"CDR ARE ESTABLISHED AS FLW,
RTE PERIOD MNM APPLICABLE ALT
1) Z29 2606281500/2606282100 MEA
2) Z31 2606281500/2606282100 MEA
3) Z32 2606281500/2606282100 MEA
4) Z34 2606281500/2606282100 MEA
RMK: REF AIP ENR3.3"

RJAAQ1383/26 (25 JUN 26)

REF AIP SUP 073/26 (CHANGE TO READ)
NO LONGER IN FORCE
LAUNCH OF ROCKET H3-F6 WAS COMPLETED

RJAAZ0810/26 (25 JUN 26)

1910-2200
"FLOW CTL AT FIR BDRY AS FLWS,
RTE: B576/Y741/Y743
ACFT: NB ENTERING INCHEON FIR
PROC: FL390 NOT AVBL AT SALMI AND LIPLO
RMK: REF AIP ENR1.9-1"

*RJAAP2607/26 (07 JUN 26)

21 JUN 2026 22:00-28 JUN 2026 12:00
2200-1200
FRNG EXER
AREA: BOUNDED BY FLW POINTS
370011N1345950E - 372211N1353949E - 370211N1353949E - 364011N1345950E
- 370011N1345950E
(N OF WAKASA-WAN/THE-HIGH-SEAS)
F) SFC
G) 50000FT AMSL

*RJAAP2608/26 (07 JUN 26)

21 JUN 2026 21:00-28 JUN 2026 09:00
2100-0900
FRNG EXER
AREA : RADIUS 25NM CENTER 311414N1442648E
(SE OF HACHIJOJIMA/THE-HIGH-SEAS)
F) SFC
G) 60000FT AMSL

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 11/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

RJAAQ1173/26 (22 MAY 26)

OPERATORS OF AIRCRAFT REGISTERED IN JAPAN ARE ADVISED NOT TO ENTER
MINSK(UMMV) FIR DUE TO SERIOUS SAFETY AND SECURITY CONCERNS TO
COMMERCIAL AVIATION.

19 MAY 26 00:54 UNTIL 18 AUG 26 14:59 ESTIMATED

RJAAP2331/26 (18 MAY 26)

"ALL ACFT INTENDING TO FLY WI FUKUOKA FIR ARE ADVISED TO PAY
SPECIAL ATTENTION TO THE FOLLOWING INFORMATION.
IN ACCORDANCE WITH ARTICLE 82-3 OF JAPAN SELF DEFENSE FORCE LAW,
ANTIBALLISTIC MISSILES MAY BE LAUNCHED FOR THE DESTRUCTION OF THE
ROCKET EXPECTED TO BE LAUNCHED FROM NORTH KOREA.

THE ANTIBALLISTIC MISSILES ARE DEPLOYED AT POSITIONS BLW,

(1)NAHA-SHI : 261219N1273929E

(2)MIYAKOJIMA : 244602N1251930E

(3)ISHIGAKIJIMA : 242404N1241121E

(4)YONAGUNIJIMA : 242638N1225716E"

F) SFC

G) UNL

18 MAY 26 08:35 UNTIL 17 AUG 26 15:00 ESTIMATED

// (COM-INFO) //

THA 00046/20 (13 MAY 26)

COM INFO:--FOR DATA LINK COST-EFFICIENT OPERATIONS:

1) PREFLIGHT:

VERIFY BOTH HF SET TO VOICE MODE

DISREGARD MEMO MESSAGE ABOUT HF DATALINK

NOTE: HF SHALL BE SET TO DATA IF BOTH VHF (DATA) AND SAT (DATA) ARE LOST

2) IN FLIGHT PROCEDURE:

WHEN ENTERING JAPANS FIR .. SET ACARS VHF TO VOICE

WHEN EXITING JAPANS FIR .. SET ACARS VHF TO DATA

IF SATCOM DATA IS UNSERVICEABLE,

SET VHF3 BACK TO DATA TO RECOVER DATALINK CAPABILITY.

(ISSUED 02JAN25/TN001/25/OP/UFN)

--AWY A593 (ONIKU-NIRAT-SADLI-LAMEN) (FUKUOKA FIR-INCHEON FIR-SHANGHAI FIR)

FOLLOWING ALTITUDE ARE USED BY FUKUOKA ACC:

WESTBOUND: FL240, FL280 OR FL300, FL400,

EASTBOUND: FL250, FL290 OR FL310, FL390

(ISSUED 27JUN/REF AIP REPUBLIC OF KOREA/OW/UFN)

RJAAP2070/26 (30 APR 26)

REF AIP SUP 073/26 (CHANGE TO READ)

3. UNUSABLE FLIGHT PROCEDURES ETC.

3-1. UNUSABLE FLIGHT PROCEDURES ETC.

CHANGE TO READ

(2) FROM 10 MINUTES PRIOR TO THE ROCKET LAUNCH UNTIL THE PASSAGE OF
THE ROCKET FROM THE AREA OF 2.(2) IS IDENTIFIED:

DELETE TEXT

7) AWY

A339(BTN SABGU AND KEITH)

R584(BTN SALVA AND KEITH)

R595(BTN SALVA AND KEITH)

ADD IN TEXT

(3) FROM 10 MINUTES PRIOR TO THE LAUNCH UNTIL THE IMPACT OF THE 1ST
STAGE MAIN ENGINE:

CANCELLATION OF THE UNUSABLE AWY AND RNAV5 ROUTE WILL BE NOTIFIED BY
FURTHER NOTAM RJJJ.

(FOR RNP10 AIRCRAFT AND NON-RNP10 AIRCRAFT)

A339(BTN SABGU AND KEITH)

R584(BTN SALVA AND KEITH)

R595(BTN SALVA AND KEITH)

TWN / TAIWAN

N I L

RCAA / TAIPEI FIR

RCTPA2136/26 (27 JUN 26)

27 JUN 2026 12:45-28 JUN 2026 16:00

"CONSEQUENT TO FLOW CTL IMPOSED BY MANILA ACC, FLOW CTL AT FIR

BDRY AS FLW:

ACFT DEP FM KOREA/JAPAN OVERFLYING TAIPEI FIR ENTERING MANILA FIR

VIA KABAM IS SUBJECT TO THE FLW RESTRICTIONS:

(1) 10 MIN INTERVAL REGARDLESS OF ALT AT SALMI

(2) 15 MIN INTERVAL REGARDLESS OF ALT AT BULAN

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 12/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

(3) 12 MIN INTERVAL REGARDLESS OF ALT AT IGURU
(DEP FM KOREA VIA SALMI ONLY)
(DEP FM JAPAN VIA BULAN/IGURU ONLY)"

*RCTPA1725/26 (07 JUN 26)

1800-2100
FLOW CTL AT FIR BDRY AS FLW:
1.RTE: M750
2.ACFT: NB FOR ENTERING RKRR
3.PROC: FL390 NOT AVBL AT ENVAR

*RCTPA0638/26 (19 MAR 26)

"AIP SUP 07/26 WEF 10 APR 2026 TIL 30 JUN 2026, ALTERNATE ROUTES
AND MEASURES FOR AIRSPACE BLOCKED DUE TO FLIGHT TESTING
(APR TO JUN 2026)."

RCTPA0600/26 (11 MAR 26)

"REF AIP SUP 06/26, AIR TRAFFIC FLOW MANAGEMENT (ATFM),
TAIPEI AIR TRAFFIC FLOW MANAGEMENT UNIT (ATFMU)
BEGINS OPERATIONS AT 16 MAR 2026, 0000 UTC.
RMK: FOR QUERY, CONTACT TAIPEI ATFMU
TEL +886-3-3841090, +886-3-3841091, +886-3-3841092."
16 MAR 26 00:00 UNTIL 31 MAR 27 23:59 ESTIMATED

RCTPA0135/25 (28 JAN 25)

"REF AIP SUP 06/24 UNSERVICEABILITY OF LUDAO VOR GID,
END DATE OF THIS SUP REVISED AS 31 DEC 2026.
THE REST NC."
17 JAN 25 02:00 UNTIL 31 DEC 26 23:59 ESTIMATED

HKG / HONG KONG
N I L

VHHK / HONG KONG FIR

*VHHHA1163/26 (02 JUN 26)

DAILY 1700-2030
"DUE TO RESTRICTION FROM TAIPEI ACC (REFER TO NOTAM RCAA
A1725/26),
OVERFLYING ACFT ENTERING HONG KONG FIR VIA IKELA EXITING ENVAR
ENTERING RKRR, FL390 NOT AVBL AT IKELA.
(RMK: RESTRICTION MAY BE ADJUSTED SUBJECT TO SITUATION AND
DISCRETION OF HONG KONG ATS FLOW MANAGER.)"

VHHHA1155/26 (01 JUN 26)

01 03 04 08 10 11 15 17 22 23 24 25 29 2315-0600
"DUE TO SURVEILLANCE EQUIPMENT CAPABILITY, ACFT OPERATING
ON IFR FPL WITHOUT SERVICABLE ADS-B OUT ARE NOT PERMITTED
TO OPERATE WI VHHK OR DEPART FROM VHHH.
EXEMPTION MAY BE GRANTED WITH PRIOR COOR VIA HONG KONG ATS WATCH
SUPERVISOR.
REFER TO AIP HK GEN 1.5 PARAGRAPH 3.7.6 FOR REQUIREMENTS FOR ADS-B
OUT EQUIPAGE."

**** A1048/26 ****

VHHHA1048/26 (25 MAY 26)

"REF AIP HK ENR 1.8 PARA 8C, FLAS BTN HONG KONG FIR AND SANYA
FIR/CONTROL AREA FOR ROUTES A202 AND R339, CHANGES AS FLW:
HONG KONG FIR TO SANYA CONTROL AREA:
1) FLAS FOR A202, POINTS BEYOND ASSAD:
S0840 (SUBJ COOR), S1040, S1160, S1220
2) FLAS FOR R339, POINTS BEYOND NANNING:
S0840 (SUBJ COOR), S0980, S1040, S1100, S1160, S1220"

VHHHA0738/26 (25 MAY 26)

DAILY 1600-2030
"FOR TRAFFIC OVERFLYING HONG KONG FIR VIA ATS ROUTE A1 OR PBN
ROUTE
P901 TO ENVAR M750 DESTINED FOR INCHEON FIR. DUE TO DOWNSTREAM ACC'S
REQUIREMENT, 5 MINUTES CONSTANT OR INCREASING LONGITUDINAL
SEPARATION BETWEEN FLIGHTS AT THE SAME LEVEL SHALL BE PROVIDED AT
IKELA.
RMK: RESTRICTION MAY BE ADJUSTED SUBJECT TO SITUATION AND DISCRETION
OF HONG KONG ATS FLOW MANAGER."

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

CHN / CHINA
N I L

CH2 / CHINA SANYA
N I L

ZJSA / SANYA FIR

ZBBBA0783/26 (23 MAR 26)

"SANYA FIR(ZJSA)EXECUTE OCS(ONE CTOT SOLUTION)PROCEDURE,ALL ACFT
OVERFLYING SANYA FIR(ZJSA) SHALL OPERATE CTOT (CALCULATED TAKE OFF
TIME) .
EXECUTION BY CTOT(CALCULATED TAKE OFF TIME) ."

VNM / VIETNAM
N I L

VVHM / HO CHI MINH FIR

VVVVA2128/26 (27 JUN 26)

28 JUN 2026 00:00-28 JUN 2026 11:30
AIRBORNE GRAVITY SURVEY FLT WILL TAKE PLACE WI:
140318N1073127E - 140300N1075746E - 131408N1075709E
131418N1074112E - 132427N1074259E - 133340N1074209E
133830N1073943E - 134255N1073845E - 134814N1073604E -
135003N1073412E - 140318N1073127E
F) 2000M AGL
G) 4000M AGL

VVVVA2129/26 (27 JUN 26)

28 JUN 2026 00:00-28 JUN 2026 11:30
AIRBORNE GRAVITY SURVEY FLT WILL TAKE PLACE WI:
140304N1075213E - 140232N1083306E - 132309N1083230E
131333N1084150E - 131412N1075137E - 140304N1075213E
F) 2000M AGL
G) 4000M AGL

VVVVA1539/26 (22 MAY 26)

"RADIO CHECK ON THE FOLLOWING FREQ DRG PERIODS OF LOW AIR
TFC DENSITY, NO ADVERSE WX PHENOMENA:
- SECTOR 1: 134.050 MHZ (PRI), 125.375 MHZ (SRY)
- SECTOR 2: 120.100 MHZ (PRI), 128.775 MHZ (SRY)
- SECTOR 3: 120.900 MHZ (PRI), 133.850 MHZ (SRY)
- SECTOR 4: 133.050 MHZ (PRI), 119.350 MHZ (SRY)
- SECTOR 5: 120.700 MHZ (PRI), 133.150 MHZ (SRY)
- SECTOR 6: 132.350 MHZ (PRI), 128.775 MHZ (SRY)
- SECTOR 7: 128.175 MHZ (PRI), 133.850 MHZ (SRY)
- EMERG: 121.500 MHZ
- TAN SON NHAT TMC: 125.500 MHZ (PRI), 124.075 MHZ (SRY)
- TAN SON NHAT ARR: 126.350 MHZ (PRI), 127.725 MHZ (SRY)
- HF ACC HO CHI MINH: 11297/11396/13300/5655/8942 KHZ."

LAO / LAOS
N I L

VLVT / VIENTIANE FIR

*VLVTA0130/26 (24 JUN 26)

27 JUN 2026 02:00-28 JUN 2026 12:00
DAILY 0200-1200
ROCKET (BANGFAI) FRNG WILL TAKE PLACE RADIUS 6NM CENTER
183254.6N1015816.5E (NONHINHAIE VILLAGE FEUANG DISTRICT
VIENTIANE PROVINCE). ALL ACFT ARE FLW ATC INSTRUCTION.
F) GND
G) FL410

VLVTA0094/26 (08 MAY 26)

PAKSE VOR/DME 'PAK' 115.00MHZ/CH97X LIMITED TO USE:
1. DVOR/DME U/S ON RADIAL 119DEG-299DEG CLOCKWISE.
2. DOVR/DME U/S ON RADIAL 010DEG-190DEG CLOCKWISE.
08 MAY 26 04:05 UNTIL 08 AUG 26 23:59 ESTIMATED

THA / THAILAND
N I L

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 14/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

VTBB / BANGKOK FIR

*VTBDJ5255/26 (26 JUN 26)

28 JUN 2026 02:00-28 JUN 2026 10:00
"ROCKET (BANGFAI) FRNG WILL TAKE PLACE RADIUS 5NM CENTRE
155346.98N1041032.21E (MUEANG DISTRICT YASOTHON PROVINCE)
RMK: COOR CTC TEL +668 1393 0595, +669 0912 1201"
F) GND
G) 19000FT AGL

VTBDC3430/26 (23 JUN 26)

"ALL ACFT VIA RTE B346, R474, W21 AND G473 ADVICE CTC
BANGKOK ACC PRI FREQ 126.500MHZ AND SRY FREQ 122.00MHZ
DUE TO RADIO FREQ INTERFERENCE"

*VTBDJ5189/26 (22 JUN 26)

28 JUN 2026 01:00-28 JUN 2026 11:00
"ROCKET (BANGFAI) FRNG WILL TAKE PLACE RADIUS 5NM CENTRE
160423.2N1033133.9E (MUEANG DISTRICT ROI ET PROVINCE)
RMK: COOR CTC TEL +668 1574 7345, +668 1739 2397"
F) GND
G) 12000FT AGL

VTBDC2855/26 (26 MAY 26)

"AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM
THE DEMOCRATIC REPUBLIC OF THE CONGO AND THE REPUBLIC OF UGANDA
1. PURSUANT TO THE RESOLUTION OF THE NATIONAL COMMUNICABLE DISEASE
COMMITTEE, EFFECTIVE FROM 27 MAY 2026 AT 1800 HOURS (LOCAL TIME)
ONWARDS, PASSENGERS AND CREW MEMBERS DEPARTING FROM THE DEMOCRATIC
REPUBLIC OF THE CONGO (DR CONGO) AND THE REPUBLIC OF UGANDA SHALL BE
PERMITTED TO ENTER THE KINGDOM OF THAILAND ONLY VIA SUVARNABHUMI
AIRPORT AND SHALL BE SUBJECT TO A MANDATORY QUARANTINE PERIOD OF
TWENTY-ONE (21) DAYS, CALCULATED FROM THE DATE OF DEPARTURE FROM
THE AFFECTED AREAS, IN ACCORDANCE WITH THE PRESCRIBED PUBLIC
HEALTH PROCEDURES.
2. ALL AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM
THE ABOVE-MENTIONED AREAS ARE REQUESTED TO COMPLY WITH AND IMPLEMENT
THE PRESCRIBED MEASURES ACCORDINGLY."

// (COM-INFO) //

THA 00126/26 (14 MAY 26)

COM INFO:--REF AIP SUP A19/26;

1

INTRODUCTION

With effect from 14 May 2026 at 0001 UTC to 31 December 2026 at 0001 UTC, the purpose of this
AIRAC AIP Supplement is to inform all
concerned regarding Temporary suspension of SURAT THANI DVOR/DME (STN) due to relocation
details are as follows.

2

THE PERIOD OF TEMPORARY SUSPENSION

STN DVOR/DME will be temporarily suspension from 14 May 2026 at 0001 UTC to 31 December 2026
at 0001 UTC.

3

FLIGHT PROCEDURE

A temporary reporting point name SAPUD (090746.24N 0990805.09E) will be established at the
same coordinates of SURAT THANI DVOR/
DME (STN) for ATS routes G458, W17, W24, W28, W32 and Y8 and a portion of ATS route G458
between STN and MENEX will be suspended
until STN normal operations resume.

4

FLIGHT PLANNING PROCEDURES

Reference to the AIP-THAILAND part ENR 1.10 item 4.1.1.1, 4.1.1.2 a, 4.1.1.2 b, 4.1.1.3 a,
4.1.1.3 b non-RNAV2 approved aircraft. To maintain
efficiency of ATS during SURAT THANI DVOR/DME (STN) relocation, non-RNAV approved aircraft
that intend to operate on G458 between
SAPUD and MENEX shall file flight plan, depending on ACFT capability.

5

CONTACT

Unit: Air Traffic Navigation Systems Engineering Department, Aeronautical Radio of Thailand
Ltd.

Email: pariwat.ch@aerorhai.co.th

6

VALIDITY

This AIRAC AIP Supplement will remain current until 31 December 2026 at 0001 UTC. Any changes
to this AIRAC AIP Supplement will be
notified by NOTAM.

VTBDJ3551/26 (14 MAY 26)

DAILY 0100-0230 0600-1130
"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA 5NM EITHER SIDE OF
A LINE:151638.34N1001745.12E-145407.02N1004920.52E-
143000.00N1022800.00E-143107.26N1051100.12E
(CHAINAT, NAKHON SAWAN, LOP BURI, SURIN, SI SA KET,
UBON RATCHATHANI, BURI RAM AND NAKHON RATCHASIMA PROVINCE)
RMK: ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR VECTORED
BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC"
F) FL150
G) FL200

VTBDC2184/26 (20 APR 26)

"DUE TO VT D41A ACT FPL PROC FOR ACFT OPR FM/TO VTCC DETAIL AS FLW:
1. PERIOD MON-FRI 0000-1100
DEP/OVERFLY DEST/OVERFLY RTE
VTCC VTCT W12 IKISU W22
VTCC PONUK R207 IKISU W22 CTR A581
VTCT VTCC W22 IKISU W12
PONUK VTCC Y27 DUBEN Y28 CRIST R207 (FOR RNAV)
PONUK VTCC A581 CTR W22 IKISU R207 (FOR NON-RNAV)
2. PERIOD MON-FRI 1101-2359, SAT SUN H24
DEP/OVERFLY DEST/OVERFLY RTE
VTCC VTCT W20
VTCC PONUK A581
VTCT VTCC W20
PONUK VTCC A581"

VTBDJ2001/26 (05 APR 26)

"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA :
144705N1033019E - 143541N1051246E - 142051N1051232E -
141826N1030616E - 142521N1030558E - 144705N1033019E
(SI SAKET, UBON RATCHATHANI, BURIRAM AND SURIN PROVINCE
EXCLUDING PHNOM PENH FIR)
RMK : ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR
VECTORED BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC."
F) 8000FT AMSL
G) FL170

AEROPLANE INFORMATION

AIRCRAFT CATEGORY = D
N I L

AIRCRAFT TYPE = B777
N I L

AIRCRAFT SUBTYPE = B773E
N I L

AIRCRAFT REGISTRATION = HSTTC
N I L

ADDITIONAL INFORMATION

VHHH / HKG

VHHHA1388/26 (26 JUN 26)

28 JUN 2026 18:01-28 JUN 2026 22:45
THE FLW TWY CLSD DUE WIP:
TWY W BTN TWY B AND TXL W2
TWY V1

VHHHA1389/26 (26 JUN 26)

28 JUN 2026 18:01-28 JUN 2026 23:30
THE FLW TWY CLSD DUE WIP:
TWY B12
TWY F WEST OF TXL E4
TWY F1 SOUTH OF TWY E
TWY F2 SOUTH OF TWY E
TWY A1 NORTH OF TWY B
TWY A2 NORTH OF TWY B
TWY A BTN TXL P AND TWY S

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 16/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

// (COM-INFO)//

THA 00281/17 (17 MAY 26)

VHHH:--REF AIP SUP 27/25:

1 Introduction

1.1 This AIP SUP promulgates the runway closure programme and associated closure period.

2 Runway Closure Programme

2.1 RWY 07L/25R (North Runway) will be closed for 5 nights per week, either on Standby or Maintenance.

2.2 RWY 07C/25C (Centre Runway) will be closed for 2 nights per week, on Maintenance only.

2.3 RWY 07R/25L (South Runway) will be closed for 7 nights per week, either on Standby or Maintenance

-Runway RWY 07L/25R(North Runway)

Closure Mode Standby:

Closure Period (UTC) 1800-2259

Days of Closure (UTC)

Every Monday, Wednesday and Saturday

Closure Mode Maintenance:

Closure Period (UTC) 1800-2359

Days of Closure (UTC)

Every Tuesday and Thursday

-Runway RWY 07C/25C(Centre Runway)

Closure Mode Maintenance:

Closure Period (UTC) 1800-2359

Days of Closure (UTC)

Every Sunday and Friday

-Runway RWY 07R/25L(South Runway)

Closure Mode Standby:

Closure Period (UTC) 1800-2259

Days of Closure (UTC)

Every Sunday, Tuesday, Thursday and Friday

Closure Mode Maintenance:

Closure Period (UTC) 1800-2359

Days of Closure (UTC)

Every Monday, Wednesday and Saturday

3 Runway Availability During Closure Periods

3.1 In the event that the operational runway becomes unavailable, the closed runway on Standby will be available within

20 minutes. Dependent on the work being carried out at the time, it may take up to 2 hours for a closed runway on

Maintenance to return to services.

4 Revisions to Runway Closure Programme

4.1 The runway closure schedule may be revised in the event of forecast or actual adverse weather conditions or other extenuating circumstances.

4.2 Any revision to the runway closure programme will be promulgated by NOTAM.

// (COM-INFO)//

THA 00072/26 (17 MAY 26)

VHHH:+++ (NEW) --Effective from 23 Mar 26 until further notice, applicable to all Airbus* aircraft types as follows:

Please modify altitude constraint at waypoint VH515 from "At or above 4 300 ft" to "At 4 500 ft" to reduce the probability of missed altitude constraints along the ILS approach to runway 25R.

This modification will create a pseudo continuous descent path starting at VH515 and will reduce the number of vertical transitions.
(ISSUED 23MAR26/BKKDP/UFN)

VHHHA0805/26 (17 MAY 26)

"REF AIP HK VHHH AD 2.8 PARA. 3 MAINTENANCE AND LONG TERM PARKING APRON, COORDINATES FOR STOP LOCATION OF ACFT STANDS L424, L425 AND L426 AMD AS FLW:

- STAND L424 : 221828.80N 1135425.85E

- STAND L425 : 221826.57N 1135426.67E

- STAND L426 : 221824.35N 1135427.50E"

VHHHA0523/26 (17 MAY 26)

"REF AIP HK VHHH AD 2.8 PARA. 3 MAINTENANCE AND LONG TERM
PARKING APRON, COORDINATES FOR STOP LOCATION OF ACFT STANDS L421,
L422 AND L423 AMD AS FLW:
-STAND L421 : 221835.48N 1135423.36E
-STAND L422 : 221833.26N 1135424.19E
-STAND L423 : 221831.03N 1135425.02E"

VTSP / HKT

VTBDC3381/26 (22 JUN 26)

ACFT STAND NR 9 CLSD DUE TO WIP

VTBDC3380/26 (22 JUN 26)

ACFT STAND NR 10 CLSD DUE TO WIP

VTBDJ5144/26 (19 JUN 26)

DAILY 0100-1000
UNMANNED AIRCRAFT WILL TAKE PLACE
RADIUS 1.3NM CENTRE 080510.87N 0982201.96E.
F) GND
G) 295FT AGL

// (COM-INFO)//

THA 00094/26 (04 JUN 26)

VTSP:--REF AIP SUP A18/26:
1 INTRODUCTION
With effect from 5 May 2026 at 0101 UTC. The purpose of this AIP Supplement is to inform
pilots and operators concerning the Visual Docking
Guidance System (VDGS) of aircraft stand number 31 at Phuket International Airport (VTSP).
2 DETAILS
2.1 The Visual Docking Guidance System (VDGS) of aircraft stand number 31 is unserviceable.
2.2 The aircraft are strongly advised to strictly follow the Marshallers signal.

VTBDC2995/26 (04 JUN 26)

RVR RWY 09/27 U/S

VTBDC2924/26 (04 JUN 26)

RWY CLOSURE FOR MAINT WORKS AT PHUKET INTERNATIONAL AIRPORT
(VTSP) (MARCH-OCTOBER 2026)
ITEM 2. CLOSURE AREAS AND PERIODS OF RWY PREVENTIVE MAINT
AMEND AS FLW:
MONTH DATES PERIOD OF CLOSURE
MAY 31 1730-2330
JUN 01-09 23 1730-2330
JUL 07 21 1815-2330
AUG 04 1815-2330
REF AIRAC AIP SUP A14/26

RJTT / HND

RJAAJ1410/26 (27 JUN 26)

OBST DAY MARKING ERASED
TYPE: CHIMNEY
PSN: 353046.7N1394420.4E ELEV: 245FT AMSL
(KAWASAKI-SHI IN KANAGAWA

RJAAE3272/26 (27 JUN 26)

28 JUN 2026 14:30-28 JUN 2026 21:00
"TWY A3,A4,A9,A11,A14,L3,L4,L9,L11,L13,L14 CLSD DUE TO CONST"

RJAAE3231/26 (25 JUN 26)

26 30 1530-2130
TWY C1 THRU C14 CLSD DUE TO MAINT

*RJAAJ1401/26 (25 JUN 26)

26 30 1530-2130
RWY 16L/34R CLSD DUE TO MAINT
RMK: SEE AIP RJTT AD2.23

RJAAE3109/26 (20 JUN 26)

28 JUN 2026 15:00-28 JUN 2026 21:00
"TWY J (BTN R AND W), J1 (BTN J AND K), J2 (BTN J AND K)

CLSD DUE TO CONST."

RJAAE3108/26 (20 JUN 26)

28 JUN 2026 15:00-28 JUN 2026 21:00
"TWY P3,P4,P(BTN P3 AND P8),P(INT OF P3),L(INT OF L3),L(BTN L3 AND L4) CLSD DUE TO CONST"

RJAAE3107/26 (20 JUN 26)

28 JUN 2026 15:00-28 JUN 2026 21:00
"TWY A (BTN W6 AND W11), W9, W10 CLSD DUE TO CONST."

NAV DATABASE ADDENDUM ##THA 00169/26 (18 JUN 26)

// (SEE ATTCH) //

// (COM-INFO)//THA 00140/26 (18 JUN 26)

RJTT:--SUBJ: GATE/SPOT ASSIGNMENT AT HND DURING 01JUN26-30JUN26

AA.. DATE: 01JUN26-30JUN26

TG682 ARR AT GATE/SPOT 141 (TOWING OUT 132)
TG683 DEP AT GATE/SPOT 145

BB.. DATE: 01JUN26-30JUN26

TG660 ARR AT GATE/SPOT 105P
TG661 DEP AT GATE/SPOT 105P

EXCEPT FOLLOWING DAYS
TG660/24JUN AT GATE 108
TG661/25JUN/DEP AT GATE 108

KINDLY BE REPORTED ACCORDINGLY STP
BRGDS/HNDKP K.NAGASE

RJAAJ1321/26 (18 JUN 26)

0200-1300
FOUNTAIN:
PLACE : 353745N1394612E
(APRX QTE/353DEG 4.6NM FM RJTT ARP)
(MINATO-KU IN TOKYO)
WX COND: VMC ONLY
F) SFC
G) 493FT AMSL

RJAAJ1290/26 (18 JUN 26)

0100-0800
UNMANNED ACFT:
AREA: BOUNDED BY FLW POINTS
353943N1394556E - 353954N1394609E - 353944N1394622E - 353934N1394609E
- 353943N1394556E
(CHUO-KU IN TOKYO)
WT: 2.1KG
RMK: THIS NOTAM WILL BE INCORPORATED IN SUP
F) SFC
G) 683FT AMSL

RJAAJ1289/26 (18 JUN 26)

0000-0700
UNMANNED ACFT:
AREA: BOUNDED BY FLW POINTS
353943N1394557E - 353945N1394559E - 353943N1394601E - 353939N1394608E
- 353937N1394605E - 353943N1394557E
(CHUO-KU IN TOKYO)
WT: 0.9KG
F) SFC
G) 601FT AMSL

RJAAJ1285/26 (18 JUN 26)

0300-1459
UNMANNED ACFT:
AREA: BOUNDED BY FLW POINTS
354021N1394720E - 354021N1394719E - 354016N1394720E - 354017N1394725E
- 354021N1394720E
(KOTO-KU IN TOKYO)
WT: 0.6KG

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 19/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

NUMBER: 1000
F) SFC
G) 566FT AMSL

RJAAJ1255/26 (18 JUN 26)

"ACFT-STAND-ID-SIGN FOR SPOT 47 U/S
VISUAL-DOCKING-GUIDANCE-SYSTEM FOR SPOT 47 U/S
APN-FLOOD-LGT FOR SPOT 401 PARTLY U/S
APN-FLOOD-LGT FOR SPOT 909 PARTLY U/S
RMK: (1)REF AIP SUP 148/26 ITEM APRON:3,8,9,11
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAJ1254/26 (18 JUN 26)

TWY-EDGE-LGT FOR J(BTN R AND J1) PARTLY TEMPO INSTALLED
RMK: (1)REF AIP SUP 148/26 ITEM TWY:46
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAJ1253/26 (18 JUN 26)

"TAXIING-GUIDANCE-SIGN FOR T12,T14,Q,Q1,Q2 U/S
RAPID-EXIT-TWY-INDICATOR-LGT FOR C10 U/S
RMK: (1)REF AIP SUP 148/26 ITEM TWY:13,43
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAJ1252/26 (18 JUN 26)

"TWY-CL-LGT FOR M1,R1,W11(BTN W AND R1),K(BTN C AND R),E(INT OF
K),A16,T12,T14,Q,Q1,Q2,C(INT OF C3),C(INT OF C5),C7,C8,C9,J(BTN R AND
W),J1(BTN J AND K),J2(BTN J AND K) U/S
RMK: (1)REF AIP SUP 148/26 ITEM TWY:2,4,6,12,33,44,45
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

*RJAAJ1250/26 (18 JUN 26)

RCLL FOR RWY 16L/34R U/S
RMK: (1)REF AIP SUP 148/26 ITEM RWY:51
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

*RJAAJ1249/26 (18 JUN 26)

"RWY-THR-ID-LGT FOR RWY 16L U/S
SEQUENCED-FLG-LGT FOR RWY 34L U/S
REDL FOR RWY 16L/34R PARTLY U/S
APCH-GUIDANCE-LGT FOR RWY 16R/16L(NR.4) U/S
APCH-GUIDANCE-LGT FOR RWY 16R/16L(NR.6,NR.8) PARTLY U/S
LIGHTING SYSTEM CAT-2,3 FOR RWY 34R DOWNGRADED TO CAT-1
RMK: (1)REF AIP SUP 148/26 ITEM RWY:30,49,52,54,55,56
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAJ1212/26 (18 JUN 26)

0000-1100
UNMANNED ACFT:
AREA: BOUNDED BY FLW POINTS
353939N1394617E - 354006N1394649E - 353943N1394715E - 353919N1394639E
- 353939N1394617E
(CHUO-KU IN TOKYO)
WT: 4.3KG
F) SFC
G) 644FT AMSL

RJAAJ1211/26 (18 JUN 26)

REF AIP SUP 148/26 ITEM RWY:57 (CHANGE TO READ)
SEQUENCED-FLG-LGT FOR RWY 34R U/S
START OF VALIDITY
CHANGE TO READ
NOV 2026

RJAAJ1202/26 (18 JUN 26)

MARKING FOR COMPASS AREA ERASED
RMK: (1)REF AIP SUP 148/26 ITEM APRON:10
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAJ1201/26 (18 JUN 26)

"SPOT 401 RELOCATED
SPOT 47 RELOCATED
RMK: (1)REF AIP SUP 148/26 ITEM APRON:5,7
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 20/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

RJAAJ1200/26 (18 JUN 26)

COMPASS AREA CLSD
RMK: (1)REF AIP SUP 148/26 ITEM APRON:C
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAJ1197/26 (18 JUN 26)

"SURFACE PAINTED DIRECTION SIGN FOR N(INT OF N2) ERASED
TWY SIDE STRIPE MARKING FOR F ERASED
RMK: (1)REF AIP SUP 148/26 ITEM TWY:16,49
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAJ1198/26 (18 JUN 26)

"SPOT 23,31,32,33,34,35,36 CLSD
SPOT 402 CLSD
RMK: (1)REF AIP SUP 148/26 ITEM APRON:B,D
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAE2739/26 (18 JUN 26)

"TWY M1(BEHIND SPOT 23) CLSD
TWY N2(BTN N AND SPOT 935) CLSD
TWY F CLSD
RMK: (1)REF AIP SUP 148/26 ITEM TWY:A,B,D
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAJ1196/26 (18 JUN 26)

"TWY CL MARKING FOR N2 PARTLY ERASED
TWY CL MARKING FOR F,T(INT OF F),N(INT OF F) PARTLY ERASED
SURFACE PAINTED DIRECTION SIGN FOR F,T(INT OF F),N(INT OF F),
N5(BEHIND SPOT 941) PARTLY ERASED
RMK: (1)REF AIP SUP 148/26 ITEM TWY:15,47,48
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAJ1194/26 (18 JUN 26)

"GROOVING FOR RWY 16L/34R PARTLY,GRADUALLY ERASED OR INSTALLED
RMK: (1)REF AIP SUP 148/26 ITEM RWY:53
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAJ1195/26 (18 JUN 26)

"GROOVING FOR RWY 16L/34R PARTLY,GRADUALLY ERASED OR INSTALLED
RMK: (1)REF AIP SUP 148/26 ITEM RWY:58
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAJ1172/26 (18 JUN 26)

0100-1100
UNMANNED ACFT:
AREA: BOUNDED BY FLW POINTS
353939N1394340E - 353939N1394338E - 353938N1394338E - 353937N1394336E
- 353935N1394337E - 353934N1394338E - 353933N1394337E -
353933N1394339E - 353939N1394341E - 353939N1394340E
(MINATO-KU IN TOKYO)
WT: 15.5KG
F) SFC
G) 650FT AMSL

RJAAJ1171/26 (18 JUN 26)

0100-1100
UNMANNED ACFT:
AREA: BOUNDED BY FLW POINTS
353939N1394341E - 353939N1394340E - 353938N1394335E - 353932N1394336E
- 353930N1394336E - 353930N1394339E - 353939N1394341E
(MINATO-KU IN TOKYO)
WT: 1KG
F) SFC
G) 650FT AMSL

RJAAJ1166/26 (18 JUN 26)

02 05 14 JUL 0100-0700
BEYOND VISUAL LINE OF SIGHT UNMANNED ACFT:
AREA: BOUNDED BY FLW POINTS
352247N1394006E - 352132N1394006E - 352132N1394135E - 352247N1394135E
- 352247N1394006E
(YOKOHAMA-SHI IN KANAGAWA)
WT: 0.7KG
CONTACT INFORMATION: 045-719-4321

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 21/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

F) SFC
G) 489FT AMSL

RJAAE2612/26 (18 JUN 26)

07 JUN 2026 14:30-28 JUN 2026 21:00
07 14 21 28 1430-2100
"TWY B5,B9 THRU B11,T5,T9,T11,A16,L16,Q CLSD DUE TO MAINT"

*RJAAJ1150/26 (18 JUN 26)

01-02 04-05 07-09 11-12 14-16 18-19 21-23 25-26 28-30 1430-2100
RWY 04/22 CLSD DUE TO MAINT
RMK: (1)AVBL CROSS RWY 04/22 VIA TWY OTHER THAN CLSD TWY
(2)SEE AIP RJTT AD2.23

RJAAE2598/26 (18 JUN 26)

01-02 04-05 07-09 11-12 14-16 18-19 21-23 25-26 28-30 1430-2100
"TWY B3,B4,B6,B8,B13,T3,T4,T6,T8 CLSD DUE TO MAINT"

RJAAE2594/26 (18 JUN 26)

01 03 06-08 10 13-15 17 20-22 24 27-29 1430-2100
"TWY A1,A2,A5,A7,A8,A10,A12,A13,L5,L10,L12 CLSD DUE TO MAINT"

*RJAAJ1149/26 (18 JUN 26)

01 03 06-08 10 13-15 17 20-22 24 27-29 1430-2100
RWY 16R/34L CLSD DUE TO MAINT
RMK: (1)AVBL CROSS RWY 16R/34L VIA TWY OTHER THAN CLSD TWY
(2)SEE AIP RJTT AD2.23

RJAAJ1145/26 (18 JUN 26)

01-02 04-05 07-09 11-12 14-16 18-19 21-23 25-26 28-30 1430-2100
"ILS-LOC,GP,DME FOR RWY 22 U/S DUE TO CONST"

RJAAJ1143/26 (18 JUN 26)

01 03 06-08 10 13-15 17 20-22 24 27-29 1430-2100
"ILS-LOC,GP,DME FOR RWY 34L U/S DUE TO CONST"

RJAAJ1141/26 (18 JUN 26)

01 03 06-08 10 13-15 17 20-22 24 27-29 1430-2100
"ILS-LOC,GP,DME FOR RWY 16R U/S DUE TO CONST"

RJAAJ1092/26 (18 JUN 26)

DISPLAY OF TARGET START UP APPROVAL TIME(TSAT) ON
VISUAL-DOCKING-GUIDANCE-SYSTEM FOR SPOT 18 THRU 23 U/S DUE TO TROUBLE
RMK:REF AIP RJTT AD 2.20

RJAAJ1049/26 (18 JUN 26)

RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT

RJSS / SDJ

RJAAK1670/26 (18 JUN 26)

"REF AIP SUP 131/26 ITEM 2-6(CHANGE TO READ)
UNSERVICEABILITY AND ALTERNATE PROCEDURES OF SENDAI VOR/DME(SDE)
ADD IN TEXT
2-6.TEMPORARY CHANGE OF LOST COMMUNICATION PROCEDURES FOR ARRIVAL
AIRCRAFT UNDER RADAR NAVIGATIONAL GUIDANCE FOR SENDAI AP/RJSS:
LOST COMMUNICATION PROCEDURES FOR ARRIVAL AIRCRAFT UNDER RADAR
NAVIGATIONAL GUIDANCE
IF RADIO COMMUNICATIONS WITH SENDAI APPROACH/RADAR ARE LOST FOR
1 MINUTE, SQUAWK MODE A/3 CODE 7600 AND:
(I) 1.CONTACT SENDAI TOWER / SENDAI RADIO.
2.IF UNABLE, PROCEED IN ACCORDANCE WITH VISUAL FLIGHT RULES.
3.IF UNABLE, PROCEED TO MIYAGI VOR/DME AT LAST ASSIGNED
ALTITUDE OR 3000 FEET WHICHEVER IS HIGHER, AND EXECUTE
INSTRUMENT APPROACH.
(II) PROCEDURES OTHER THAN ABOVE WILL BE ISSUED WHEN SITUATION
REQUIRED."

RJAAK1499/26 (22 MAY 26)

1914-1004
"AEROBATICS:
1.FLT AREA : WI A RADIUS OF 1.1NM OF 380025N 1404820E
(APRX QTE/214DEG 9.6NM FM RJSS ARP)
(AROUND KAKUDA GLIDER SITE,KAKUDA-SHI IN MIYAGI)

2.FLT TIME : HJ
3.USING ACFT : GLIDER,PTS2
4.WX COND : VMC ONLY"
F) 1030FT AMSL
G) 3030FT AMSL

// (COM-INFO)//

THA 00189/15 (08 DEC 24)

COM INFO:--ATS HOURS 2230-1230 (OW-INFO)

--NO GHS FOR TG, DO NOT USE RJSS AS DEST/ENRTE ALTN (ISSUED 23MAY23/OW-INFO/UFN)

RJGG / NGO

*RJAAG1564/26 (25 JUN 26)

27 JUN 2026 14:50-28 JUN 2026 20:45
1450-2045
RWY 18/36 CLSD DUE TO CONST

RJAAG1554/26 (24 JUN 26)

28 JUN 2026 14:50-28 JUN 2026 20:45
"ACFT STAND TXL E,E2 THRU E6,P,J,K3 CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

RJAAG1555/26 (24 JUN 26)

28 JUN 2026 14:50-28 JUN 2026 20:45
"ACFT STAND TXL D,D5 THRU D7,N CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

RJAAG1553/26 (24 JUN 26)

28 JUN 2026 14:50-28 JUN 2026 20:45
"TWY A(INT OF B1),A(INT OF B3),A(FM B5 TO B6),A(INT OF B8),A(INT OF
B10),A1,A3S,A3,A5,A6,A8,A8N,A10,B,B1,B3,B5,B6,B8,B10,C,C7 THRU C10
CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

RJAAG1354/26 (03 JUN 26)

"TWY-CL-LGT FOR A,A1 THRU A4,A6 THRU A10,B2 THRU B10,C7,C9,E4 U/S
RMK: (1)REF AIP SUP 109/26 ITEM TWY:4
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAG1353/26 (03 JUN 26)

"TWY A(BTN B1 AND B3),A2,B2,A(BTN B3 AND B5),A4,B4,A(BTN B6 AND
B8),A7,B6N,B7,A(BTN B8 AND B10),A9,B9 CLSD
RMK: (1)REF AIP SUP 109/26 ITEM TWY:C
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAG1350/26 (03 JUN 26)

"TWY-CL-MARKING FOR A,A1 THRU A10,B1 THRU B10,C7,C9,E4 PARTLY
ERASED
RMK: (1)REF AIP SUP 109/26 ITEM TWY:6
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAG1325/26 (31 MAY 26)

RWY-SIDE-STRIPE-MARKING FOR RWY 18/36 TEMPO INSTL
RMK: (1)REF AIP SUP 109/26 ITEM RWY:2
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAG1274/26 (23 MAY 26)

"TWY-SIDE-STRIPE-MARKING FOR A1,A3S,A3,A8,A8N,A10,B1,B3,B8,B10
TEMPO
INSTL
RMK:REF AIP SUP 109/26 ITEM TWY:8"

RJAAG1273/26 (23 MAY 26)

"TWY-EDGE-LGT FOR A3S,A3,A8,A8N,B3,B8 TEMPO INSTL
RMK:REF AIP SUP 109/26 ITEM TWY:7"

RJAAG1181/26 (11 MAY 26)

RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT

RJAAG1156/26 (08 MAY 26)

"STOP-BAR-LGT FOR A1,A2,A3,A3S,A4,A5,A6,A7,A8,A8N,A9,A10 U/S
RMK:(1)REF AIP SUP 109/26 ITEM TWY:3

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 23/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

// (COM-INFO) //

THA 00104/12 (29 MAR 26)

COM INFO:--REGARDING GPU AND ACU USING AT NGO AIRPORT,
KINDLY REMIND AND INFO AS FOLLOWS:
AA. WHEN AIRCRAFT PARK AT REMOTE BAY, PLEASE KINDLY USE APU ON ARR.
BB. WHEN AIRCRAFT PARK AT SPOT WITH PASSENGER BOARDING BRIDGE,
KINDLY USE GPU AND ACU DUE TO FUEL MANAGEMENT POLICY
AND AIRPORT AUTHORITY REQUESTED. (ISSUE/16DEC/NGOKKTG/INFO)

RJ00 / ITM

RJAAK1711/26 (25 JUN 26)

RLLS NR.7 FOR RWY 14R U/S DUE TO TROUBLE

RJAAK1692/26 (23 JUN 26)

"REF AIP SUP 084/26 ITEM TWY:6 (CHANGE TO READ)
RWY-ENTRANCE-LGT FOR B4,C1,W6,W7 U/S
END OF VALIDITY
CHANGE TO READ
AUG 2026"

RJAAK1690/26 (23 JUN 26)

"TWY-SIDE-STRIPE-MARKING FOR C1,C2,C6,W6,W7,W10,B4 PARTLY,GRADUALLY
ERASED OR INSTALLED
RMK: REF AIP SUP 084/26 ITEM TWY:12"

RJAAK1689/26 (23 JUN 26)

MANDATORY-INSTRUCTION-MARKING FOR W9 GRADUALLY ERASED OR INSTALLED
RMK: REF AIP SUP 084/26 ITEM TWY:11

RJAAK1688/26 (23 JUN 26)

MANDATORY-INSTRUCTION-MARKING FOR C1 GRADUALLY ERASED OR INSTALLED
RMK: REF AIP SUP 084/26 ITEM TWY:10

RJAAK1691/26 (23 JUN 26)

TWY-SIDE-STRIPE-MARKING FOR W9 GRADUALLY ERASED OR INSTALLED
RMK: REF AIP SUP 084/26 ITEM TWY:13

RJAAK1686/26 (23 JUN 26)

"RWY-ENTRANCE-LGT FOR B4,C1,W6,W7 U/S
RMK: REF AIP SUP 084/26 ITEM TWY:6"

RJAAK1687/26 (23 JUN 26)

"FLW LGT U/S
RWY-ENTRANCE-LGT FOR C6,W10
INTERMEDIATE-HLDG-PSN-LGT FOR TWY A1
RMK: (1)REF AIP SUP 084/26 ITEM TWY:7,9
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

RJAAK1685/26 (23 JUN 26)

"TWY-CL-LGT FOR TWY A1,B4,C1,C2,C6,E1,W2,W5,W9 U/S
RMK: (1)REF AIP SUP 084/26 ITEM TWY:1,2,3,4,5
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

*RJAAK1682/26 (23 JUN 26)

RCLL FOR RWY 14L/32R U/S
RMK: (1)REF AIP SUP 084/26 ITEM RWY:2
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

*RJAAK1684/26 (23 JUN 26)

RCLL FOR RWY 14R/32L U/S
RMK: (1)REF AIP SUP 084/26 ITEM RWY:6
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAK1683/26 (23 JUN 26)

"FLW LGT U/S
TKOF-HOLD-LGT FOR RWY 14L/32R
OVERRUN-AREA-EDGE-LGT ON RWY 32R SIDE
RMK: (1)REF AIP SUP 084/26 ITEM RWY:3,4
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 24/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

RJAAK1614/26 (08 JUN 26)

09-12 15-19 22-26 29-30 0500-0800
"BEYOND VISUAL LINE OF SIGHT UNMANNED ACFT:
AREA: BOUNDED BY FLW POINTS
345107N1353014E - 345207N1353013E - 345216N1352510E - 345130N1352533E
- 345134N1352544E - 345118N1352545E - 345103N1352522E -
345007N1352553E - 345038N1352933E - 345107N1353014E
(IKEDA-SHI, MINOO-SHI IN OSAKA, KAWANISHI-SHI IN HYOGO)
WT: 2.5KG
CONTACT INFORMATION: 03-4485-1606"
F) SFC
G) 2304FT AMSL

RJAAK1585/26 (02 JUN 26)

"GROOVING FOR RWY 32R PARTLY,GURADUALLY ERASED OR INSTALLED
RMK:REF AIP SUP 084/26 ITEM RWY:13"

RJAAK1584/26 (02 JUN 26)

"GROOVING FOR RWY 14L PARTLY, GURADUALLY ERASED OR INSTALLED
RMK:REF AIP SUP 084/26 ITEM RWY:12"

RJAAK1580/26 (02 JUN 26)

"TDZ MARKING FOR RWY 14L/32R PARTLY,GURADUALLY ERASED OR INSTALLED
RMK:REF AIP SUP 084/26 ITEM RWY:9"

RJAAK1583/26 (02 JUN 26)

"RWY SIDE STRIPE MARKING FOR RWY 14L/32R PARTLY, GURADUALLY ERASED
OR INSTALLED
RMK:REF AIP SUP 084/26 ITEM RWY:11"

RJAAK1582/26 (02 JUN 26)

"TDZ MARKING FOR RWY 14L/32R PARTLY,GURADUALLY ERASED OR INSTALLED
RMK:REF AIP SUP 084/26 ITEM RWY:9"

RJAAK1579/26 (02 JUN 26)

RWY DESIGNATION MARKING FOR RWY 14L/32R GURADUALLY ERASED OR
INSTALLED
RMK:REF AIP SUP 084/26 ITEM RWY:8

RJAAK1578/26 (02 JUN 26)

RWY THR MARKING FOR RWY 14L/32R GURADUALLY ERASED OR INSTALLED
RMK:REF AIP SUP 084/26 ITEM RWY:7

RJAAK1573/26 (02 JUN 26)

"REF AIP SUP 084/26 ITEM RWY:7,8,9,11,12,13
(CHANGE TO READ)
RWY THR MARKING FOR RWY 14L/32R GURADUALLY ERASED OR INSTALLED
RWY DESIGNATION MARKING FOR RWY 14L/32R GURADUALLY ERASED OR
INSTALLED
TDZ MARKING FOR RWY 14L/32R PARTLY,GURADUALLY ERASED OR INSTALLED
RWY SIDE STRIPE MARKING FOR RWY 14L/32R PARTLY,GURADUALLY ERASED OR
INSTALLED
GROOVING FOR RWY 14L PARTLY,GURADUALLY ERASED OR INSTALLED
GROOVING FOR RWY 32R PARTLY,GURADUALLY ERASED OR INSTALLED
START OF VALIDITY
CHANGE TO READ
JUN 2026"

RJAAK1549/26 (29 MAY 26)

REF AIP SUP 084/26 ITEM 8 (CHANGE TO READ)
NO LONGER IN FORCE
CONST CMPL

RJAAK1535/26 (28 MAY 26)

OBST DAY MARKING ERASED
TYPE: POWER LINE TOWER
PSN: 344450.0N1352315.0E ELEV: 241FT AMSL
(AMAGASAKI-SHI IN HYOGO)

RJAAK1392/26 (11 MAY 26)

RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT

RJAAK1348/26 (01 MAY 26)

GROOVING FOR RWY 14R/32L PARTLY GRADUALLY ERASED OR INSTALLED
RMK: (1)REF AIP SUP 084/26 ITEM RWY:14
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAK1347/26 (01 MAY 26)

"TDZ MARKING FOR RWY 32L PARTLY,GRADUALLY ERASED OR INSTALLED
RMK: (1)REF AIP SUP 084/26 ITEM RWY:10
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM"

// (COM-INFO) //THA 00188/15 (24 MAY 25)

COM INFO:--TAKE OFF AND LANDING NOT PERMITTED BETWEEN 1200-2200,
EXCEPT IN EMERGENCY (OW-INFO)

RJBB / KIX

RJAAB1607/26 (27 JUN 26)

28 JUN 2026 14:00-29 JUN 2026 23:30
1400-2330
"TWY B1,B3,B5,B6,B7,B8,B9,B10,B12,B14,Y,J3(BTN Y AND Z),J4(BTN Y
AND
Z),W6(BTN Y AND Z),W8(BTN Y AND Z) CLSD DUE TO MAINT"

*RJAAB1605/26 (27 JUN 26)

28 JUN 2026 14:00-29 JUN 2026 23:30
1400-2330
RWY 06L/24R CLSD DUE TO MAINT

RJAAB1359/26 (31 MAY 26)

1006-1944
TWY-CL-LGT FOR TWY B12 U/S DUE TO MAINT

RJAAB1360/26 (31 MAY 26)

1006-1944
TWY-CL-LGT FOR TWY B14 U/S DUE TO MAINT

RJAAB1339/26 (28 MAY 26)

2200-2159
TWY Q(BTN S4 AND S5) CLSD DUE TO MAINT

RJAAB1334/26 (28 MAY 26)

1006-1944
TWY-CL-LGT FOR TWY Y(BTN B9 AND B14) U/S DUE TO MAINT

RJAAB1335/26 (28 MAY 26)

1006-1944
TWY-CL-LGT FOR TWY B10 U/S DUE TO MAINT

RJAAB1273/26 (25 MAY 26)

REF AIP SUP 038/26 ITEM RWY:1
LIGHTING SYSTEM CAT-2 FOR RWY 06L DOWNGRADED TO CAT-1
RMK/THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAB1135/26 (11 MAY 26)

CEILOMETER FOR RWY 24R U/S DUE TO CONST
RMK: THIS NOTAM WILL BE INCORPORATED IN SUP

RJAAB1134/26 (11 MAY 26)

RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT

RJFF / FUK

RJAAF0624/26 (10 JUN 26)

"JUN 15-19 22-26 29 30 1330-2100, JUL 01-03 06-10 1330-2100"
"LOC,LOC-DME FOR RWY 34L U/S DUE TO MAINT
RMK/VMC ONLY"

RJAAF0626/26 (10 JUN 26)

"JUN 15-19 22-26 29 30 1330-2100, JUL 01-03 06-10 1330-2100"
"LOC,LOC-DME FOR RWY 16R U/S DUE TO MAINT
RMK/VMC ONLY"

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 26/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

RJAAF0625/26 (10 JUN 26)

"15-19 22-26 29 30 1330-2100, JUL 03 06-10 1330-2100"
"ILS-LOC,GP FOR RWY 16L U/S DUE TO MAINT
RMK: VMC ONLY"

RJAAF0623/26 (10 JUN 26)

"JUN 15-19 22-26 29 30 1330-2100, JUL 01-03 06-10 1330-2100"
"ILS-LOC,GP FOR RWY 34R U/S DUE TO MAINT
RMK: VMC ONLY"

RJAAF0606/26 (05 JUN 26)

1330-2130
"TWY A(BTN E8 AND E13),E1 THRU E13,C1 THRU C9,W1 THRU W10,J1 THRU
J5,B,ACFT STAND TXL U CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

RJAAF0596/26 (04 JUN 26)

TWY-CL-LGT FOR TWY C6 U/S
RMK: (1)REF AIP SUP 145/26 ITEM TWY:1
(2)THE EXACT TIME OF NEXT PERIOD WILL BE NOTIFIED BY FURTHER NOTAM

RJAAF0557/26 (28 MAY 26)

07 10-30 1400-2130
"TWY A(FM K1 TO E8),ACFT STAND TXL K1 THRU K7,Y CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

*RJAAF0553/26 (28 MAY 26)

07 10-30 1330-2130
RWY 16L/34R CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR

*RJAAF0554/26 (28 MAY 26)

1330-2130
RWY 16R/34L CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR

RJAAF0497/26 (11 MAY 26)

RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT

RJAAF0470/26 (28 APR 26)

TWY-EDGE-LGT FOR WEST APN(S OF SPOT 59) U/S DUE TO CONST

RJAAF0429/26 (19 APR 26)

ACFT-STAND-ID-SIGN FOR SPOT 56 THRU 58 U/S DUE TO CONST

ROAH / OKA

RJAAH2344/26 (24 JUN 26)

RWY-ENTRANCE-LGT FOR E10 U/S
RMK: REF AIP SUP 147/26 ITEM TWY:3

RJAAH2332/26 (24 JUN 26)

"TWY-CL-MARKING FOR E10 PARTLY, GRADUALLY ERASED OR INSTALLED
RMK: REF AIP SUP 147/26 ITEM TWY:4"

RJAAH2333/26 (24 JUN 26)

TWY-SIDE-STRIP-MARKING FOR E10 PARTLY ERASED
RMK: REF AIP SUP 147/26 ITEM TWY:5

RJAAH2202/26 (13 JUN 26)

16 30 1400-2130
"TWY E3 THRU E10,A4(BTN SPOT 15 AND A5),A5 THRU A9,W2 THRU W5,B(BTN
J2 AND W5) CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

*RJAAH2198/26 (13 JUN 26)

15-17 30 1400-2130
RWY 18L/36R CLSD DUE TO MAINT
1)AVBL CROSS RWY18L/36R VIA OTHER THAN CLSD TWY
2)EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 27/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

RJAAH2172/26 (11 JUN 26)

11 15-17 22-26 29-30 1400-2100
"ILS-LOC,GP,DME FOR RWY 36R-U/S DUE TO CONST"

RJAAH2157/26 (11 JUN 26)

"MANDATORY-INSTRUCTION-MARKING FOR E10 PARTLY, GRADUALLY ERASED OR
INSTALLED
RMK: REF AIP SUP 147/26 ITEM TWY:6"

RJAAH2153/26 (11 JUN 26)

13 JUN 2026 14:00-28 JUN 2026 21:00
13-14 20-21 27-28 1400-2100
"ILS-LOC,GP,DME FOR RWY 18R U/S DUE TO CONST"

RJAAH2152/26 (11 JUN 26)

13 JUN 2026 14:00-28 JUN 2026 21:00
13-14 20-21 27-28 1400-2100
"ILS-LOC,GP,DME FOR RWY 36L U/S DUE TO CONST"

RJAAH2143/26 (10 JUN 26)

29 JUN 2026 00:00-29 JUN 2026 08:00
"ACFT STAND ID SIGN FOR SPOT 21 THRU 27,31 THRU 37,41 THRU 44
U/S DUE TO MAINT"

RJAAH2141/26 (10 JUN 26)

29 JUN 2026 00:00-29 JUN 2026 08:00
"APN-FLOOD-LGT FOR SPOT 11 THRU 16,21 THRU 27,31 THRU 37,41 THRU
46,51,52,57D,61 THRU 66,71 THRU 74,98 THRU 107,LIGHT ACFT SPOT 1 THRU
6,RUN UP AREA U/S DUE TO MAINT"

RJAAH2136/26 (10 JUN 26)

TWY-CL-LGT FOR TWY E10 U/S
RMK: REF AIP SUP 147/26 ITEM TWY:2

RJAAH2010/26 (31 MAY 26)

"TWY-CL-LGT FOR TWY D3,E7,N3 U/S DUE TO MAINT"

RJAAH1978/26 (28 MAY 26)

22 24 26 29 1400-2130
"TWY E1,E2,E4(BTN RWY 18L/36R AND E4C),E5 THRU E9,A4(BTN SPOT 15
AND
A5),A5 THRU A9,W1(BTN RWY 18L/36R AND W2),W3(BTN RWY 18L/36R AND
W3C),W4,W5,B(BTN J2 AND W5) CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

RJAAH1968/26 (28 MAY 26)

01 04-05 08 11-12 15 18-19 22 25-26 29 1530-2030
"TWY A1,A2,A3,A4(FM E4C TO SPOT 15),C1,C2,D1,D2,D3,N1,N2,N3 CLSD
DUE
TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

RJAAH1966/26 (28 MAY 26)

02-03 09-10 16-17 30 1500-2130
"TWY A1,A2,A3,A4(FM E4C TO SPOT 15),C1,C2,D1,D2,D3,N1,N2,N3 CLSD
DUE
TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

*RJAAH1963/26 (28 MAY 26)

06 JUN 2026 14:00-28 JUN 2026 21:30
06-07 13-14 20-21 27-28 1400-2130
RWY 18R/36L CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR

RJAAH1965/26 (28 MAY 26)

06 JUN 2026 14:00-28 JUN 2026 21:30
06-07 13-14 20-21 27-28 1400-2130
"TWY T1 THRU T9,C,J1,J2,R,B(FM W1 TO J2),W1(FM W2 TO B),W2,W3,W3C
CLSD DUE TO MAINT
EXC ACFT WITH PRIOR PERMISSION AT LEAST 1HR BFR"

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 28/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

RJAAH1740/26 (11 MAY 26)

RWY INCURSION WARNING OPERATION SUSPENDED DUE TO MAINT

RCTP / TPE

RCTPA2073/26 (25 JUN 26)

24 JUN 2026 17:00-28 JUN 2026 22:20
JUN 24 28 1700-2220
PORTION OF TWY E BTN TWY P (EXCLUDED) AND TWY Q (EXCLUDED) CLSD
DUE TO WIP.
RMK:
1.ACFT IN/OUT CAL MAINTENANCE APRON VIA SOUTH EXIT ONLY.
2.PORTION OF TWY E BTN NORTH EXIT OF CAL MAINTENANCE
APRON (EXCLUDED) AND TWY P (EXCLUDED) ONLY AVBL FOR
TOWING ACFT.

RCTPA2069/26 (25 JUN 26)

"PORTION OF TWY E BTN TWY P (EXCLUDED) AND TWY Q (EXCLUDED) ONLY
AVBL FOR ACFT WITH CODE LETTER A, B, C, D, E.
(REF ICAO ANNEX 14 AERODROMES, TABLE 1-1 AERODROME REFERENCE CODE)
RMK: ACFT TYPE B748 TOWING IS PERMITTED."
23 JUN 26 22:20 UNTIL 31 AUG 26 09:00 ESTIMATED

*RCTPA1969/26 (25 JUN 26)

0400-0430
RWY 05R/23L CLSD DUE TO INSPECTION.

*RCTPA1967/26 (25 JUN 26)

0300-0330
RWY 05L/23R CLSD DUE TO INSPECTION.

RCTPA1707/26 (07 JUN 26)

"BIRD CONCENTRATION DRG 2100-1100:
1.IN THE VCY OF THE AP, AND AT AP
IN THE APPROACH PATH OF RWY 23L,
HGT: 0-1500FT, BIRD WT: 370 GRAMS.
2.IN THE VCY OF THE AP AND AT AP
IN THE APPROACH PATH OF RWY 05L/23R AND RWY 05R/23L,
HGT: 0-300FT, BIRD WT: 750-1500 GRAMS.
3.IN THE VCY OF THE AP AND AT NORTH OF RWY 05L/23R,
HGT: 0-300FT, BIRD WT: 87 GRAMS."

RCTPA1664/26 (07 JUN 26)

TWY Q4 BTN TWY Q (EXCLUDED) AND TWY S (EXCLUDED)
NOT AVBL FOR A380 ACFT TAX AND TOWING.
29 MAY 26 22:20 UNTIL 25 AUG 26 08:00 ESTIMATED

RCTPA1665/26 (07 JUN 26)

A380 ACFT SHALL FLW FOLLOW ME GUIDANCE OR BE TOWED WHEN MOVING
ALONG TWY P10.
29 MAY 26 09:45 UNTIL 25 AUG 26 08:00 ESTIMATED

RCTPA1648/26 (07 JUN 26)

PORTION OF TWY R BTN TWY R1 (INCLUDED) AND TWY R3 (EXCLUDED)
CLSD FOR ACFT PRKG.
29 MAY 26 00:37 UNTIL 25 AUG 26 08:00 ESTIMATED

RCTPA1191/26 (17 MAY 26)

"PORTION OF TWY L BEHIND PRKG BAY 525 CLSD
FOR ACFT PRKG AND TOWING.
RMK: DEP ACFT IN PRKG BAY 524 PUSH BACK TO FACE EAST
UNTIL ABEAM PRKG BAY 520, THEN TAX."
27 APR 26 09:32 UNTIL 20 JUL 26 10:00 ESTIMATED

RCTPA1152/26 (17 MAY 26)

"ACFT WITH CODE LETTER F (REF ICAO ANNEX 14 AERODROMES, TABLE 1-1
AERODROME REFERENCE CODE) SHALL FLW FOLLOW ME GUIDANCE OR BE TOWED
WHEN MOVING ALONG TWY Q BTN TWY Q2 (EXCLUDED) AND TWY Q4 (INCLUDED)."
24 APR 26 09:32 UNTIL 23 JUL 26 08:00 ESTIMATED

RCTPA0981/26 (17 MAY 26)

0330-0400
"SCHEDULED CLOSURE OF RWY 05R/23L SUSPENDED.

REF AIP RCTP AD 2.20.1, ITEM 4."
11 APR 26 03:30 UNTIL 30 JUN 26 04:00 ESTIMATED

RCTPA0979/26 (17 MAY 26)

0230-0300
"SCHEDULED CLOSURE OF RWY 05L/23R SUSPENDED.
REF AIP RCTP AD 2.20.1, ITEM 4."
11 APR 26 02:30 UNTIL 30 JUN 26 03:00 ESTIMATED

RCTPA2908/25 (08 SEP 25)

"REF AIP SUP 14/22, GROUND MANEUVERING RESTRICTIONS FOR AD
REFERENCE
CODE F ACFT AT TAIPEI/TAIWAN TAOYUAN INTL AP, END DATE REVISED AS
31 AUG 2028, 1559UTC. THE REST NC."

RCKH / KHH

RCTPA2086/26 (25 JUN 26)

"UNEVEN SFC EXIST IN RWY 09 STRIPS DUE TO CONST WORK,
INFO AS FLW:
1.OPR AREA:
223436N/1202030E
223436N/1202050E
223432N/1202050E
223432N/1202030E
(WITH A LENGTH OF 600M AND A WIDTH OF 135M, AT PSN 30M-165M
SOUTH FM RWY 09 RCL AND 39.9M-639.9M EAST OF TWY B CENTER LINE)
2.TWY S NOT AFFECTED."

RCTPA2085/26 (25 JUN 26)

"UNEVEN SFC EXIST IN RWY 27 STRIPS DUE TO CONST WORK,
INFO AS FLW:
OPR AREA:
223436N/1202121E
223435N/1202132E
223431N/1202132E
223431N/1202121E
(WITH A LENGTH OF 298M AND A WIDTH OF 135M, AT PSN 35M-170M
SOUTH FM RWY 27 RCL AND 40M-338M WEST OF TWY D CENTER LINE)."

RCTPA2048/26 (25 JUN 26)

TWY J CLSD DUE TO WIP.

RCTPA1980/26 (25 JUN 26)

TWY E CLSD DUE TO INSPECTION.

// (COM-INFO)//

THA 00352/17 (10 JUN 26)

COM-INFO:--1) ATS HRS (2200-1600)
2) DUE TO NOISE ABATEMENT, TAKE OFF/LDG IS PROHIBITED
DURING THE PERIOD FM 1601-2230 UTC EXCEPT EMERGENCY.
(REF AIP TAIPEI AD 2-RCKH)

RCTPA1643/26 (07 JUN 26)

"REF AIP SUP 27/25 DATED 23 OCT 2025, CONST WORK AT
KAOHSIUNG INTL AIRPORT, PHASE 9 ACT:
1.TWY B CLOSED BETWEEN TWY S (EXCLUDED) AND TWY A (EXCLUDED).
2.STAND 522 CLOSED."

RCTPA1627/26 (07 JUN 26)

TWY B BTN RWY 09/27 (EXCLUDED) AND TWY S (EXCLUDED)
CLSD DUE TO WIP.

RCTPA1492/26 (18 MAY 26)

"REF AIP SUP 27/25 DATED 23 OCT 2025, CONST WORK AT
KAOHSIUNG INTL AIRPORT, PHASE 8 ACT:
TWY D CLSD."

RCTPA1367/26 (17 MAY 26)

0530-0630
TRG FLT NOT ALLOWED FM 0530 TIL 0630.

*RCTPA4786/25 (09 JAN 26)

1601-2230
"REF AIP SUP 27/25 DATED 23 OCT 2025, CONST WORK AT KAOHSIUNG INTL

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 30/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

AIRPORT,
PHASE 1 (DURING CURFEW) ACT. RWY 09/27 AND ALL TWY CLSD."

RCTPA3894/25 (29 OCT 25)

"AIP SUP 27/25, CONST WORK AT KAOHSIUNG INTL AIRPORT.
REPLACES AIP SUP 17/25.
THE DATE AND TIME OF EACH CONST PHASE ACTIVATION WILL BE NOTIFIED BY
NOTAM."
23 OCT 25 01:35 UNTIL 31 JUL 27 23:59 ESTIMATED

RCTPA2199/25 (08 SEP 25)

"AIP SUP 17/25, CONST WORK AT KAOHSIUNG INTL AIRPORT.
REPLACES AIP SUP 31/24.
THE DATE AND TIME OF EACH CONST PHASE ACTIVATION WILL BE NOTIFIED BY
NOTAM."
10 JUL 25 02:50 UNTIL 30 JUN 26 23:59 ESTIMATED

RPLL / MNL

RPLLB3026/26 (27 JUN 26)

EXER CTN WHEN TAX PORTION OF TWY D (BTN TWY F2 AND F5) DUE
PRESENCE OF SOFT SPOT AND UNEVEN PAVEMENT SFC.

RPLLB3002/26 (26 JUN 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (LOADING AND UNLOADING
OF EQPT) AT COORD: 143116.06N 1210015.07E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 16FT).

RPLLB3001/26 (26 JUN 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (LOADING AND
UNLOADING OF ACFT PARTS) AT COORD: 143113N 1210008E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 100FT).

RPLLB3000/26 (26 JUN 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (DEMOLITION OF HANGAR) AT
COORD: 143137.84N 1210013.11E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 36FT).

RPLLB2999/26 (26 JUN 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (DEMOLITION OF HANGAR) AT
COORD: 143059.65N 1210011.23E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 148FT).

RPLLB2998/26 (26 JUN 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (UNLOADING OF EQPT)
AT COORD: 143134N 1210027E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 148FT).

RPLLB2997/26 (26 JUN 26)

EXER CTN WHEN OPR RPA GA APN PRKG BAY NR 71 DUE WIP (LOADING AND
UNLOADING OF ACFT PARTS) AT COORD: 143122N 1210006E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 36FT).

RPLLB2995/26 (26 JUN 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (LOADING AND UNLOADING
OF ACFT PARTS) AT COORD: 143109N 1210008E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 115FT).

RPLLB2996/26 (26 JUN 26)

EXER CTN WHEN OPR GA MOV AREA DUE WIP (LOADING AND UNLOADING
OF EQPT) AT COORD: 143110N 1210016E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 53FT).

RPLLB2977/26 (25 JUN 26)

EXER CTN WHEN TAX TWY G3 DUE PRESENCE OF UNEVEN PAVEMENT SFC.

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 31/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

RPLLB2978/26 (25 JUN 26)

EXER CTN WHEN TAX TWY C (ABM TWY G9) DUE PRESENCE OF UNEVEN PAVEMENT SFC.

RPLLB2939/26 (24 JUN 26)

EXER CTN WHEN TAX PORTION OF TWY L (ABM TERMINAL 1 APN STARTING POINT S3 AND S5) DUE PRESENCE OF DAMAGED AND UNEVEN PAVEMENT.

RPLLB2938/26 (24 JUN 26)

EXER CTN DRG LDG/TKOF RWY 06/24 DUE WIP (GRADING OF RWY STRIP) FM COORD 142948.01N 1210000.15E TO 143048.41N 1210149.59E.

RMK: PRESENCE OF MEN AND EQPT.

RPLLB2863/26 (21 JUN 26)

EXER CTN WHEN OPR TERMINAL 3 REMOTE PRKG APN (RPA T3) BAY NR 128 AND 129 DUE PRESENCE OF RUTTING/UNEVEN PAVEMENT.

RPLLB2844/26 (19 JUN 26)

EXER CTN WHEN TAX PORTION OF TWY C (BTN TWY E1 AND E2) DUE PRESENCE OF UNEVEN PAVEMENT SFC.

RPLLB2747/26 (15 JUN 26)

"EXER CTN WHEN TAX TWY Y (ABM TERMINAL 3 APN PRKG BAY NR 102, 103, 104 AND 105) DUE PRESENCE OF RUTTING PAVEMENT."

RPLLB2739/26 (15 JUN 26)

EXER CTN WHEN OPR GA MOV AREA DUE PRESENCE OF POTHOLES AT COORD: 143106.71N 1210023.79E.

RPLLB2696/26 (11 JUN 26)

"EXER CTN WHEN OPR GA MOV AREA DUE PRESENCE OF POTHOLES AT COORD: 143132.09N 1210025.14E, 143132.43N 1210028.21E AND 143135.64N 1210007.96E."

RPLLB2695/26 (11 JUN 26)

EXER CTN WHEN OPR RPA GA BAY NR 79 AND 80 DUE PRESENCE OF SOFT SPOT AND UNEVEN PAVEMENT SFC.

RPLLB2674/26 (10 JUN 26)

"STOPBAR LGT U/S ON THE FLW AREAS: PORTION OF TWY C (BTN TWY G2, G3, G5 AND G6), TWY E1, E2, E4, E5, H1, H2, RAPID EXIT TWY R2, R3 AND R4."

RPLLB2581/26 (10 JUN 26)

"EXER CTN WHEN TAX TWY F1, G11 AND PORTION OF TWY N (ABM RPA T3 PRKG BAY NR 123, 124, 125 AND 126) DUE WIP (CONST OF TWY AT COORD: 143120.24N 1210026.09E)

RMK: PRESENCE OF MEN AND EQPT.

ALL ARRIVING ACFT TAX PORTION OF TWY N (ABM RPA T3 PRKG BAY NR 123, 124, 125 AND 126) AND TWY G11 SHALL FLW DIVERTED TWY CL MARKINGS AND MNM TAX PWR. TERMINAL 3 APN STARTING POINT S13 REPOSITIONED TEMPO DIVERTED CL MARKINGS ABM RPA T3 PRKG BAY NR 124."

RPLLB2561/26 (10 JUN 26)

EXER CTN WHEN TAX PORTION OF TWY D (BTN TWY G11 AND G12) AND F1 DUE WIP (CONST OF TWY AT COORD: 143120.24N 1210026.09E).

RMK: ALLOWED FOR ACFT CODE C TOWING OPS ONLY.
ACFT CODE B AND BLW ALLOWED FOR TAX PWR.

RPLLB2522/26 (10 JUN 26)

EXER CTN WHEN OPR TERMINAL 3 APN STARTING POINT S13 DUE WIP (CONST OF TWY AT COORD: 143120.24N 1210026.09E)

RMK: PRESENCE OF MEN AND EQPT.

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 32/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

RPLLB2460/26 (10 JUN 26)

"EXER CTN WHEN OPR TERMINAL 1 APN PRKG BAY NR 2, 5, 14, AND 15 DUE PRESENCE OF SOFT SPOTS AND POTHOLES."

RPLLB2160/26 (10 JUN 26)

TERMINAL 2 APN PRKG BAY NR 49 LTD TO CODE C AND LOWER CAT ACFT DUE WIP (CONST OF NEW TERMINAL 5 APN).

*RPLLB2161/26 (10 JUN 26)

"RWY 13/31 HR OF OPS:
TUE, WED, FRI, SUN: H24
MON, THU, SAT: 0000-1400, 2000-2359."

RPLLB2162/26 (10 JUN 26)

MON THU SAT 1400-2000
TWY J AND P CLSD DUE WIP (CONST OF TWY).

RPLLB2159/26 (10 JUN 26)

EXER CTN WHEN TAX PORTION OF TWY K (FM COORD 143045.25N 1210047.50E TO 143057.77N 1210034.83E) DUE WIP (CONST OF TWY).

RPLLB2158/26 (10 JUN 26)

TWY F1B CLSD DUE WIP (CONST OF TWY FM COORD 143124N 1210011E TO 143046N 1210050E).

RMK: PRESENCE OF MEN AND EQPT.

RPLLB2156/26 (10 JUN 26)

EXER CTN WHEN TAX ABM TWY H3 DUE WIP (CONST OF TWY).

RPLLB2157/26 (10 JUN 26)

EXER CTN WHEN TAX TWY P DUE PRESENCE OF OPEN TRENCH AT COORD: 143045N 1210049E.

RPLLB2155/26 (10 JUN 26)

EXER CTN WHEN TAX PORTION OF TWY K AT COORD: 143044N 1210048E DUE WIP (CONST OF TWY).

RPLLB2154/26 (10 JUN 26)

EXER CTN DRG LDG/TKOF RWY 06/24 DUE RANDOM LASER LGT EMITTING FM UNIDENTIFIED SOURCES.

RPLLB1948/26 (16 MAY 26)

EXER CTN WHEN OPR 5J RAMP 1 APN DUE WIP (LOADING AND UNLOADING OF EQPT) AT COORD: 143046N 1210113E.

RMK: PRESENCE OF MEN AND EQPT (CRANE WITH BOOM HGT APRX 28M).

ZGGG / CAN

ZBBBG2606/26 (26 JUN 26)

"TWY T1 CLSD BTN TWY C AND TWY D, DUE TO WIP."

ZBBBG2375/26 (15 JUN 26)

"ACTIVITIES OF BIRD FLOCKS MIGRATION WILL TAKE PLACE AROUND AD: SPORADIC BIRD ACTIVITY TIME: 2130-1500(NEXT DAY), ALT: 0M-50M. SOME BIRDS ARE ACTIVE AT ALT OF 60M-150M PRIOR TO LANDING ON RWY20L/02R/03/21/01L. AERODROME AUTHORITY RESORTS TO DISPERSAL METHODS TO REDUCE BIRD ACTIVITIES. EXERCISE CAUTION WHILE LANDING AND TAKE-OFF."

ZBBBG2328/26 (12 JUN 26)

LONGMEN VOR/DME 'LMN' 116.3MHZ/CH110X U/S DUE TO MAINT. 12 JUN 26 07:17 UNTIL 31 DEC 26 15:59 ESTIMATED

// (COM-INFO)//

THA 00290/17 (10 JUN 26)

COMP INFO:--RE GROUND POWER UNIT UTILIZATION AT GUANGZHOU BAIYUN INTL A/P AS NOTIFICATION TO AIRMAN-NOTAM STP INFO FROM CANKKTG:
" GPU N ACU WLBE CONNECTED TO A/C AFTER PARKING BRIDGE HAS BEEN

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 33/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

CONNECTED- REPEAT -ALL EXTERNAL POWER WLBE CONNECTED AFTER A/C
BLOCKED ON N BRIDGE CONNECTION IS COMPLETED STP"
(UPDATE 02JAN26/CANKK-INFO/UFN)

ZBBBBG1589/26 (10 JUN 26)

TWY B1 CLSD EAST OF TWY Y.
27 APR 26 06:23 UNTIL 29 JUL 26 15:59 ESTIMATED

ZBBBBG1566/26 (10 JUN 26)

FLW TWY ONLY AVBL FOR ACFT WITH WING SPAN NOT MORE THAN 65M:
1.TWY Q15 NORTH OF TWY Q10.
2.TWY Q16.
26 APR 26 04:00 UNTIL 26 JUL 26 04:00 ESTIMATED

ZBBBBG1489/26 (10 JUN 26)

TWY S1 CLSD.
21 APR 26 02:18 UNTIL 03 SEP 26 15:59 ESTIMATED

ZBBBBG1472/26 (10 JUN 26)

"DUE TO OPERATIONAL REQUIREMENTS, TWY B EASTBOUND, TURN RIGHT TO
TWY T1 ONLY AVBL FOR ACFT WITH WINGSPAN NOT MORE THAN 36M(ACFT
TYPE C AND BELOW)."
20 APR 26 06:24 UNTIL 17 JUL 26 15:59 ESTIMATED

ZBBBBG1471/26 (10 JUN 26)

TWY Q11 CLSD BTN TWY Q AND TWY Q15.
20 APR 26 06:20 UNTIL 17 JUL 26 15:59 ESTIMATED

ZBBBBG1329/26 (10 JUN 26)

"AD ADD LIMITATION AS FLW,DUE TO WIP:
1.WHEN TAXI IN TWY E,ACFT ARE FORBIDDEN TO TURN LEFT TO TWY J1.
2.WHEN TAXI IN TWY J1,ACFT ARE FORBIDDEN TO TURN RIGHT TO TWY E."
11 APR 26 05:55 UNTIL 10 JUL 26 15:59 ESTIMATED

ZBBBBG1005/26 (05 APR 26)

"TWY N CLSD BTN TWY T12 AND TWY T13,DUE TO OPERATION
REQUIREMENT."

ZBBBBG0023/26 (05 APR 26)

"DUE TO PINGZHOU VOR/DME 'POU' U/S,FLW SID PROCEDURE U/S:
1.SID RWY01L/01R(ZGGG-3V-5):SAREX-1.
2.SID RWY01L/01R(ZGGG-3V-7):VIBOS-1."
04 JAN 26 07:43 UNTIL 30 JUN 26 15:59 ESTIMATED

VMMC / MFM

VMMCA0227/26 (27 JUN 26)

"REFERRING TO AIP GEN 3.6.1, TABLE 3.6.3, AND AD 2.6, 3 BOATS USED
FOR RESCUE AND FIRE FIGHTING IN THE VICINITY OF AIRPORT ARE
AVAILABLE, EACH BOAT EQUIPPED WITH 2 LIFE RAFTS WITH A CAPACITY OF 38
PERSONS PER EACH RAFT.
SAR VESSELS OF MARINE AND WATER BUREAU AVAILABLE AT 2212.25N
11332.24E WITH 1 LIFE RAFT FOR 15 PERSONS. AT 2212.55N 11332.41E WITH
1 LIFE RAFT FOR 15 PERSONS, ONE BOAT WITH CAPACITY 43 PERSONS PLUS 4
LIFE RAFTS FOR 50 PERSONS PER EACH RAFT AND ONE BOAT WITH 4 LIFE
RAFTS FOR 100 PERSONS PER EACH RAFT."
27 JUN 26 13:51 UNTIL 31 JUL 26 23:59 ESTIMATED

VMMCA0225/26 (26 JUN 26)

TUE THU FRI SUN 1600-2359
TWY C1 CLOSED DUE TO WIP.SINGLE TWY OPERATION IMPLEMENTED.ALL
ARRIVING AND DEPARTING AIRCRAFT WILL PROCEED TO/FROM APRON VIA TWY H.

VMMCA0224/26 (26 JUN 26)

TUE THU FRI SUN 1600-2359
ILS CAT II RWY34 NOT AVAILABLE DUE TO WIP.

*VMMCA0195/26 (28 MAY 26)

TUE THU SUN 2000-2200
RWY 16/34 CLOSED DUE TO MAINTENANCE.

VMMCA0190/26 (22 MAY 26)

AIRCRAFT STAND B2 CLOSED DUE TO WIP.

Official Pilot Briefing

THA677 28JUN26 HSTTC B773E RJAA 0825 VTBS 1455

Page 34/34
Trans ID: 5041390
Creation Time: 28.06.2026 01:50UTC

VMMCA0163/26 (27 APR 26)

"UNLESS SPECIFIED BY MACAU ATC, IN CASE OF RWY34 MISSED APPROACH,
ALL TRAFFIC SHALL INITIALLY CLIMB TO 4000FT AND MAINTAIN. EXPECT
FURTHER CLIMB BY ZHUHAI ATC."

VVDN / DAD

VVVVA1937/26 (17 JUN 26)

"REF AIP SUP 12/26 WEF 04 MAR 2026,
FREE OF CHARGE FOLLOW-ME CAR IS PROVIDED TO GUIDE ACFT TAX
IN/OUT STANDS WI CONST AREA DURING CONST PERIOD."

VVVVA1805/26 (10 JUN 26)

CLEANING ON RWY 35R/17L WHEN THERE ARE NO FLT OPS OR DRG
INTERMITTENT TIME BTN FLTS.

VVVVA1512/26 (20 MAY 26)

MAY 30 JUN 06 13 20 27 JUL 11 1330-1355 1405-1430

"DUE TO FIREWORK DISPLAY ACT,
DO NOT USE THE FLT PROCEDURES AS FLW :
- CIRCLING CAT B, C, D
- PBN PROCEDURES:
IAP: RNP Z/Y RWY 35L/R
(SEE NOTAM VVVV A1511/26)."

VVVVA1487/26 (18 MAY 26)

"SON TRA 1 RADAR (SSR/PSR) CMPL WITHDRAW
REF AIP VIET NAM ENR 1.6, ITEM 1.1.4A."

VVVVA1151/26 (21 APR 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS) AT ACFT STAND 27
CMPL WITHDRAWN. REF AIP VIETNAM ITEM VVDN AD 2.9.

VVVVA1328/22 (17 OCT 23)

THE ADJUSTMENT OF STOP LINE OF ACFT FOR STANDS 1-9 AS FLW:
114.7 M FM TAXILANE D TO THE EAST.

VVVVA1209/22 (17 OCT 23)

"VISUAL DOCKING GUIDANCE SYSTEM (VDGS) IS SAFEDOCK TYPE T1
(T-TYPES),
AVBL AT ACFT STANDS 21, 23, 25
- REF AIP VIET NAM ITEM VVDN AD 2.9 PAGE AD 2.VVDN-7 DATED 30 JUL
2021."

VVNB / HAN

VVVVA2135/26 (27 JUN 26)

28 JUN 2026 09:15-28 JUN 2026 09:25
DEP/ARR ACFT MAY BE DLA DUE TO VIP MOV.

VVVVA1971/26 (19 JUN 26)

"WIP ON APN (FM STANDS 77 TO 86, STANDS 1H, 2H, 3H, 9H) DRG
INTERMITTENT TIME BTN FLIGHTS
RMK: THE WORKING AREA WILL BE STOPPED WHEN THERE ARE VIP FLT
OPS, VIS LESS THAN 2000M OR BAD WX CONDITIONS."

THA677 28JUN26/0825 RJAA/VTBS

N I L