

GENERAL INFORMATION**## Company Fuel Guidelines ##**

THA 00159/26 (18 JUN 26)

OM INFO:--WEF 19JUN26,
Company Fuel Guidelines:
1) Flight Outbound from VTBS:
1.1) 15 mins:
-TG319
-ETA within TEMPO ±1 hr with adverse weather condition

1.2) 5 mins:
-BLR (ONLY WHEN SINGLE RWY OPS)
-TG317, TG407, TG409*

2) Flight Inbound to VTBS:
2.1) 20 mins:
ETA within TEMPO ±2 hrs with adverse weather condition*

2.2) 5 mins:
ETA 22:00-24:00 (BKK local time)

3) European Flights:
3.1) Outbound flight to European: CF 3 PERCENT (Except TG916/CF5)

3.2) Inbound flight to VTBS: RCFP + 05MINS

4) Flight Level Plan for VTUK,
-Outbound from VTBS: FL250
-Inbound to VTBS: FL240

5) Planning for Arrival WADD:
To improve flight planning accuracy, for WADD arrivals,
after waypoint KOLTA, flights shall plan to DOBMA
and then follow DOBMA## STAR.

6) TG649: Flight level shall not be planned above FL380.

7) TG900: When ETA falls within TEMPO ±2 hrs and adverse weather conditions, LTAC shall be
designated as the destination alternate.

8) Destination VTUD*:

Remove altitude restrictions and use the optimum altitude for planning.

Remark:
1) Pilot Management Department (PA)

1.1) Destinations ZBAA and ZSPD:

Flights shall be planned as Economic Tankage without company fuel, with the following
conditions:

-Widebody aircraft shall be planned with far alternates (RKSI, RJFF).

-Narrowbody aircraft shall be planned with ZBTJ as the alternate; however, ZFW shall be
restricted to ensure the carriage of at least 30 minutes of extra fuel.

1.2) Destination YPPH: ALTN YGEL (+05MINS EXTRA FUEL)*

YGEL shall be used as ALTN airport effective 25 Apr 2026 following revision of OM-A section
8.3.26 (Operations at Uncontrolled Aerodromes)

2) Everything else regarding fuel planning policy remains the same as last month.

3) Adverse weather conditions*:
RA, TS or TSRA and visibility 5000m or less

(REVISED NO.1/REF EMAIL Summary of Fuel Initiatives Meeting - 08JUN26
For Fuel Committee member/BKKPC)

// (COM-INFO) //

THA 00002/13 (31 MAY 26)

COM INFO:--All A350 and BOEING 787:
are now eligible and included in EUROCONTROL airspace CPDLC Logon list.
Action Required: Pilots are required to initiate CPDLC logon when entering European airspace.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 2/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

(ISSUED 23MAR26/BKKPC2/UFN)

--IN CASE CANNOT BE CONTACTED BKKOC VIA TELEPHONE,
PILOTS MAY CONTACT VIA MS TEAMS CHANNEL: "OC.CENTER".
(ISSUED 30JUL24/BKKOC/UFN)

-- To improve CTOT for all flights both outbound from BKK and inbound to BKK, pilots may contact TOCC when ready for departure to request an earlier CTOT through any of the following channels:

: MS Teams chat
: LINE CLC-Pilot
: CUT 129.325
: Phone 02-137-1202

In addition to above contact channels, for DOMESTIC flight, pilots may also directly contact ground staff to request earlier CTOT. (ISSUED 15FEB25/BKKOP/UFN)

--DELEGATED FUNCTIONS PHONE DIRECTORY (Direct Number)

1. OPEN BOARDING GATE : 02-137-1260
2. BUS GATE - REMOTE BAY & DOMESTIC V.V. : 02-137-1260
3. CREW BUS OPC-TERMINAL V.V. : 02-137-1019, 02-137-1020
4. CONFIRM BOARDING GATE/BAY/BELT : 02-137-1263
5. ZFW/WEIGHT & BALANCE/LOAD SHEET : 02-137-1291, 02-137-1292
6. TG LOST & FOUND : 02-134-5454
7. OTHER INQUIRIES/BKKOC : 02-137-1202

(ISSUED 17JUL22/BKKOC-INFO/UFN)

--If expected divert due to weather or traffic congestion at any TG destination airports, please kindly advise TOCC, via ACARS using OPERATIONS prompt or SITA address BKKOPTG, the current fuel on board immediately to keep close monitoring of the flight.
(ISSUED 08MAY25/BKKOP/UFN)

--In case of pilot receives information from ground staff to delay departure due to connecting passenger, please kindly confirm with TOCC via CUT channel.
(ISSUED 27NOV24/BKKOP/UFN)

--FOR FLIGHTS PLANNED NAVIGATING THROUGH KABUL FIR,
ONCE FINAL FL TO ENTER KABUL FIR IS AVAILABLE,
PLEASE ACARS DOWNLINK ETO/ENTRY WPT/FL TO BKKOPTG
(ISSUED 12DEC24/BKKOC/UFN)

--Please kindly consider and issue recommendation for route P500 G500 as soon as possible in order to reduce operational risk.

1. Due to limitation of passenger oxygen chemical type (22 minutes).
If weather deviation is required, pilots shall deviate west of route only.

2. In an event of critical in-flight emergency, the aircraft should follow ICAO emergency descent procedures, broadcast status and intentions on 125.2 MHZ and 121.5 MHZ. Thereafter, proceed at the discretion of the PIC until clear Kabul FIR and in contact with the ATC responsible for the airspace.
(ISSUED 31JUL24/D1/OC/UFN)

--Any flight operation by TG into the uncontrolled airspace and conflict zone, the latest operational information " Closures and Warnings" issued by means of ICAO State letters,
NOTAMs, AICs/AIPs, and EASA CZIB - TG are subject to strictly following the guidance/directions from their national authority as well as their own risk assessment.
(ISSUED 15APR24 CORR/TN003/22/OW/UFN)

--WEF 01JUN26,
SUBJ: SPECIAL SECURITY ARRANGEMENT:SSA006/2026
ATTN ALL CONCERNED

THE AVIATION SECURITY COMMITTEE (ASC) MTG ON 21MAY2026
AGREED TO ANNOUNCE SSA006/2026 AS FLWS:

AA PLS BE INFM THT THIS SSA WILL SUPERSEDE SSA005/2026
FROM 01JUN2026 UNTIL FURTHER TLX ADV

BB FR FLT DEP FRM STATION EUROPE: ARN BRU CDG CPH FRA IST LHR MUC
MXP OSL ZRH

LEVEL: LOW CMA PERFORM SSA ACCORDING TO EU REQUIREMENTS
AS FLWS:

A1 - A/C PRE-FLIGHT SECURITY SEARCH CONDUCTED BY PIC CMA
CABIN CREW CMA ASM/SMT/DELEGATED PERSONNEL N GROUND/
STATION ENGINEER

A18-1 5% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
CONDUCTED BY CABIN CREW

CC FR FLT DEP FRM STATION: DAC KHI KTI ISB LHE RGN SAI

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW

DD FR DOM FLT DEP FRM STATION: HDY HKT UBP

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW

EE FR FLT DEP FRM MAINBASE STATION: BKK

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW
F2 - IDENTITY CHECK OF CREW MEMBERS BEFORE BOARDING AT
BOARDING GATE
P2 - SECONDARY CHECK AT GATE
(APPLY ONLY FLT FRM BKK TO MEL PER N SYD)

FF THE FLWG SSA SHALL BE IMPLEMENTED FR ALL ROUTE AS NORMAL PROC
P5 - INTENSIVELY PERFORM IDENTITY CHECK N VERIFICATION OF PAX
BEFORE BOARDING A/C BY
- COMPARING PAX WZ PHOTOGRAPH N PASSPORT/TVL DOCS TO
ENSURE PAX IS BONA FIDE N
- VERIFYING THE NAMES IN THE TICKETS CORRESPOND TO THOSE
ON THE IDENTITY DOCS
V1 - ALERT STAFF TO OBSERVE UNUSUAL BEHAVIOR OF PAX N ALL
PERSONNEL INVOLVED N ANY SUSPICIOUS ITEM IN THE
OPERATING AREA

GG THOSE STN NOT ON THE LIST ABOVE ARE LOW LEVEL STP
APPLY NORMAL SECURITY PROC AS MENTIONED IN OPERATION MANUAL

ADDITIONAL INSTRUCTION.

FR FLT OPS TO BLR MAA N CCU PLS IMPLEMENT THE FLW MEASURES AT THE
CHK-IN COUNTERS;

1. PROV DEDICATED CHK-IN COUNTERS FR FLT TO BLR MAA N CCU
2. DISPLAY WARNING N INFO SIGNAGE AT:
-CHK-IN COUNTERS
-B/D GATE
-FLT INFO DISPLAY SYSTEM (FIDS) AT CHK-IN COUNTERS
3. CONDUCT RANDOM X-RAY SCREENING OF SUSPICIOUS BAG AT CHK-IN
COUNTERS
4. CONDUCT RANDOM SCREENING BY USING SNIFFER DOGS IN THE CHK-IN AREA.

IN CASE OF THREAT SITU N EXTRA MEASURES ARE REQ CMA
STN MONITORING TEAM/SMT MAY RAISE UP MEASURES AS APPROPRIATE

ANY SECURITY INCIDENTS MAY OCCUR SHALL INFO MANAGEMENT CONCERNED
N BKKD1 ACCLY STP

REMARK

A18-1 5% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
WILL BE REVISED IN SPM NEXT REVISION

PLS ACK N CFM ACTUAL PERFORM TO OFC BKKD1-B
BRGDS/CAPT. CHINGCHEEP B./BKKD1 ASC CHAIRMAN

Minima for flight planning

THA 00136/26 (29 MAY 26)

COM INFO: Application of planning minima for flight planning

Due to limited space in the OFP fuel planning box, any display of "BASIC FUEL SCHEME" shall be interpreted as "BASIC FUEL SCHEME WITH VARIATION."

All THAI flights are planned using Basic Fuel Scheme with Variation, unless otherwise specified by Flight Dispatcher.

Alternate planning minima shall be applied in accordance with OMA 8.1.7.5.2.
Display format will be reviewed and updated following stakeholder discussion.

OFP - TCAR format

THA 00093/26 (18 MAY 26)

COM INFO: SFP/OFP change format according to OM-A (TCAR version)

Due to identified limitations in the current OFP template,
the following temporary procedures shall apply with immediate effect:

1. RVSM - Standby Altimeter

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 4/90

Trans ID: 5040609

Creation Time: 27.06.2026 12:51UTC

The current OFP does not provide a dedicated line for Standby Altimeter recording as required by OMA 14.4.4.

Action: Record the Standby Altimeter value adjacent to the existing record row.

This procedure is mandatory to ensure compliance with OMA 14.4.4.

2. RAIM Information

RAIM shown in the OFP is for terminal operations only.

Action: For flights requiring NPA, crew shall verify RAIM availability separately using an approved RAIM Forecast Report.

3. RCFP - MINF at DP

the displayed MINF at DP may be incorrect.

Action: Disregard the displayed value and refer to the minimum fuel at DP provided in the eOFP application to maintain information consistency.

These instructions are mandatory until corrected in the next OFP version.

FLIGHT LEG INFORMATION

VTBSEBBR

AIP SUP 014/26

THA 00080/26 (27 MAR 26)

// (SEE ATTCH) //

AERODROME INFORMATION

VTBS / BKK

VTBDC3502/26 (26 JUN 26)

26 JUN 2026 10:15-27 JUN 2026 19:00
ACFT STAND NR E5 CLSD DUE TO WIP

*VTBDC3500/26 (26 JUN 26)

28 JUN 2026 19:00-28 JUN 2026 23:00
RWY 01/19 CLSD DUE TO WIP

VTBDC3499/26 (26 JUN 26)

28 JUN 2026 19:00-28 JUN 2026 22:30
TXL CLSD DUE TO WIP DETAIL AS FLW:
-TXL T13 BEHIND ACFT STAND NR E2 E4 E6 E8 E10 401 402 403
-TXL T14 BEHIND ACFT STAND NR F1 F3 F5

VTBDC3498/26 (26 JUN 26)

27 JUN 2026 19:00-27 JUN 2026 23:00
TXL CLSD DUE TO WIP DETAIL AS FLW:
-TXL T11 BEHIND ACFT STAND NR E1 E3 E5 E7 E9
-TXL T12 BEHIND ACFT STAND NR D7 D8

VTBDC3491/26 (26 JUN 26)

BANGKOK / SUVARNABHUMI INTERNATIONAL AIRPORT PSR U/S

*VTBDC3478/26 (25 JUN 26)

27 JUN 2026 20:30-27 JUN 2026 21:45
RWY 01/19 CLSD DUE TO WIP

VTBDC3476/26 (25 JUN 26)

26 JUN 2026 17:00-27 JUN 2026 23:30
"26 1700-2315, 27 1700-2330"
TWY CLSD DUE TO WIP DETAIL AS FLW:
-TWY F
-TWY F1 TO TWY F12
-TWY F15
-TWY W
-TWY Y
-TWY Z

*VTBDC3474/26 (25 JUN 26)

26 JUN 2026 17:00-27 JUN 2026 23:30
"26 1700-2315, 27 1700-2330"
RWY 02L/20R CLSD DUE TO WIP

OB Company Safety NOTAM-BKK

THA 00161/26 (22 JUN 26)

// (SEE ATTCH) //

// (COM-INFO) //

THA 00029/26 (18 JUN 26)

COM INFO:--WEF 16FEB26 04:00LT
The operation of opening aircraft doors from outside for all arriving flight
by ground staff at BKK station will be fully implemented.
(refer IOC GB/SS/005-26 date 30JAN 26/UFN)

// (COM-INFO) //

THA 00064/25 (18 JUN 26)

COM INFO:--REF AIP SUP A53/25:
RETILs U/S:
RWY 01/19: TWYs B3, B5, B7, B8, B10 and B11
RWY 02R/20L: TWYs E5, E7, E9, E12, E13, E15.

--1) The Visual Docking Guidance System (VDGS) at
the ACFT stands 101 - 114 are U/S. (14 ACFT stands).
2) Airlines or Ground service providers shall provide a License Mechanic
performed as Marshaller to guide the aircraft from taxilane to the
parking position.
3) The ACFT are strongly advised to strictly follow the Marshaller's signal.
(REF AIP SUP A13/25*)

--Suvarnabhumi:
DVOR/DME (SVB) (133932.5N 1004353.2E) (111.4 MHZ, CH51X) temporary suspended
from 28 November 2024 at 0001 UTC to 02 October 2026 at 0949 UTC.
(REF AIP SUP A54/24*)

--Taxiway C between Taxilane T1 and Taxilane T2, Taxiway C1 closed.
(REF AIP SUP A01/25*)

VTBDC2661/26 (07 JUN 26)

"AD 2.24 CHARTS RELATED TO AN AD,
IAC-ICAO CHANGED ALT AT IF AS FLW:
AD2-VTBS 8-9 ILS OR LOC Z RWY 19 CAT II
:READ ALT2500 (2496) INSTEAD OF ALT3000
AD2-VTBS 8-13 ILS OR LOC Z RWY 20L CAT II
:READ ALT3500 (3496) INSTEAD OF ALT4000
AD2-VTBS 8-23 RNP RWY 19 :READ ALT2500 (2496) INSTEAD OF ALT3000
AD2-VTBS 8-25 RNP RWY 20L :READ ALT3500 (3496) INSTEAD OF ALT4000
AD2-VTBS 8-27 RNP RWY 20R :READ ALT3500 (3492) INSTEAD OF ALT4000
REF AIRAC AIP AMDT AD2-VTBS-8-9, AD2-VTBS-8-13, AD2-VTBS-8-23,
AD2-VTBS-8-25, AD2-VTBS-8-27"

VTBDC2039/26 (19 APR 26)

ADVANCED VISUAL DOCKING GUIDANCE SYSTEM (A-VDGS)
ACFT STAND NR 119 308 516 AND 520 U/S DUE TO MAINT
RMK: ACFT HAVE TO FLW MARSHALLING SIGNALS STRICTLY

EBBR / BRU

EBBRD0373/26 (27 JUN 26)

27 JUN 2026 12:00-27 JUN 2026 19:00
BRUSSELS TMA (IFR TRG / PJE / VFR FLT) PPR BLW FL075.

*EBBRA2197/26 (27 JUN 26)

28 JUN 2026 18:50-28 JUN 2026 19:10
"AD LTD: ARR AND DEP NOT ALLOWED, DUE TO SPECIAL EVENT."

EBBRA2170/26 (25 JUN 26)

STOPBAR LIGHTS 1/2 U/S ON TWY F4

EBBRA2157/26 (24 JUN 26)

TWY C6 CLSD

EBBRD0351/26 (23 JUN 26)

IAP VOR RWY 07L NOT AVBL
23 JUN 26 20:42 UNTIL 30 SEP 26 20:00 ESTIMATED

EBBRA2113/26 (22 JUN 26)

22 JUN 2026 13:50-28 JUN 2026 21:59
"DUE TO HIGH TEMPERATURES, USE OF AIRCRAFT APU IS PERMITTED AT ALL
TIMES WITHOUT PRIOR APPROVAL FROM AIRSIDE INSPECTION"

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 6/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

EBBRA2097/26 (22 JUN 26)

"TWY OUT-6, B3 AND INT BTN THESE TWY CLSD DUE TO WIP"

EBBRA2098/26 (22 JUN 26)

INT INN-6 WITH OUT-7 AND INT OUT-7 WITH B1 RESTRICTED TO ACFT
WITH WINGSPAN SMALLER THAN 68.6M

EBBRA2079/26 (19 JUN 26)

28 JUN 2026 07:30-28 JUN 2026 13:00
RWY 19 ILS IBM U/S DUE TO MAINT. DO NOT USE. FALSE INDICATIONS
POSSIBLE

EBBRA1970/26 (12 JUN 26)

"ACFT STAND 400,402,404 HANDLING ONLY ALLOWED BY DAY"

EBBRA1877/26 (06 JUN 26)

DAILY 0600-1400
TWY OUT-5 RESTRICTED TO ACFT WITH WINGSPAN SMALLER THAN 68.6M

EBBRD0246/26 (06 JUN 26)

DAILY 1500-0700
"IAP RNP RWY07L LPV INCREASED OCA CAT A: 428FT, CAT B: 438FT, CAT
C: 447FT, CAT D: 457FT"

EBBRD0245/26 (06 JUN 26)

DAILY 1500-0700
"IAP RNP RWY07L LNAV/VNAV INCREASED OCA CAT A: 428FT, CAT B:
438FT, CAT C: 447FT, CAT D: 457FT"

EBBRA1055/26 (12 APR 26)

"INT BTN TWY OUT-5, OUT-6, INN-5 AND INN-6 CL LIGHTS U/S"

EBBRA0669/26 (11 MAR 26)

RWY 25R ILS U/S DUE TO MAINT. DO NOT USE. FALSE INDICATIONS
POSSIBLE. NO IDENT CODE RADIATED

EHAM / AMS

EHAMA1474/26 (26 JUN 26)

CHANGE OF OPERATING MINIMA OCA(OCH) RWY 27 DUE TO CRANE.
LOC ACFT CAT A-DL INCREASED TO 762(772).
LNAV ACFT CAT A-DL INCREASED TO 631(642).
REF AIP AD 2.EHAM IAC RNP RWY 27 AND AD 2.EHAM IAC LOC RWY 27.

EHAMA1463/26 (26 JUN 26)

"CHANGE OF CIRCLING MINIMA OCA(OCH) DUE TO CRANE.
CAT A AND B INCREASED TO 916(927),
CAT C AND D AND DL INCREASED TO 1014(1025)."
26 JUN 26 08:12 UNTIL 05 JUL 26 22:00 ESTIMATED

EHAMA1462/26 (26 JUN 26)

CHANGE OF OPERATING MINIMA OCA(OCH) RWY 18C DUE TO CRANE.
LOC ACFT CAT A-DL INCREASED TO 867(877).
LNAV ACFT CAT A-DL INCREASED TO 823(834).
REF AIP AD IAC ILS CAT II AND III OR LOC RWY 18C AND IAC RNP RWY
18C.
26 JUN 26 08:11 UNTIL 05 JUL 26 22:00 ESTIMATED

EHAMA1432/26 (23 JUN 26)

TWY S1 CLSD.

EHAMA1429/26 (23 JUN 26)

TWY R CLSD.

EHAMA1404/26 (18 JUN 26)

TURN FROM TWY A TO TWY A15 AND TURN FROM TWY A15 TO TWY A
PROHIBITED IF DISTANCE BTN OUTSIDE EDGES OF THE ACFT MAIN GEAR WHEELS
IS 9M OR MORE.
18 JUN 26 11:21 UNTIL 18 SEP 26 10:00 ESTIMATED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 7/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

EHAMA1403/26 (18 JUN 26)

CL LGHTS TWY A BTN TWY A21 AND TWY A25 U/S. MARSHALLER GUIDANCE
REQUIRED IF RVR 350M OR LESS.

EHAMA1401/26 (18 JUN 26)

CL LIGHTS TWY A25 U/S. MARSHALLER GUIDANCE REQUIRED IF RVR 350M OR
LESS.

EHAMA1379/26 (15 JUN 26)

"TWY CENTRE LINE LIGHTS TWY A4W BTN ACFT STAND B15 AND B27 U/S,
TWY CENTRE LINE LIGHTS TWY A4E BTN ACFT STAND C6 AND C10 U/S,
MARSHALLER GUIDANCE REQUIRED IF RVR 350M OR LESS."
19 JUN 26 07:00 UNTIL 15 SEP 26 12:00 ESTIMATED

EHAMA1355/26 (12 JUN 26)

ILS RWY 18C DOWNGRADED TO I/C/1 (SUPPORT CAT 1 OPERATIONS).

EHAMA1354/26 (12 JUN 26)

ILS RWY 36C OUT OF SERVICE.
12 JUN 26 06:44 UNTIL 03 JUL 26 12:00 ESTIMATED

EHAMA1330/26 (09 JUN 26)

"CORRECT WPT AM096 COORDINATE ON CHART TO READ 521626.65N
0044022.06E
REF AIP AIRAC AMDT 06/2026 WEF 11 JUN 2026, EHAM AD 2 SID 24 WEST RF."

EHAMA1316/26 (08 JUN 26)

MON-FRI 0500-1500
"REF AIP NETHERLANDS AD 2.EHAM AOC TYPE A RWY 18C-36C.
CRANE ERECTED AT PSN 521700.1N 0044411.0E, 2000M BEYOND TORA RWY 18C
ON EXTD RCL, 138FT AMSL, MARKED AND LGTD.)"

EHAMA1315/26 (08 JUN 26)

MON-FRI 0500-1500
CHANGE OF OPERATING MINIMA OCA(OCH) RWY 36C DUE TO CRANE.
LOC ACFT CAT A-DL INCREASED TO 384(396).
REF AIP AD 2 EHAM IAC ILS CAT II AND III OR LOC RWY 36C.

EHAMA1314/26 (08 JUN 26)

MON-FRI 0500-1500
"CHANGE OF OPERATING MINIMA OCA(OCH) RWY 06 DUE TO CRANE
LPV ACFT CAT A INCREASED TO 270(281), CAT B INCREASED TO 279(290),
CAT C INCREASED TO 289(300), CAT D-DL INCREASED 299(310).
REF AIP AD 2.EHAM IAC RNP RWY 06.)"

EHAMA1263/26 (01 JUN 26)

TWY A4W BTN STAND B15 AND STAND B23 CLSD.

EHAMA1201/26 (28 MAY 26)

MON-FRI 0500-1500
"CHANGE OF OPERATING MINIMA OCA(OCH) RWY 22 DUE TO CRANE.
ILS CAT I ACFT CAT A-D INCREASED TO:
CAT A 184 (198), CAT B 196 (210),
CAT C 205 (218), CAT D 215 (228).
REF AIP AD 2 EHAM IAC ILS OR LOC RWY 22."

EHAMA1200/26 (28 MAY 26)

MON-FRI 0500-1500
"CHANGE OF OPERATING MINIMA OCA(OCH) RWY 04 DUE TO CRANE.
RNP LPV CAT A-D INCREASED TO:
CAT A 254 (267), CAT B 267 (280),
CAT C 275 (288), CAT D 285 (298).
REF AIP AD2. EHAM IAC RNP RWY 04."

EHAMA1091/26 (12 MAY 26)

"SIDS RWY 36L BERGI5V, SPY4V AND VOLLA3V CHANGED DUE TO CRANE.
A MINIMUM OF 3.5 PERCENT CLIMB GRADIENT REQUIRED UNTIL LEVKI.
CRANE ERECTED BTN PSN 522245.1N 0044226.1E AND 522247.4N 0044211.7E.
1700M BEYOND TORA RWY 36L AND 410M LEFT OF EXTD RCL, 158FT AMSL,
MARKED AND LGTD."

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 8/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

EHAMA1090/26 (12 MAY 26)

"RWY 36L DEVIATION FROM SID STRICTLY PROHIBITED UP TO 500FT AMSL
DUE TO CRANES BTN PSN 522245.1N0044226.1E AND 522247.4N0044211.7E.
1700M BEYOND TORA RWY 36L AND 410M LEFT OF EXTD RCL, 158FT AMSL,
MARKED AND LGTD."

EHAMA1057/26 (07 MAY 26)

CHANGE OF OPERATING MINIMA OCA (OCH) RWY 04 LPV ACFT
CAT A INCREASED TO 364 (377)
CAT B INCREASED TO 376 (389)
CAT C INCREASED TO 395 (409)
CAT D INCREASED TO 423 (436)
REF AIP NETHERLANDS AD 2 EHAM IAC RNP RWY 04.
07 MAY 26 16:00 UNTIL 06 AUG 26 23:59 ESTIMATED

EHAMA1058/26 (07 MAY 26)

CHANGE OF OPERATING MINIMA OCA (OCH) RWY 24 LPV ACFT
CAT A INCREASED TO 363 (374)
CAT B INCREASED TO 375 (386)
CAT C INCREASED TO 394 (405)
CAT D-DL INCREASED TO 421 (432)
REF AIP NETHERLANDS AD 2 EHAM IAC RNP RWY 24.
07 MAY 26 18:00 UNTIL 06 AUG 26 23:59 ESTIMATED

EHAMA1056/26 (07 MAY 26)

CHANGE OF OPERATING MINIMA OCA (OCH) RWY 09 LPV ACFT
CAT A INCREASED TO 345 (357)
CAT B INCREASED TO 357 (369)
CAT C INCREASED TO 376 (388)
CAT D-DL INCREASED TO 403 (415)
REF AIP NETHERLANDS AD 2 EHAM IAC RNP RWY 09.
07 MAY 26 18:00 UNTIL 06 AUG 26 23:59 ESTIMATED

EHAMA0990/26 (30 APR 26)

INCREASED BIRD ACTIVITY ON AND AROUND AD. AN INCREASED POTENTIAL
FOR BIRD STRIKES EXISTS FOR ALL INBD AND OUBD ACFT.
30 APR 26 11:03 UNTIL 30 JUL 26 12:00 ESTIMATED

EHAMA0942/26 (23 APR 26)

28 JUN 2026 15:00-03 JUL 2026 13:00
TWY CL LIGHTS TWY A BTN TWY A22 AND TWY A25 U/S.
MARSHALLER GUIDANCE REQUIRED IF RVR 350M OR LESS.

EHAMA0765/26 (31 MAR 26)

ACFT TOWED BY A YELLOW-COLOURED TOW TRUCK EQUIPPED WITH
ANTI-COLLISION LIGHTS IS UNDER THE PILOTS COMMAND AND REFERRED TO BY
ATC AS TAXITOW. RIGHT-OF-WAY IN ACCORDANCE WITH TAXIING ACFT IS
APPLICABLE.
31 MAR 26 09:28 UNTIL 30 JUN 26 12:00 ESTIMATED

EHAMA0722/26 (31 MAR 26)

CONSTRUCTION PHASE 26.0 IN PROGRESS. REF AIP SUP 30/2025.

EHAMA3004/25 (31 MAR 26)

TWY A BTN TWY A28 AND TWY A29 ACFT WITH WINGSPAN MORE THAN 69M
MUST BE GUIDED BY MARSHALLER.
17 DEC 25 23:46 UNTIL 31 DEC 26 23:00 ESTIMATED

ADDITIONAL INFORMATION

EDDK / CGN

EDDZA3299/26 (27 JUN 26)

27 JUN 2026 20:00-29 JUN 2026 04:00
"SAT 2000-0400, SUN 1200-0400"
NOISE ABATEMENT FACILITY U/S.

EDDZA2728/26 (06 JUN 26)

"NOERVENICH DVORTAC NVO 116.20MHZ/CH109X, DVOR PART NO USABLE
OPERATIONAL COVERAGE IN SECT 070DEG TO 130DEG (CLOCKWISE) UP TO 20NM
AT OR BELOW 3000FT AMSL."
27 MAY 26 15:10 UNTIL 27 AUG 26 15:00 ESTIMATED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 9/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

EDDZA2678/26 (06 JUN 26)

"LPV APCH REOPERATIVE.
OCA(H) VALUES RAISED:
LPV RWY 06: A 553 (324), B 564 (335), C 591 (362), D 601 (372)FT.
LPV RWY 13L: A 607 (378), B 617 (388), C 624 (395), D 633 (404)FT.
LPV RWY 13R: A 581 (361), B 591 (371), C 598 (378), D 607 (387)FT.
LPV RWY 24: A 721 (450), B 734 (463), C 742 (471), D 752 (481)FT.
LPV RWY 31L: A 655 (397), B 667 (409), C 675 (417), D 685 (427)FT.
LPV RWY 31R: A 651 (351), B 664 (364), C 672 (372), D 682 (382)FT.
DUE TO INADEQUATE PROTECTION PROVIDED IN THE MISSED APCH SEGMENT
FOR SOME NAVIGATION SYSTEMS AUTHORISED FOR LPV OPS."
26 MAY 26 12:34 UNTIL 18 AUG 26 23:59 ESTIMATED

ETCZP4398/26 (06 JUN 26)

AD EDDK MIL PART:
LIMITED PARKING POSITIONS ON MIL APRON

TO AVOID DELAY DUE TO GROUND HANDLING
ACFT USING KOELN/BONN MILITARY APRON ARE MANDATORY TO CONTACT
WOC ADDITIONALLY ON MIL FREQUENCY 15 MIN PRIOR TO LANDING:

VHF 136.255 MHZ
UHF 378.225 MHZ

IN CASE OF CHG ETA PRIOR DEP OTHER THAN PPR PLS CONTACT WOC:
BW 90 3451 3267 CIV 0049 (0)2203 908 3267
18 MAY 26 14:19 UNTIL 18 AUG 26 15:18 ESTIMATED

EDDZA1886/26 (30 APR 26)

KOELN-BONN LOCATOR LJ 365.00KHZ OUT OF SERVICE.

EDDZA1826/26 (30 APR 26)

"ALL RNP APCH PROC RWY 13R/31L TEMPO SUSPENDED DUE TO MISSING
FLIGHT VALIDATION. REF AIP PAGES AD 2 EDDK 4-6-7, 4-6-8, 4-6-9,
4-6-13, 4-6-14, 4-6-15 ALL EFFECTIVE 16 APR 2026."
16 APR 26 00:00 UNTIL 16 JUL 26 23:59 ESTIMATED

EDDZA1825/26 (30 APR 26)

"OMNIDIRECTIONAL INSTRUMENT DEP PROC EDDK 1M AND EDDK 1E FOR RWY
13R/31L TEMPO SUSPENDED DUE TO MISSING FLIGHT VALIDATION.
REF AIP PAGES AD 2 EDDK 5-7-1, 5-7-4, 5-7-6 EFFECTIVE 16 APR 2026."
16 APR 26 00:00 UNTIL 16 JUL 26 23:59 ESTIMATED

EDDZA1792/26 (30 APR 26)

"ILS OM RWY 13L, CHECK DME READING KBO ADDN.
MARKER NOT REMOTE CONTROLLED."

EDDZA1791/26 (30 APR 26)

"ILS MM RWY 13L, CHECK DME READING KBO ADDN.
MARKER NOT REMOTE CONTROLLED."

EDDZA1660/26 (05 APR 26)

COLA DVOR/DME COL 108.80MHZ/CH25X RADIAL 250 UNUSABLE FROM
ONM - 31NM BELOW 6000FT AMSL.

EDDZA1577/26 (05 APR 26)

"OCA(H) VALUES RAISED:
SRA RWY 13L: ACFT CAT A-D 920 (690)FT.
DUE TO HIGH CRANES 13500M (7.3NM) BFR THR RWY 13L, 1560M SW OF
EXTD RCL, 505738N 0065855E, ELEV 671FT, MARKED AND LGTD."
30 MAR 26 12:51 UNTIL 29 JUN 26 23:59 ESTIMATED

EDDZA3910/25 (04 OCT 25)

NEW ACFT STANDS INSTALLED:
A25: 505234.79095N 0070710.85488E
A27: 505235.25636N 0070709.11813E
A29: 505235.28775N 0070707.14353E
A31: 505237.18196N 0070706.22441E
A33: 505237.20853N 0070708.26597E
A35: 505237.20688N 0070710.33309E

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 10/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

LFPG / CDG

LFFAA4340/26 (27 JUN 26)

27 JUN 2026 16:00-27 JUN 2026 22:00
"DUE TO WEATHER SITUATION, ARR FLIGHTS TO LFPG SHALL PLAN AT LEAST
ONE DEST ALTERNATE AD DIFFERENT FROM LFPO/LFOB.
EMERGENCY DIVERSIONS REMAIN POSSIBLE."

LFFAA4286/26 (25 JUN 26)

TAXIWAY T3 CLOSED.

LFFAA4285/26 (25 JUN 26)

TWY ST CLOSED.

LFFAA4182/26 (23 JUN 26)

TWY M CLOSED FM ENGINE RUN-UP STAND PM2 TO TWY EM7 INCLUDED

LFFAA4164/26 (23 JUN 26)

TWY MD2 CLSD.

LFFAA4128/26 (22 JUN 26)

AIRAC AIP SUP 019/26 : PHASE 2 ACTIVATED

LFFAA4126/26 (22 JUN 26)

TRIGGER NOTAM - AIRAC AIP SUP 019/26 :
RESTRICTIONS ON USE OF AD PARIS CHARLES DE GAULLE - REHABILITATION
AND CLOSURE OF PART OF TAXIWAYS F AND E.
THE DATES OF PHASES ARE CONFIRMED BY NOTAM.

THE PROVISIONS CONTAINED IN THE AIP SUP 019/26 ARE EXTENDED UNTIL 07
JUL 2026.

THIS AIP SUP IS AVBL AT WWW.SIA.AVIATION-CIVILE.GOUV.FR

LFFAA3923/26 (15 JUN 26)

STAR RNAV ENORI 9J RWY 26L 26R 27L 27R NOT AVBL.

LFFAA3857/26 (11 JUN 26)

TRIPLE AXIS TWY A4 NOT AVBL
USE ONLY CENTRAL AXIS A4.

LFFAA3840/26 (11 JUN 26)

"FLW STAR MODIFIED- REF AIP FRANCE :
AD2 LFPG STAR RWY EAST RNAV BIBAX LUKIP 9E 9D
AD2 LFPG STAR RWY WEST RNAV BIBAX LUKIP 9W 9V
AD2 LFPG STAR RWY WEST RNAV BIBAX LUKIP 9P
READ :
MSA MOBRO 2400FT,
MSA MOPAR 2400FT,
READ :
MOCA HOLDING BIBAX 1900FT,
MOCA HOLDING LUKIP 2000FT,
MOCA HOLDING MOPAR 2200FT,
MOCA HOLDING ROU 2400FT."

LFFAA3740/26 (08 JUN 26)

IMPLEMENTATION OF A NEW DEPARTURE SEQUENCING SYSTEM (GLD) : THE
DEPARTURE SEQUENCING ALGORITHM AND TSAT CALCULATION ARE MODIFIED.
RULES RELATED TO TOBT/EOBT MANAGEMENT AND SEQUENCE EXIT CONDITIONS
(SEQOUT) ARE UPDATED.
PLEASE REFER TO : WWW.CDMPARIS.NET WEBSITE FOR FURTHER INFORMATION

LFFAA2935/26 (06 JUN 26)

TRIGGER NOTAM - AIRAC AIP SUP 096/26.
PHASED REHABILITATION OF THE M TAXIWAY.
WORKS PHASES WILL BE ACTIVATED BY NOTAM.
THIS AIP SUP IS AVBL AT WWW.SIA.AVIATION-CIVILE.GOUV.FR

LFFAF0822/26 (06 JUN 26)

DME 'CGN' CH100Y U/S.

// (COM-INFO)//

THA 00133/12 (12 APR 26)

COM INFO--PILOT SHOULD PLAN TO LAND AT CDG AFTER 0600LT,
TO AVOID EXTRA CHARGES.
RMK/1. A/C ON BLOCK DUE 2200-0600LT,
HIGHER RATE OF PARKING FEE WILL BE APPLIED.
2. NOISE TAX FOR FLT MOVEMENT DUR 2200-0600LT,
HIGHER RATE WILL BE APPLIED. (ISSUED/28JUN/TN028/14/OS-A380/UFN)

LFFAA2208/26 (12 APR 26)

TWY BD4 CLSD

LFFAA4055/25 (04 OCT 25)

TWY EM5 LIMITED TO ACFT WITH A MAXIMUM WINGSPAN OF 36M FROM STAND
EN81.
REF AD 2 LFPG.20-3.3.2.2 LIMITATIONS ACCESSIBILITY.

LFFAA3549/25 (04 JUL 25)

"REF :
AD2 LFPG STAR RWY EAST RNAV BIBAX LUKIP
AD2 LFPG STAR RWY EAST RNAV EPL TRO
AD2 LFPG STAR RWY EAST RNAV KEPER ROMGO
AD2 LFPG STAR RWY EAST RNAV MATIX VEDUS
AD2 LFPG STAR RWY EAST RNAV MOPIL VEDUS
AD2 LFPG STAR RWY EAST RNAV TINIL
AD2 LFPG STAR RWYWEST RNAV BIBAX LUKIP 01
AD2 LFPG STAR RWY WEST RNAV BIBAX LUKIP 02
AD2 LFPG STAR RWY WEST RNAV BIBAX LUKIPH
AD2 LFPG STAR RWY WEST RNAV EPL TRO
AD2 LFPG STAR RWY WEST RNAV KEPER
AD2 LFPG STAR RWY WEST RNAV KEPER ROMGO
AD2 LFPG STAR RWY WEST RNAV MATIX VEDUS
READ :
MSA BANOX 2700FT,
MSA LORNI 2700FT,
MSA MOBRO 2400FT,
MSA MOPAR 2400FT,
MSA OKIPA 2300FT,.
LIRE
MOCA HOLDING BANOX 2700FT,
MOCA HOLDING BIBAX 1900FT,
MOCA HOLDING ENORI 2400FT,
MOCA HOLDING LORNI 2100FT,
MOCA HOLDING LUKIP 2000FT,
MOCAHOLDING MOPAR 2200FT,
MOCA HOLDING NANOP 2900FT,
MOCA HOLDING OKIPA 2300FT,
MOCA HOLDING ROMGO 2700FT,
MOCA HOLDING ROU 2400FT,
MOCA HOLDING XERAN 2800FT."

LFFAF0990/22 (09 NOV 23)

VOR PART OF VOR/DME PGS 117.050MHZ NOT AVBL (COMPLETELY WITHDRAWN

EDDF / FRA

EDDZA3316/26 (26 JUN 26)

RWY 07C DECLARED DISTANCES FOR INTERSECTION TKOF CHANGED.
NEW DECLARED DISTANCES FOR INTERSECTION TKOF FROM TWY L20:
TORA 3939M - TODA 3939M - ASDA 3939M.
DISREGARD DECLARED DISTANCES FOR INTERSECTION TAKE OFF FROM TWY L20.
REF AIP AD2 EDDF 1-10.

*EDDZA3305/26 (26 JUN 26)

DAILY 2100-0300
RWY 07C/25C CLSD.

EDDZA3137/26 (18 JUN 26)

RWY 07L/25R CENTRE LINE LIGHTS:
LIGHT EMITTING DIODE (LED) LIGHTS USED IN THE FULL LENGTH OF THE
RWY CENTRELINE.

EDDZA3138/26 (18 JUN 26)

RWY 07L/25R TOUCHDOWN ZONE LIGHTING SYSTEM:
LIGHT EMITTING DIODE (LED) LIGHTS USED.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 12/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

EDDZA3046/26 (12 JUN 26)

USE OF RWY HLDG PSN T6 NOT PERMITTED FOR AIRCRAFT WITH WINGSPAN
BTN 36M AND 65M (UP TO BUT NOT INCLUDING).

EDDZA3045/26 (12 JUN 26)

ACFT STAND A26 CLSD.

EDDZA3047/26 (12 JUN 26)

TWY W SOUTH OF DP2 CLSD. TWY W9 CLSD.

// (COM-INFO) //

THA 00081/15 (07 JUN 26)

COM INFO:--EDDF NIGHT RESTRICTION 2300-0500LT (OP-INFO/UFN)

EDDZA2768/26 (07 JUN 26)

NEW TWY S17 BTN TWY S AND TWY R IN OPERATION.
NEW TWY S19 BTN TWY S AND TWY R IN OPERATION.
NEW TWY S20 IN OPERATION.
NEW TWY S21 BTN TWY S AND TWY R IN OPERATION.
NEW TWY S23 IN OPERATION.

EDDZA2717/26 (07 JUN 26)

"CHARLIE DME CHA 115.35MHZ/CH100Y, ON MAINT. DO NOT USE, FALSE
INDICATION POSS."

EDDZA2715/26 (07 JUN 26)

ILS 25C OUT OF SERVICE.
27 MAY 26 11:15 UNTIL 15 JUL 26 12:00 ESTIMATED

EDDZA2716/26 (07 JUN 26)

ILS 07C DOWNGRADED TO CAT I LVL 2 (ICAO CLASSIFICATION I/E/2).
LOW VIS OPS PROC NOT POSS.
27 MAY 26 11:16 UNTIL 15 JUL 26 12:00 ESTIMATED

EDDZA2680/26 (07 JUN 26)

"LPV APCH Z RWY 07L SUSPENDED,
LPV APCH Y RWY 07L SUSPENDED,
LPV APCH Z RWY 25R SUSPENDED,
LPV APCH Y RWY 25R SUSPENDED
DUE TO INADEQUATE PROTECTION PROVIDED IN MISSED APCH SEGMENT FOR
SOME NAVIGATION SYSTEMS AUTH FOR LPV OPS."
26 MAY 26 12:50 UNTIL 18 AUG 26 23:59 ESTIMATED

EDDZA2676/26 (07 JUN 26)

TWY DP2 CLSD.

EDDZA2626/26 (07 JUN 26)

DAILY 2100-0300
WIP IN THE VCY OF ILS LOC RWY 25C AND IN THE VCY OF ILS GP RWY
25C.

EDDZA2573/26 (07 JUN 26)

NEW ACFT STAND INSTALLED. V333: N 50 1 45.42431 E 8 33 54.04565
NEW ACFT STANDS INSTALLED. V335: N 50 1 47.9537 E 8 33 52.58912
NEW ACFT STAND INSTALLED. V337: N 50 1 50.65133 E 8 33 51.03558
NEW ACFT STAND INSTALLED. V340: N 50 1 50.3976 E 8 33 50.26489.

EDDZA2574/26 (07 JUN 26)

NEW TWY S21 SOUTH OF TWY S INOPERATION.

EDDZA2575/26 (07 JUN 26)

BREAK-AWAY INSTALLED ON TWY S21. REF AIP SUP IFR 03/26.

EDDZA2531/26 (07 JUN 26)

OCA(H) VALUES RAISED AS FOLLOWS:
LPV APCH Z RWY 07C: A 652(324) B 665(337) C 692(364) D 701(373)FT.
LPV APCH Y RWY 07C: A 652(324) B 665(337) C 692(364) D 701(373)FT.
LPV APCH Z RWY 07R: A 652(325) B 665(338) C 673(346) D 715(388)FT.
LPV APCH Y RWY 07R: A 652(325) B 665(338) C 673(346) D 715(388)FT.
LPV APCH Z RWY 25L: A 726(365) B 738(377) C 747(386) D 757(396)FT.
LPV APCH Y RWY 25L: A 729(368) B 742(381) C 750(389) D 760(399)FT.
LPV APCH Z RWY 25C: A 691(328) B 700(337) C 706(343) D 714(351)FT.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 13/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

LPV APCH Y RWY 25C: A 694(331) B 703(340) C 709(346) D 716(353)FT.
19 MAY 26 13:34 UNTIL 18 AUG 26 23:59 ESTIMATED

EDDZA2193/26 (07 JUN 26)

ACFT STAND A28 CLSD.

EDDZA2178/26 (07 JUN 26)

"DISREGARD TAXI RESTRICTION FOR A346, B773, B779, A35K, B748 AND
A388
ON TWY S8 BTWN TWY S AND ACFT STAND H5. REF AIP AD2 EDDF 2-9 AND EDDF
2-9A."

EDDZA2008/26 (30 APR 26)

"REF AIP EDDF AD 2.20 LOCAL AERODROME REGULATIONS 6. OPERATION OF
A RUNWAY INCURSION ALERTING SYSTEM (RIAS (AD 2 EDDF 1-33) IS
SUSPENDED .
CLEARANCES WILL BE ISSUED TO THE CAT I HOLDING POSITIONS ON
TWY M6, M8 AND M30 UNDER CAT I CONDITIONS.
A RWY INCURSION MONITORING SYSTEM IS IMPLEMENTED IN THE ATC GROUND
RADAR SYSTEM."

EDDZA1648/26 (05 APR 26)

NEW TWY S13 WEST OF S11 IN OPERATION. REF AIP SUP IFR 03/26.

EDDZA1647/26 (05 APR 26)

NEW TWY S19 SOUTH OF TWY S IN OPERATION. REF AIP SUP IFR 03/26.

EDDZA1646/26 (05 APR 26)

BREAK-AWAYS 1 AND 2 INSTALLED ON TWY S19. REF AIP SUP IFR 03/26.

EDDZA1644/26 (05 APR 26)

NEW TWY S17 SOUTH OF TWY S IN OPERATION. REF AIP SUP IFR 03/26.

EDDZA1599/26 (05 APR 26)

"ILS APCH CHANGED DUE TO FRD DME PSN AT 500147N 0083406E.
ILS Z CAT II/III RWY 07L
AMEND 19.2 DME FRD TO READ 20.3 DME FRD.
AMEND 16.0 DME FRD TO READ 17.1 DME FRD.
AMEND 5.4 DME FRD TO READ 6.5 DME FRD.
ILS Z CAT II/III RWY 07C
AMEND 14.7 DME FRD TO READ 15.7 DME FRD.
AMEND 11.5 DME FRD TO READ 12.5 DME FRD.
AMEND 4.1 DME FRD TO READ 5.1 DME FRD.
ILS CAT II/III RWY 07R
AMEND 14.9 DME FRD TO READ 15.9 DME FRD.
AMEND 11.7 DME FRD TO READ 12.7 DME FRD.
AMEND 4.2 DME FRD TO READ 5.2 DME FRD.
ILS CAT II/III RWY 25L
AMEND 16.3 DME FRD TO READ 15.4 DME FRD.
AMEND 13.2 DME FRD TO READ 12.2 DME FRD.
AMEND 5.8 DME FRD TO READ 4.8 DME FRD.
ILS Z CAT II/III RWY 25C
AMEND 16.5 DME FRD TO READ 15.5 DME FRD.
AMEND 13.3 DME FRD TO READ 12.3 DME FRD.
AMEND 5.9 DME FRD TO READ 5.0 DME FRD.
ILS Z CAT II/III RWY 25R
AMEND 17.7 DME FRD TO READ 16.8 DME FRD.
AMEND 14.5 DME FRD TO READ 13.6 DME FRD.
AMEND 4.1 DME FRD TO READ 3.3 DME FRD.
ILS Y RWY 07L
AMEND 19.2 DME FRD TO READ 20.3 DME FRD.
AMEND 15.1 DME FRD TO READ 16.2 DME FRD.
AMEND 5.4 DME FRD TO READ 6.5 DME FRD.
ILS Y RWY 25R
AMEND 17.7 DME FRD TO READ 16.8 DME FRD.
AMEND 13.6 DME FRD TO READ 12.7 DME FRD.
AMEND 4.1 DME FRD TO READ 3.3 DME FRD.
ILS X CAT II/III OR LOC RWY 07C
AMEND 26.7 DME FRD TO READ 27.3 DME FRD.
AMEND 16.5 DME FRD TO READ 17.5 DME FRD.
AMEND 11.5 DME FRD TO READ 12.5 DME FRD.
AMEND 8.0 DME FRD TO READ 9.0 DME FRD.
AMEND 4.1 DME FRD TO READ 5.1 DME FRD.
AMEND 0.2 DME FRD TO READ 1.3 DME FRD.
ILS X CAT II/III OR LOC RWY 25C
AMEND 26.0 DME FRD TO READ 24.8 DME FRD."

AMEND 18.3 DME FRD TO READ 17.3 DME FRD.
AMEND 13.3 DME FRD TO READ 12.3 DME FRD.
AMEND 8.9 DME FRD TO READ 8.0 DME FRD.
AMEND 5.9 DME FRD TO READ 5.0 DME FRD.
AMEND 2.0 DME FRD TO READ 1.2 DME FRD.
REF AD 2 EDDF 4-2-1, 4-2-7 BOTH DATED 30 OCT 2025, 4-2-2 THRU 4-2-6
AND 4-2-8 THRU 4-2-10 ALL EFF 10 JUL 2025."
31 MAR 26 10:48 UNTIL 30 JUN 26 23:59 ESTIMATED

EDDZA1598/26 (05 APR 26)

"SID CHANGED DUE TO FRD DME PSN AT 500147N 0083406E:
MARUN 8M, OBOKA 3M AND TOBAK 8M:
AMEND 1.0 DME FRD TO READ 2.1 DME FRD.
AMEND 6.9 DME FRD TO READ 7.2 DME FRD.
MARUN 6H, OBOKA 3H AND TOBAK 6H:
AMEND 1.2 DME FRD TO READ 2.2 DME FRD.
AMEND 6.9 DME FRD TO READ 7.2 DME FRD.
FKS 2C:
AMEND 6.9 DME FRD TO READ 6.0 DME FRD.
FKS 2Q:
AMEND 0.5 DME FRD TO READ 1.5 DME FRD.
REF AD 2 EDDF 5-7-11, 5-7-13, 5-7-132 AND 5-7-133 ALL DATED
10 JUL 2025, 5-7-36, 5-7-37 BOTH EFFECTIVE 10 JUL 2025."
31 MAR 26 10:47 UNTIL 30 JUN 26 23:59 ESTIMATED

EDDZA1371/26 (05 APR 26)

"ILS RWY 25Y IFWR,
GP COVERAGE UP TO 15NM IN SECTOR -4 DEG (LEFT) TO +1 DEG (RIGHT) IN
RELATION TO RCL AND DISTANCE TO THR,
MNM RECEPTION ALT IN THIS AREA 2800FT AMSL."

EDDZA4054/25 (11 SEP 25)

SURFACE TEST AREAS INSTALLED WITHIN TOUCHDOWN ZONE RWY 07L.
SURFACE TEXTURE AND FRICTION MAY DIFFER SLIGHTLY FROM ADJACENT
PAVEMENT.
NO IMPACT ON RWY USABILITY.

EDDZA2357/25 (18 MAY 25)

BREAK-AWAY AREAS 3 AND 5 INSTALLED ON TWY S13.

EBLG / LGG

*A2179/26*EBBRA2179/26 (27 JUN 26)

PAX FLT DIVERSION NOT AUTHORIZED DUE TO OPR RESTRICTIONS

EBBRA2180/26 (26 JUN 26)

MON-FRI 0400-1600
TWY A4 CLSD DUE TO WIP EXC LVP

EBBRA2148/26 (24 JUN 26)

RWY 04R/22L SURFACE FRICTION IS 0.5 AT 65KM/H AND 0.45 AT 95KM/H
BTN S2 AND S3
24 JUN 26 10:03 UNTIL 24 SEP 26 10:00 ESTIMATED

ENROUTE INFORMATION

ASP / ASIA/PACIFIC
N I L

THA / THAILAND
N I L

VTBB / BANGKOK FIR

VTBDH0767/26 (27 JUN 26)

27 JUN 2026 17:45-27 JUN 2026 18:40
"THE AIRSPACE HEREUNDER UPGRADED TO PINK AWY, LATERAL LIMITS
5NM EITHER SIDE OF THE ROUTE AND THE MENTIONED AIRSPACE WILL BE
RELEASED AS VACATED 15 MIN AFTER VIP ACFT HAS PASSED THE KNOWN
POSITION ALONG THE ESTABLISHED ROUTE
AAA: VTBD/L507/NUNLI FM GND UP TO FL360
BBB: NUNLI/L507/LUDVI FM FL320 TO FL360"
F) GND
G) FL360

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 15/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

*VTBDJ5255/26 (26 JUN 26)

28 JUN 2026 02:00-28 JUN 2026 10:00
"ROCKET (BANGFAI) FRNG WILL TAKE PLACE RADIUS 5NM CENTRE
155346.98N1041032.21E (MUEANG DISTRICT YASOTHON PROVINCE)
RMK: COOR CTC TEL +668 1393 0595, +669 0912 1201"
F) GND
G) 19000FT AGL

*VTBDJ5239/26 (25 JUN 26)

28 JUN 2026 02:30-28 JUN 2026 05:00
"ROCKET (BANGFAI) FRNG WILL TAKE PLACE RADIUS 5NM CENTRE
165116.20N1011344.50E (LOM KAO DISTRICT PHETCHABUN PROVINCE)
RMK: COOR CTC TEL +666 4070 8746, +666 2143 0364"
F) GND
G) 19000FT AGL

VTBDC3430/26 (23 JUN 26)

"ALL ACFT VIA RTE B346, R474, W21 AND G473 ADVICE CTC
BANGKOK ACC PRI FREQ 126.500MHZ AND SRY FREQ 122.00MHZ
DUE TO RADIO FREQ INTERFERENCE"

*VTBDJ5189/26 (22 JUN 26)

28 JUN 2026 01:00-28 JUN 2026 11:00
"ROCKET (BANGFAI) FRNG WILL TAKE PLACE RADIUS 5NM CENTRE
160423.2N1033133.9E (MUEANG DISTRICT ROI ET PROVINCE)
RMK: COOR CTC TEL +668 1574 7345, +668 1739 2397"
F) GND
G) 12000FT AGL

VTBDC2855/26 (26 MAY 26)

"AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM
THE DEMOCRATIC REPUBLIC OF THE CONGO AND THE REPUBLIC OF UGANDA
1. PURSUANT TO THE RESOLUTION OF THE NATIONAL COMMUNICABLE DISEASE
COMMITTEE, EFFECTIVE FROM 27 MAY 2026 AT 1800 HOURS (LOCAL TIME)
ONWARDS, PASSENGERS AND CREW MEMBERS DEPARTING FROM THE DEMOCRATIC
REPUBLIC OF THE CONGO (DR CONGO) AND THE REPUBLIC OF UGANDA SHALL BE
PERMITTED TO ENTER THE KINGDOM OF THAILAND ONLY VIA SUVARNABHUMI
AIRPORT AND SHALL BE SUBJECT TO A MANDATORY QUARANTINE PERIOD OF
TWENTY-ONE (21) DAYS, CALCULATED FROM THE DATE OF DEPARTURE FROM
THE AFFECTED AREAS, IN ACCORDANCE WITH THE PRESCRIBED PUBLIC
HEALTH PROCEDURES.
2. ALL AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM
THE ABOVE-MENTIONED AREAS ARE REQUESTED TO COMPLY WITH AND IMPLEMENT
THE PRESCRIBED MEASURES ACCORDINGLY."

// (COM-INFO) //

THA 00126/26 (14 MAY 26)

COM INFO:--REF AIP SUP A19/26;

1

INTRODUCTION

With effect from 14 May 2026 at 0001 UTC to 31 December 2026 at 0001 UTC, the purpose of this
AIRAC AIP Supplement is to inform all
concerned regarding Temporary suspension of SURAT THANI DVOR/DME (STN) due to relocation
details are as follows.

2

THE PERIOD OF TEMPORARY SUSPENSION

STN DVOR/DME will be temporarily suspension from 14 May 2026 at 0001 UTC to 31 December 2026
at 0001 UTC.

3

FLIGHT PROCEDURE

A temporary reporting point name SAPUD (090746.24N 0990805.09E) will be established at the
same coordinates of SURAT THANI DVOR/
DME (STN) for ATS routes G458, W17, W24, W28, W32 and Y8 and a portion of ATS route G458
between STN and MENEX will be suspended
until STN normal operations resume.

4

FLIGHT PLANNING PROCEDURES

Reference to the AIP-THAILAND part ENR 1.10 item 4.1.1.1, 4.1.1.2 a, 4.1.1.2 b, 4.1.1.3 a,
4.1.1.3 b non-RNAV2 approved aircraft. To maintain
efficiency of ATS during SURAT THANI DVOR/DME (STN) relocation, non-RNAV approved aircraft
that intend to operate on G458 between
SAPUD and MENEX shall file flight plan, depending on ACFT capability.

5

CONTACT

Unit: Air Traffic Navigation Systems Engineering Department, Aeronautical Radio of Thailand
Ltd.

Email: pariwat.ch@aerothai.co.th

6
VALIDITY
This AIRAC AIP Supplement will remain current until 31 December 2026 at 0001 UTC. Any changes to this AIRAC AIP Supplement will be notified by NOTAM.

VTBDJ3551/26 (14 MAY 26)

DAILY 0100-0230 0600-1130
"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA 5NM EITHER SIDE OF
A LINE:151638.34N1001745.12E-145407.02N1004920.52E-
143000.00N1022800.00E-143107.26N1051100.12E
(CHAINAT, NAKHON SAWAN, LOP BURI, SURIN, SI SA KET,
UBON RATCHATHANI, BURI RAM AND NAKHON RATCHASIMA PROVINCE)
RMK: ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR VECTORED
BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC"
F) FL150
G) FL200

VTBDC2184/26 (20 APR 26)

"DUE TO VT D41A ACT FPL PROC FOR ACFT OPR FM/TO VTCC DETAIL AS FLW:
1. PERIOD MON-FRI 0000-1100
DEP/OVERFLY DEST/OVERFLY RTE
VTCC VTCT W12 IKISU W22
VTCC PONUK R207 IKISU W22 CTR A581
VTCT VTCC W22 IKISU W12
PONUK VTCC Y27 DUBEN Y28 CRIST R207 (FOR RNAV)
PONUK VTCC A581 CTR W22 IKISU R207 (FOR NON-RNAV)
2. PERIOD MON-FRI 1101-2359, SAT SUN H24
DEP/OVERFLY DEST/OVERFLY RTE
VTCC VTCT W20
VTCC PONUK A581
VTCT VTCC W20
PONUK VTCC A581"

VTBDJ2001/26 (05 APR 26)

"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA :
144705N1033019E - 143541N1051246E - 142051N1051232E -
141826N1030616E - 142521N1030558E - 144705N1033019E
(SI SAKET, UBON RATCHATHANI, BURIRAM AND SURIN PROVINCE
EXCLUDING PHNOM PENH FIR)
RMK : ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR
VECTORED BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC."
F) 8000FT AMSL
G) FL170

MMR / MYANMAR
N I L

VYYF / YANGON FIR

*VYYA0129/26 (25 JUN 26)

27 JUN 2026 23:30-01 JUL 2026 11:30
2330-1130
"GUNFIRING EXERCISE WILL TAKE PLACE WITH THE FLW DETAILS:
THE COORDINATES OF THE DANGER ZONES(MALON GUNFIRING AREA)
ARE AS FOLLOWS:
POINT(A)194000N 0943000E
POINT(B)194000N 0951000E
POINT(C)200000N 0951000E
POINT(D)200000N 0943000E
POINT(E)194000N 0943000E
NO OVERFLYING ACTIVITY IS PERMISSIBLE WITHIN THE ABOVE MENTIONED
DANGER ZONE.DURING HOURS OF ACTIVITY,THE FOLLOWING ATS ROUTES
ARE NOT AVBL IN YANGON FIR:
1)G463 NOT AVBL,BTN AVLED AND NIVOG.
ALT RTE-AVLED-DCT-POINT(K)193000N 0941800E-DCT-NIVOG-G463 BGO/VOR.
(BIDIRECTIONAL).
2)W8,W12,W14,W15,W22 NOT AVBL."
F) GND
G) 48000FT AGL

IND / INDIA
N I L

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 17/90

Trans ID: 5040609

Creation Time: 27.06.2026 12:51UTC

VECF / KOLKATA FIR

VOMMA2021/26 (25 JUN 26)

27 JUN 2026 00:00-27 JUN 2026 23:59
AIRSPACE USE PLAN (AUP)
TSA/TRA/AMC-MANAGEABLE AIRSPACE ACT AS FLW:
NR AIRSPACE ID TIME FM TIME TO LOWER FL UPPER FL
1 TRA509A 0000 2359 SFC FL270
2 TRA509B 0230 0730 FL270 UNL
3 TRA509B 1000 1100 FL270 UNL
4 TRA509B 1430 1630 FL270 UNL
5 TRA509C 0230 0730 FL270 UNL
6 TRA509C 1000 1100 FL270 UNL
7 TRA509C 1430 1630 FL270 UNL
8 TRA607(A) CHABUA 0130 1730 FL325 FL460
9 TRA607(B) CHABUA 0130 1730 FL325 FL460
10 TRA607(C) CHABUA 0130 1730 FL325 FL460
11 TRA611(A) KALAIKUNDA 0400 0700 FL325 FL500
12 TRA611(A) KALAIKUNDA 0830 1130 FL325 FL500
13 TRA611(B) KALAIKUNDA 0400 0700 FL325 FL500
14 TRA611(B) KALAIKUNDA 0830 1130 FL325 FL500
15 TRA611(C) KALAIKUNDA 0400 0700 FL325 FL500
16 TRA611(C) KALAIKUNDA 0830 1130 FL325 FL500
17 TRA806(A) COCHIN 0300 1730 6000 FT AMSL 6000 FT AMSL
18 TRA806(B) COCHIN 0300 1730 FL060 FL170
19 TRA806(C) COCHIN 0300 1730 FL150 FL170
20 TRA806(D) COCHIN 0300 2100 FL060 FL130
21 TRA806(E) COCHIN 0300 2100 FL060 FL170
22 TRA806(F) COCHIN 0300 2100 FL060 FL130
23 TRA806(G) COCHIN 0300 2100 FL060 FL170
24 TSA602 DUDHKUNDI 0000 2359 GND FL215
CONDITIONAL RTE (CDR2) AVBL AS FLW:
NR CDR2 ID TIME FM TIME TO LOWER FL UPPER FL
1 J1 0000 0129 FL080 FL410
2 J1 0130 1130 FL290 FL410
3 J1 1131 1830 FL080 FL410
4 J3 0000 0030 FL100 FL250
5 J3 1330 2359 FL100 FL250
6 J4 0000 0030 FL110 FL460
7 J4 0031 0359 FL330 FL460
8 J4 0701 0829 FL330 FL460
9 J4 1131 1258 FL330 FL460
10 J4 1259 1829 FL250 FL460
11 J4 1830 2359 FL110 FL460
12 J5 0000 2359 FL260 FL410
13 J7 0500 1120 FL130 FL320
14 J8 0215 1145 FL130 FL380
15 J10 0230 1130 FL130 FL380
16 J11 0235 1220 FL130 FL380
17 J13 0240 0440 FL140 FL400
18 J13 0655 0855 FL140 FL400
19 J13 1230 1825 FL140 FL400
20 J15 0000 2359 FL110 FL460
21 J17 0015 0300 FL110 FL460
22 J17 1130 1310 FL110 FL460
23 J17 1435 1935 FL110 FL460
24 J18 0000 0300 FL110 FL460
25 J18 1130 2359 FL110 FL460
26 J23 0250 1200 FL210 FL300
27 J26 0000 0030 FL160 FL460
28 J26 0031 0359 FL330 FL460
29 J26 0701 0829 FL330 FL460
30 J26 1131 1258 FL330 FL460
31 J26 1259 1829 FL250 FL460
32 J26 1830 2359 FL160 FL460
33 J27 0000 0030 FL110 FL460
34 J27 0031 0359 FL330 FL460
35 J27 0701 0829 FL330 FL460
36 J27 1131 1258 FL330 FL460
37 J27 1259 1829 FL250 FL460
38 J27 1830 2359 FL110 FL460
39 J29 0000 2359 FL150 FL250
40 J36 0000 2359 FL110 FL245
41 J39 0000 0129 FL170 FL460
42 J39 0130 1130 FL290 FL460
43 J39 1131 2359 FL170 FL460
44 J41 0100 1400 FL330 FL410
45 J42 0000 0030 FL110 FL245
46 J42 1230 2359 FL110 FL245

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 18/90

Trans ID: 5040609

Creation Time: 27.06.2026 12:51UTC

47 J44 0000 0155 FL110 FL210
48 J44 1149 1800 FL110 FL210
49 J45 0000 0030 FL110 FL460
50 J45 0031 0359 FL330 FL460
51 J45 0701 0829 FL330 FL460
52 J45 1131 1258 FL330 FL460
53 J45 1259 1829 FL250 FL460
54 J45 1830 2359 FL110 FL460
55 J46 0000 0030 FL110 FL460
56 J46 0031 0359 FL330 FL460
57 J46 0701 0829 FL330 FL460
58 J46 1131 1258 FL330 FL460
59 J46 1259 1829 FL250 FL460
60 J46 1830 2359 FL110 FL460
61 J47 0100 0129 FL170 FL410
62 J47 0130 1130 FL290 FL410
63 J47 1131 1300 FL170 FL410
64 J48 0400 0930 FL290 FL410
65 J56 0000 2359 FL080 FL250
66 J57 0200 1530 FL080 FL250
67 J59 0200 1530 FL110 FL410
68 J63 0000 0030 FL110 FL410
69 J63 0031 1229 FL255 FL410
70 J63 1230 2359 FL110 FL410
71 J64 1230 1400 FL150 FL410
72 J65 0000 2359 FL230 FL410
73 J66 0000 0030 FL110 FL250
74 J66 1330 2359 FL110 FL250
75 J67 0000 0030 FL110 FL255
76 J67 1330 2359 FL110 FL255
77 J71 0200 1730 FL110 FL460
78 J71 1731 1930 FL250 FL460
79 J71 1931 2000 FL110 FL460
80 J73 0100 1300 FL330 FL410
81 J75 0000 0030 FL110 FL400
82 J75 0031 0359 FL330 FL400
83 J75 0701 0829 FL330 FL400
84 J75 1131 1258 FL330 FL400
85 J75 1259 1829 FL250 FL400
86 J75 1830 2359 FL110 FL400
87 J82 0000 2359 FL330 FL400
88 J83 0200 1900 FL110 FL400
89 J89 0000 0030 FL110 FL245
90 J89 1230 2359 FL110 FL245
91 J92 0200 1400 FL110 FL380
92 J93 0000 0030 FL150 FL460
93 J93 1230 2359 FL150 FL460
94 J95 0000 0155 FL110 FL460
95 J95 0156 0300 FL255 FL460
96 J95 1130 1148 FL255 FL460
97 J95 1149 2359 FL110 FL460
98 J96 0000 0300 FL110 FL250
99 J96 1130 2359 FL110 FL250
100 J97 0000 0030 FL080 FL245
101 J97 1230 2359 FL080 FL245
102 J98 0000 1730 FL160 FL280
103 J98 1731 1930 FL250 FL280
104 J98 1931 2359 FL160 FL280
105 J104 0000 2359 FL110 FL380
106 J105 0230 1300 FL075 FL460
107 J107 0000 0030 FL110 FL255
108 J107 1230 2359 FL110 FL255
109 J116 0000 2359 FL080 FL250
110 J120 0000 2359 FL085 FL460
111 J121 0000 2359 FL085 FL460
112 J122 0000 2359 FL085 FL460
113 Z2 0000 2359 FL330 FL460
114 Z5 0000 2359 FL290 FL410
115 Z12 0000 0359 FL330 FL460
116 Z12 0701 0829 FL330 FL460
117 Z12 1131 2359 FL330 FL460
118 Z13 0000 2359 FL110 FL410
119 Z14 0000 0359 FL330 FL460
120 Z14 0701 0829 FL330 FL460
121 Z14 1131 2359 FL330 FL460

NOTE: AIRSPACE USERS AND ATC UNITS ARE REQUIRED TO ENSURE THAT
AIRSPACE ACTIVITIES ARE NOT CONFLICTING WITH OTHER NOTAMS FOR
AIRSPACE CLOSURES.

F) SFC

G) UNL

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 19/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

*VECCA1222/26 (19 JUN 26)

"20 27 29 30 0200-1200, 22-26 0200-0429 0631-0859 1101-1200"
"ARTILLERY FRNG ACT BY PXE INPR WI AREA BOUNDED BY
POINT A 212730.00N 0870200.00E,
POINT C 211140.00N 0871900.00E,
POINT B 210400.00N 0865130.00E AND THEN ALONG THE COASTLINE TO POINT
A 212730.00N 0870200.00E EXC COMMON AREA OF VED 53."
F) SFC
G) 25000FT AMSL

VIDPG0742/26 (19 JUN 26)

INDIAN AIRSPACE NOT AVBL FOR PAKISTAN REGISTERED ACFT
AND ACFT OPERATED/OWNED OR LEASED BY PAKISTAN AIRLINES/OPERATORS
INCLUDING MILITARY FLIGHTS. FROM GND - UP TO UNL.
19 JUN 26 11:52 UNTIL 23 JUL 26 23:59 ESTIMATED

*VECCA1191/26 (15 JUN 26)

0130-1430
VED-50 ACT AND ARMY FLY ACT INPR WI COORD:
POINT A 191740.33N 0845512.40E
POINT B 191044.80N 0844722.85E
POINT C 185601.96N 0845238.50E
POINT D 191219.81N 0851455.09E AND
POINT A 191740.33N 0845512.40E
F) SFC
G) 20000FT AMSL

VECCA1154/26 (11 JUN 26)

"TRIAL OPS OF SECT KOLKATA OCEANIC NORTH AVBL ON OPPORTUNITY BASIS
WI AREA BOUNDED BY COORD:
182558N 0861115E,
201507N 0872651E,182318N 0920000E THEN ALONG INDIA-MYANMAR FIR BDRY
TO 161035N 0920000E AND 182558N 0861115E.
AIRSPACE CLASSIFIED AS CLASS : E WI ATS RTE AND CLASS: G OUTSIDE ATS
RTE UNIT PROVIDING SER:KOLKATA OCAENIC NORTH FREQ 123.775 MHZ ACTUAL
TIMINGS WILL BE DECIDED BY KOLKATA ATC AND ACFT SHALL BE ADVISED
ACCORDINGLY.
FROM SFC TO UNL"

VECCA1153/26 (11 JUN 26)

"TRIAL OPS OF SECT KOLKATA OCEANIC SOUTH AVBL ON OPPORTUNITY BASIS
WI AREA BOUNDED BY COORD:
182558N 0861115E, 161035N 0920000E THEN ALONG INDIA-MYANMAR FIR BDRY
TO 140000N 0920000E THEN ALONG KOLKATA-CHENNAI FIR BDRY TO 154200N
0855400E,163721N 0845647E AND 182558N 0861115E.
AIRSPACE CLASSIFIED AS CLASS : E WI ATS RTE AND CLASS: G OUTSIDE ATS
RTE UNIT PROVIDING SER:KOLKATA OCAENIC SOUTH FREQ 128.300 MHZ ACTUAL
TIMINGS WILL BE DECIDED BY KOLKATA ATC.
FROM SFC TO UNL"

// (COM-INFO)//

THA 00156/13 (29 MAY 26)

COM INFO:--1.Route P646 segment DOPID - Jamshedpur VOR (JJS)
available only between 1630UTC to 2330UTC.

VECCA1019/26 (27 MAY 26)

OPPORTUNITY BASIS TRIAL OPS OF SECTOR UPPER BHUBANESWAR (UBS)
INPR WI AREA BOUNDED BY:
P9: 195331.08N 0804815.53E
P10: 182447.34N 0800549.06E
SAPNU
XOPOX
P11: 160620.64N 0843429.68E
P12: 201517.19N 0872703.15E
P13: 205140.37N 0862158.87E
BBS VOR
P18: 195350.22N 0842614.93E
AND P9: 195331.08N 0804815.53E.
AIRSPACE CLASSIFIED AS CLASS: D
UNIT PROVIDING SER: KOLKATA CTL / KOLKATA RADAR
FREQ: 132.350 MHZ
ACTUAL TIMINGS WILL BE DECIDED BY WSO KOLKATA AND ACFT SHALL BE
ADVISED ACCORDINGLY.
FROM 25500FT AMSL TO 46000FT AMSL

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 20/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

VECCA1018/26 (27 MAY 26)

OPPORTUNITY BASIS TRIAL OPS OF SECTOR UPPER RAIPUR (URP) INPR WI
AREA BOUNDED BY:
P7: 223342.78N 0801441.50E
TEGIG
P8: 203427.40N 0810337.65E
P9: 195331.08N 0804815.53E
P18: 195350.22N 0842614.93E
BBS VOR
P13: 205140.37N 0862158.87E
P14: 224646.10N 0842032.87E
AND P7: 223342.78N 0801441.50E.
AIRSPACE CLASSIFIED AS CLASS: D
UNIT PROVIDING SER: KOLKATA CTL/KOLKATA RADAR
FREQ: 125.900 MHZ ACTUAL TIMINGS WILL BE DECIDED BY WSO KOLKATA AND
ACFT SHALL BE ADVISED ACCORDINGLY.
FROM 25500FT AMSL TO 46000FT AMSL

VECCA1017/26 (27 MAY 26)

OPPORTUNITY BASIS TRIAL OPS OF SECTOR UPPER KHAJURAHO (UKJ) INPR W
I
AREA BOUNDED BY:
P3: 262359.43N 0801240.56E
P4: 251831.86N 0800851.21E
P5: 253601.78N 0793534.75E
P6: 250839.00N 0790132.87E
ASOPO
P7: 223342.78N 0801441.50E
P14: 224646.10N 0842032.87E
LAPAN
P15: 241326.46N 0840859.31E
ALH VOR
AND P3: 262359.43N 0801240.56E.
AIRSPACE CLASSIFIED AS CLASS: D
UNIT PROVIDING SER: KOLKATA CTL / KOLKATA RADAR
FREQ: 124.650 MHZ
ACTUAL TIMINGS WILL BE DECIDED BY WSO KOLKATA AND ACFT
SHALL BE ADVISED ACCORDINGLY.
FROM 25500FT AMSL TO 46000FT AMSL

VECCA1016/26 (27 MAY 26)

OPPORTUNITY BASIS TRIAL OPS OF SECTOR UPPER VARANASI (UBN) INPR WI

AREA BOUNDED BY:
P1: 273339.10N 0824136.34E?
P2: 270921.85N 0813515.75E?
P3: 262359.43N 0801240.56E?
ALH VOR?
P15: 241326.46N 0840859.31E?
GGC VOR?
P16: 244425.25N 0851849.17E?
P17: 265328.59N 0850151.53E?
THEN ALONG THE BORDER OF NEPAL AND INDIA TO
P1: 273339.10N 0824136.34E.
AIRSPACE CLASSIFIED AS CLASS: D
UNIT PROVIDING SER: KOLKATA CTL / KOLKATA RADAR
FREQ: 127.525 MHZ ACTUAL TIMINGS WILL BE DECIDED BY WSO KOLKATA AND
ACFT SHALL BE ADVISED ACCORDINGLY.
FROM 25500FT AMSL TO 46000FT AMSL

*VIDPA1123/26 (29 MAY 26)

"01 03 04 08 10 11 15 17 18 22 24 25 29 0200-0730 1300-1629, 02 05
09 12 16 19 23 30 0200-0730"
"IN ADDN TO RTE AVBL OF ATS RTE L509 BTN GAYA DVOR (GGC) AND SULOM
(VIDF/OPLR) FM 1630-2230 UTC DLY, ATS RTE L509 BTN GAYA DVOR (GGC)
AND SULOM (VIDF/OPLR) ALSO AVBL AT OR ABV FL330 ON ABV MENTIONED
DATES AND TIMINGS. ALL OTHER RTE SPECIFICATIONS/ RESTRICTIONS FOR
ATS RTE L509 AS PUBLISHED IN E-AIP INDIA ENR 3.1 SHALL BE APPLICABLE
ON ABV MENTIONED DATES AND TIMINGS. INTL OVERFLYING FLT TRANSITING
THRU DELHI FIR (VIDF) ENCOURAGED TO FPL VIA ATS RTE L509 INSTEAD OF
ATS RTE M890 AS TFC CONGESTION EXP OVER LUCKNOW VOR (LKN) DRG PERIOD
OF AIR EXER. FLT MAY ALSO BE RE RTE DYNAMICALLY VIA ATS RTE L509 BY
ATC.
FROM FL330 TO FL460"

*VECCA0988/26 (22 MAY 26)

VED 232 LPR KHAMARIA JABALPUR ACT

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 21/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

F) SFC
G) 25000FT AMSL

***VIDPA1101/26 (29 MAY 26)**

"JUN 01-04 08-11 15-18 22-25 29-30 0330-0630 1430-1625, JUN 05 12 19 0330-0630"
AIRSPACE BOUNDED WI COORD (EX-ROME0):
273705N0780907E - 265812N0795114E - 264038N0800214E -
250612N0791341E - 250920N0772625E - 262242N0772304E -
263754N0775411E - 264208N0781515E - 273705N0780907E
NOT AVBL DUE AIR EXER (EXCLUDING DANGER AREA FALLING WI EXER AREA).
DRG EXER PERIOD FLW RESTRICTIONS APPLY:
1.ATS RTE L759 BTN DELHI VOR (DPN) AND KHAJURAHO VOR (KKJ) NOT AVBL.
ALTN RTE AVBL: DPN DCT ALI G452 LKN KCH KKJ OR DPN-W19-BPL-W68-KKJ.
2. ATS RTE L760 BTN KHAJURAHO VOR (KKJ) AND DELHI VOR (DPN) NOT AVBL.
ALTN RTE AVBL: KKJ-KCH- JAL-SSB-DPN OR KKJ-W68-BPL-W20-DPN.
3. ATS RTE W33 NOT AVBL.
4. ATS RTE W10N BTN BILAN AND POSIG NOT AVBL.
5. ATS RTE W10S BTN AGRA VOR (AGG) AND BILAN NOT AVBL.
6. ATS RTE W13 BTN KKJ-MULMO NOT AVBL.
7. AIRLINE SHALL COORDINATE IN ADVANCE WITH INDIAN AIRFORCE (IAF) FOR ARR/DEP ACFT TO/FM AERODROMES FALLING IN EXER AREA.
F) GND
G) FL460

***VIDPA1100/26 (29 MAY 26)**

"JUN 01-04 08-11 15-18 22-25 29-30 0130-0329 0631-1130 1626-1829, JUN 05 12 19 0130-0329 0631-1130"
AIRSPACE BOUNDED WI COORD (EX-ROME0):
273705N0780907E - 265812N0795114E - 264038N0800214E -
250612N0791341E - 250920N0772625E - 262242N0772304E -
263754N0775411E - 264208N0781515E - 273705N0780907E
NOT AVBL DUE AIR EXER (EXCLUDING DANGER AREA FALLING WI EXER AREA).
DRG EXER PERIOD FLW RESTRICTIONS APPLY:
1.ATS RTE W33 NOT AVBL. ALTN RTE AVBL FOR CIVIL SKED FLIGHT OPERATING BTN DELHI AND KKJ.
FOR EASTBOUND : DPN-W19 BPL-W68-KKJ OR DPN-ALI-PAVRU-LKN-KCH-KKJ AND
FOR WESTBOUND : KKJ-W68-BPL-W20-DPN OR KKJ-KCH-JAL-SSB-DPN.
2. ATS RTE W10N BTN BILAN AND POSIG NOT AVBL.
3. ATS RTE W10S BTN AGRA VOR (AGG) AND BILAN NOT AVBL.
4. ATS RTE W13 BTN KKJ-MULMO NOT AVBL.
5. AIRLINE SHALL COORDINATE IN ADVANCE WITH INDIAN AIRFORCE (IAF) FOR ARR/DEP ACFT TO/FM AERODROMES FALLING IN EXER AREA.
F) GND
G) FL270

***VGHSA0143/26 (19 MAY 26)**

MON TUE WED 0000-1600
BANGLADESH NAVY SHIPS WILL CARRY OUT ANTI AIR FRNG PRACTICE WI THE AREA VGD-32.
F) SFC
G) FL400

***VGHSA0145/26 (19 MAY 26)**

MON TUE WED 0000-1600
BANGLADESH NAVY SHIPS WILL CARRY OUT ANTI AIR FRNG PRACTICE WI THE AREA VGD-34.
F) SFC
G) FL400

***VECCA0759/26 (20 APR 26)**

0230-1030
VED 71 ACT.
F) GND
G) 35000FT AMSL

VECCA0645/26 (02 APR 26)

GNSS SIGNAL INTERFERENCE/LOSS REPORTED IN KOLKATA FIR. ALL ACFT TO EXER CTN.

VIDF / DELHI FIR

VIDPA1382/26 (25 JUN 26)

27 JUN 2026 00:00-27 JUN 2026 23:59

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 22/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

AIRSPACE USE PLAN (AUP)
TSA/TRA /AMC-MANAGEABLE AIRSPACE ACT AS FLW :
NR AIRSPACE ID TIME FM TIME TO LOWER FL UPPER FL
1 TRA509A 0000 2359 SFC FL270
2 TRA509B 0230 0730 FL270 UNL
3 TRA509B 1000 1100 FL270 UNL
4 TRA509B 1430 1630 FL270 UNL
5 TRA509C 0230 0730 FL270 UNL
6 TRA509C 1000 1100 FL270 UNL
7 TRA509C 1430 1630 FL270 UNL
8 TSA701 (A) ADAMPUR 0000 2359 FL145 FL280
9 TSA701 (B) ADAMPUR 0000 2359 GND FL280
10 TRA709(C) JODHPUR 0130 1200 FL325 FL380
11 TSA722 ?GRASS BIR - 13? 0130 1130 GND FL280
CONDITIONAL ROUTE (CDR2) AVBL AS FLW :
NR CDR2 ID TIME FM TIME TO LOWER FL UPPER FL
1 J1 0000 0129 FL080 FL410
2 J1 0130 1130 FL290 FL410
3 J1 1131 1830 FL080 FL410
4 J2 0000 2359 FL110 FL410
5 J3 0000 0030 FL100 FL250
6 J3 1330 2359 FL100 FL250
7 J5 0000 2359 FL260 FL410
8 J6 0100 1600 FL140 FL410
9 J19 0231 0400 FL210 FL410
10 J20 0000 0129 FL110 FL410
11 J20 0130 1130 FL290 FL410
12 J20 1131 2359 FL110 FL410
13 J21 0000 2359 FL140 FL410
14 J22 0000 2030 FL290 FL410
15 J24 0000 2359 FL345 FL460
16 J29 0000 2359 FL150 FL250
17 J36 0000 2359 FL110 FL245
18 J38 0100 0129 FL170 FL410
19 J38 0130 1130 FL290 FL410
20 J38 1131 1300 FL170 FL410
21 J39 0000 0129 FL170 FL460
22 J39 0130 1130 FL290 FL460
23 J39 1131 2359 FL170 FL460
24 J40 0000 2359 FL330 FL410
25 J41 0100 1400 FL330 FL410
26 J42 0000 0030 FL110 FL245
27 J42 1230 2359 FL110 FL245
28 J43 0000 0129 FL170 FL410
29 J43 0130 1130 FL290 FL410
30 J43 1131 1700 FL170 FL410
31 J47 0100 0129 FL170 FL410
32 J47 0130 1130 FL290 FL410
33 J47 1131 1300 FL170 FL410
34 J48 0400 0930 FL290 FL410
35 J50 0000 0129 FL110 FL460
36 J50 0130 1200 FL400 FL460
37 J50 1201 2359 FL110 FL460
38 J51 0000 0129 FL170 FL460
39 J51 0130 1200 FL400 FL460
40 J51 1201 1300 FL330 FL460
41 J51 1301 1359 FL170 FL460
42 J51 1400 1730 FL330 FL460
43 J51 1731 2359 FL170 FL460
44 J52 0000 0129 FL110 FL460
45 J52 0130 1130 FL290 FL460
46 J52 1131 2359 FL110 FL460
47 J53 0100 0229 FL080 FL250
48 J55 0000 0229 FL090 FL250
49 J55 1301 1359 FL090 FL250
50 J55 1731 2359 FL090 FL250
51 J56 0000 2359 FL080 FL250
52 J58 0100 1300 FL110 FL410
53 J59 0200 1530 FL110 FL410
54 J60 0100 0129 FL170 FL460
55 J60 0130 1130 FL290 FL460
56 J60 1131 1440 FL170 FL460
57 J61 0000 0229 FL110 FL460
58 J61 0230 1300 FL330 FL460
59 J61 1301 1359 FL110 FL460
60 J61 1400 1730 FL330 FL460
61 J61 1731 2359 FL110 FL460
62 J62 0000 0129 FL110 FL460
63 J62 0130 1200 FL400 FL460
64 J62 1201 2359 FL110 FL460
65 J64 1230 1400 FL150 FL410

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 23/90

Trans ID: 5040609

Creation Time: 27.06.2026 12:51UTC

66 J65 0000 2359 FL230 FL410
67 J67 0000 0030 FL110 FL255
68 J67 1330 2359 FL110 FL255
69 J68 0231 0400 FL110 FL410
70 J69 0231 0400 FL110 FL410
71 J70 0231 0400 FL110 FL410
72 J71 0200 1730 FL110 FL460
73 J71 1731 1930 FL250 FL460
74 J71 1931 2000 FL110 FL460
75 J72 0100 1600 FL330 FL410
76 J73 0100 1300 FL330 FL410
77 J74 0100 1600 FL330 FL410
78 J81 0100 1600 FL330 FL400
79 J82 0000 2359 FL330 FL400
80 J83 0200 1900 FL110 FL400
81 J84 0000 0229 FL110 FL250
82 J84 1301 1359 FL110 FL250
83 J84 1731 2359 FL110 FL250
84 J85 0000 0229 FL110 FL250
85 J85 1301 1359 FL110 FL250
86 J85 1731 2359 FL110 FL250
87 J86 0000 0229 FL110 FL290
88 J86 1301 1359 FL110 FL290
89 J86 1731 2359 FL110 FL290
90 J87 0100 0229 FL110 FL290
91 J88 0100 0229 FL110 FL290
92 J89 0000 0030 FL110 FL245
93 J89 1230 2359 FL110 FL245
94 J93 0000 0030 FL150 FL460
95 J93 1230 2359 FL150 FL460
96 J94 0030 0229 FL110 FL250
97 J94 1301 1359 FL110 FL250
98 J98 0000 1730 FL160 FL280
99 J98 1731 1930 FL250 FL280
100 J98 1931 2359 FL160 FL280
101 J100 0000 0229 FL080 FL280
102 J100 1301 1359 FL080 FL280
103 J100 1731 2359 FL080 FL280
104 J101 0100 0229 FL080 FL280
105 J102 0100 0229 FL080 FL280
106 J103 0000 0229 FL080 FL280
107 J103 1301 1359 FL080 FL280
108 J103 1731 2359 FL080 FL280
109 J104 0000 2359 FL110 FL380
110 J107 0000 0030 FL110 FL255
111 J107 1230 2359 FL110 FL255
112 J110 0000 2359 FL345 FL400
113 J115 0100 2359 FL080 FL250
114 J116 0000 2359 FL080 FL250
115 J119 0000 1730 FL110 FL460
116 L639 0000 2359 FL290 FL460
117 Z1 0000 2359 FL330 FL460
118 Z2 0000 2359 FL330 FL460
119 Z3 0231 0400 FL210 FL410
120 Z4 0231 0400 FL210 FL410
121 Z5 0000 2359 FL290 FL410
122 Z6 0000 2359 FL330 FL460
123 Z7 0000 2359 FL290 FL460
124 Z8 0000 0129 FL330 FL460
125 Z8 0130 1200 FL400 FL460
126 Z8 1201 1829 FL330 FL460
127 Z8 1830 2359 FL290 FL460
128 Z9 0200 1200 FL400 FL410
129 Z9 1201 1730 FL330 FL410
130 Z10 0000 2359 FL330 FL460
131 Z11 0231 0400 FL210 FL410
132 Z13 0000 2359 FL110 FL410
133 Z14 0000 0359 FL330 FL460
134 Z14 0701 0829 FL330 FL460
135 Z14 1131 2359 FL330 FL460
136 Z15 0000 0129 FL290 FL410
137 Z15 0130 1200 FL400 FL410
138 Z15 1201 1630 FL290 FL410
139 Z16 0000 0129 FL160 FL400
140 Z16 0130 1130 FL290 FL400
141 Z16 1131 2359 FL160 FL400

NOTE: AIRSPACE USERS AND ATC UNITS ARE REQUIRED TO ENSURE THAT
AIRSPACE ACTIVITIES ARE NOT CONFLICTING WITH OTHER NOTAM FOR
AIRSPACE CLOSURES.

F) SFC

G) UNL

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 24/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

VIDPG0742/26 (19 JUN 26)

INDIAN AIRSPACE NOT AVBL FOR PAKISTAN REGISTERED ACFT
AND ACFT OPERATED/OWNED OR LEASED BY PAKISTAN AIRLINES/OPERATORS
INCLUDING MILITARY FLIGHTS. FROM GND - UP TO UNL.
19 JUN 26 11:52 UNTIL 23 JUL 26 23:59 ESTIMATED

VIDPG0741/26 (19 JUN 26)

"REF EAIP INDIA SECTION ENR 3.1, FLW AMENDMENTS ARE MADE IN
REMARKS SECTION OF ATS RTE V12:
DELETE POINT NR.2 OF REMARKS SECTION THE ROUTE SEGMENT IKAVA - KOTA
NDB (KO) IS TREATED AS EASTBOUND."

*VIDPA1320/26 (18 JUN 26)

VID 129 ACT. NO ACFT PERMITTED TO OVERFLY WI VID 129
F) GND
G) 20000FT AMSL

VIDPA1220/26 (05 JUN 26)

"DAILY 0430-0930, 1230-1530"
ARMY DRONE OPS PLANNED WITHIN 3NM RADIUS AROUND COORD
303140N0793410E(AULI).
F) GND
G) 05000FT AGL

// (COM-INFO) //

THA 00123/12 (29 MAY 26)

COM INFO---ATS ROUTE RESTRICTIONS AS FOLLOWS:
-P646 (RNP10) DOPID-JJS AVAILABLE BETWEEN 1630-2330 UTC, (FL280/FL460),
-M875(RNP10) KAKID-GUGAL AVAILABLE BETWEEN 1630-2230 UTC, (FL280/FL460),
-L509 (RNP10) GGC-SULOM AVAILABLE BETWEEN 1630-2230 UTC, (FL320/FL460),
-M770 (RNP10) BUBKO-JJS AVAILABLE ONLY BETWEEN 1630-2330 UTC.
-L333 (RNP10) KKJ-MERUN AVAILABLE BETWEEN 1630-0030 UTC, (FL300/FL460)
-B209 (CDR1) REALIGNED JJS-KKJ (H24-FL75/FL460)
RMK/ROUTE SEGMENT JJS-KKJ IS NOT AVAILABLE FOR AIRCRAFT INTENDING TO USE
L759 AFTER KKJ AND OVER-FLYING DELHI VOR (DPN)
-J1 ESTABLISHMENT OF CDR3 ROUTE J1 KKJ-JJP (FL75/FL460)
RMK/ROUTE TO BE FLOWN ON ATC INSTRUCTION ONLY, NOT AVBL FOR FLT PLANNING.
(REF AIP INDIA AND AIP SUP 76/14, 77/14/PERM)

--PILOTS FLYING ON AWY M890, L509, A466E, A466W, ARE REQUESTED TO CONTACT
ALPHA CONTROL ON 119.7MHZ PRIOR TO CROSSING THE DELHI AND LAHORE FIR
BOUNDARIES. (ISSUED 15JAN07/TN074/07/CHECKED 07JAN22/OB/UFN)

VIDPG0630/26 (29 MAY 26)

REF ENR 5.1 OF EAIP INDIA. THE RESTRICTED AREA VAR 44-A GOA-I IS
DELETED
F) SFC
G) UNL

VIDPG0629/26 (29 MAY 26)

"REF SUP 84/2026 REGARDING ESTABLISHMENT OF TEMPO RESERVED AREA
TRA509A, TRA509B AND TRA509C. AT SERIAL NR 1, THE TEXT MUMBAI FIR IS
AMD AS MUMBAI AND CHENNAI FIRS."
F) SFC
G) UNL

*VIDPA1123/26 (29 MAY 26)

"01 03 04 08 10 11 15 17 18 22 24 25 29 0200-0730 1300-1629, 02 05
09 12 16 19 23 30 0200-0730"
"IN ADDN TO RTE AVBL OF ATS RTE L509 BTN GAYA DVOR (GGC) AND SULOM
(VIDF/OPLR) FM 1630-2230 UTC DLY, ATS RTE L509 BTN GAYA DVOR (GGC)
AND SULOM (VIDF/OPLR) ALSO AVBL AT OR ABV FL330 ON ABV MENTIONED
DATES AND TIMINGS. ALL OTHER RTE SPECIFICATIONS/ RESTRICTIONS FOR
ATS RTE L509 AS PUBLISHED IN E-AIP INDIA ENR 3.1 SHALL BE APPLICABLE
ON ABV MENTIONED DATES AND TIMINGS. INTL OVERFLYING FLT TRANSITING
THRU DELHI FIR (VIDF) ENCOURAGED TO FPL VIA ATS RTE L509 INSTEAD OF
ATS RTE M890 AS TFC CONGESTION EXP OVER LUCKNOW VOR (LKN) DRG PERIOD
OF AIR EXER. FLT MAY ALSO BE RE RTE DYNAMICALLY VIA ATS RTE L509 BY
ATC.
FROM FL330 TO FL460"

*VIDPA1101/26 (29 MAY 26)

"JUN 01-04 08-11 15-18 22-25 29-30 0330-0630 1430-1625, JUN 05 12
19 0330-0630"
AIRSPACE BOUNDED WI COORD (EX-ROME0):
273705N0780907E - 265812N0795114E - 264038N0800214E -

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 25/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

250612N0791341E - 250920N0772625E - 262242N0772304E -
263754N0775411E - 264208N0781515E - 273705N0780907E
NOT AVBL DUE AIR EXER (EXCLUDING DANGER AREA FALLING WI EXER AREA).
DRG EXER PERIOD FLW RESTRICTIONS APPLY:
1.ATS RTE L759 BTN DELHI VOR (DPN) AND KHAJURAHO VOR (KKJ) NOT AVBL.
ALTN RTE AVBL: DPN DCT ALI G452 LKN KCH KKJ OR DPN-W19-BPL-W68-KKJ.
2. ATS RTE L760 BTN KHAJURAHO VOR (KKJ) AND DELHI VOR (DPN) NOT
AVBL.
ALTN RTE AVBL: KKJ-KCH- JAL-SSB-DPN OR KKJ-W68-BPL-W20-DPN.
3. ATS RTE W33 NOT AVBL.
4. ATS RTE W10N BTN BILAN AND POSIG NOT AVBL.
5. ATS RTE W10S BTN AGRA VOR (AGG) AND BILAN NOT AVBL.
6. ATS RTE W13 BTN KKJ-MULMO NOT AVBL.
7. AIRLINE SHALL COORDINATE IN ADVANCE WITH INDIAN AIRFORCE (IAF)FOR
ARR/DEP ACFT TO/FM AERODROMES FALLING IN EXER AREA.
F) GND
G) FL460

***VIDPA1100/26 (29 MAY 26)**

"JUN 01-04 08-11 15-18 22-25 29-30 0130-0329 0631-1130 1626-1829,
JUN 05 12 19 0130-0329 0631-1130"
AIRSPACE BOUNDED WI COORD (EX-ROMEO):
273705N0780907E - 265812N0795114E - 264038N0800214E -
250612N0791341E - 250920N0772625E - 262242N0772304E -
263754N0775411E - 264208N0781515E - 273705N0780907E
NOT AVBL DUE AIR EXER (EXCLUDING DANGER AREA FALLING WI EXER AREA).
DRG EXER PERIOD FLW RESTRICTIONS APPLY:
1.ATS RTE W33 NOT AVBL. ALTN RTE AVBL FOR CIVIL SKED FLIGHT
OPERATING BTN DELHI AND KKJ.
FOR EASTBOUND : DPN-W19 BPL-W68-KKJ OR
DPN-ALI-PAVRU-LKN-KCH-KKJ AND
FOR WESTBOUND : KKJ-W68-BPL-W20-DPN OR
KKJ-KCH-JAL-SSB-DPN.
2. ATS RTE W10N BTN BILAN AND POSIG NOT AVBL.
3. ATS RTE W10S BTN AGRA VOR (AGG) AND BILAN NOT AVBL.
4. ATS RTE W13 BTN KKJ-MULMO NOT AVBL.
5. AIRLINE SHALL COORDINATE IN ADVANCE WITH INDIAN AIRFORCE (IAF)
FOR ARR/DEP ACFT TO/FM AERODROMES FALLING IN EXER AREA.
F) GND
G) FL270

VIDPG0592/26 (29 MAY 26)

REFER EAIP INDIA SECTION ENR 5.2? THE FOLLOWING CHANGES ARE MADE
IN REMARKS COLUMN:
1. IN TRA724 (PHALODI) REMARK 9: TRA VALID UNTIL 18TH MAY 2026
REPLACED BY TRA VALID UNTIL 17TH MAY 2029.
AMEND ACCORDINGLY.
F) SFC
G) UNL

VIDPG0558/26 (29 MAY 26)

"PERFORMANCE BASED LONGITUDINAL SEPARATION MINIMA OF 30NM/ 5MIN
BASED ON PBCS CRITERIA WILL BE APPLIED WITHIN WP AGELA AND IGOGU ON
ATS ROUTE N571 BTN ACFT HAVING FUNCTIONAL ADS-C AND CPDLC HAVING
OPERATIONAL APPROVAL FOR RNP2/RNP4, RCP240 AND RSP180 ON OPPORTUNITY
BASIS AS AN OPERATIONAL TRIAL. ACFT TO INDICATE RNP2/RNP4, ADS-C,
CPDLC, RCP240, RSP180 AVAILABILITY IN RESPECTIVE FIELDS OF FPL."
11 MAY 26 09:46 UNTIL 12 AUG 26 23:59 ESTIMATED

VIDPG0529/26 (29 MAY 26)

"LONGITUDINAL SEPARATION MINIMA OF 20NM BASED ON SPACE BASED ADS-B
SURVEILLANCE WILL BE APPLIED ON OPPORTUNITY BASIS FOR ACFT PASSING
WPT PARAR H24. ACFT WITH RNP2/RNP4 APPROVAL, FUNCTIONAL ADS-B OUT,
CPDLC WITH RCP240 CONNECTION ON VABF WILL BE SUBJ TO THIS
SEPARATION. THIS WILL BE APPLIED ON ATS RTE N571 BTN WPT PARAR AND
WPT SUGID ON TRIAL BASIS. ACFT TO INDICATE RNP2/RNP4, CPDLC, RCP240,
ADS-B AVAILABILITY IN RESPECTIVE FIELDS OF FPL."
27 APR 26 05:15 UNTIL 28 JUL 26 23:59 ESTIMATED

VIDPA0748/26 (29 MAY 26)

GNSS SIGNAL INTERFERENCE/LOSS REPORTED IN DELHI FIR. ALL ACFT TO
EXER CTN.

***VIDPA0678/26 (29 MAY 26)**

DAILY 0030 -1630
TSA707 MANDALTHANG FLD FRNG RANGE ACT.
F) GND

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 26/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

G) 40000FT AMSL

*VIDPA0595/26 (29 MAY 26)

DAILY 0030-1630
TSA717 KHARONALA FLD FRNG RANGE (KNFFR) ACT.
F) GND
G) FL400

MID / MIDDLE EAST

N I L

PAK / PAKISTAN

N I L

OPKR / KARACHI FIR

// (COM-INFO) //

THA 00049/26 (23 JUN 26)

COM INFO:--REF AIP SUP S09/26;
GPS (GNSS) RADIO FREQUENCY SIGNAL INTERFERENCE
1. From 1st January 2026 to 31st December, 2026.
2. OPKR / OPLR.
3. Occasionally GPS signal interferences have been reported 100NM around AIIAP Lahore (OPLA), IIAP Islamabad (OPIS), JIAP Karachi (OPKC), and also in some other parts of Karachi and Lahore FIRs. All pilots promptly report to ATC of such interference with appropriate details. During frequency interference, take necessary measures for safe and efficient continuation of flight navigation and in case of navigational difficulty, notify ATC for assistance.

--REF AIP SUP S01/26;
NON AVAILABILITY OF AIR TRAFFIC SERVICES IN KABUL FIR
1. From 1st January, 2026 to 30th June, 2026.
2. OPKR / OPLR.
3. GND / UNL.

4. During non-availability of Air Traffic Services (ATS) in Kabul FIR, all traffic entering Karachi and Lahore FIR shall contact Karachi, Lahore and Islamabad ACC 15 minutes prior as per following details:

i. N636 SERKA KARACHI ACC WEST PRI/128.350 MHz SEC/121.650 MHz
ii. P628 ASLUM LAHORE ACC WEST PRI/124.100 MHz SEC/118.950 MHz
iii. L750 BIROS LAHORE ACC WEST PRI/124.100 MHz SEC/118.950 MHz
iv. N644 DOBAT LAHORE ACC WEST PRI/124.100 MHz SEC/118.950 MHz
v. L509 LAJAK ISLAMABAD ACC PRI/120.750 MHz SEC/125.750 MHz
vi. P500 MOTMO ISLAMABAD ACC PRI/120.750 MHz SEC/125.750 MHz

5. Flights entering / exiting via MOTMO (P500) will be accepted and / or handed over directly between Islamabad ACC and Dushanbe ACC.

6. Any flight intends to transit from Karachi or Lahore FIR to Kabul FIR at their own risk (except for ATS route P500 via MOTMO) will be provided ATS till transfer of control points. Fifteen (15) minutes separation will be applicable at same level (as per Kabul ATM contingency plan).

7. For availability of flight levels and TIBA procedures in Kabul FIR, see latest NOTAMs issued by Kabul NOF in this regard.

OPKCA0367/26 (23 JUN 26)

LAKPASS MSSR NOT AVBL WI 250NM AROUND LAKPASS
DUE OPR REASON. DRG THE PERIOD ADS-B DATA OF
LAKPASS AND MSSR/ADS-B DATA OF OTHER STATIONS
WILL REMAIN AVBL AT LAHORE AND KARACHI ACC
22 JUN 26 07:37 UNTIL 06 JUL 26 23:59 ESTIMATED

// (COM-INFO) //

THA 00860/17 (19 JUN 26)

COM-INFO:--AIRWAYS RESTRICTION:
1) P757: NH-PG Route avbl btn 1900 to 0001 UTC (FL310/390)
outside this time subject to prior approval from:
Karachi ACC East
Primary FREQ 126.5 MHz.
Secondary FREQ 133.2 MHz

2) P628: Route AVBL btn way-points RK to ASLUM from 1901 to 2359UTC
(FL310/390)
(REF AIP PAKISTAN ENR 3.2/OW-INFO)

OPKCA0357/26 (17 JUN 26)

PAKISTAN AIRSPACE NOT AVBL FOR INDIAN REGISTERED
ACFT AND ACFT OPERATED/OWNED OR LEASED BY INDIAN

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 27/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

AIRLINES/OPERATORS INCLUDING MILITARY FLIGHTS.
F) GND
G) UNL
16 JUN 26 12:50 UNTIL 23 JUL 26 23:59 ESTIMATED

*OPKCA0304/26 (10 JUN 26)

01-05 08-12 15-19 22-26 29-30 0300-1859
OP/D132 (AREA HOTEL-2) ACT
F) SFC
G) FL200

*OPKCA0303/26 (10 JUN 26)

01-05 08-12 15-19 22-26 29-30 0300-1859
OP/D131 (AREA HOTEL-1) ACT
F) SFC
G) FL200

*OPKCA0302/26 (10 JUN 26)

01-05 08-12 15-19 22-26 29-30 0300-1859
OP/D110 (AREA BRAVO) ACT
F) SFC
G) FL280

*OPKCA0296/26 (10 JUN 26)

01-30 0130-1000 1300-1600
SONMIANI RANGE (OP/R106) ACT WI FLW COORD:
251124N 0664334E
252030N 0663334E
252151N 0663751E
251131N 0664503E
F) GND
G) FL260

OPLR / LAHORE FIR

// (COM-INFO)//

THA 00049/26 (23 JUN 26)

COM INFO:--REF AIP SUP S09/26;
GPS (GNSS) RADIO FREQUENCY SIGNAL INTERFERENCE
1. From 1st January 2026 to 31st December, 2026.
2. OPKR / OPLR.
3. Occasionally GPS signal interferences have been reported 100NM around AIIAP Lahore (OPLA), IIAP Islamabad (OPIS), JIAP Karachi (OPKC), and also in some other parts of Karachi and Lahore FIRs. All pilots promptly report to ATC of such interference with appropriate details. During frequency interference, take necessary measures for safe and efficient continuation of flight navigation and in case of navigational difficulty, notify ATC for assistance.

--REF AIP SUP S01/26;
NON AVAILABILITY OF AIR TRAFFIC SERVICES IN KABUL FIR
1. From 1st January, 2026 to 30th June, 2026.
2. OPKR / OPLR.
3. GND / UNL.
4. During non-availability of Air Traffic Services (ATS) in Kabul FIR, all traffic entering Karachi and Lahore FIR shall contact Karachi, Lahore and Islamabad ACC 15 minutes prior as per following details:

i. N636 SERKA KARACHI ACC WEST PRI/128.350 MHz SEC/121.650 MHz
ii. P628 ASLUM LAHORE ACC WEST PRI/124.100 MHz SEC/118.950 MHz
iii. L750 BIROS LAHORE ACC WEST PRI/124.100 MHz SEC/118.950 MHz
iv. N644 DOBAT LAHORE ACC WEST PRI/124.100 MHz SEC/118.950 MHz
v. L509 LAJAK ISLAMABAD ACC PRI/120.750 MHz SEC/125.750 MHz
vi. P500 MOTMO ISLAMABAD ACC PRI/120.750 MHz SEC/125.750 MHz

5. Flights entering / exiting via MOTMO (P500) will be accepted and / or handed over directly between Islamabad ACC and Dushanbe ACC.

6. Any flight intends to transit from Karachi or Lahore FIR to Kabul FIR at their own risk (except for ATS route P500 via MOTMO) will be provided ATS till transfer of control points. Fifteen (15) minutes separation will be applicable at same level (as per Kabul ATM contingency plan).

7. For availability of flight levels and TIBA procedures in Kabul FIR, see latest NOTAMs issued by Kabul NOF in this regard.

// (COM-INFO)//

THA 00124/12 (23 JUN 26)

COM INFO--AWY RESTRICTION AS FOLLOWS:
1) M875 SEGMENT (SITAX-SAJAN-DI-LEBIB-JHANG-NITIV-GUGAL V.V.)

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 28/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

AVAILABLE ONLY BETWEEN 1500-2359 UTC (FL290-FL410),
RMK/FL280 AVAILABLE BETWEEN 2000-2400 UTC.
1.1) AWY A466 (SULOM-SITAX V.V.) AVBL 24HRS
1.2) AWY N644 (DI-DOBAT V.V.) AVBL 24HRS,

2) L509 SEGMENT (SULOM-INDEX-NONIB-HANGU-LAJAK V.V.) AVAILABLE:
BETWEEN 1500-2359 UTC (FL300-410)
BETWEEN 1900-2359 UTC (FL280-410)
2.1) T400 (SULOM-PS V.V.) AVBL 24HRS
2.2) P500 (DI-MOTMO V.V.) AVBL 24HRS
(REF AIP PAKISTAN PAGE ENR 3.2/OW-INFO)

OPKCA0367/26 (23 JUN 26)

LAKPASS MSSR NOT AVBL WI 250NM AROUND LAKPASS
DUE OPR REASON. DRG THE PERIOD ADS-B DATA OF
LAKPASS AND MSSR/ADS-B DATA OF OTHER STATIONS
WILL REMAIN AVBL AT LAHORE AND KARACHI ACC
22 JUN 26 07:37 UNTIL 06 JUL 26 23:59 ESTIMATED

OPKCA0357/26 (17 JUN 26)

PAKISTAN AIRSPACE NOT AVBL FOR INDIAN REGISTERED
ACFT AND ACFT OPERATED/OWNED OR LEASED BY INDIAN
AIRLINES/OPERATORS INCLUDING MILITARY FLIGHTS.
F) GND
G) UNL
16 JUN 26 12:50 UNTIL 23 JUL 26 23:59 ESTIMATED

AFG / AFGHANISTAN

N I L

OAKX / KABUL FIR

// (COM-INFO) //

THA 00180/13 (17 JUN 26)

COM INFO--According to active NOTAMs below routes are not available:
A. LAJAK-L509-TAPIS-P173-DAVET (vice versa)
B. SITAX-M875-AMDAR (vice versa) (OW-INFO/UFN)

**** G0168/26 ****

OAKBG0168/26 (17 JUN 26)

FLIGHTS SHALL NOT CHANGE THEIR CRUISING FLIGHT LEVEL
OR CRUISING IAS/MACH NUMBER WITHIN THE KABUL FIR EXCEPT
IN CASE OF TRAFFIC AVOIDANCE OR EMERGENCY.
23 APR 26 05:00 UNTIL 20 JUL 26 23:59 ESTIMATED

**** G0219/26 ****

*OAKBG0219/26 (17 JUN 26)

ALL AIRCRAFT OPERATING INTO THE KABUL FIR SHALL FOLLOW BELOW HIGH
AND LOW SECTORS FLT LEVELS.
HIGH SECTOR:
AWY A453 CLOSED
AWY Z627 CLOSED
FIRUZ-P500-MOTMO (FL300-FL510)
AMDAR-M875-TAPIS-L509-LAJAK (FL300-FL510)
LEMOD-N644-DOBAT (FL320-FL510)
RANAH-L750-BIROs (FL320-FL510)
ASLUM-P628-PAMTU (FL320-FL510)
SOKAM-UL333-SERKA (FL320-FL510)
LOW SECTOR:
GADER-A453-TAPIS (FL170-FL290)
PAROD-G202-RIMPA (FL160-FL290)
GADER-G206 -TAPIS (FL180-FL290)
PAROD-M375-KHOLM (FL190-FL290)
SAKUX-V338-TAPIS (FL190-FL290)
PAROD-V390-SERKA (FL190-FL290)
SAKUX-V717-OLDEX (FL160-FL290)
RARNU-Z627-BUDBO (FL260-FL290).
12 JUN 26 05:25 UNTIL 08 SEP 26 23:59 ESTIMATED

**** G0220/26 ****

*OAKBG0220/26 (17 JUN 26)

ALL OVERFLIGHTS SHALL USE THE FOLLOWING LATERALLY DE-CONFLICTED
HIGH ROUTES (HIGH SECTOR) STARTING AT FL320-FL510 EXCEPT ON M875/L509
ROUTES SHALL USE FL300-FL510 AND P500 SHALL USE FL300-FL510
TRANSMISSION SHALL TAKE PLACE EVERY 5 MINUTES ON TIBA FREQ 125.2MHZ
FOR THE TEMPORARY PURPOSE ONLY.
1. FIRUZ-P500-MOTMO (FL300-FL510)
2. AMDAR-M875-TAPIS-L509-LAJAK (FL300-FL510)
3. LEMOD-N644-DOBAT (FL320-FL510)
4. RANAH-L750-BIROs (FL320-FL510)
5. PAMTU-P628-ASLUM (FL320-FL510)

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 29/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

6. SOKAM-UL333-SERKA (FL320-FL510).
12 JUN 26 05:25 UNTIL 08 SEP 26 23:59 ESTIMATED

**** G0198/26****

OAKBG0198/26 (17 JUN 26)

ATS NOT AVAILABLE IN THE KABUL FIR.
25 MAY 26 07:00 UNTIL 20 AUG 26 23:59 ESTIMATED

OAKBG0221/26 (17 JUN 26)

NAVIGATION AND ANTI-COLLISION LIGHTS SHALL BE DISPLAYED
AT ALL TIMES.
12 JUN 26 05:25 UNTIL 08 SEP 26 23:59 ESTIMATED

OAKBG0222/26 (17 JUN 26)

"1: ALL AIRCRAFT FLYING ON M875 AMDAR-TAPIS L509-LAJAK SHALL
BE OFFSET 8NM TO THE RIGHT OF CENTER LINE AT DOSHI, AFTER PASSING
POSITION GIDOG RESUMED CENTRELINE, DUE TO ACTIVE PROHIBITED AREA
(OAP)201.
2: ALL AIRCRAFT FLYING ON L509 LAJAK- TAPIS- M875 AMDAR SHALL
BE OFFSET 8NM TO THE LEFT OF CENTERLINE AT POSITION GIDOG UNTIL
DOSHI, AFTER PASSING DOSHI RESUMED CENTRELINE, DUE TO ACTIVE
PROHIBITED AREA (OAP)201."
12 JUN 26 05:25 UNTIL 08 SEP 26 23:59 ESTIMATED

OAKBG0223/26 (17 JUN 26)

AFGHANISTAN FIR IS UNCONTROLLED CLASS G AIRSPACE.
ALL INTERNATIONAL AND DOMESTIC AIRLINES ARE REQUESTED TO FILL
FLIGHT PERMISSIONS FORM AT LEAST 72 HOURS PRIOR FLIGHT AND
SHALL EMAIL TO FLIGHTPERMISSIONS.ACAA(A)GMAIL.COM
FOR PROCESSING PERMISSIONS.
12 JUN 26 05:25 UNTIL 08 SEP 26 23:59 ESTIMATED

OAKBG0216/26 (17 JUN 26)

"IN THE EVENT OF EMERGENCY DESCENT, THE PROCEDURES IN
ICAO DOC 4444 PANS-ATM SECTION 15.1.4.2 APPLY EXCEPT THAT
IN LIEU OF ADVISING ATS OF THE EMERGENCY DESCENT THE PILOT
SHALL BROADCAST ON THE RELEVANT TIBA FREQUENCY.
FLIGHTS OPERATING IN THE KABUL FIR SHALL COMPLY WITH TIBA
PROCEDURES DEFINED IN ICAO ANNEX-11 ATTACHMENT B AND
DESCRIBED USING THE FOLLOWING FREQUENCIES.
ALL OVERFLIGHTS SHALL COMPLY WITH TIBA PROCEDURE FOR
BROADCAST INTENTIONS ON FREQ 125.2MHZ 10 MINS PRIOR ENTERING
TO FIR. ARRIVAL AND DEPARTURE OPERATIONS AS FOLLOWS:
1. KABUL OAKB - 120.6MHZ
2. MAZAR-E-SHARIF OAMS - 135.35MHZ
3. KANDAHAR OAKN - 125.5MHZ
4. HERAT OAHR - 123.35MHZ
IN ADDITION TO THE ABOVE-MENTIONED TIBA BROADCASTS PILOTS
SHALL BROADCAST THEIR INTENTIONS INCLUDING RUNWAY, DEPARTURE
TRACK AND INTEND CRUISING LEVEL ON THE RELEVANT TIBA
FREQUENCIES NOT LESS THAN 10 MINUTES BEFORE TAKEOFF."
10 JUN 26 06:00 UNTIL 05 SEP 26 23:59 ESTIMATED

OAKBG0217/26 (17 JUN 26)

PILOTS ARE RESPONSIBLE AT ALL TIMES FOR TERRAIN CLEARANCE.
10 JUN 26 06:00 UNTIL 05 SEP 26 23:59 ESTIMATED

OAKBG0218/26 (17 JUN 26)

PILOTS ARE RESPONSIBLE AT ALL TIMES FOR SEPARATION FROM
OTHER TRAFFIC SSR TRANSPONDERS SHALL BE OPERATED AT ALL TIMES.
FLIGHTS ENTERING THE KABUL FIR SHALL CONTINUE TO SQUAWK THE LAST
ASSIGNED SSR CODE FLIGHTS DEPARTING AERODROMES WITH THE KABUL FIR
SHALL SQUAWK CODE A2000 (UNTIL ASSIGNED) A NEW CODE BY THE FIRST
RELEVANT ATS UNIT.
10 JUN 26 06:00 UNTIL 05 SEP 26 23:59 ESTIMATED

OAKBG0215/26 (17 JUN 26)

NON-RVSM OPERATIONS ARE NOT PERMITTED.
06 JUN 26 10:00 UNTIL 02 SEP 26 23:59 ESTIMATED

OAKBG0199/26 (17 JUN 26)

FLIGHTS MAY BE SUBJECT TO DELAYING ACTION PRIOR TO
ENTERING THE KABUL FIR TO ENSURE 15 MINUTES LONGITUDINAL
SPACING FROM PRECEDING TRAFFIC AT THE SAME LEVEL.
25 MAY 26 07:00 UNTIL 20 AUG 26 23:59 ESTIMATED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 30/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

OAKBG0197/26 (17 JUN 26)

"FLIGHTS DEPARTING THE KABUL FIR SHALL CONTACT THE RELEVANT ACC IN THE NEXT FIR ENTERED NOT LESS THAN 15 MINUTES BEFORE THE FIR BOUNDARY POINT, ON IN ACCORDANCE WITH ANY OTHER REQUIREMENT SPECIFIED BY THE RELEVANT AUTHORITY FOR THE FIR."
23 MAY 26 05:45 UNTIL 18 AUG 26 23:59 ESTIMATED

OAKBG0193/26 (17 JUN 26)

ALL CLIMB AND DESCENT SHOULD BE CARRIED OUT 5NM TO THE RIGHT OF TRACK EXCEPT FOR ARRIVING AND DEPARTING TRAFFIC WHILE OPERATING MSA SHOULD FOLLOW THE PUBLISHED INSTRUMENT FLIGHT PROCEDURE.
22 MAY 26 16:31 UNTIL 17 AUG 26 23:59 ESTIMATED

OAKBG0185/26 (05 MAY 26)

"P173 ROUTE IS CLOSED, DUE TO CONGESTION WITH LOW AIRWAYS."
04 MAY 26 07:41 UNTIL 31 JUL 26 23:59 ESTIMATED

*OAKBG0171/26 (05 MAY 26)

ALL FLIGHTS ARRIVING OR DEPARTING FROM AERODROMES IN KABUL FIR SHALL FILL FLIGHT PLAN AND OPERATE AT CRUISING LEVEL AT OR BELOW FL290. TRANSMISSION SHALL TAKE PLACE EVERY 5 MINUTES ON TIBA FREQ 125.2 MHZ FOR THE TEMPORARY PURPOSE ONLY.
25 APR 26 04:20 UNTIL 21 JUL 26 23:59 ESTIMATED

OAKBG0169/26 (05 MAY 26)

PILOTS IN COMMAND AND/OR AIRCRAFT OPERATORS ARE SOLELY RESPONSIBLE FOR SAFETY AND SECURITY ASSESSMENT FOR ANY PLANNED OPERATIONS IN THE KABUL FIR.
23 APR 26 05:00 UNTIL 20 JUL 26 23:59 ESTIMATED

OAKBG0170/26 (05 MAY 26)

"VFR ACFT WILL FLY IN ACCORDANCE WITH VFR PORTION OF THE TABLE OF CRUISING LEVELS IN APPENDIX-3 OF ICAO ANNEX-2 (ALSO REFERRED TO AS SEMI-CIRCULAR CRUISING LEVELS 0-179 DEGREES ODD FLIGHT LEVELS, 180-359 DEGREES EVEN FLIGHT LEVELS."
23 APR 26 05:00 UNTIL 20 JUL 26 23:59 ESTIMATED

EUR / EUROPE

N I L

TKM / TURKMENISTAN

N I L

UTAV / TURKMENABAT FIR

*UUUUU00208/26 (31 MAY 26)

01-05 08-12 15-19 22-26 29-30 0200-1700
"ATS RTE SEGMENTS CLSD:
B361 RAPTA-RARUN-RAPTA,
A125 RARUN-ABNEP-RARUN.
FROM SFC TO FL170"

UUUUU00213/26 (31 MAY 26)

JUN 01-05 08-12 15-19 22-26 29-30 0300-1700
"ATS RTE SEGMENTS CLSD BTN SFC AND FL070 :
A909 NINOP-LEMOD-NINOP,
B801 NINOP-RANAH-NINOP."

UUUUU00211/26 (31 MAY 26)

JUN 01-05 08-12 15-19 22-26 29-30 0330-1700
"ATS RTE CLSD WI SEGMENTS AS FLW :
A847 TURKMENABAT LBA-OLCHE-TURKMENABAT LBA,
B362 TURKMENABAT LBA-NURSA-TURKMENABAT LBA,
A230 DERKI-DUTAR-DERKI,
A118 TURKMENABAT LBA-VATIN-TURKMENABAT LBA,
A117 TURKMENABAT LBA-DUTAR-TURKMENABAT LBA.
FROM SFC - UP TO FL100."

// (COM-INFO) //

THA 00182/13 (21 MAR 25)

COM INFO:--ACFT crews entering Turkmenistan airspace from airspace of Afganistan and Iran shall establish communication with Turkmenistan ATC units at 81-108NM before crossing FIR boundary.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 31/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

ACFT crews entering Turkmenistan airspace from airspace of Azerbaijan, Kazakhstan and Uzbekistan do not need to establish communication with Turkmenistan ATC units before crossing FIR boundary unless otherwise instructed by ATC units.

ACFT flying from Kabul FIR to Turkmenabat FIR (A909 LEMOD, L750 RANAH) must establish contact with Turkmenabat Control on 134.500MHz (backup 128.500MHz) within 10min to the entrance to Turkmenabat FIR.

ACFT flying from Turkmenabat FIR to Kabul FIR, ATS service will be provided to the border of Turkmenabat FIR with a 15min interval along one route and at one echelon.
(ISSUED 16JAN25/REF CRAR Turkmenistan/C-20/UFN)

UTAA / ASHGABAT FIR

UUUUU00216/26 (31 MAY 26)

JUN 01-05 08-12 15-19 22-26 29-30 0300-1700
ATS RTE P130 SEGMENT MAMED-ARBAT-MAMED CLSD
BTN SFC AND FL070.

*UUUUU00207/26 (31 MAY 26)

01-05 08-12 15-19 22-26 29-30 0300-1700
ATS RTE B449 CLSD WI SEGMENT KEMOR-ZAMIR
BTN SFC AND FL170.

UTAK / TURKMENBASHI FIR

UUUUU00233/26 (17 JUN 26)

UTAK TAR U/S.

*UUUUU00222/26 (31 MAY 26)

JUN 01-05 08-12 15-19 22-26 29-30 0300-1700
ATS RTE V305 SEGMENT KESEK-BALKANABAT 'LA' CLSD
BTN SFC AND FL150.

*UUUUU00220/26 (31 MAY 26)

01-05 08-12 15-19 22-26 29-30 0300-1700
"ATS RTE SEGMENTS CLSD:
G667 NESIR-SAVUZ-NESIR,
R373 TIMGA-TABUN-TIMGA,
B711 OGLID-NESIR-OGLID.
FROM SFC TO FL120"

*UUUUU00217/26 (31 MAY 26)

JUN 01-05 08-12 15-19 22-26 29-30 0300-1700
"ATS RTE SEGMENTS CLSD BTN SFC AND FL270 :
P130 ARBAT-DOGAM-ARBAT,
B449 SAHET-ETRAP-SAHET."

AZE / AZERBAIJAN

N I L

UBBA / BAKU FIR

// (COM-INFO) //

THA 00249/25 (05 APR 26)

COM INFO:--Dispatch Note:
Portion ADEKI-RASAM is not available for eastbound traffic.

*UBBUA00093/26 (02 APR 26)

TEMPORARY RESTRICTION FOR FLIGHT OPERATIONS BETWEEN THE
AERODROMES OF THE REPUBLIC OF AZERBAIJAN AND THE FOLLOWING
AERODROMES OF THE RUSSIAN FEDERATION ARE APPLIED UNTIL FURTHER
NOTICE:
ASTRAKHAN - URWA
GROZNY - URMG
KAZAN - UWKD
MAKHACHKALA - URML
MINERALNYYE VODY - URMM
NIZHNY NOVGOROD - UWGG
SAMARA - UWWW
SARATOV - UWSG
SOCHI - URSS
UFA - UWUU

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 32/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

VLADIKAVKAZ - URMO
VOLGOGRAD - URWW
ANY FLIGHT REQUESTS WILL BE CONSIDERED AFTER AGREED FLIGHT ROUTES ON
AN EXCEPTIONAL BASIS.
RESTRICTION NOT APPLICABLE TO EMERGENCY LANDING.
30 MAR 26 12:00 UNTIL 30 JUN 26 23:59 ESTIMATED

GEO / GEORGIA

N I L

UGGG / TBILISI FIR

N I L

TUR / TURKEY

N I L

LTAA / ANKARA FIR

*LTAAA2853/26 (27 JUN 26)

0700-1000 1130-1330 EXC SAT SUN
TEST FLT WILL TAKE PLACE (WITHOUT FIRING) WI:
385218N0332418E 390824N0335630E 381818N0343836E
374812N0334618E 385218N0332418E
F) 29000FT AMSL
G) 41000FT AMSL

*LTAAA2610/26 (23 JUN 26)

20 21 27 28 0900-1530
SEE NOTAM: A2606/26
ATS ROUTES AND SEGMENTS AFFECTED DURING ACTIVITIES AS FOLLOWS:

1. AWY UW704 SIN-CRM SEGMENT CLSD.
 2. AWY W/UW96 ODIRA-SIN SEGMENT CLSD.
INSTEAD OF THIS ROUTE ALL ACFT COULD FOLLOW WESTBOUND
ODIRA-N/UN743-GAKSU-T/UT310.
 3. AWY W/UW99 ODIRA-CRM SEGMENT CLSD.
 4. AWY W/UW86 SIN-CRM SEGMENT CLSD.
 5. AWY G/UG901 CRM-BALUM SEGMENT CLSD.
- VERTICAL LIMITS: SFC-99000FT AMSL

*LTAAA2608/26 (23 JUN 26)

20 21 27 28 0900-1530
SEE NOTAM: A2606/26
RNAV ROUTES AND SEGMENTS AFFECTED DURING ACTIVITIES AS FOLLOWS:

1. AWY L/UL851 KUGOS-OLUPO SEGMENT CLSD.
 2. AWY M/UM859 OSDIP-KARDE SEGMENT CLSD.
ALL ACFT THAT WILL EXIT FROM 'ROLIN' VIA THIS ROUTE COULD FOLLOW
UDROS-DCT-CRM-DCT-ROLIN.
ALL ACFT THAT WILL EXIT FROM 'REBLO' AND 'NOLGA' VIA THIS ROUTE
COULD FOLLOW UDROS-DCT-CRM-M/UM11-TBN.
 3. AWY N/UN644 SIN-FALAZ SEGMENT CLSD.
ALL ACFT THAT WILL EXIT FROM 'ROLIN' VIA THIS ROUTE COULD FOLLOW
MIMTO-DCT-CRM-DCT-ROLIN.
ALL ACFT USING THIS ROUTE VIA WESTBOUND COULD FOLLOW FALAZ-DCT-CRM.
 4. AWY UM860 SIN-CRM SEGMENT CLSD.
 5. AWY M/UM10 OLUPO-GOKPA SEGMENT CLSD.
INSTEAD OF THIS ROUTE ALL ACFT COULD FOLLOW ATVAM-DCT-CRM.
- VERTICAL LIMITS: SFC-99000FT AMSL

*LTAAA2606/26 (23 JUN 26)

20 21 27 28 0900-1530
GUN FIRING WILL TAKE PLACE WI SINOP TMA AND SAMSUN CARSAMBA TMA
RMK: AIR TRAFFIC FLOW REGULATION NOTAM SHALL BE ISSUED
AREA (LTTSA-17R): 421238N0350909E 422037N0371446E 420814N0372025E
413420N0370841E 413747N0362948E 412924N0362650E 413004N0360604E
414040N0360357E 415319N0350208E 421238N0350909E
VERTICAL LIMITS : SFC-99000FT AMSL
F) SFC
G) UNL

*LTAAA2596/26 (23 JUN 26)

"16-19 0900-1530, 22-26 0900-1530, JUN 29-JUL 03 0900-1530"
SEE NOTAM: A2594/26

ATS ROUTES AND SEGMENTS AFFECTED DURING ACTIVITIES (WITH FIRING)
AS FOLLOWS

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 33/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

1. AWY W/UW96 ODIRA-SIN SEGMENT CLSD.
 2. AWY UW704 KUGOS-CRM SEGMENT CLSD.
- VERTICAL LIMITS SFC-30000FT AMSL

*LTAAA2595/26 (23 JUN 26)

"16-19 0900-1530, 22-26 0900-1530, JUN 29-JUL 03 0900-1530"
SEE NOTAM: A2594/26

RNAV ROUTES AND SEGMENTS AFFECTED DURING ACTIVITIES(WITH FIRING)
AS FOLLOWS:

1. AWY N/UN644 SIN KARDE SEGMENT CLSD.
ALL ACFT THAT WILL EXIT FROM 'ROLIN' VIA THIS ROUTE
COULD FOLLOW MIMTO-DCT-DETOS-DCT-ROLIN
ALL ACFT USING THIS ROUTE VIA WESTBOUND COULD FOLLOW
FALAZ-DCT-CRM

2. AWY M/UM859 OSDIP-KARDE SEGMENT CLSD.
ALL ACFT THAT WILL EXIT FROM 'ROLIN' VIA THIS ROUTE
COULD FOLLOW UDROS-DCT-CRM-DCT-ROLIN

ALL ACFT THAT WILL EXIT FROM 'REBLO' AND 'NOLGA' VIA THIS ROUTE
COULD FOLLOW UDROS-DCT-CRM-M/UM11-TBN

3. AWY UM860 KUGOS-CRM SEGMENT CLSD.
- VERTICAL LIMITS SFC-30000FT AMSL

*LTAAA2594/26 (23 JUN 26)

"16-19 0900-1530, 22-26 0900-1530, JUN 29-JUL 03 0900-1530"
GUN FIRING WILL TAKE PLACE WI SINOP TMA
RMK: AIR TRAFFIC FLOW REGULATION NOTAM SHALL BE ISSUED.
AREA: 420456N0350727E 421136N0350915E 421004N0351907E
420445N0352434E 415730N0352332E 415803N0351418E 420456N0350727E
VERTICAL LIMITS SFC-30000FT AMSL
F) SFC
G) 30000FT AMSL

*LTAAA2568/26 (23 JUN 26)

JUN 15-16 18 22-23 25 29-30 JUL 02 0600-0859
SEE NOTAM: A2565/26

ATS ROUTES AND SEGMENTS AFFECTED DURING ACTIVITIES(WITH FIRING)
AS FOLLOWS

1. AWY W/UW96 ODIRA-SIN SEGMENT CLSD.
2. AWY UW704 KUGOS-CRM SEGMENT CLSD.

VERTICAL LIMITS SFC-30000FT AMSL

*LTAAA2567/26 (23 JUN 26)

JUN 15-16 18 22-23 25 29-30 JUL 02 0600-0859
SEE NOTAM: A2565/26

RNAV ROUTES AND SEGMENTS AFFECTED DURING ACTIVITIES(WITH FIRING)
AS FOLLOWS:

1. AWY N/UN644 SIN KARDE SEGMENT CLSD.
ALL ACFT THAT WILL EXIT FROM 'ROLIN' VIA THIS ROUTE
COULD FOLLOW MIMTO-DCT-DETOS-DCT-ROLIN
ALL ACFT USING THIS ROUTE VIA WESTBOUND COULD FOLLOW
FALAZ-DCT-CRM

2. AWY M/UM859 OSDIP-KARDE SEGMENT CLSD.
ALL ACFT THAT WILL EXIT FROM 'ROLIN' VIA THIS ROUTE
COULD FOLLOW UDROS-DCT-CRM-DCT-ROLIN

ALL ACFT THAT WILL EXIT FROM 'REBLO' AND 'NOLGA' VIA THIS ROUTE
COULD FOLLOW UDROS-DCT-CRM-M/UM11-TBN

3. AWY UM860 KUGOS-CRM SEGMENT CLSD.
- VERTICAL LIMITS SFC-30000FT AMSL

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 34/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

*LTAAA2565/26 (23 JUN 26)

JUN 15-16 18 22-23 25 29-30 JUL 02 0600-0859
GUN FIRING WILL TAKE PLACE WI SINOP TMA
RMK: AIR TRAFFIC FLOW REGULATION NOTAM SHALL BE ISSUED.
AREA: 420456N0350727E 421136N0350915E 421004N0351907E
420445N0352434E 415730N0352332E 415803N0351418E 420456N0350727E
F) SFC
G) 30000FT AMSL

*LTAAA2540/26 (23 JUN 26)

RESTRICTED AREA: CENTERED ON 382049N0374741E WITH RADIUS 14 NM
WITHIN MALATYA MILITARY TMA

AIRSPACE IS NOT DECONFLICTED FROM AIRSPACE. TURKIYE AIRSPACE IS
SOVEREIGN. USER IS RESPONSIBLE FOR OBTAINING CIVIL OR MILITARY
CLEARANCE TO ENTER AND OPERATE IN THIS AIRSPACE IN ACCORDANCE WITH
HOST NATION REGULATIONS. REFER TO SPINS FOR C2 DETAILS
VERTICAL LIMITS: SFC-80000FT AMSL
F) SFC
G) UNL

*LTAAA2511/26 (17 JUN 26)

"JUN 18 0700-1000, JUN 22-26 29-30 JUL 01-02 0700-1000 1130-1330"
SEE NOTAM: A2509/26
RNAV ROUTES AND SEGMENTS AFFECTED DURING THE EXERCISE AS FOLLOWS:
1- AWY P29 HALIL-HISAR SEGMENT CLSD.
2- AWY M853 OKLAM-BUK SEGMENT CLSD.
VERTICAL LIMITS: 15000FT AMSL-23000FT AMSL

*LTAAA2509/26 (23 JUN 26)

"JUN 18 0700-1000, JUN 22-26 29-30 JUL 01-02 0700-1000 1130-1330"
EXERCISE WILL TAKE PLACE.
RMK: AIR TRAFFIC FLOW REGULATION NOTAM SHALL BE ISSUED.
AREA: 385500N0322600E 390941N0320004E 390228N0313807E
383129N0311824E 380711N0315257E 385500N0322600E
F) 15000FT AMSL
G) 23000FT AMSL

*LTAAA2510/26 (23 JUN 26)

"JUN 18 0700-1000, JUN 22-26 29-30 JUL 01-02 0700-1000 1130-1330"
SEE NOTAM: A2509/26
ATS ROUTES AND SEGMENTS AFFECTED DURING EXERCISE AS FOLLOWS:
1. AWY W77 HALIL-HISAR SEGMENT CLSD.
VERTICAL LIMITS: 15000FT AMSL-23000FT AMSL

*LTAAA2467/26 (06 JUN 26)

"JUN 18 0700-1000, JUN 22-JUL 02 0700-1000 1130-1330 EXC SAT SUN"
SEE NOTAM: A2457/26
RNAV ROUTES AND SEGMENTS AFFECTED DURING EXERCISE AS FOLLOWS:
1. AWY L/UL601 SELVI -ADA SEGMENT CLSD.
ALL ACFT THAT PLANNING TKOF/LDG FROM/TO LTAF-LTAG-LTDA AND
LTDB AERODROMES COULD FOLLOW G/UG8 OR L/UL614-GEM-DCT-MILBA
BIDIRECTIONALLY.
2. AWY T/UT339 MUT-ERCIS SEGMENT CLSD.
3. AWY UT284 INPOR-UDVET SEGMENT CLSD.
VERTICAL LIMITS: SFC-30000FT AMSL

*LTAAA2459/26 (06 JUN 26)

"JUN 18 0700-1000, JUN 22-JUL 02 0700-1000 1130-1330 EXC SAT SUN"
SEE NOTAM: A2457/26
ATS ROUTES AND SEGMENTS AFFECTED DURING EXERCISE AS FOLLOWS:
1. AWY A/UA285 MUT-ERCIS SEGMENT CLSD.
2. AWY W/UW75 SELVI -ADA SEGMENT CLSD.
ALL ACFT THAT PLANNING TKOF/LDG FROM/TO LTAF-LTAG-LTDA AND
LTDB AERODROMES COULD FOLLOW G/UG8 OR L/UL614-GEM-DCT-MILBA
BIDIRECTIONALLY.
VERTICAL LIMITS: SFC-30000FT AMSL

*LTAAA2457/26 (06 JUN 26)

"JUN 18 0700-1000, JUN 22-JUL 02 0700-1000 1130-1330 EXC SAT SUN"
EXERCISE WILL TAKE PLACE.
RMK: AIR TRAFFIC FLOW REGULATION NOTAM SHALL BE ISSUED.
AREA: 381200N0343700E 381200N0350200E 372500N0350200E
370300N0343500E 370300N0332600E 370600N0331600E 381200N0343700E
WI ADANA MILITARY TMA

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 35/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

F) SFC
G) 30000FT AMSL

*LTAAA2455/26 (06 JUN 26)

"JUN 18 0700-1000, JUN 22-26 0700-1000 1130-1330, JUN 29-JUL 02
0700-1000 1130-1330"
SEE NOTAM: A2454/26
RNAV ROUTES AND SEGMENTS AFFECTED DURING EXERCISE AS FOLLOWS:
1- AWY UT244 OKMOT-REBTA SEGMENT CLSD.
2- AWY UL742 OKMOT-REBTA SEGMENT CLSD.
VERTICAL LIMITS: 15000FT AMSL-50000FT AMSL

*LTAAA2454/26 (06 JUN 26)

"JUN 18 0700-1000, JUN 22-26 0700-1000 1130-1330, JUN 29-JUL 02
0700-1000 1130-1330"
RMK: AIR TRAFFIC FLOW REGULATION NOTAM SHALL BE ISSUED.
EXERCISE WILL TAKE PLACE WI AREA (LT TSA62R): 382446N0320519E
382459N0324353E 381518N0325242E 380211N0323706E 374641N0323711E
374114N0324501E 373504N0323701E 380700N0315300E 382446N0320519E
F) 15000FT AMSL
G) 50000FT AMSL

*LTAAA2452/26 (06 JUN 26)

"JUN 18 0700-1000, JUN 22-26 0700-1000 1130-1330, JUN 29-JUL 02
0700-1000 1130-1330"
SEE NOTAM: A2450/26
RNAV ROUTES AND SEGMENTS AFFECTED DURING EXERCISE AS FOLLOWS:
1. AWY L/UL601 AZBUL-SELVI SEGMENT CLSD.
ALL ACFT PLANNING TAKE-OFF/LANDING FROM/TO LTAZ AD VIA
AZBUL-L/UL601-URGUP-W/UW106-TZK VOR COULD FOLLOW AZBUL W/UW105-ULRAS
BIDIRECTIONALLY.
ALL ACFT THAT PLANNING TAKE-OFF/LANDING FROM/TO LTAF-LTAG-LTDA AND
LTDB AERODROMES COULD FOLLOW G/UG8 OR L/UL614-GEM-DCT-MILBA
BIDIRECTIONALLY.
2. AWY UL621 BUK-MUT SEGMENT CLSD.
3. AWY UL742 OKMOT-MUT SEGMENT CLSD.
4. AWY M/UM856 ERKUK-MUT SEGMENT CLSD.
5. AWY T244 REBTA-MANAZ SEGMENT CLSD.
6. AWY UT244 OKMOT-MANAZ SEGMENT CLSD.
VERTICAL LIMITS: SFC-50000FT AMSL

*LTAAA2451/26 (06 JUN 26)

"JUN 18 0700-1000, JUN 22-26 0700-1000 1130-1330, JUN 29-JUL 02
0700-1000 1130-1330"
SEE NOTAM: A2450/26
ATS ROUTES AND SEGMENTS AFFECTED DURING EXERCISE AS FOLLOWS:
1. AWY A/UA28 ERKUK-MUT SEGMENT CLSD.
2. AWY W/UW75 ARMUD-SELVI SEGMENT CLSD.
ALL ACFT THAT PLANNING TAKE-OFF/LANDING FROM/TO LTAF-LTAG-LTDA AND
LTDB AERODROMES COULD FOLLOW G/UG8 OR L/UL614-GEM-DCT-MILBA
BIDIRECTIONALLY.
3. AWY W/UW106 URGUP-ETVER SEGMENT CLSD.
VERTICAL LIMITS: SFC-50000FT AMSL

*LTAAA2450/26 (06 JUN 26)

"JUN 18 0700-1000, JUN 22-26 0700-1000 1130-1330, JUN 29-JUL 02
0700-1000 1130-1330"
RMK: AIR TRAFFIC FLOW REGULATION NOTAM SHALL BE ISSUED.
EXERCISE(WITHOUT FIRING) WILL TAKE PLACE WI
AREA(LT TSA61R):382446N0320519E 390543N0323402E 390148N0330013E
391435N0332551E 390500N0334449E 382557N0342005E 381200N0343700E
370600N0331600E 373504N0323701E 374114N0324501E 374641N0323711E
380211N0323706E 381518N0325248E 382459N0324353E 382446N0320519E
F) SFC
G) 50000FT AMSL

*LTAAA2443/26 (06 JUN 26)

"JUN 18 0700-1000, JUN 22-JUL 02 0700-1000 1130-1330 EXC SAT SUN"
SEE NOTAM: A2442/26
RNAV ROUTES AND SEGMENTS AFFECTED DURING EXERCISE AS FOLLOWS:
1- AWY T62 KONAK-RUKAP SEGMENT CLSD.
VERTICAL LIMITS: SFC-20000FT AMSL

*LTAAA2442/26 (06 JUN 26)

"JUN 18 0700-1000, JUN 22-JUL 02 0700-1000 1130-1330 EXC SAT SUN"
EXERCISE WILL TAKE PLACE.
RMK:AIR TRAFFIC REGULATION NOTAM SHALL BE ISSUED.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 36/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

AREA: 374900N0314000E 371100N0323000E 370400N0323000E
370400N0313400E 374900N0314000E
F) SFC
G) 20000FT AMSL

*LTAAA2438/26 (06 JUN 26)

"JUN 18 0630-1030, JUN 22-JUL 02 0630-1030 1100-1400 EXC SAT SUN"
EXERCISE WILL TAKE PLACE WI: 372500N0350200E 372500N0354500E
382500N0354500E 382500N0350200E 372500N0350200E
F) 31000FT AMSL
G) 31000FT AMSL

*LTAAA2393/26 (06 JUN 26)

"JUN 18 0700-1000, JUN 22-JUL 02 0700-1000 1130-1330 EXC SAT SUN"
EXERCISE WILL TAKE PLACE WI AREA:
373900N0350200E 370300N0341850E 370300N0332600E
370600N0331600E 373450N0323700E 374100N0324500E 371200N0332300E
371100N0333100E 371100N0341400E 375050N0350200E 373900N0350200E
F) SFC
G) 30000FT AMSL

*LTAAA2391/26 (06 JUN 26)

"18 0700-1000, JUN 22-26 29-30 JUL 01-02 0700-1000 1130-1330"
SEE NOTAM: A2387/26
ATS ROUTES AND SEGMENTS AFFECTED DURING EXERCISE AS FOLLOWS:
1- AWY B545 OKLAM-EVKIT SEGMENT CLSD.
2- AWY R55 KETEK-MUT SEGMENT CLSD.
3- AWY W74 MUT-ADA SEGMENT CLSD.
VERTICAL LIMITS: SFC-15000FT AMSL

*LTAAA2389/26 (06 JUN 26)

"18 0700-1000, JUN 22-26 29-30 JUL 01-02 0700-1000 1130-1330"
SEE NOTAM: A2387/26
RNAV ROUTES AND SEGMENTS AFFECTED DURING EXERCISE AS FOLLOWS:
1- AWY L620 OKLAM-EVKIT SEGMENT CLSD.
2- AWY T339 MUT-ELROP SEGMENT CLSD.
VERTICAL LIMITS: SFC-15000FT AMSL

*LTAAA2387/26 (06 JUN 26)

"18 0700-1000, JUN 22-26 29-30 JUL 01-02 0700-1000 1130-1330"
RMK: AIR TRAFFIC FLOW REGULATION NOTAM SHALL BE ISSUED.
EXERCISE WILL TAKE PLACE WI: 380101N0320125E 370600N0331600E
370300N0332600E 370300N0343500E 364600N0341900E 364600N0330400E
374246N0314829E 380101N0320125E
F) SFC
G) 15000FT AMSL

LTAAA2369/26 (06 JUN 26)

RNAV AIR CORRIDOR IDENTIFIED AS UM861 REVISED AS FOLLOWS:

BTN NISAP-TEVDA TRACK MAG:318/138 EVEN/ODD
BTN TEVDA-BUK:317/137 EVEN/ODD
BTN BUK-RAKUR:339 EVEN

OTHER INFORMATION NOT CHANGED.

REF AIP ENR 3.2
03 JUN 26 14:15 UNTIL 03 SEP 26 13:00 ESTIMATED

LTAAA2362/26 (06 JUN 26)

"JUN 04 08 10 12 16 18 22 24 26 30 0600-2059, JUL 02 06 08 10 14
16 20 22 24 28 30 0600-2059, AUG 03 05 07 11 13 17 0600-2059"
UNMANNED ACFT TEST FLT WILL TAKE PLACE WI:
385513N0312028E 390936N0320156E 384213N0314248E 385513N0312028E
F) 13000FT AMSL
G) 35000FT AMSL

LTAAA2349/26 (06 JUN 26)

MON WED FRI 0915-1115
UNMANNED ACFT WILL TAKE PLACE
AREA: 381620N0333332E 382600N0332100E 383559N0334632E 382721N0335410E
381620N0333332E
F) SFC
G) 40000FT AMSL

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 37/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

*LTAAA2127/26 (21 MAY 26)

0700-1400 EXC SAT SUN
SEE NOTAM: A2125/26
ATS ROUTES AND SEGMENTS AFFECTED DURING TEST FLT AS FLW:
1. AWY W/UW100 SUMOL-INB SEGMENT CLSD.
2. AWY W/UW101 KUGOS-GAKSU SEGMENT CLSD.
VERTICAL LIMITS: SFC-40000FT AMSL

*LTAAA2126/26 (21 MAY 26)

0700-1400 EXC SAT SUN
SEE NOTAM: A2125/26
RNAV ROUTES AND SEGMENTS AFFECTED DURING TEST FLT AS FLW:
1. AWY M/UM854 SUMOL-INB SEGMENT CLSD.
2. AWY P/UP29 SUMOL-BIMVO SEGMENT CLSD.
3. AWY M/UM853 KUGOS-GAKSU SEGMENT CLSD.
VERTICAL LIMITS: SFC-40000FT AMSL

*LTAAA2125/26 (21 MAY 26)

0700-1400 EXC SAT SUN
TEST FLT WILL TAKE PLACE WI (LTSA-3R):
424456N0330020E 424432N0335425E 424030N0340849E 422530N0340633E
423400N0325953E 424456N0330020E
RMK: AIR TRAFFIC FLOW REGULATION NOTAM SHALL BE ISSUED.
F) SFC
G) 40000FT AMSL

LTAAA2027/26 (14 MAY 26)

URFA KORCIK MSSR UNRELIABLE BTN 250-360 DEGREES.

*LTAAA1722/26 (28 APR 26)

"RESTRICTED AREA WI ADANA MIL TMA:
CENTERED ON 370006N0352532E WITH RADIUS 14NM
VERTICAL LIMITS: SFC-80000FT AMSL

NOTE 1: WHEN AIR DEFENCE SYSTEMS ARE IN NORMAL STATUS, ALL MIL/CIV
TFCS WILL NOT BE AFFECTED.

NOTE 2: WHEN AIR DEFENCE SYSTEMS BECOME ACTIVE, ALL TFCS WI (10NM)
OF INCIRLIK AD, CUKUROVA INTERNATIONAL AD, SAKIRPASA AD AND HUR AD
WILL BE SEQUENCED FOR LDG BY INCIRLIK APCH.
TFCS OUTSIDE (10NM) WILL BE PUT ON HOLD AT APPROPRIATE POINTS NORTH
OF THE AREA. DEP TFCS FROM THE AFFECTED AERODROMES WILL NOT BE
PERMITTED.

NOTE 3: DUE TO THE REQUIREMENT FOR TWO-WAY COMMUNICATION, CONTINUOUS
AND REAL-TIME RTF CONTACT WITH ANKARA ACC OR INCIRLIK ATC IS
ESSENTIAL. CONTINUOUS MONITORING OF THE GUARD FREQ IS REQUIRED."
F) SFC
G) UNL

*LTAAA1721/26 (28 APR 26)

"RESTRICTED AREA WI ADANA MIL TMA:
373949N0353344E 370015N0352513E 363911N0344154E 363221N0344838E
362534N0350031E 362238N0350823E 362051N0351638E 362013N0352514E
362051N0353345E 362234N0354204E 362538N0354952E 362935N0355657E
363422N0360318E 364006N0360817E 364619N0361201E 365316N0361414E
370006N0361513E 370704N0361427E 371351N0361214E 372003N0360840E
372559N0360350E 373059N0355726E 373453N0354956E 373819N0354208E
374002N0353342E 373949N0353344E
VERTICAL LIMITS: SFC-70000FT AMSL

NOTE 1: WHEN AIR DEFENCE SYSTEMS ARE IN NORMAL STATUS, ALL MIL/CIV
TFCS WILL NOT BE AFFECTED.

NOTE 2: WHEN AIR DEFENCE SYSTEMS BECOME ACTIVE, ALL TFCS WI (10NM)
OF INCIRLIK AD, CUKUROVA INTERNATIONAL AD, SAKIRPASA AD AND HUR AD
WILL BE SEQUENCED FOR LDG BY INCIRLIK APCH.
TFCS OUTSIDE (10NM) WILL BE PUT ON HOLD AT APPROPRIATE POINTS NORTH
OF THE AREA. DEP TFCS FROM THE AFFECTED AERODROMES WILL NOT BE
PERMITTED.

NOTE 3: DUE TO THE REQUIREMENT FOR TWO-WAY COMMUNICATION, CONTINUOUS
AND REAL-TIME RTF CONTACT WITH ANKARA ACC OR INCIRLIK ATC IS
ESSENTIAL. CONTINUOUS MONITORING OF THE GUARD FREQ IS REQUIRED."
F) SFC
G) UNL

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 38/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

LTAAA1217/26 (31 MAR 26)

IT IS REPORTED BY PILOTS THAT GPS SIGNALS CAN NOT BE RECEIVED
OCCASSIONALLY IN SOME PARTS OF TURKISH AIRSPACE.
PILOTS WHO PLAN RNAV FLIGHT OR EXECUTE RNAV/RNP PROCEDURES WITHIN
TURKISH AIRSPACE ARE ADVISED TO BE CAUTIOUS ABOUT GPS SIGNAL LOSSES.
31 MAR 26 07:30 UNTIL 30 JUN 26 07:30 ESTIMATED

*LTAAA1191/26 (31 MAR 26)

SEE NOTAM: A1189/26
RNAV ROUTES AND SEGMENTS AFFECTED DURING FIRING EXERCISE AS FOLLOWS:
1. AWY UM860 NINVA-SRT SEGMENT CLSD.
2. AWY UM688 OTKEP-RATVO SEGMENT CLSD.
3. AWY UT332 OTKEP-KABAN SEGMENT CLSD.
4. AWY UT301 NARLI-LUMOM SEGMENT CLSD.
VERTICAL LIMITS: 31000FT AMSL-33000FT AMSL

*LTAAA1189/26 (31 MAR 26)

FIRING EXERCISE WILL TAKE PLACE WI:
371826N0424330E 372900N0423000E 374559N0423000E 373700N0443600E
372644N0443448E 371707N0444838E 371411N0444435E 371018N0444602E
371134N0443821E 370724N0443226E 365859N0441748E 370611N0441115E
371018N0441726E 371613N0441429E 372000N0440336E 371247N0435057E
371510N0433045E 372246N0430751E 371916N0425718E 372257N0424659E
371826N0424330E
RMK: AIR TRAFFIC FLOW REGULATION NOTAM SHALL BE ISSUED.
AREA CLSD TO TFC BTN FL310-FL330.
F) 31000FT AMSL
G) 33000FT AMSL

*LTAAA1075/26 (18 MAR 26)

SEE NOTAM: A1065/26
RNAV ROUTES AND SEGMENTS AFFECTED DURING EXERCISE FLIGHT (WITHOUT
FIRING) AS FOLLOWS
1.AWY T333 SRT-LESRI SEGMENT CLOSED.
2.AWY M860 EFFEZ-SRT SEGMENT CLOSED.
3.AWY T306 SRT-ABDIK SEGMENT CLOSED.

VERTICAL LIMITS: FL170-FL260

*LTAAA1076/26 (18 MAR 26)

SEE NOTAM: A1065/26
ATS ROUTES AND SEGMENTS AFFECTED DURING EXERCISE FLIGHT (WITHOUT
FIRING) AS FOLLOWS
1.AWY W197 SRT-ABDIK SEGMENT CLOSED.
2.AWY R21 KABAN-SRT SEGMENT CLOSED.

VERTICAL LIMITS: FL170-FL260

*LTAAA1072/26 (18 MAR 26)

KABAN FIR BDRY CLSD TO ALL TFC AT AND BELOW FL310

*LTAAA1071/26 (18 MAR 26)

"SEE NOTAM: A1068/26
RNAV ROUTE AND SEGMENTS AFFECTED DURING FIRING ACTIVITY AS FOLLOWS:
1. AWY M/UM860 NINVA-SRT SEGMENT CLOSED.
2. AWY M/UM688 OTKEP-RATVO SEGMENT CLOSED.
3. AWY T/UT332 OTKEP-KABAN SEGMENT CLOSED.
4. AWY UT301 INLAP-LUMOM SEGMENT CLOSED.
5. AWY T301 INLAP-YKV SEGMENT CLOSED.
VERTICAL LIMITS FOR ABOVE ROUTES: SFC-FL310
6. HAKKARI YUKSEKOVA SELAHADDIN EYYUBI AIRPORT(LTCW) PLANNING TAKE
-OFF/LANDING SHALL USE THE ROUTE WITH DETAILS PROVIDED BELOW,WHEN
DEEMED NECESSARY BY ATC
ROTA: VAN VOR(382758N0431930E)-RUPOM(375016N0435725E)-
YKV VOR(373257N0441433E)
MAG TRACK: 137/317(VAN VOR-YKV VOR)
DISTANCE: BTN VAN VOR-RUPOM 48.1NM
BTN RUPOM-YKV VOR 22.0NM
FLIGHT LEVELS:BTN VAN VOR-RUPOM FL220
BTN RUPOM-YKV VOR MIN FL180)"

*LTAAA1069/26 (18 MAR 26)

"SEE NOTAM: A1063/26
RNAV ROUTES AND SEGMENTS AFFECTED DURING EXERCISE FLIGHT (WITHOUT
FIRING) AS FOLLOWS

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 39/90

Trans ID: 5040609

Creation Time: 27.06.2026 12:51UTC

1.AWY L/UL614 ULSAB-DERIL SEGMENT CLOSED.
2.AWY M/UM860 RENGİ-EFFEZ SEGMENT CLOSED.
3.AWY M/UM688 ULTED-RATVO SEGMENT CLOSED.
4.AWY UT253 RENGİ-OTKEP SEGMENT CLOSED.
5.AWY UT301 ULTED-YKV SEGMENT CLOSED.
6.AWY T/UT36 ULTED-ALRAM SEGMENT CLOSED.
7.AWY UT888 ALRAM-BAYIR SEGMENT CLOSED.
8.AWY UL718 ULSAB-ESOTA SEGMENT CLOSED.
9.AWY T/UT333 BEYAZ-ESOTA SEGMENT CLOSED.
10.AWY T/UT332 BEYAZ-EFFEZ SEGMENT CLOSED.
11.AWY T301 NARLI-YKV SEGMENT CLOSED.
12.AWY R/UR21 KABAN-SRT SEGMENT CLOSED.
13.AWY T/UT306 SRT-ABDIK SEGMENT CLOSED.
VERTICAL LIMITS FOR ABOVE RTS: FL240-FL310
14.HAKKARI YUKSEKOVA SELAHADDIN EYYUBI AIRPORT(LTCW),ACFT PLANNING
TAKE-OFF/LANDING SHALL USE THE ROUTE WITH DETAILS PROVIDED BELOW
WHEN DEEMED NECESSARY BY ATC
ROUTE: VAN VOR(382758N0431930E)-RUPOM(375016N0435725E)-
YKV VOR(373257N0441433E)
MAG TRACK: 137/317(VAN VOR-YKV VOR)
DISTANCE:
BTN VAN VOR-RUPOM 48.1NM
BTN RUPOM-YKV VOR 22.0NM
FLIGHT LEVELS:
BTN VAN VOR-RUPOM FL220
BTN RUPOM-YKV VOR MIN FL180"

*LTAAA1068/26 (18 MAR 26)

"FIRING EXERCISE WILL TAKE PLACE.
RMK: AIR TRAFFIC FLOW REGULATION NOTAM WILL BE ISSUED.
AREA: 371830N0424330E 372900N0423000E 374600N0423000E
373700N0443600E 372652N0443448E 371708N0444846E 371412N0444435E
371018N0444604E 371142N0443823E 370725N0443227E 365859N0441749E
370611N0441117E 371018N0441726E 371613N0441429E 372001N0440344E
371247N0435057E 371512N0433045E 372247N0430752E 371916N0425718E
372258N0424706E 371830N0424330E
1ST NOTE: IFR TRAFFICS DEPARTING OR LANDING FROM LTCV,LTCL, LTCW,
LTCI AIRPORTS AND IFR TRAFFICS LANDING THROUGH TO OR DEPARTING FROM
BAGHDAD FIR ARE EXCLUDED. THESE TRAFFIC'S AREA USAGE REQUESTS SHALL
BE DECIDED UPON THE COORDINATION BETWEEN ANKARA ACC AND BIKIM.
2ND NOTE: FOLLOW ALONG BORDER OF TURKISH-IRAQ, TURKISH-IRAN. IT IS
STRICTLY ADVISED NOT TO MAKE AVOIDANCE MANEUVERES TOWARDS THIS AREA."
F) SFC
G) 31000FT AMSL

*LTAAA1063/26 (18 MAR 26)

"EXERCISE WILL TAKE PLACE (WITHOUT FIRING) (H24)
AIR TRAFFIC FLOW REGULATION NOTAM WILL BE ISSUED
AREA: 373700N0443600E 375000N0413000E 382000N0413000E
382034N0432322E 375755N0441520E 375312N0441322E 375121N0441754E
375038N0442316E 374513N0442817E 374603N0443342E 374218N0443637E
373923N0443329E 373700N0443600E

RMK: IFR TRAFFICS DEPARTING OR LANDING FROM LTCV ,LTCL, LTCW , LTCI
AIRPORTS AND IFR TRAFFICS LANDING THROUGH TO OR DEPARTING FROM
BAGHDAD FIR ARE EXCLUDED. THESE TRAFFIC'S AREA USAGE REQUESTS SHALL
BE DECIDED UPON THE COORDINATION BETWEEN ANKARA ACC AND BIKIM.
THE PILOTS OF AIRCRAFT THAT ARE MAKING AVOIDANCE MANEUVERS OUTSIDE
THE AIRWAY OR UNABLE COMPLY WITH THE FLIGHT LEVELS, SHALL INFORM ATC
UNIT IMMEDIATELY.
IN SUCH A CASE, FLIGHT WILL BE CONTINUED SAFELY WITHIN EXERCISE AREA
BY MEANS OF CIVIL/MILITARY COORDINATION
TRAFFIC FLYING ON AWYS G/UG8, T/UT888 AND T/UT36 SHALL MAKE
AVOIDANCE MANEUVERS TO THE NORTH OF THE AWY IN ORDER TO AVOID FIRING
EXERCISE AREAS."
F) 24000FT AMSL
G) 31000FT AMSL

*LTAAA1065/26 (18 MAR 26)

"EXERCISE WILL TAKE PLACE(WITHOUT FIRING) (H24) .
AIR TRAFFIC FLOW REGULATION NOTAM SHALL BE ISSUED.
AREA: 375000N0413000E 372200N0413000E 372200N0423000E
374600N0423000E 375000N0413000E

RMK: IFR TRAFFICS DEPARTING OR LANDING FROM LTCV, LTCL, LTCW, LTCI
AIRPORTS AND IFR TRAFFICS LANDING THROUGH TO OR DEPARTING FROM
BAGHDAD FIR ARE EXCLUDED. THESE TRAFFIC'S AREA USAGE REQUESTS SHALL
BE DECIDED UPON THE COORDINATION BETWEEN ANKARA ACC AND BIKIM.
THE PILOTS OF AIRCRAFT THAT ARE MAKING AVOIDANCE MANEUVERS OUTSIDE

THE AIRWAY OR UNABLE COMPLY WITH THE FLIGHT LEVELS, SHALL INFORM ATC UNIT IMMEDIATELY. IN SUCH A CASE, FLIGHT WILL BE CONTINUED SAFELY WITHIN EXERCISE AREA BY MEANS OF CIVIL/MILITARY COORDINATION. TRAFFIC FLYING ON AWYS R/UR21, M/UM860 AND UT334 SHALL MAKE AVOIDANCE MANEUVERS TO THE WEST OF THE AWY IN ORDER TO AVOID FIRING EXERCISE AREAS."

F) 17000FT AMSL

G) 26000FT AMSL

*LTAAA5879/25 (01 JAN 26)

"SEE NOTAM: A5860/25

RNAV ROUTE AND SEGMENTS AFFECTED BECAUSE OF THE AIR DEFENCE ZONE AND ALTERNATIVE ROUTES ARE GIVEN BELOW:

A)

AWY UL601 CLOSED TO TRAFFIC BTN SEGMENTS KEMER-ADA-TUNLA.

AWY L601 CLOSED TO TRAFFIC BTN SEGMENTS KEMER-ADA

VERTICAL LIMITS:FL110-FL450

FLIGHTS SHALL BE PLANNED AS BELOW:

KEMER DCT ADKAR (364733N0351152E) OR

KEMER DCT ADKAR (364733N0351152E) DCT TUNLA OR

KEMER DCT ADKAR (364733N0351152E) T/UT470 MILBA OR

KEMER DCT ADKAR (364733N0351152E) DCT HTY. (MIN FL280)

DCT RAD ADKAR-MILBA SHALL NOT BE USED.

B)

CIVIL TRAFFICS OPERATING TO/FROM LTAF, LTDB AND LTDA AIRPORTS ARE EXEMPTED FROM THESE REGULATIONS AND SHOULD CONTINUE TO USE AWYS, SIDS, STARS AND INSTRUMENT APPROACH PROCEDURES PUBLISHED AT TURKISH AIP. INCIRLIK RAPCON WILL PROVIDE AIR TRAFFIC CONTROL SERVICES TO CIVIL TRAFFIC WITHIN ADANA MIL TMA AND VECTOR AROUND ADZ."

*LTAAA5862/25 (01 JAN 26)

"SEE NOTAM: A5860/25

ATS ROUTE AND SEGMENTS AFFECTED DURING THE AIR DEFENCE ZONE ARE GIVEN BELOW.

A)

AWY W/UW75 CLSD TO TFC BTN SEGMENTS KEMER-ADA.

AWY W/UW74 CLSD TO TFC BTN SEGMENTS MANAZ-ADA-MILBA.

AWY W/UW84 CLSD TO TFC BTN SEGMENTS YAPZU-ADA.

AWY W/UW717 CLSD TO TFC.

VERTICAL LIMITS: FL110-FL450

FLIGHTS SHALL BE PLANNED AS BELOW:

AWY W/UW75

KEMER DCT ADKAR (364733N-0351152E) OR

KEMER DCT ADKAR (364733N-0351152E) DCT TUNLA OR

KEMER DCT ADKAR (364733N-0351152E) T/UT470 MILBA OR

KEMER DCT ADKAR (364733N-0351152E) DCT HTY

(MIN FL280)

AWY W/UW74

MANAZ DCT ADKAR (364733N-0351152E) OR

MANAZ DCT ADKAR (364733N-0351152E) T/UT470 MILBA OR

MANAZ DCT ADKAR (364733N-0351152E) DCT TUNLA OR

MANAZ DCT ADKAR (364733N-0351152E) DCT KEMER OR

MANAZ DCT ADKAR (364733N-0351152E) DCT HTY

MIN FL280)

AWY W/UW84

YAPZU DCT ADKAR (364733N-0351152E) OR

YAPZU DCT ADKAR (364733N-0351152E) T/UT470 MILBA OR

YAPZU DCT ADKAR (364733N-0351152E) DCT KEMER OR

YAPZU DCT ADKAR (364733N-0351152E) DCT HTY

(MIN FL280)

B)

CIVIL TRAFFICS OPERATING TO/FROM LTAF, LTDB AND LTDA AIRPORTS ARE EXEMPTED FROM THESE REGULATIONS AND SHOULD CONTINUE TO USE AWYS, SIDS, STARS AND INSTRUMENT APPROACH PROCEDURES PUBLISHED AT TURKISH AIP. INCIRLIK RAPCON WILL PROVIDE AIR TRAFFIC CONTROL SERVICES TO CIVIL TRAFFIC WITHIN ADANA MIL TMA AND VECTOR AROUND ADZ.)"

*LTAAA5860/25 (01 JAN 26)

AIR DEFENCE ZONE ESTABLISHED WITH THE FOLLOWING COORDINATES:

AREA: 365846N0352254E 370023N0352409E 370015N0353134E

365745N0353101E 365527N0352837E 365424N0352528E 365358N0352133E

365846N0352254E

NOTE: AIR TRAFFIC FLOW REGULATIONS AND ALTERNATIVE ROUTES NOTAMS SHALL BE ISSUED.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 41/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

F) FL110
G) FL450

LTAAA1342/08 (08 SEP 25)

"WARNING
WITH REFERANS TO THE NOTE IN REMARKS COLUMN OF TURKISH AIP PAGES
ENR 3.1-5,ENR 3.1-25,ENR 3.2-5,ENR 3.2-25,ENR 3.3-16 AND ENR 3.4-16
THE SEGMENT OF ATS ROUTES A/UA 28 BTN MUT-DOREN,AND THE SEGMENT OF
ATS ROUTES N/UN131 AND W/UW83 BTN AYT VOR-DOREN WILL ONLY BE
AUTHORIZED FOR TRAFFIC TO OR FROM ERCAN AIRPORT (LCEN).
ALL OPERATORS SHALL FILE FLIGHT PLANS IN ACORDANCE WITH THESE
REGULATIONS."

LTAAA5712/22 (17 OCT 23)

"AMEND TO READ AWY B/UB545 MUT VOR COORDINATE AS 365146N0331730E
INSTEAD OF 373906N0321213E
REF AIP ENR 3.1.10 , ENR 3.2.10"

LTBB / ISTANBUL FIR

*LTAAA2511/26 (17 JUN 26)

"JUN 18 0700-1000, JUN 22-26 29-30 JUL 01-02 0700-1000 1130-1330"
SEE NOTAM: A2509/26
RNAV ROUTES AND SEGMENTS AFFECTED DURING THE EXERCISE AS FOLLOWS:
1- AWY P29 HALIL-HISAR SEGMENT CLSD.
2- AWY M853 OKLAM-BUK SEGMENT CLSD.
VERTICAL LIMITS: 15000FT AMSL-23000FT AMSL

LTAAA1217/26 (31 MAR 26)

IT IS REPORTED BY PILOTS THAT GPS SIGNALS CAN NOT BE RECEIVED
OCCASSIONALLY IN SOME PARTS OF TURKISH AIRSPACE.
PILOTS WHO PLAN RNAV FLIGHT OR EXECUTE RNAV/RNP PROCEDURES WITHIN
TURKISH AIRSPACE ARE ADVISED TO BE CAUTIOUS ABOUT GPS SIGNAL LOSES.
31 MAR 26 07:30 UNTIL 30 JUN 26 07:30 ESTIMATED

LTAAA1150/26 (27 MAR 26)

UNMANNED ACFT WILL TAKE PLACE.
AREA: 404615N0261531E 403640N0260513E 403605N0262720E
404640N0265343E 404745N0265340E 404615N0261531E
F) 3000FT AMSL
G) 35000FT AMSL

LTAAA1147/26 (27 MAR 26)

UNMANNED ACFT WILL TAKE PLACE WI AREA:
403757N0263201E 403032N0263635E 403554N0265013E
404330N0264547E 403757N0263201E
F) SFC
G) 35000FT AMSL

LTAAA1144/26 (27 MAR 26)

UNMANNED ACFT WILL TAKE PLACE
AREA: 403640N0260513E 403419N0260304E 402537N0262018E
403032N0263635E 403757N0263201E 403605N0262720E 403640N0260513E
F) 10000FT AMSL
G) 35000FT AMSL

*LTAAA0954/26 (10 MAR 26)

0600-2000 EXC SAT SUN
"GUN FIRING WILL TAKE PLACE WI ISTANBUL TMA: 414300N0272520E
414300N0273700E 413816N0273700E 413759N0273323E 414021N0272509E
414300N0272520E
NOTE: WHEN RWY 16, 17 AND 18 ARE IN USE AT ISTANBUL AD, THE UPPER
LIMIT SHALL BE 11000FT AMSL."
F) SFC
G) 14000FT AMSL

LTAAA3208/06 (27 SEP 25)

"NAVIGATIONAL WARNING TO ALL CONCERNED:
THE CONSIDERABLE PORTION OF THE AWYS G/UG18,L/UL609,R/UR19 AND
L/UL995 CROSS OVER THE SOVEREIGN AIR SPACE OF TURKEY AND REMAINS
WITHIN MILAS TMA.FOR THE SAFETY OF FLIGHTS AND SECURITY REASONS,
ALL AIRCRAFT USING LARKI 3723.9N-02650.3E RHODES PORTION OF THE AWYS
G/UG18,L/UL609,AND:KOPAR 3650.9N-02642.0E RHODES PORTION OF THE AWYS
R/UR19,L/UL995 SHALL ALWAYS FLY AT OR ABOVE FL250 DURING THEIR
FLIGHTS WITHIN TURKISH AIRSPACE."

BGR / BULGARIA

N I L

LBSR / SOFIA FIR

LBSFA0719/26 (26 JUN 26)

"MIDDLE EAST CRISIS:

AIR CARRIERS AND CAPTAINS OF ACFT IN CHARGE OF AIR SERVICE MANAGED BY CARRIERS HOLDERS OF OPERATING LICENCE ISSUED BY REPUBLIC OF BULGARIA, WHETHER THEY ARE CONTRACTUAL CARRIERS AND/OR DE FACTO CARRIERS, OR PERFORMING AIR SERVICE WITH COMMERCIAL CHARTER AGREEMENT OR WITH CODE SHARING AND TO ALL FLIGHTS PERFORMED WITH BULGARIAN ACFT REGISTRATION ARE STRONGLY ADVISED TO:

1. NOT TO OPERATE WITHIN THE AFFECTED AIRSPACE OF IRAN, IRAQ, LEBANON AT ALL FLIGHT LEVELS AND ALTITUDES.
2. EXERCISE CAUTION AND TAKE POTENTIAL RISKS INTO ACCOUNT WHEN OPERATING WITHIN THE AIRSPACE OF BAHRAIN, KUWAIT, ISRAEL, JORDAN, QATAR, OMAN, THE UAE AND SAUDI ARABIA.
3. ENSURE THAT AN UP-TO-DATE RISK ASSESSMENT AND HIGH LEVEL OF CONTINGENCY PLANNING ARE IN PLACE FOR OPERATIONS WITHIN THE AIRSPACE SPECIFIED IN POINT 2 ABOVE, AND BE PREPARED FOR SHORT NOTICE INSTRUCTIONS FROM THE STATE AUTHORITIES.
4. CLOSELY MONITOR AIRSPACE DEVELOPMENTS IN THE REGION AND FOLLOW ALL AVAILABLE AERONAUTICAL PUBLICATIONS CONCERNING THE REGION, INCLUDING INFORMATION SHARED THROUGH THE EUROPEAN INFORMATION SHARING AND COOPERATION PLATFORM ON CONFLICT ZONES, ALONGSIDE AVAILABLE GUIDANCE OR DIRECTION FROM THEIR NATIONAL AUTHORITIES.

OPERATORS SHALL ENSURE THAT ALL FLIGHT CREWS AND RELEVANT OPERATIONAL PERSONNEL ARE PROPERLY INFORMED OF ALL APPLICABLE RESTRICTIONS, RECOMMENDATIONS, AND MITIGATION MEASURES PRIOR TO CONDUCTING OPERATIONS.

GD CAA REQUESTS STRICT COMPLIANCE WITH THE ABOVE MEASURES IN THE INTEREST OF MAINTAINING THE HIGHEST LEVEL OF AVIATION SAFETY AND SECURITY."

24 JUN 26 11:49 UNTIL 01 JUL 26 23:59 ESTIMATED

LBSFA0412/26 (01 MAY 26)

GNSS JAMMING AND SPOOFING OCCURRENCES HAVE BEEN REPORTED WITHIN LBSR FIR. CONVENTIONAL NAVAIDS AVAILABLE.

AIR CREWS TO REMAIN VIGILANT AND REPORT TO ATC.

28 APR 26 08:28 UNTIL 27 JUL 26 12:00 ESTIMATED

LBSFA0352/26 (08 APR 26)

"BULGARIAN AIR CARRIERS AND CAPTAINS OF ACFT IN CHARGE OF AIR SERVICE MANAGED BY CARRIERS HOLDERS OF OPERATING LICENCE ISSUED BY BULGARIAN CAA, WHETHER THEY ARE CONTRACTUAL CARRIERS AND/OR DE FACTO CARRIERS, OR PERFORMING AIR SERVICE WITH COMMERCIAL CHARTER AGREEMENT OR WITH CODE SHARING AND TO ALL FLIGHT PERFORMED WITH BULGARIAN ACFT REGISTRATION, ARE NOT ALLOWED TO CONDUCT OPERATIONS IN BELARUSIAN AIRSPACE /FIR MINSK - UMMV/ UNLESS THE USE OF THAT AIRSPACE IS DEEMED NECESSARY TO ENSURE SAFE OPERATION IN CASE OF UNFORESEEN CIRCUMSTANCES. FOREIGN AIR CARRIERS INBOUND EU ARE RECOMMENDED TO AVOID BELARUS MINSK FIR /UMMV/."

08 APR 26 09:14 UNTIL 01 JUL 26 23:59 ESTIMATED

LBSFA0350/26 (08 APR 26)

"UKRAINIAN CRISIS:

IT SHALL BE PROHIBITED FOR ANY ACFT OPERATED BY RUSSIAN AIR CARRIERS, OR FOR ANY RUSSIAN REGISTERED ACFT, OR FOR ANY NON-RUSSIAN-REGISTERED ACFT WHICH IS OWNED OR CHARTERED, OR OTHERWISE CONTROLLED BY ANY RUSSIAN NATURAL OR LEGAL PERSON, ENTITY OR BODY, TO LAND IN, TAKE-OFF FROM OR OVERFLY THE TERRITORY OF THE REPUBLIC OF BULGARIA.

THE PROHIBITION SHALL NOT APPLY IN THE CASE OF AN EMERGENCY LANDING OR AN EMERGENCY OVERFLIGHT AND TO ACFT THAT HAVE A MAXIMUM SEATING CAPACITY OF 4 PERSONS AND A MAXIMUM TAKE-OFF MASS OF NO MORE THAN 2000KG WHEN USED FOR PRIVATE, NON-CORPORATE, FLIGHTS FOR RECREATIONAL PURPOSES OR FOR THE PURPOSE OF TRAINING FOR PRIVATE PILOT LICENSES AND RELATED RATINGS WITH UNION TRAINING PROVIDERS."

08 APR 26 09:01 UNTIL 01 JUL 26 23:59 ESTIMATED

LBSFA0353/26 (08 APR 26)

"UKRAINE CRISIS:

ONGOING MILITARY ACTIVITY IN UKRAINE AND

ALONG BORDER UKRAINE/RUSSIA AND ALONG BORDER UKRAINE/BELARUS

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 43/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

AS WELL AS THE USE OF A WIDE RANGE OF GROUND AND AIRBORNE WARFARE SYSTEMS POSES A HIGH RISK FOR CIVIL FLIGHTS OPERATING AT ALL ALTITUDES AND FLIGHT LEVELS.
AIR CARRIERS AND CAPTAINS OF ACFT IN CHARGE OF AIR SERVICE MANAGED BY CARRIERS HOLDERS OF OPERATING LICENCE ISSUED BY REPUBLIC OF BULGARIA, WHETHER THEY ARE CONTRACTUAL CARRIERS AND/OR DE FACTO CARRIERS, OR PERFORMING AIR SERVICE WITH COMMERCIAL CHARTER AGREEMENT OR WITH CODE SHARING AND TO ALL FLIGHT PERFORMED WITH BULGARIAN ACFT REGISTRATION ARE REQUESTED TO:
- NOT ENTER FIR LVIV (UKLV), FIR KYIV (UKBV), UIR KYIV (UKBU), FIR DNIPROPETROVSK (UKDV), FIR SIMFEROPOL (UKFV) AND FIR ODESA (UKOV)."
08 APR 26 09:19 UNTIL 01 JUL 26 23:59 ESTIMATED

LBSFA0351/26 (08 APR 26)

"AIRCRAFT OPERATED BY BELARUSIAN AIR CARRIERS, INCLUDING AS A MARKETING CARRIER IN CODE-SHARING OR BLOCKED-SPACE ARRANGEMENTS, ARE PROHIBITED TO LAND IN, TAKE OFF FROM OR OVERFLY TERRITORY OF THE REPUBLIC OF BULGARIA, EXCEPT IN THE CASE OF AN EMERGENCY LANDING, AN EMERGENCY OVERFLIGHT OR HUMANITARIAN FLIGHTS.
NOTE:
HUMANITARIAN FLIGHTS ARE REQUIRED TO OBTAIN PRIOR PERMISSION BY THE BULGARIAN MINISTRY OF FOREIGN AFFAIRS - CONSULAR DEPARTMENT FOR OPERATIONS TO/FROM THE AIRPORTS OR OVERFLYING THE TERRITORY OF REPUBLIC OF BULGARIA."
08 APR 26 09:08 UNTIL 01 JUL 26 23:59 ESTIMATED

LBSFA0274/26 (23 MAR 26)

"DME VIT CH 81Y RANGE OF OPR:
SECTOR 029DEG - 090DEG 100NM,
SECTOR 091DEG - 028DEG 160NM."
15 APR 26 12:01 UNTIL 14 JUL 26 12:00 ESTIMATED

ROU / ROMANIA
N I L

LRBB / BUCHAREST FIR

LRBBA3459/26 (23 JUN 26)

"OPERATIONS IN FLIGHT INFORMATION REGIONS
ONGOING MILITARY ACTIVITY IN UKRAINE AND ALONG THE BORDER OF UKRAINE/RUSSIA AND USE OF A WIDE RANGE OF GROUND AND AIRBORNE WARFARE SYSTEMS POSES A HIGH RISK FOR CIVIL FLIGHTS OPERATING AT ALL ALTITUDES AND FLIGHT LEVELS.
ROMANIAN AIR OPERATORS AND OWNERS OF ACFT REGISTERED IN ROMANIA ARE ADVISED NOT TO ENTER FIR LVIV (UKLV), FIR KYIV (UKBV), FIR DNIPROPETROVSK (UKDV), FIR SIMFEROPOL (UKFV), FIR ODESA (UKOV), FIR ROSTOV (URRV) AND TO TAKE ALL POTENTIAL RISK INTO ACCOUNT IN RISK ASSESSMENT AND FLIGHT PLANNING DECISIONS WHEN OPERATING 200NM SURROUNDING THE BORDERS WITH UKRAINE IN THE FIR MOSCOW (UUWW) AND FIR ROSTOV (URRV)."
22 JUN 26 06:37 UNTIL 21 SEP 26 23:59 ESTIMATED

LRBBA3034/26 (06 JUN 26)

DAILY 0800-1810
ATS ROUTE T139 BETWEEN CRV AND PANZU CLSD FOR FLIGHT PLANNING
03 JUN 26 08:58 UNTIL 31 JUL 26 18:10 ESTIMATED

LRBBA3033/26 (06 JUN 26)

DAILY 0800-1810
ATS ROUTE T226 BETWEEN NAVOD AND ELDET CLSD FOR FLIGHT PLANNING
03 JUN 26 08:55 UNTIL 31 JUL 26 18:00 ESTIMATED

LRBBA2589/26 (16 MAY 26)

"ROMANIAN AIR OPERATORS INVOLVED IN AIR OPERATIONS IN ACCORDANCE WITH COMMISSION REGULATION (EU) 965/2012 SHALL NOT CONDUCT OPERATIONS IN FIR MINSK (UMMV), UNLESS THE USE OF THAT AIRSPACE IS DEEMED NECESSARY TO ENSURE SAFE OPERATION IN CASE OF UNFORESEEN CIRCUMSTANCES.
THE FLIGHT PLANS WILL BE FILLED ACCORDINGLY."
14 MAY 26 13:43 UNTIL 14 AUG 26 23:59 ESTIMATED

LRBBA2588/26 (16 MAY 26)

"ANY AIRCRAFT OPERATED BY AN AIR TRANSPORT UNDERTAKING HOLDING A VALID OPERATING LICENCE OR EQUIVALENT ISSUED BY THE COMPETENT AUTHORITIES OF BELARUS, INCLUDING AS A MARKETING CARRIER IN

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 44/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

CODE-SHARING OR BLOCKED-SPACE ARRANGEMENTS, ARE PROHIBITED TO
TAKE OFF FROM, LAND IN OR OVERFLY THE ROMANIAN TERRITORY EXCEPT
IN THE CASE OF AN EMERGENCY LANDING OR AN EMERGENCY OVERFLIGHT."
14 MAY 26 13:42 UNTIL 14 AUG 26 23:59 ESTIMATED

LRBBA2091/26 (24 APR 26)

"FLIGHT RESTRICTIONS

MILITARY INVASION OF UKRAINE BY RUSSIAN FEDERATION - ROMANIAN
AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN ROMANIA SHALL
NOT ENTER FIR KYIV (UKBU), FIR LVIV (UKLV), FIR KYIV (UKBV),
FIR DNIPROPETROVSK (UKDV), FIR SIMFEROPOL (UKFV), FIR ODESA
(UKOV), FIR ROSTOV-NA-DONU (URRV).
SAID OPERATORS AND AIRCRAFT OWNERS SHALL ALSO AVOID FLIGHT
OPERATIONS WITHIN THE BUFFER ZONE EXTENDING OUT TO 200NM ALONG
THE UKRAINE/RUSSIA BORDER.
OPERATIONS WITHIN THE FIR CHISINAU (LUUU) AIRSPACE SHALL ONLY
BE UNDERTAKEN IN COMPLIANCE WITH APPLICABLE AERONAUTICAL
PUBLICATIONS ISSUED BY REPUBLIC OF MOLDOVA.
OPERATORS ARE REMINDED THAT OPERATIONS WITHIN FIR MINSK (UMMV)
ARE PROHIBITED IN ACCORDANCE WITH EASA SAFETY DIRECTIVES
SD-2021-02 AND SD-2021-03.
ADDITIONAL RISK ASSESSMENT AND FLIGHT PLANNING DECISIONS SHALL
BE TAKEN BEFORE OPERATING IN THE FOLLOWING AIRSPACE:
MOSCOW (UUWV)"

23 APR 26 12:02 UNTIL 23 JUL 26 23:59 ESTIMATED

LRBBA2090/26 (24 APR 26)

"FLIGHT RESTRICTIONS.

UKRAINIAN CRISIS - ALL RUSSIAN REGISTERED AIRCRAFT AND AIRCRAFT
OWNED, CHARTERED OR OPERATED BY NATURAL OR LEGAL PERSONS FROM
THE RUSSIAN FEDERATION OR BY OPERATORS HOLDING AIR OPERATOR
CERTIFICATE (AOC) ISSUED BY THE RUSSIAN FEDERATION AUTHORITIES
ARE PROHIBITED TO ENTER, EXIT OR OVERFLY ROMANIAN AIRSPACE
EXCEPT HUMANITARIAN, SAR AND LEASED AIRCRAFT ONE-WAY RETURN
FLIGHTS WITH THE PERMISSION OF THE APPROPRIATE ROMANIAN
AUTHORITIES AND IN CASE OF EMERGENCY LANDING OR EMERGENCY
OVERFLIGHT."

23 APR 26 11:50 UNTIL 23 JUL 26 23:59 ESTIMATED

HUN / HUNGARY
N I L

LHCC / BUDAPEST FIR

LHBPA4073/26 (25 JUN 26)

"HUNGARIAN ATC SERVICE IS NOT ELIGIBLE TO GIVE ENTRY OR CROSSING
CLEARANCE INTO THE UKRAINE AIRSPACE IN ANY CIRCUMSTANCES (E.G.
DURING THUNDERSTORM AVOIDING ACTION) UNLESS AIRCRAFT IS EXEMPTED
ACCORDING TO NOTAM REF NUMBER A0050/26 ISSUED BY UKKR NOF.
HUNGARIAN ATS AND SEARCH AND RESCUE IS PROVIDED ONLY WITHIN BUDAPEST
FIR. ATS IS NOT PROVIDED IN THE AIRSPACE OF UKRAINE ACCORDING TO
NOTAM REF NUMBER A0050/26 ISSUED BY UKKR NOF. ENTERING INTO THE
AIRSPACE OF UKRAINE CAN BE EXECUTED SOLELY AT PILOT DISCRETION,
HUNGARIAN ATS CANNOT GUARANTEE THE CONTACT AND/OR THE APPROVAL OF
THE UKRAINIAN ARMED FORCES FOR ENTERING INTO THE AIRSPACE OF
UKRAINE, IRRESPECTIVE OF THE REASON."

23 JUN 26 11:20 UNTIL 22 SEP 26 23:59 ESTIMATED

LHBPA4009/26 (25 JUN 26)

NATIONAL AIR SEARCH AND RESCUE SYSTEM AVAILABLE FACILITIES
CHANGED FROM FROM MI-17/H-145M TO H-145M/H-225M.
18 JUN 26 09:30 UNTIL 17 SEP 26 16:00 ESTIMATED

LHBPA3984/26 (25 JUN 26)

"PILOTS OF UNMANNED AIRCRAFT ARE ADVISED THAT WITHIN 30 KM ZONE
ALONG THE UKRAINIAN STATE BORDER IN SZABOLCS-SZATMAR-BEREG COUNTY,
INTERFERENCE AFFECTING UAS COMMAND, CONTROL AND GNSS SIGNALS MAY
OCCUR.
THE INTERFERENCE MAY RESULT IN DEGRADED OR LOST COMMUNICATION,
NAVIGATION OR CONTROL CAPABILITIES OF UNMANNED AIRCRAFT, WHICH MAY
POSE A SAFETY RISK TO UAS OPERATIONS. UAS OPERATORS ARE STRONGLY
ADVISED TO AVOID OPERATIONS IN THE AFFECTED AREA DUE TO POSSIBLE
INTERFERENCE WITH COMMAND, CONTROL AND GNSS SIGNALS."

*LHBPA3967/26 (25 JUN 26)

MILITARY INVASION OF UKRAINE BY RUSSIAN FEDERATION
AIRSPACE RESERVATION ACTIVATED DUE TO MILITARY AND UNMANNED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 45/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

AIRCRAFT OPERATIONS WITHIN AREA BOUNDED BY THE FOLLOWING COORD
POINTS:
480305N0204807E
474559N0213335E
474730N0213710E
474137N0215008E
473104N0220055E
STATE BORDER
471828N0215336E
474133N0203516E
480305N0204807E (KP FIXW SOUTH).
THE AIRSPACE IS SEGREGATED AND SHALL BE AVOIDED ACCORDING TO AIP
HUNGARY ENR 5.3.
FURTHER INFO ABOUT THE ACTUAL OPR HR VIA TEL: +36 88 543 036.
F) 9500FT AMSL
G) FL315

*LHBPA3700/26 (25 JUN 26)

MILITARY INVASION OF UKRAINE BY RUSSIAN FEDERATION
AIRSPACE RESERVATION ACTIVATED DUE TO MILITARY AND UNMANNED AIRCRAFT
OPERATIONS WITHIN AREA BOUNDED BY THE FOLLOWING COORD POINTS:
481610N0213840E
482628N0213837E
STATE BORDER
482145N0215325E
475109N0224631E
474622N0223329E
481610N0213840E (WILEY CORRIDOR).
THE AIRSPACE IS SEGREGATED AND SHALL BE AVOIDED ACCORDING TO AIP
HUNGARY ENR 5.3.
FURTHER INFO ABOUT THE ACTUAL OPR HR VIA TEL: +36 88 543 036.
F) 9500FT AMSL
G) FL315

*LHBPA3698/26 (25 JUN 26)

MILITARY INVASION OF UKRAINE BY RUSSIAN FEDERATION
AIRSPACE RESERVATION ACTIVATED DUE TO MILITARY OPERATIONS
WITHIN AREA BOUNDED BY THE FOLLOWING COORD POINTS:
481635N0201511E
STATE BORDER
482803N0202838E
474133N0203516E
471828N0215336E
STATE BORDER
470908N0214816E
473429N0202124E
481635N0201511E (PITOK-MEGIK).
THE AIRSPACE IS SEGREGATED AND SHALL BE AVOIDED ACCORDING TO AIP
HUNGARY ENR 5.3.
FURTHER INFO ABOUT THE ACTUAL OPR HR VIA TEL: +36 88 543 036.
F) FL245
G) FL315

*LHBPA3659/26 (25 JUN 26)

MILITARY INVASION OF UKRAINE BY RUSSIAN FEDERATION
AIRSPACE RESERVATION ACTIVATED DUE TO MILITARY OPERATIONS AND
UNMANNED AIRCRAFT OPERATIONS WITHIN AREA BOUNDED BY THE FOLLOWING
COORD POINTS:
480305N0204807E
481105N0210601E
481610N0213840E
474622N0223329E
STATE BORDER
473104N0220055E
474137N0215008E
474730N0213710E
474559N0213335E
480305N0204807E (KP FIXW HIGH).
THE AIRSPACE IS SEGREGATED AND SHALL BE AVOIDED ACCORDING TO AIP
HUNGARY ENR 5.3.
FURTHER INFO ABOUT THE ACTUAL OPR HR VIA TEL: +36 88 543 036.
F) 9500FT AMSL
G) FL315

AUT / AUSTRIA
N I L

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 46/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

LOVV / VIENNA FIR

LOWWA1531/26 (25 JUN 26)

"REF AIP AUSTRIA, GEN 3.4 ITEM 3.4.
INCREASED CPDLC USAGE WILL BE ENDEAVOURED BY ATC IN THE AREA OF
RESPONSIBILITY OF ACC WIEN AND APP LOWW.
ALL DATA LINK EQUIPPED AIRCRAFT (CPDLC ATN VDL MODE 2) ARE REQUESTED
TO LOG ON TO ACC WIEN / APP WIEN. THE DATA LINK ADDRESS FOR ACC WIEN/
APP WIEN IS LOVV.
FLIGHT CREWS SHALL EXPECT TO RECEIVE UPLINK MESSAGES ESPECIALLY IN
SITUATIONS OF HIGH RTF FREQUENCY LOAD AND ARE REQUESTED TO REACT TO
THEM ASAP."

LOWWA1533/26 (25 JUN 26)

"FOR EN-ROUTE OPERATIONS THE RESPECTIVE VOR SHALL BE SELECTED FOR
NAVIGATION INSTEAD OF THE NDB IN CASE OF HOMONYMOUS IDENTIFIERS.
THIS APPLIES TO KFT.
FLIGHT CREWS ARE ADVISED TO MONITOR THE CORRECT SELECTION OF THE VOR
FOR EN-ROUTE OPERATIONS. IN CASE THE USAGE OF THE RESPECTIVE NDB IS
REQUIRED, ATC SHALL BE INFORMED UPON INITIAL CONTACT."

LOWWA1481/26 (23 JUN 26)

"SER HOURS OF MILITARY CONTROL CENTER MCC (WIEN) ARE:
JUN 22 0600-1430
JUN 23 0600-1430
JUN 24 0600-1800
JUN 25 0600-1800
JUN 26 0600-1800
JUN 27 0700-1800
JUN 28 0700-1900
REF AIP AUSTRIA, ENR 1.1, ITEM 2.8.2.4.2."

DEU / GERMANY

N I L

EDUU / RHEIN UIR

N I L

EDMM / MUNICH FIR

ETCZM2117/26 (26 JUN 26)

1600-0400
GERMAN MIL COM CENTER LIMITED DUE TO LACK OF PERSONNEL.
GERMAN MIL NOTAM OFFICE PROVIDES NORMAL SERVICE.

EDDZB0512/26 (25 JUN 26)

"CORRECTION OF AIP SUP IFR 15/26 AND AIP SUP VFR 08/26 (RESTRICTED
AREA EDR OTTOBEUREN) NEW TIMES OF ACTIVITY, PAGE 1 POINT 3 (TIMES OF
ACTIVITY) SHOULD READ: 01 APR 2026 - 31 JUL 2026 DAILY 1930-0200."
F) GND
G) FL500

ETCZM2103/26 (25 JUN 26)

TRIGGER NOTAM - MILAIP GERMANY AIRAC AMDT EFF 06 AUG 2026 NIL.

EDDZB0478/26 (23 JUN 26)

"PUBLICATION OF CTA/UTA IN DELEGATED AIRSPACE OVER AUSTRIAN
TERRITORY:
IN GERMAN AIP CTA/UTA DATA ARE PUBLISHED IN ENR 2.1. EVEN THOUGH
CTA/UTA ARE DESCRIBED CONSISTING OF THE FLW SECTORS, MUENCHEN CTA
AND KARLSRUHE UTA END AT THE GERMAN-AUSTRIAN BORDER AND ARE NOT
VALID OVERHEAD WIEN FIR (LOVV).
PUBLISHED BOUNDARIES OF ATC SECTORS EDUUALP 14-44, EDUAMM 14-44,
EDMMZUG, EDMMTEG, EDMMTRU AND EDMMSTA ARE NOT AFFECTED.
(AIP GERMANY PAGES ENR 2.1-89FF REFER)."
16 JUN 26 05:43 UNTIL 16 SEP 26 23:59 ESTIMATED

EDDZB0436/26 (23 JUN 26)

"SECURITY - HAZARDOUS SITUATION IN LEBANON
CIVIL GERMAN AIR OPERATORS ARE RECOMMENDED NOT TO ENTER FIR BEIRUT.
POTENTIAL RISK FROM ANTI-AVIATION WEAPONRY, MILITARY OPERATIONS AND
ARMED CONFLICTS."
03 JUN 26 08:42 UNTIL 03 SEP 26 23:59 ESTIMATED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 47/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

EDDZB0437/26 (23 JUN 26)

SECURITY - HAZARDOUS SITUATION IN IRAN
CIVIL GERMAN AIR OPERATORS ARE RECOMMENDED NOT TO ENTER
FIR TEHRAN (OIIX). POTENTIAL RISK TO AVIATION FROM ESCALATING
CONFLICT AND ANTI-AVIATION WEAPONRY.
THIS NOTAM OVERRULES THE RECOMMENDATION PROVIDED IN THE CURRENTLY
APPLICABLE AIC.
03 JUN 26 08:43 UNTIL 03 SEP 26 23:59 ESTIMATED

EDDZB0341/26 (25 MAY 26)

FOR FLIGHTS OVER OR NEAR CONFLICT ZONES OUTSIDE GERMANY REFER TO
THE GERMAN AERONAUTICAL INFORMATION CIRCULAR (AIC).
14 MAY 26 03:32 UNTIL 14 AUG 26 23:59 ESTIMATED

EDDZB0337/26 (25 MAY 26)

"MILITARY INVASION OF UKRAINE BY RUSSIAN FEDERATION.
REROUTINGS, EXTENDED ROUTE PORTIONS BELOW FL245 AND DELAY MAY BE
EXPECTED WITHIN LOWER AND UPPER GERMAN AIRSPACE DUE TO AIRSPACE
RESTRICTIONS FOR THE EXECUTION OF MILITARY MISSIONS.
IT IS RECOMMENDED TO CONSIDER THE USE OF EXTRA-FUEL."
12 MAY 26 08:51 UNTIL 11 AUG 26 23:59 ESTIMATED

EDGG / LANGEN FIR

ETCZM2117/26 (26 JUN 26)

1600-0400
GERMAN MIL COM CENTER LIMITED DUE TO LACK OF PERSONNEL.
GERMAN MIL NOTAM OFFICE PROVIDES NORMAL SERVICE.

ETCZM2103/26 (25 JUN 26)

TRIGGER NOTAM - MILAIP GERMANY AIRAC AMDT EFF 06 AUG 2026 NIL.

EDDZB0497/26 (23 JUN 26)

GEDERN TACAN GED 110.80MHZ/CH45X U/S.
25 JUN 26 06:00 UNTIL 25 SEP 26 06:00 ESTIMATED

EDDZB0483/26 (16 JUN 26)

MUENSTER/OSNABRUECK NDB MYN 371KHZ OUT OF SERVICE.

EDDZB0478/26 (23 JUN 26)

"PUBLICATION OF CTA/UTA IN DELEGATED AIRSPACE OVER AUSTRIAN
TERRITORY:
IN GERMAN AIP CTA/UTA DATA ARE PUBLISHED IN ENR 2.1. EVEN THOUGH
CTA/UTA ARE DESCRIBED CONSISTING OF THE FLW SECTORS, MUENCHEN CTA
AND KARLSRUHE UTA END AT THE GERMAN-AUSTRIAN BORDER AND ARE NOT
VALID OVERHEAD WIEN FIR (LOVV).
PUBLISHED BOUNDARIES OF ATC SECTORS EDUUALP 14-44, EDUUAAM 14-44,
EDMMZUG, EDMMTEG, EDMMTRU AND EDMMSTA ARE NOT AFFECTED.
(AIP GERMANY PAGES ENR 2.1-89FF REFER)."
16 JUN 26 05:43 UNTIL 16 SEP 26 23:59 ESTIMATED

EDDZB0436/26 (23 JUN 26)

"SECURITY - HAZARDOUS SITUATION IN LEBANON
CIVIL GERMAN AIR OPERATORS ARE RECOMMENDED NOT TO ENTER FIR BEIRUT.
POTENTIAL RISK FROM ANTI-AVIATION WEAPONRY, MILITARY OPERATIONS AND
ARMED CONFLICTS."
03 JUN 26 08:42 UNTIL 03 SEP 26 23:59 ESTIMATED

EDDZB0437/26 (23 JUN 26)

SECURITY - HAZARDOUS SITUATION IN IRAN
CIVIL GERMAN AIR OPERATORS ARE RECOMMENDED NOT TO ENTER
FIR TEHRAN (OIIX). POTENTIAL RISK TO AVIATION FROM ESCALATING
CONFLICT AND ANTI-AVIATION WEAPONRY.
THIS NOTAM OVERRULES THE RECOMMENDATION PROVIDED IN THE CURRENTLY
APPLICABLE AIC.
03 JUN 26 08:43 UNTIL 03 SEP 26 23:59 ESTIMATED

EDDZB0341/26 (25 MAY 26)

FOR FLIGHTS OVER OR NEAR CONFLICT ZONES OUTSIDE GERMANY REFER TO
THE GERMAN AERONAUTICAL INFORMATION CIRCULAR (AIC).
14 MAY 26 03:32 UNTIL 14 AUG 26 23:59 ESTIMATED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 48/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

EDDZB0337/26 (25 MAY 26)

"MILITARY INVASION OF UKRAINE BY RUSSIAN FEDERATION.
REROUTINGS, EXTENDED ROUTE PORTIONS BELOW FL245 AND DELAY MAY BE
EXPECTED WITHIN LOWER AND UPPER GERMAN AIRSPACE DUE TO AIRSPACE
RESTRICTIONS FOR THE EXECUTION OF MILITARY MISSIONS.
IT IS RECOMMENDED TO CONSIDER THE USE OF EXTRA-FUEL."
12 MAY 26 08:51 UNTIL 11 AUG 26 23:59 ESTIMATED

EDDZB0237/26 (16 APR 26)

WIPPER VOR WYP 109.6MHZ OUT OF SERVICE.

EDDZB0123/26 (04 MAR 26)

DAILY SS PLUS30 - 2200
LASER ACTIVITIES/SKYBEAMER RADIUS 0.5NM CENTERED ON 521511N
0075914E OSNABRUECK (8.9NM NE MUENSTER/OSNABRUECK NDB MYN)
F) GND
G) UNL

EDDZC1537/22 (12 JUN 22)

HAMM DVOR/DME HMM 115.65 / CH103Y RANGE OF DVOR R199 LIMITED TO
39NM.

EDVV / HANNOVER UIR
N I L

BEL / BELGIUM
N I L

EBUR / BRUSSELS UIR
N I L

EBBU / BRUSSELS FIR

EBBRD0374/26 (27 JUN 26)

27 JUN 2026 12:00-27 JUN 2026 19:00
BRUSSELS CTA EAST ONE AND TWO (IFR TRG/PJE/VFR FLT) PPR BLW FL075.

EBBRE0075/26 (23 JUN 26)

"BRUNO DME BUN CH43X U/S DUE TO MAINT. DO NOT USE, FALSE
INDICATIONS POSSIBLE"

NLD / NETHERLANDS
N I L

EHAA / AMSTERDAM FIR

EHMCM3176/26 (27 JUN 26)

DAILY 2200-0430
DUE TO LACK OF PERSONNEL NO FIS AND ALRS SERVICE WILL BE PROVIDED
BELOW FL095 FROM 2200 TO 0430 IN THE FOLLOWING AREAS:
ALL NIEUW MILLIGEN TMA AND BELOW, EELDE TMA AND BELOW OUTSIDE OPR HR
OF GRONINGEN AIRPORT EELDE, MAASTRICHT TMA1 AND BELOW OUTSIDE OPR HR
OF MAASTRICHT AACHEN AIRPORT, ALL EINDHOVEN TMA AND BELOW EINDHOVEN
TMA1 OUTSIDE OPR HR OF EINDHOVEN AIRPORT, ALL LELYSTAD TMA.
22 JUN 26 22:00 UNTIL 22 SEP 26 04:30 ESTIMATED

EHMCM3174/26 (27 JUN 26)

DAILY 2200-0430
DUE TO LACK OF PERSONNEL NO ATC WILL BE PROVIDED BY MILATCC
SCHIPHOL BELOW FL095 FROM 2200 TO 0430 UNLESS PPR OBTAINED BEFORE
1500 VIA DUTCH MIL SUPERVISOR PHONE +31(0)88 747 5700.
THE FOLLOWING AREAS ARE AFFECTED:
ALL NIEUW MILLIGEN TMA, CTA NORTH, EELDE TMA, MAASTRICHT TMA1
OUTSIDE OPR HR OF MAASTRICHT AACHEN AIRPORT, ALL EINDHOVEN TMA,
LELYSTAD TMA 1 AND 2.
22 JUN 26 22:00 UNTIL 22 SEP 26 04:30 ESTIMATED

EHMCM3172/26 (27 JUN 26)

DUE TO LACK OF PERSONNEL NO OAT ATS WILL BE PROVIDED IN EHAA FIR
BY DUTCHMIL BTN GND AND FL245 UNLESS PPR IS OBTAINED VIA DUTCHMIL
SUPERVISOR PHONE +31(0)88 747 5700. PPR CAN BE OBTAINED DAILY BTN
0700-1500.
22 JUN 26 07:35 UNTIL 21 SEP 26 23:59 ESTIMATED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 49/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

EHMCM2859/26 (07 JUN 26)

OUTSIDE OPERATING HRS OF EHBK AD, EXPECT LTD RADIO COVERAGE BELOW 4000FT AMSL ON DUTCH MIL INFO FREQ 132.350MHZ AND 341.600MHZ IN AND BELOW MAASTRICHT TMA 1. FIS AND ALERTING SERVICE LTD AVBL IN AND BELOW MAASTRICHT TMA 1 DURING THIS PERIOD OF TIME.

EHMCM2637/26 (28 MAY 26)

"MILITARY TRAFFIC WITH DEPARTURE OR DESTINATION ETNG OVERFLYING EHAA FIR SHALL FILE A GAT FLIGHT PLAN, FILED IN ACCORDANCE WITH AIP THE NETHERLANDS SECTION ENR 1.10 AND ACKNOWLEDGED BY IFPS."
23 MAY 26 06:58 UNTIL 22 AUG 26 23:59 ESTIMATED

EHAMB0581/26 (21 MAY 26)

LIMITED SURVEILLANCE COVERAGE OVER THE NORTH SEA BELOW FL055.
05 MAY 26 09:13 UNTIL 05 AUG 26 12:00 ESTIMATED

EHAMA0825/26 (23 APR 26)

"AMSTERDAM INFORMATION 124.300MHZ, EXPECT LIMITED RADIO COVERAGE BELOW 1500FT BETWEEN EHRD CTR AND EHSE."

EHAMB0494/26 (23 APR 26)

AMSTERDAM INFORMATION 119.175MHZ EXPECT LIMITED RADIO COVERAGE BELOW 1500FT AROUND 541257N 0044938E (OIL RIG F15-A) RADIUS 30NM.
08 APR 26 06:00 UNTIL 08 JUL 26 14:00 ESTIMATED

LUX

N I L

LUX / LUXEMBOURG

N I L

AEROPLANE INFORMATION

AIRCRAFT CATEGORY = D

N I L

AIRCRAFT TYPE = B787

// (COM-INFO) //

THA 00143/26 (04 JUN 26)

B787:+++ (NEW) --Single Engine Taxi-in (SETI) shall not be performed on B787-8 Registration HS-TQB* due to technical issue until further notice.
(ISSUED 04JUN06/PC/UFN)

AIRCRAFT SUBTYPE = B789

N I L

AIRCRAFT REGISTRATION = HSTWD

N I L

ADDITIONAL INFORMATION

LTFM / IST

LTAAB2614/26 (25 JUN 26)

TWY G1 BTN TWY H AND TWY G1D SHALL BE USED BY ACFT UP TO CATEGORY C (A B C). MAX WINGSPAN 36M

LTAAB2523/26 (18 JUN 26)

"PARKING POSITIONS 501, 502, 503, 504 AND 505 CLSD."

LTAAB2522/26 (18 JUN 26)

TWY T1 AND TWY T12 CLSD TO TFC

LTAAB2460/26 (16 JUN 26)

"ISTANBUL AD,

ALL PILOTS WHO OPERATES ON ISTANBUL AIRPORT (LTFM) MUST BE INFORMED ABOUT THE CONTENT OF THE 'TRO AWARENESS LEAFLET' ANNOUNCED ON THE DHMI GENERAL DIRECTORATE WEBSITE VIA THE

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 50/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

HTTPS://WWW.DHMI.GOV.TR/SAYFALAR/SSD/ANASAYFA.ASPX LINK BEFORE THE
FLIGHT AND MUST OPERATE ACCORDINGLY."
16 JUN 26 08:45 UNTIL 16 SEP 26 08:45 ESTIMATED

LTAAB2410/26 (12 JUN 26)

"TWY G7 AND TWY G7A SHALL BE USED BY ACFT UP TO CATEGORY C (A,B,C)
(MAX SPAN 36M).
SEE NOTAM: B2306/26"

LTAAB2306/26 (07 JUN 26)

TWY G CLSD TO TFC BTN TWY G3 AND TWY G7 DUE TO MAINT.

LTAAB2017/26 (07 JUN 26)

"BIRD CONCENTRATION INFORMATION FOR ALL RWYS AND APPROACH SURFACES
AS FOLLOWS:
AT THE BEGINNING OF RWYS: 0-200M THE MOST DENSE
AT APPROACH SURFACES : 0-200M THE MOST DENSE, 200-400M DENSE,
400-1000M LOW DENSE
DENSITY LEVEL: 5
LOW ALTITUDE : SFC
HIGH ALTITUDE: 3000FT

1. IT IS LIKELY TO ENCOUNTER WITH GROUPS OF SEAGULL(670-1150G)
AT BEGINNING OF RWYS AND APPROACH SURFACE, ESPECIALLY ON SUNRISE
SUNSET HOURS AND PARTIALLY DURING THE DAY.

2. IT IS LIKELY TO ENCOUNTER WITH BIG GROUPS OF
STORK(2275-4400G),FALCON(130-1600G), HAWK(420-1180GR) AND
EAGLE(1000-2200G) MOVING FROM EAST-SOUTHEAST TO WEST-NORTHWEST
DIRECTION.

3. IT IS LIKELY TO ENCOUNTER WITH SMALL GROUPS OF
PIGEON(240-380G),JACKDAW(220-270G), STARLING(55-100G), SWALLOW
BIRD(14-20G), SWIFT BIRD(38-100G) AND LITTLE SONG BIRD(15-30G)."

*LTAAB1707/26 (29 APR 26)

RWY 16L/34R CLSD TO LANDING TFC DUE TO CONST.

*LTAAB1708/26 (29 APR 26)

RWY 17R/35L CLSD TO LANDING TFC DUE TO CONST A-B HANGAR.

EGKK / LGW

EGGNA2413/26 (26 JUN 26)

28 JUN 2026 11:50-28 JUN 2026 12:20
BATTLE OF BRITAIN MEMORIAL FLIGHT FLYPAST WI 1NM RADIUS OF
510346N 0001939W (HORSHAM). FOR OPERATIONAL CALLS ONLY CTC 01526
347716. AR-2026-5490/01.
F) SFC
G) 2300FT AMSL

EGGNA1828/26 (14 MAY 26)

TWY ECHO AVBL FOR ACFT VACATING RWY 26L VIA ECHO ROMEO RAPID EXIT
TWY. TWY ECHO AVBL FOR NORTHBOUND ACFT ONLY.
UK AIP SUP 100/2025 REFERS.

EGLL / LHR

EGGNA2431/26 (27 JUN 26)

27 JUN 2026 05:15-27 JUN 2026 23:00
RWY 09R/27L ENTRY/EXIT POINT NB1/N1 AND LINK 41 CLOSED DUE WIP.
AIRCRAFT THAT REQUIRE FULL LENGTH DEPARTURE FROM 27L ARE TO ADVISE
DELIVERY WHEN REPORTING READY FOR PUSH.

EGGNA2304/26 (22 JUN 26)

RWY 09L/27R IS UNGROOVED AND MAY BE SLIPPERY WHEN WET BTN 2155M
AND 2465M FM RWY 09L THR AND BTN 1127M AND 1473M FM RWY 27R THR.

// (COM-INFO)//

THA 00128/12 (10 JUN 26)

COM INFO:-ALL FLIGHTS SHOULD BE ON BLOCK NOT EARLIER THAN 15 MINUTES BEFORE STA IN ORDER TO
AVOID THE EFFECT OF FUTURE SLOT.
(ISSUED 15SEP22/TN007/22/PA/UFN)

--FLT TO LHR , SHALL NOT ARRIVE BEFORE 0600LT DUE TO CURFEW TIME.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 51/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

(UPDATE 12DEC24/OP-INFO)

EGGNA2159/26 (09 JUN 26)

AIP SUPPLEMENT 047/2026 LONDON HEATHROW AIRPORT (EGLL) - NORTHERN
RUNWAY 09L/27R RESURFACING WORKS 2026 - PHASE 2 ACTIVE

EGGNA2122/26 (07 JUN 26)

RWY 27R MANDATORY INFO SIGN AT A1 ON EASTERN SIDE NOT AVBL DUE WIP

EGGNA2057/26 (06 JUN 26)

TWY B (SOUTH) CLSD BTN ITS JUNCTIONS WITH TWY E AND TWY F DUE WIP.

EGGNA2029/26 (06 JUN 26)

NDB BUR/BURNHAM 421KHZ U/S

EGGNA1918/26 (25 MAY 26)

RWY 09L/27R ENRTY/EXIT A10W CLSD.

EGGNA1912/26 (25 MAY 26)

RWY 27R MANDATORY INFO SIGN AT A2 ON EASTERN SIDE REMOVED DUE WIP.

EGGNA1484/26 (21 APR 26)

INSTRUMENT APPROACH CHART - RNP RWY 27R - MOCA BETWEEN IVLAR AND
L27RF TO INCREASE FROM 900 (822) TO 1100 (1022).
UK AIP AD 2.EGLL-8-12 REFERS.

EGGNA1483/26 (21 APR 26)

INSTRUMENT APPROACH CHART - RNP RWY 27L - MOCA BETWEEN NEKSA AND
L27LF TO INCREASE FROM 900 (823) TO 1100 (1023).
UK AIP AD 2.EGLL-8-9 REFERS.

EGGNA1482/26 (21 APR 26)

INSTRUMENT APPROACH CHART - ILS/DME I-RR RWY 27R - PROCEDURE
OCA(H)
FOR CAT I ILS TO INCREASE AS FOLLOWS:
CAT C INCREASE FROM 247 (169) TO 249 (171)
CAT D INCREASE FROM 263 (185) TO 268 (190)
UK AIP AD 2.EGLL-8-10 REFERS.

EGGNA1479/26 (21 APR 26)

INSTRUMENT APPROACH CHART - ILS/DME I-LL RWY 27L - PROCEDURE
OCA(H)
FOR CAT II ILS TO INCREASE AS FOLLOWS:
CAT D INCREASE FROM 174 (97) TO 177 (100)
UK AIP AD 2.EGLL-8-7 REFERS.

EGGNA1477/26 (21 APR 26)

INSTRUMENT APPROACH CHART - ILS/DME I-LL RWY 27L - PROCEDURE
OCA(H)
FOR CAT I ILS TO INCREASE AS FOLLOWS:
CAT B INCREASE FROM 238 (161) TO 241 (164)
CAT C INCREASE FROM 252 (175) TO 255 (178)
CAT D INCREASE FROM 270 (193) TO 273 (196)
UK AIP AD 2.EGLL-8-7 REFERS.

EGGNA1473/26 (21 APR 26)

INSTRUMENT APPROACH CHARTS - VM(C)OCA(OCH AAL) CAT B MINIMA TO BE
INCREASED FROM 770 (687) TO 800 (717).
UK AIP AD 2.EGLL-8-1 TO 8-12.

EGGNA1481/26 (21 APR 26)

INSTRUMENT APPROACH CHART - RNP RWY 09R - MOCA BETWEEN BENPA AND
L09RF TO INCREASE FROM 800 (725) TO 900 (825).
UK AIP AD 2.EGLL-8-6 REFERS.

EGGNA1480/26 (21 APR 26)

INSTRUMENT APPROACH CHART - ILS/DME I-RR RWY 27R - PROCEDURE
OCA(H)
FOR CAT II ILS TO INCREASE AS FOLLOWS:
CAT D INCREASE FROM 171 (93) TO 172 (94)
UK AIP AD 2.EGLL-8-10 REFERS.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 52/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

EGGNA1475/26 (21 APR 26)

INSTRUMENT APPROACH CHART - ILS/DME I-BB RWY 09R - PROCEDURE
OCA(H)
FOR CAT I ILS TO INCREASE AS FOLLOWS:
CAT A INCREASE FROM 215 (140) TO 221 (146)
CAT B INCREASE FROM 226 (151) TO 233 (158)
CAT C INCREASE FROM 240 (165) TO 248 (173)
CAT D INCREASE FROM 258 (183) TO 266 (191)
UK AIP AD 2.EGLL-8-4 REFERS.

EGGNA1478/26 (21 APR 26)

INSTRUMENT APPROACH CHART - RNP RWY 09L - PROCEDURE OCA(H) FOR
LNAV/VNAV TO INCREASE AS FOLLOWS:
CAT A INCREASE FROM 450 (371) TO 500 (421)
CAT B INCREASE FROM 460 (381) TO 510 (431)
CAT C INCREASE FROM 470 (391) TO 520 (441)
UK AIP AD 2.EGLL-8-3 REFERS.

EGGNA1476/26 (21 APR 26)

INSTRUMENT APPROACH CHART - ILS/DME I-BB RWY 09R - PROCEDURE
OCA(H)
FOR CAT II ILS TO INCREASE AS FOLLOWS:
CAT B INCREASE FROM 134 (59) TO 136 (61)
CAT C INCREASE FROM 148 (73) TO 151 (76)
CAT D INCREASE FROM 165 (90) TO 174 (99)
UK AIP AD 2.EGLL-8-4 REFERS.

EGGNA1474/26 (21 APR 26)

INSTRUMENT APPROACH CHART - ILS/DME I-AA RWY 09L - PROCEDURE
OCA(H)
FOR CAT I ILS TO INCREASE AS FOLLOWS:
CAT A INCREASE FROM 222 (143) TO 224 (145)
CAT B INCREASE FROM 234 (155) TO 236 (157)
CAT C INCREASE FROM 248 (169) TO 251 (172)
CAT D INCREASE FROM 267 (188) TO 271 (192)
UK AIP AD 2.EGLL-8-1 REFERS.

VTBD / DMK

VTBDH0766/26 (27 JUN 26)

27 JUN 2026 17:45-27 JUN 2026 18:15
AD DEP/ARR ACFT WILL BE DLA DUE TO VIP MOV

*VTBDC3446/26 (24 JUN 26)

24 JUN 2026 16:00-28 JUN 2026 22:00
"24 1600-2200, 26 1500-1600, 27 28 1600-2200"
RWY 03R/21L CLSD DUE TO WIP

*VTBDC3440/26 (24 JUN 26)

25 26 29 1600-2200
RWY 03L/21R CLSD DUE TO WIP

VTBDC1938/26 (19 APR 26)

RAPID EXIT TWY INDICATOR LGT RWY 21R TOWARD RAPID EXIT TWY O U/S

VTBDJ1987/26 (19 APR 26)

"TEMPO RESTRICTED AREA ACT WI 0.5NM CENTRE OF 135526.22N1003713.11E
APPROVAL SHALL BE MADE BEFORE ENTERING, EXCEPT DEP AND ARR ACFT AT
VTBD PILOT IN COMMAND SHALL STRICTLY COMPLY WITH ATC INSTRUCTION"
F) GND
G) 3000FT AGL

// (COM-INFO)//

THA 00435/14 (16 DEC 24)

COM INFO:-- DMK TG LINE MAINTENANCE WILL PROVIDE RAMP HANDLING SERVICE ON
TG FLIGHTS DIVERTED TO DMK, WHILE PIC MUST PERFORM REDUCE LINE CHECK
TO RELEASE AIRCRAFT. PRIOR TO FLIGHT DIVERSION TO DMK PLS INFORM
TOCC COMMAND CENTER (OC) VIA CUT FREQUENCY 129.325 MHZ
TO COORDINATE WITH DMK TG LINE MAINTENANCE IN ADVANCE FOR SMOOTH
HANDLING UPON ARRIVAL AT DMK
CONTACT POINTS FOR DMK LINE MAINTENANCE IN (24hrs)
AT DMK ARE AS FLW
1. TEL: 02-563-8178 (66-8178, 9999)
2. Email dmkjcb@thaairways.com
(ISSUED 12DEC24/OP/UFN)

VTBU / UTP

*VTBDC3302/26 (18 JUN 26)

PALS CAT 1 RWY 18 AND SALS RWY 36 U/S DUE TO MAINT

*c3100/26*VTBDC3100/26 (07 JUN 26)

ILS RWY 18 U/S DUE TO MAINT

*VTBDC2844/26 (07 JUN 26)

AD CATEGORY FOR FIRE FIGHTING AND RESCUE SERVICES
DOWNGRADED TO CAT 9.

VTBDC2193/26 (07 JUN 26)

TWY EDGE LGT U/S DUE TO MAINT DETAIL AS FLW:
-TWY B
-TWY E BTN TWY B AND TWY F

VTBDC0333/23 (06 APR 24)

"IAC-ICAO-NDB RWY 36 CHANGED AS FLW:
-OCA/H : STRAIGHT-IN APPROACH
: READ 790(766)FT INSTEAD OF 750(726)FT
-OCA/H : CIRCLING APPROACH CAT A, B
: READ 1200(1141)FT INSTEAD OF 750(726)FT, 1190(1166)FT
-OCA/H : CIRCLING APPROACH CAT C, D
: READ 1450(1391)FT INSTEAD OF 1290(1266)FT, 1445(1421)FT
REF AIP VTBU AD 2.24, AD 2-VTBU-8-1"

VTCC / CNX

VTBDC3516/26 (27 JUN 26)

27 JUN 2026 02:00-28 JUN 2026 16:59
TWY Q BTN TWY F AND ACFT STAND NR 20R CLSD
DUE TO TEMPO ACFT PRKG

VTBDC3490/26 (26 JUN 26)

RVR RWY 36 U/S

VTBDC3385/26 (22 JUN 26)

ACFT STAND NR 5 CLSD DUE TO WIP

VTBDC3386/26 (22 JUN 26)

ACFT STAND NR 6 CLSD DUE TO WIP

VTBDC3333/26 (19 JUN 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS) ACFT STAND NR 3 U/S

VTBDC3306/26 (18 JUN 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS)
ACFT STAND NR 7 AND NR 8 U/S

// (COM-INFO) //THA 00444/15 (17 JUN 26)

VTCC:--REF AIP SUP A19/25:
1 INTRODUCTION
With effect from 17 April 2025 at 1000 UTC,
the purpose of this AIP Supplement is to inform all concerned regarding the Aircraft stand
number 1 closed at Chiang Mai International Airport.
2 DETAILS
Aircraft stand number 1 closed for improvements to enhance aircraft parking compatibility.

VTBDJ4851/26 (07 JUN 26)

"05 0842-1000, 06-30 0130-1000"
UNMANNED AIRCRAFT WILL TAKE PLACE RADIUS 1NM CENTRE
184625.67N0990008.84E
F) GND
G) 300FT AGL

VTBDJ4315/26 (07 JUN 26)

TEMPO RESTRICTED AREA ACT RADIUS 0.5NM CENTRE 184626N0985806E
(EXCLUDING LDG AND TKOF RWY 18/36)
F) GND
G) 3000FT AGL

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 54/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

VTBDC2648/26 (17 JUN 26)

"MAY 15 0412-0800, MAY 16-JUN 30 0200-0800"
OBST MOBILE CRANE HGT 65FT AGL ERECTED AT 184623.96N0985757.21E
DIST 815M BEYOND THR RWY 18 AND 320M LEFT SIDE OF RCL

VTBDC2132/26 (17 JUN 26)

DAILY 0100-1100
OBST MOBILE CRANE HGT 82FT AGL ERECTED AT
184704.31N0985757.46E DIST 390M BFR THR
RWY 18 AND 328M LEFT SIDE OF EXTD RCL

VYYY / RGN

// (COM-INFO) //

THA 00157/26 (11 JUN 26)

VYYY:+++ (NEW) --There is no fuel available at RGN airport.
Tanker fuel planning for the round trip to RGN.
Disregard payload limitations. (ISSUED 11JUN26/DO/UFN)

VYYYA0104/26 (17 JUN 26)

NEW ATM CENTER GHOSTING OPERATION CONTINUES. NO IMPACT TO ATS.
24 MAY 26 23:59 UNTIL 24 JUL 26 23:59 ESTIMATED

LIMITATION FOR B787 OPR TO RGN

THA 00118/26 (11 MAY 26)

// (SEE ATTCH) //

VGHS / DAC

VGHSA0165/26 (06 JUN 26)

CONST WORK OF BOX CULVERT WHICH DIST IS 376FT WEST SIDE OF THE RWY
CENTRE LINE AND 3460FT FM THR RWY-14 (TOWARDS RWY-32) IS IN
PROGRESS. ALL PILOTS ARE ADZ TO EXER CTN WHILE TK-OF AND LDG.

VGHSA0149/26 (25 MAY 26)

"REF AIP BANGLADESH PAGE GEN 0.4-1, DATED 25
DEC 2025, PART 1 (GEN) PLEASE READ GEN 4.1-1, DATE 23 JUN
2016 INSTEAD OF GEN 4.1-1 DATE 25 DEC 2025 AND REF PAGE
0.4-2, DATE 25 DEC 2025 PART 2 (ENR) PLEASE READ ENR 4.1-1
DATE 25 DEC 2025 INSTEAD OF ENR 4.1-1 DATE 02 OCT 2025.
PLEASE MAKE HAND CORRECTION BY INSERTING THE EFFECTIVE INFORMATION
OF MENTIONED PAGES OF AIP BANGLADESH."

VGHSA0148/26 (25 MAY 26)

"REF AIP BANGLADESH CHART VGEG AD 2-31, DATED 10
JUL 2025, RNP RWY 05 (LNAV/VNAV ONLY) AT PROFILE VIEW PLEASE
READ INTERMEDIATE FIX AS ENLIX INSTEAD OF ELNIX.
PLEASE MAKE HAND CORRECTION BY INSERTING THE EFFECTIVE INFORMATION
OF MENTIONED PAGES OF AIP BANGLADESH."

VGHSA0124/26 (16 MAY 26)

SPORADIC LASER ILLUMINATION MAY TAKE PLACE FROM UNKNOWN SOURCES OF
NEARBY POPULATED AREA OF THE AIRFIELD. ALL PILOTS ARE REQUESTED TO
EXER CTN DRG THE DEFERENT APPROACH PHASES AND INITIAL CLIMBING
PHASE WITHIN 12NM DAC DVOR
04 MAY 26 09:30 UNTIL 04 AUG 26 23:59 ESTIMATED

VGHSA0123/26 (16 MAY 26)

DME FREQ 1161MHZ IDENT 'DAC' WILL REMAIN ON TEST OPERATION
DUE TO NEW DME INSTL
04 MAY 26 09:25 UNTIL 01 AUG 26 10:00 ESTIMATED

VGHSA0122/26 (16 MAY 26)

DVOR FREQ 112.7MHZ IDENT 'DAC' WILL REMAIN ON TEST OPERATION
DUE TO NEW DVOR INSTL
04 MAY 26 09:25 UNTIL 01 AUG 26 10:00 ESTIMATED

VGHSA0121/26 (16 MAY 26)

INSTRUMENT LANDING SYSTEM (ILS) FOR RWY-14 FREQ 109.5MHZ
IDENT 'IDA' IS NORMAL IN OPR FOR CAT-I ONLY WITH
MET MINIMA VIS 1000M OR RVR 700M
03 MAY 26 12:10 UNTIL 31 JUL 26 23:59 ESTIMATED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 55/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

VGHSA0118/26 (02 MAY 26)

"REF AIP BANGLADESH PAGE VGHS AD 2-8,DATED 16 APR 2026,PARA AD 2.18
(1) ROW 03,COLUMN 4,ACC HOURS OF OPERATION PLEASE READ AS, FM 1600 TO 0200 UTC (NEXT DAY) INSTEAD OF 1400 TO 0200 UTC (NEXT DAY) AND ROW 04,COLUMN 4,ACC(UPPER)HOURS OF OPERATION PLEASE READ AS, FM 0200 TO 1600 UTC INSTEAD OF H24.
(2) ROW 04,COLUMN 4,ACC(UPPER) FREQ PLEASE READ SRY 123.775MHZ INSTEAD OF SRY 129.700MHZ.
(3) ROW 05,COLUMN 4,ACC(LOWER) FREQ PLEASE READ SRY 120.750MHZ INSTEAD OF 130.700MHZ.
(4) ROW 06,COLUMN 4, DHAKA TWR AERODROME AND APPROACH CONTROL (NON-RADAR) FREQ PLEASE READ SRY 118.925MHZ INSTEAD OF SRY 119.300MHZ.
(5) ROW 08,COLUMN 4, SURFACE MOVEMENT CONTROL DHAKA GROUND FREQ PLEASE READ 121.675MHZ AS SRY 121.675MHZ FREQ.
PLEASE MAKE HAND CORRECTION BY INSERTING THE EFFECTIVE INFORMATION OF MENTIONED PAGES OF AIP BANGLADESH"

VGHSA0388/25 (05 APR 26)

"PORTION OF TWY 'C' FROM TWY 'N', AND TWY 'S' INTERSECTION TO APN, TWY 'F' AND TWY 'E' WILL BE RENAMED AS TWY 'T7', TWY 'T9' AND TWY 'T10' RESPECTIVELY"

VGHSA0299/25 (05 APR 26)

"REF AIP BANGLADESH PAGE VGHS AD 2-1 DATED 11 JULY 2024, PARA 2.2,SERIAL NO 3 AND AERODROME CHART-ICAO PAGE VGHS AD 2-15 DATED 11 JULY 2024.PLEASE READ AERODROME ELEV AS 26 FEET INSTEAD OF 27 FEET. PLEASE MAKE HAND CORRECTION BY INSERTING THE EFFECTIVE INFORMATION OF MENTIONED PAGES OF AIP BANGLADESH"

VGHSA0261/25 (05 APR 26)

"REF IS MADE TO THE AIP SUP 03/2025 DATED 10 JUL 2025,PAGE ATTACHMENT B5.2,TABLE RNAV IKUGO 1B AND RNAV IBANU 1B,SL NO 03,COLUMN NO 09 AND PAGE ATTACHMENT B6.2,TABLE RNAV BELKU 1E,SL NO 02,COLUMN NO 09.PLEASE INSERT SPEED LIMIT '-250'.PLEASE MAKEHAND CORRECTION BY INSERTING INFORMATION IN THE MENTIONED AIP SUPP PAGE"

VGHSA0231/25 (05 APR 26)

"REF IS MADE TO THE AIP SUP 03/2025 DATED 10 JUL 2025, REGARDING THE MSA DEPICTED IN PLAN VIEW FOR ALL RNAV SID AND STAR CHART RWY 14. PLEASE READ 'MSA 25NM ARP'INSTEAD OF 'MSA 25NM DAC ARP' AND 'MSA 25NM DAC'. PLEASE MAKE HAND CORRECTION BY INSERTING THE INFORMATION IN MENTIONED AIP SUPPLEMENT"

VGHSA0232/25 (05 APR 26)

"REF IS MADE TO THE AIP SUP 03/2025 DATED 10 JUL 2025, ATTACHMENT-A 4.2, CODING TABLE OF VGHS RNAV SID IBANU IC, SL NO 01 AND SL 02. PLEASE DELETE THE SPEED LIMIT ON THE CA LEG AND CF LEG AT HS001. THERE WILL BE NO SPEED RESTRICTION. PLEASE MAKE HAND CORRECTION BY INSERTING THE INFORMATION IN MENTIONED AIP SUPPLEMENT"

VGHSA0227/25 (05 APR 26)

"REF AIP SUP 04/25 DATED 10 JUL 2025, APPENDIX-A. PLEASE READ CHART NAMING AS 'ILS Z RWY 14' INSTEAD OF 'VOR-DME ILS (CAT-II) RWY 14'. THIS PROCEDURE IS A STANDALONE PROCEDURE. PLEASE MAKE HAND CORRECTION BY INSERTING THE INFORMATION IN MENTIONED AIP SUPPLEMENT"

VECC / CCU

VECCA1323/26 (26 JUN 26)

AWOS TRANSMISSOMETER RWY 19L TDZ U/S DUE INSTR FAULT. ALT FSM AND VAISALA MITRAS RVR SYSTEM FOR SAME MET SITE ARE AVBL FOR OPS. 25 JUN 26 15:55 UNTIL 30 JUN 26 11:00 ESTIMATED

VECCA1317/26 (26 JUN 26)

AWOS TRANSMISSOMETER RWY 01R END U/S DUE INSTR FAULT. ALT FSM AND DRISHTI RVR SYSTEM FOR SAME MET SITE ARE AVBL FOR OPS. 25 JUN 26 15:44 UNTIL 30 JUN 26 11:00 ESTIMATED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 56/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

VECCA1313/26 (26 JUN 26)

AWOS TRANSMISSOMETER RWY 01R TDZ U/S DUE INSTR FAULT. ALT VAISALA
FSM AND MITRAS RVR SYSTEM FOR SAME MET SITE ARE AVBL FOR OPS.
25 JUN 26 15:35 UNTIL 30 JUN 26 11:00 ESTIMATED

VECCA1307/26 (26 JUN 26)

AWOS TRANSMISSOMETER RWY 19R TDZ U/S DUE INSTR FAULT. ALT FSM
AND DRISHTI RVR SYSTEM FOR SAME MET SITE ARE AVBL FOR OPS.
25 JUN 26 14:49 UNTIL 30 JUN 26 11:00 ESTIMATED

**** A1051/26 ****

***VECCA1051/26 (23 JUN 26)**

MON WED FRI SUN 0530-1030
RWY 19L/01R NOT AVBL FOR OPS DUE MAINT WIP WHEN VIS 1200M AND
ABV.
RMK:
1. TWY L AND JUNCTION OF RWY 01R WITH TWY C AVBL FOR OPS.
IN CASE OF URGENT RQMNTS 30 MIN PN FOR AVBL OF RWY 19L/01R. PILOTS
TO EXER CTN DUE MEN AND MATERIAL CONFINED TO WORKSITE.

VIDPG0734/26 (23 JUN 26)

REFER AIP SUP 27/2026 DATED 05 FEB 2026 REGARDING PROC ILS OR LOC
RWY 19L-KOLKATA AIRPORT. IN FINAL APP SEGMENT OF LOC ONLY PROC SDF
AND OCA(H) WITH SDF WITHDRAWN TEMPO.
17 JUN 26 06:57 UNTIL 16 SEP 26 23:59 ESTIMATED

VIDPG0732/26 (23 JUN 26)

REF AIP SUP 28/2026 REGARDING VOR RWY 01L. THE OCA(H) WITH SDF
AMENDED AS 450(430)FT IN PLACE OF 440(420)FT.
AMEND ACCORDINGLY.
17 JUN 26 06:51 UNTIL 16 SEP 26 23:59 ESTIMATED

VIDPG0733/26 (23 JUN 26)

REFER AIP SUP 196/2025 REGARDING ILS OR LOC RWY 01R PROC OF
KOLKATA.
WITH SDF OCA(H) IS AMENDED AS 480 (460)FT TEMPORARILY.
17 JUN 26 06:54 UNTIL 16 SEP 26 23:59 ESTIMATED

VIDPG0674/26 (23 JUN 26)

"ILS RWY 19R IDENT IOKL (LOC 111.300MHZ, GP 332.300MHZ, DME IOKL
CH50X) NOT AVBL DUE DISPLACEMENT OF THRESHOLD."
02 JUN 26 10:22 UNTIL 29 AUG 26 23:59 ESTIMATED

VECCA1064/26 (23 JUN 26)

"ACFT STAND IDENTIFICATION SIGN BOARD NOT AVBL FOR STAND 110,111,112.
RMK : ACFT STAND 110,111,112 AVBL FOR OPS."

VIDPG0634/26 (23 JUN 26)

REFER AIP SUP 201/2025 DATED 16 OCT 2025 REGARDING PROC VOR RWY
01R-KOLKATA AIRPORT. IN FINAL APP SEGMENT SDF AND OCA(H) WITH SDF
WITHDRAWN TEMPO.
27 MAY 26 13:06 UNTIL 28 AUG 26 23:59 ESTIMATED

VIDPG0631/26 (23 JUN 26)

REF AIP SUP 198/2025 REGARDING INSTRUMENT APPROACH CHART - ILS OR
LOC RWY 19R NETAJI SUBHASH CHANDRA BOSE INTERNATIONAL AIRPORT
KOLKATA (VECC). PROC ILS OR LOC RWY 19R TEMPO WITHDRAWN DUE TEMPO
DISPLACEMENT OF RWY 19R THR.
27 MAY 26 12:05 UNTIL 04 SEP 26 23:59 ESTIMATED

VECCA0888/26 (23 JUN 26)

RWY 19R AVBL FOR OPS WITH VOR Y APCH PROC ONLY.RMK:ALS OF RWY 19R
NOT AVBL.

***VECCA0877/26 (17 MAY 26)**

"PORTION OF RWY 19R/01L FM BEGINNING OF RWY 19R TO 130M SOUTH OF IT
S
INT WITH TWY A NOT AVBL FOR OPS.
RMK :TWY Q1,TWY Q2,TWY K,RWY 19R-N HOLDING POINT AND PORTION OF TWY
A BTN RWY 19R/01L AND 19L/01R NOT AVBL FOR OPS.
ACFT LDG RWY 01R VACATE ONLY VIA TWY B OR TWY P."

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 57/90

Trans ID: 5040609

Creation Time: 27.06.2026 12:51UTC

VECCA0852/26 (05 MAY 26)

"TORA,TODA FOR RWY 01L REDUCED TO 2404M AND LDA FOR RWY 01L REDUCED TO 1966M.RWY 19R THR DISPLACED 867M.RWY 19R THR LAT 223928.48426N, LONG 0882645.86415E, TOP ELEV:19.08872FT, ELLIPSOID HT(MS)167.155517FT,
TORA,TODA AND LDA FOR RWY 19R REDUCED TO 2404M.
RMK:1.GRADED RESA DIMENSION OF RWY 01L IS 90M*90M
2.RWY 19R/01L AVBL FOR OPS UPTO CODE C ACFT ONLY"

VIDPG0536/26 (05 MAY 26)

REF AIP SUP 203/2025 REGARDING VOR RWY 19R (CAT A/B/C) PROC.
CIRCLING PROC AND CIRCLING MINIMA WITHDRAWN. EAIP INDIA AMENDED ACCORDINGLY.

VIDPG0534/26 (05 MAY 26)

REF AIP SUP 201/2025 REGARDING VOR RWY 01R (CAT A/B/C) PROC.
CIRCLING PROC AND CIRCLING MINIMA WITHDRAWN. EAIP INDIA AMENDED ACCORDINGLY.

VIDPG0535/26 (05 MAY 26)

REF AIP SUP 202/2025 REGARDING VOR RWY 19L (CAT A/B/C) PROC.
CIRCLING PROC AND CIRCLING MINIMA WITHDRAWN. EAIP INDIA AMENDED ACCORDINGLY.

VIDPG0532/26 (05 MAY 26)

REF AIP SUP 196/2025 REGARDING ILS OR LOC RWY 01R PROC. CIRCLING PROC AND CIRCLING MINIMA WITHDRAWN. EAIP INDIA AMENDED ACCORDINGLY.

VIDPG0533/26 (05 MAY 26)

REF AIP SUP 198/2025 REGARDING ILS OR LOC RWY 19R PROC. CIRCLING PROC AND CIRCLING MINIMA WITHDRAWN. EAIP INDIA AMENDED ACCORDINGLY.

VECCA0695/26 (18 APR 26)

"OPPORTUNITY BASIS TRIAL OPS OF SMC(S) AND SMC(N) INPR:
UNIT PROVIDING SER: KOLKATA GND
FREQ OF SMC(S): 121.900 MHZ AND SMC(N): 121.725MHZ
UNLESS OTHERWISE SPECIFIED BY TWR, AFTER VACATING RWY, ARR ACFT LDG ON RWY 19L/19R SHALL CTC GND ON FREQ 121.900 MHZ AND ARR ACFT LDG ON RWY 01R/01L SHALL CTC GND ON FREQ 121.725 MHZ.
WHEN RELEASED BY CLR DELIVERY, DEP ACFT FM APN 2 AND 3 SHALL CTC GND ON FREQ 121.900 MHZ AND DEP ACFT FM APN 1 AND 4 SHALL CTC GND ON FREQ 121.725 MHZ."

VIDPG0171/26 (21 FEB 26)

REF VECC AD 2.25. THE VISUAL SEGMENT SURFACE (VSS) PENETRATION INFO REGARDING VOR RWY 01L IS DELETED.

VIDPG0168/26 (21 FEB 26)

"REF EAIP INDIA PAGE AD 2 VECC 3-903 DATED 16 MAY 2024 REGARDING RNP Y RWY 01R PROC. FLW AMENDMENTS ARE MADE:
1. IN PROFILE VIEW, MOCA OF THE SEGMENT FAF-SDF IS 670FT
2. IN PROFILE VIEW, OCA(H) - 470(450) FT IS APPLICABLE ONLY FOR SEGMENT SDF-MAPT. AMEND AIP ACCORDINGLY."

VIDPG0167/26 (21 FEB 26)

"REF EAIP INDIA PAGE AD 2 VECC 3-901 DATED 16 MAY 2024 REGARDING RNP Y RWY 01L PROC-KOLKATA AIRPORT. FLW AMENDMENTS ARE MADE:
1. IN PROFILE VIEW, MOCA OF THE SEGMENT FAF-SDF IS 670FT
2. IN PROFILE VIEW, OCA(H) - 440(420) FT IS APPLICABLE ONLY FOR SEGMENT SDF-MAPT. AMEND AIP ACCORDINGLY."

VIDPG1421/25 (21 FEB 26)

"REF AIP SUP 197/2025 REGARDING ILS RWY 01R CAT II AND III PROC OF NSCBI AP KOLKATA. FLW AMEND ARE MADE:
I) ON R-198(CEA), TEXT IAF IS INSERTED AT 16D(CEA).
II) ON R-198(CEA), IAF AT 20D(CEA) IS DELETED."

VIDPG1422/25 (21 FEB 26)

REF AIP SUP 198/2025 REGARDING ILS OR LOC RWY 19R PROC OF NSCBI AP KOLKATA. ON R-345 (CEA) TEXT 18D IS REPLACE BY 15D.

VIDPG1420/25 (21 FEB 26)

REF AIP SUP 196/2025 REGARDING ILS OR LOC RWY 01R PROC OF NSCBI AP
KOLKATA. FLW AMD ARE MADE:
I) RDH IS AMENDED AS 53FT
II) IN PROFILE VIEW AND IN DISTANCE-ALTITUDE TABLE THE ALTITUDE AT 4D IS AMENDED AS 1290FT.
III) TEXT 332DEG ON INBOUND LEG OF PROC TURN IS AMENDED AS 322DEG.

VOHS / HYD

VOMMA2014/26 (24 JUN 26)

REF E-AIP INDIA VOHS AD 2.20 LOCAL AD REGULATIONS PARA 4
SUB PARA 4.2. TWY B1 NOT AVBL AS AN ALTN ISOLATION PRKG
PSN DUE WIP

VOMMA2013/26 (24 JUN 26)

TWY B1 AVBL UPTO CODE C OPS UNDER TOWING AND
FLW ME GUIDANCE WITH ONE HOUR MNM PRIOR NOTICE

VOMMA2012/26 (24 JUN 26)

WIP AT DIST OF 110M NORTH OF RWY 09L/27R CL BTN TWY B1
AND TWY B2. MAX EQPT HGT WILL BE 2.5M. PILOTS TO EXER CTN

VOMMA1936/26 (15 JUN 26)

0000-1730 2330-2359
REF E-AIP INDIA VOHS AD 2.20 LOCAL AD REGULATIONS
PARA 5. AP COLLABORATIVE DECISION MAKING (ACDM) WILL
BE IN PLACE. ACFT OPR TO UPDATE TARGET OFF BLOCK TIME (TOBT)
AND ADHERE TO TARGET START UP APPROVAL TIME (TSAT)

VOMMA1830/26 (05 JUN 26)

0300-0500 0730-0830 1030-1230 1330-1830
BIFURCATION OF APP INTO APP DEP APP ARR SECT.
RTF CS FREQ HYDERABAD ARR 125.550MHZ
HYDERABAD DEP 120.250MHZ

VOMMA1829/26 (05 JUN 26)

0000-1830
CLR DELIVERY WITH CS SHAMSHABAD AVBL ON FREQ 121.625MHZ.
REMAINING TIME CTC SMC ON 121.850MHZ FOR CLR DELIVERY.

VOMMA1821/26 (05 JUN 26)

0200-0530 0730-0830 1230-1530 1630-1830
ARR ACFT TO EXP HLDG OR DLA DUE CONGESTION

VOMMA1770/26 (29 MAY 26)

"VISUAL DCKG GUIDANCE SYSTEM FOR STANDS 44,45,46,47,48
NOT AVBL FOR OPS.PILOTS TO FLW MARSHALLER FOR PRKG GUIDANCE"

VOMMA1674/26 (19 MAY 26)

GRASS CUTTING AND PESTICIDE SPRAYING WIP ON BOTH SIDES
OF RWY 09R/27L SHOULDERS AT A DIST OF 107M FM RWY CL.
PILOTS TO EXER CTN

VIDPG0467/26 (07 APR 26)

REF EAIP INDIA PAGE AD VOHS 2-109 DATED 17 APR 2025 REGARDING ILS
OR
LOC RWY 27L PROC OF SHAMSHABAD (VOHS) AP. ILS OR LOC RWY 27L PROC
TEMPO WITHDRAWN DUE EQPT REPLACEMENT.
07 APR 26 09:52 UNTIL 05 JUL 26 23:59 ESTIMATED

VIDPG0461/26 (07 APR 26)

"ILS RWY 27L IDENT ISAM (LOC 110.900MHZ, GP 330.800MHZ, DME ISAM
CH46X) NOT AVBL DUE EQPT REPLACEMENT."
07 APR 26 04:48 UNTIL 04 JUL 26 23:59 ESTIMATED

VOMMA1122/26 (30 MAR 26)

RWY09L IS NON PRECISION DUE WIP
ALONG THE DRAIN IN BASIC STRIP.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 59/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

VOMMA0935/26 (16 MAR 26)

REF EAIP INDIA VOHS AD 2.1 SUB PARA 2.24 CHARTS RELATED TO AN
AERODROME SNO.23 FOR RWY 27R READ TORA FOR TWY B2 INTERSECTION AS
3030M

VIDPG0075/26 (21 JAN 26)

REF EAIP INDIA PAGE AD 2 VOHS 2-205 DATED 17 APR 2025 REGARDING
VOR RWY 27L OF SHAMSHABAD AIRPORT:
THE CIRCLING OCA(H) IS DELETED FROM IAP CHART.
AMEND EAIP ACCORDINGLY.

VIDPG0074/26 (21 JAN 26)

REF EAIP INDIA PAGE AD 2 VOHS 2-203 DATED 17 APR 2025 REGARDING
VOR RWY 09R OF SHAMSHABAD AIRPORT:
THE CIRCLING OCA(H) IS DELETED FROM IAP CHART.
AMEND EAIP ACCORDINGLY.

VIDPG0076/26 (21 JAN 26)

REF EAIP INDIA PAGE AD 2 VOHS 2-207 DATED 17 APR 2025 REGARDING
VOR RWY 27R OF SHAMSHABAD AIRPORT:
THE CIRCLING OCA(H) IS DELETED FROM IAP CHART.
AMEND EAIP ACCORDINGLY.

VIDPG0073/26 (21 JAN 26)

REF EAIP INDIA PAGE AD 2 VOHS 2-201 DATED 17 APR 2025 REGARDING
VOR RWY 09L OF SHAMSHABAD AIRPORT:
THE CIRCLING OCA(H) IS DELETED FROM IAP CHART.
AMEND EAIP ACCORDINGLY.

VIDPG0072/26 (21 JAN 26)

REF EAIP INDIA PAGE AD 2 VOHS 2-109 DATED 17 APR 2025 REGARDING
ILS OR LOC RWY 27L OF SHAMSHABAD AIRPORT:
THE CIRCLING OCA(H) IS DELETED FROM IAP CHART.
AMEND EAIP ACCORDINGLY.

VIDPG0071/26 (21 JAN 26)

REF EAIP INDIA PAGE AD 2 VOHS 2-107 DATED 17 APR 2025
REGARDING ILS OR LOC RWY 09R CAT II OF SHAMSHABAD AIRPORT :
THE CIRCLING OCA(H) IS DELETED FROM IAP CHART.
AMEND EAIP ACCORDINGLY.

VAAH / AMD

VIDPG0563/26 (12 MAY 26)

CNL AIP SUP 85/2026.

VABBA0686/26 (02 MAY 26)

"ADVANCE VISUAL DOCKING GUIDANCE SYSTEM (AVDGS) NOT AVBL FOR STAND
36L, 36 AND 36R. PILOT TO EXER CTN FLW MARSHALLER GUIDANCE"

VABBA0681/26 (30 APR 26)

ARRIVALS AFTER VACATING THE RWY.CTC AHMEDABAD GND
121.675MHZ IF UNA CTC 118.100MHZ.
AMEND EAIP INDIA VAAH AD 2.22 (FLT PROCEDURES) ACCORDINGLY

VABBA0675/26 (30 APR 26)

REF EAIP INDIA AD 2 VAAH 2.14.4 APCH AND RWY LGT. AMEND
MEHT VALUE OF RWY 05 AND 23 AS FLW:
RWY 05 - 66.58FT
RWY 23 - 68.20FT

VABBA0646/26 (22 APR 26)

"WIP IN FLW AREAS:

- 1)NORTHERN SIDE OF RWY 05/23 BTN BEGINNING OF TWY G TO TWY
R4 AT A DIST OF 105M FM RCL.MAX HGT FOR MOVABLE MACHINERY
IS 3M.
- 2)TWY M AND PORTION OF TWY K FROM RUNWAY EDGE TO TWY M
CLSD DUE WIP.
- 3)AN ALTN ISOL ACFT PRKG PSN IS PROVIDED ON TWY P BTN TWY D
AND TWY R4. REFER EAIP INDIA VAAH AD 2.8.6.5.
- 4)DRAIN WIP NORTH OF TWY P, BEYOND 35M FM TWY P CL,BTN TWY
B AND TWY R4.PERSONNEL AND MOVABLE MACHINERY UP TO 3M HGT
WILL BE SHIFTED BEYOND 43.5M DRG CODE E OPS.

5)WIP AT 15M FM TWY L5. PILOTS TO EXER CTN"

VIDPG0422/26 (25 MAR 26)

REF EAIP INDIA PAGE AD 2 VAAH 2-201 DATED 27 NOV 2025 REGARDING
VOR RWY 05 PROC. CIRCLING OCA(H) WITHDRAWN.AMEND ACCORDINGLY.

VIDPG0423/26 (25 MAR 26)

REF EAIP INDIA PAGE AD 2 VAAH 2-203 DATED 27 NOV 2025 REGARDING
VOR RWY 23 PROC. CIRCLING OCA(H) WITHDRAWN. AMEND ACCORDINGLY.

VIDPG0358/26 (18 MAR 26)

REF EAIP INDIA PAGE AD 2 VAAH 3-905 16 MAY 2024 REGARDING RNP RWY
05. THE FLW AMENDMENTS ARE MADE IN OCA(H) FOR LNAV:
1. OCA(H) FOR LNAV (CAT A/B) : 660(480) FT.
2. OCA(H) FOR LNAV (CAT C) : 680(500) FT.
3. OCA(H) FOR LNAV (CAT D) : 700(520) FT.
AMEND AIP INDIA ACCORDINGLY.

// (COM-INFO) //

*THA 00320/17 (14 FEB 25)

COM INFO:--RWY MAINT: every WED 0530-0930. (REF AOI VAAH 1-10)

VABB / BOM

VABBA0891/26 (22 JUN 26)

AUTOMATED WX OBSERVING SYSTEM (AWOS) RWY-27 TDZ
TRANSMMISSOMETER RVR U/S.

VABBA0886/26 (19 JUN 26)

DRISHTI SYSTEM RVR AT METPARK-09 TDZ U/S.

VABBA0883/26 (18 JUN 26)

REFER EAIP INDIA VABB AD 2.23 ADDN INFO.I.
ACFT PRKG STAND DETAILS PCR FOR STAND G5R IS 1696/R/D/W/T.
AMEND EAIP ACCORDINGLY

VABBA0874/26 (15 JUN 26)

REFER EAIP INDIA VABB AD 2.23 ADDN INFO.II. TAXIWAYS
PCR FOR TXL L IS 1765/R/C/W/T.
AMEND EAIP ACCORDINGLY

VABBA0872/26 (15 JUN 26)

REFER EAIP INDIA VABB AD 2.23 ADDN INFO.I. ACFT PRKG
STAND DETAILS PCR FOR STAND A11 IS 1765/R/C/W/T.
AMEND EAIP ACCORDINGLY

VABBA0867/26 (12 JUN 26)

0501-0759 1430-2100
CONCENTRATION OF BIRDS IN AND AROUND VCY OF AD.
BIRDS WITH WT BTN 500 GRAMS TO 1.25KG AND
1KG TO 2KG. MAX SIZE OF FLOCK OF BIRDS UPTO
50 BIRDS.PILOTS TO EXER CTN DRG LDG/TKOF AND TAX

VIDPG0624/26 (25 MAY 26)

REF AIP SUP 180/2025 REGARDING RNP Y RWY 32.
1. IN FINAL APPROACH SEGMENT SDF (2.5 NM) AND SDF (3.6 NM) ARE
WITHDRAWN TEMPO.
2. LNAV OCA(H) AMENDED AS 1270(1245) TEMPO.
25 MAY 26 05:00 UNTIL 24 AUG 26 23:59 ESTIMATED

VABBA0714/26 (08 MAY 26)

TWY M STOP BAR LGT FOR RWY 14/32 U/S.
PILOTS TO EXER CTN

VABBA0623/26 (17 APR 26)

ACFT SHALL NOT HOLD ON ANY TWY LINKS DRG TAX.
IN CASE UNABLE DUE EXIGENCY ACFT SHALL INFORM CONTROLER
IMMEDIATELY
PILOTS TO EXER CTN WHILE TAX ON TWY LINKS C1 AND C4
TO XNG ON TWY Y1 AND TWY B1 AND VICE VERSA.

VIDPG0466/26 (07 APR 26)

REF AIP INDIA PAGE AD 2 VABB 3-905 (31 DEC 2020) REGARDING RNP Y
RWY

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 61/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

14 PROC OF MUMBAI AIRPORT. THE PROC IS TEMPO WITHDRAWN DUE VISUAL
SEGMENT SURFACE (VSS) INFRINGEMENT.
07 APR 26 09:41 UNTIL 06 JUL 26 23:59 ESTIMATED

VIDPG0354/26 (16 MAR 26)

"REF AIP SUPPLEMENT 38/2026 REGARDING INSTRUMENT APPROACH CHART -
ILS OR LOC Z RWY 27 OF VABB. IN PLAN VIEW THE BELOW TEXT IS
INSERTED?
RADAR VECTORED AIRCRAFT ESTABLISHED ON LLZ RWY 27, WHEN CLEARED FOR
APPROACH, TO DESCENT BELOW 3800FT ONLY WITHIN 13.8D (ISCZ)
AMEND ACCORDINGLY."

// (COM-INFO)//

THA 00260/12 (22 FEB 26)

COM INFO:--RWY Restriction:
1) RWY 09/27 CLSD for MAINT: MON 0830-1015, THU 0815-1015
RWY 14/32 CLSD for MAINT: WED 0545-0745.
RWY restored within 30min PN.
2) RWYs 09/27 and 14/32 CLSD daily 2150-2230, EXC FRI, due to periodic MAINT. In case of
emergency RWY restored within 10min.
(REF AOI VABB 1-10)

VIDPG0181/25 (22 FEB 26)

REF EAIP AD 2 VABB 3-905 31 DEC 2020 REGARDING RNP Y RWY 14
PROC -MUMBAI:
IN PROFILE VIEW TRANSITION ALT IS AMENDED AS 6000FT.
AMEND ACCORDINGLY.

VIDPG0183/25 (22 FEB 26)

"REF AIP SUP 84/2020 REGARDING SID AND STAR OF MUMBAI AP, MSA IS
AMENDED ON CHARTS ON PAGE 5, PAGE 6, PAGE 7, PAGE 8, PAGE 9, PAGE
10, PAGE 11, PAGE 12, PAGE 13, PAGE 30, PAGE 31, PAGE 32, PAGE 33,
PAGE 34, PAGE 35, PAGE 36, PAGE 37 AND PAGE 38 AS BELOW:IN PROFILE VIEW TRANSITION ALT IS
AMENDED AS 6000FT.
AMEND ACCORDINGLY."

VIDPG0171/25 (22 FEB 26)

REFER EAIP AD 2 VABB 3-905 31 DEC 2020
REGARDING RNP Y RWY 14 PROCEDURE -MUMBAI :
1. MSA IS AMENDED AS FLW:
A. 200 DEG (M)-330 DEG (M) CLOCKWISE - 0NM TO 25NM FM MUMBAI ARP -
MSA 2600FT.
B. 330 DEG (M)-200 DEG (M) CLOCKWISE - 0NM TO 12NM FM MUMBAI ARP -
MSA 2800FT.
C. 330 DEG (M)-200 DEG (M) CLOCKWISE - 12NM TO 25NM FM MUMBAI ARP
- MSA 3800FT.
AMEND ACCORDINGLY.

VIDPG0172/25 (22 FEB 26)

"REFER AIP SUP 84/2020 REGARDING SID AND STAR OF MUMBAI
AIRPORT, MSA IS AMENDED ON CHARTS ON PAGE 5, PAGE 6, PAGE 7, PAGE 8,
PAGE 9, PAGE 10, PAGE 11, PAGE 12, PAGE 13, PAGE 30, PAGE 31, PAGE
32, PAGE 33, PAGE 34, PAGE 35, PAGE 36, PAGE 37 AND PAGE 38 ASBELOW:
1. MSA IS AMENDED AS FLW:
A. 200 DEG (M)-330 DEG (M) CLOCKWISE - 0NM TO 25NM FM MUMBAI ARP -
MSA 2600FT.
B. 330 DEG (M)-200 DEG (M) CLOCKWISE - 0NM TO 12NM FM MUMBAI ARP -
MSA 2800FT.
C. 330 DEG (M)-200 DEG (M) CLOCKWISE - 12NM TO 25NM FM MUMBAI ARP
- MSA 3800FT.
AMEND ACCORDINGLY."

VIDP / DEL

*VIDPA1366/26 (23 JUN 26)

24 26 29 1830-2330
RWY 11L/29R NOT AVBL FOR OPS DUE MAINT.

*VIDPA1368/26 (23 JUN 26)

25 JUN 2026 18:30-28 JUN 2026 23:30
25 28 1830-2330
RWY 09/27 NOT AVBL FOR OPS DUE MAINT.

VIDPA1364/26 (23 JUN 26)

PORTION OF TWY C BTN TWY LINK 2 AND TWY LINK 3 NOT AVBL FOR OPS.
JUNCTION OF TWY LINK 2 AND TWY LINK 3 WITH TWY A AND TWY C AVBL

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 62/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

FOR OPS.

LEFT TURN VIA LINK 2 ON TWY C FROM APRON 32 NOT AVBL FOR OPS.

RIGHT TURN ON TWY C VIA LINK 3 FROM APRON 33A NOT AVBL FOR OPS.

*VIDPA1352/26 (22 JUN 26)

23 27 30 1830-2330

RWY 10/28 NOT AVBL FOR OPS DUE MAINT.

VIDPA1277/26 (12 JUN 26)

"REFER E-AIP INDIA VIDP AD 2.22 FLIGHT PROCEDURES PARA 'I' RADIO COMMUNICATION FAILURE PROCEDURE, AMEND THE FOLLOWING SUB-PARAS AS BELOW:

SUBPARA 3.1: IN CASE OF ARRIVING ACFT, WHEN RWY FOR LANDING HAS ALREADY BEEN ADVISED TO THE ACFT BY ATC, SUCH RWY SHALL BE CONSIDERED AS ASSIGNED RWY, EXCEPT AS GIVEN IN PARA 3.3 BELOW. IN CASE ARRIVING ACFT HAS NOT BEEN ADVISED ANY RWY, RWY 28 SHALL BE CONSIDERED AS ASSIGNED RWY FOR SUCH ARRIVAL. DURING THE NOTIFIED PERIODS OF MAINTENANCE/CLOSURE OF RWY 28, RWY 29L SHALL BE CONSIDERED THE PRIMARY ASSIGNED RWY, AND RWY 29R SHALL BE CONSIDERED THE SECONDARY ASSIGNED RWY.

SUBPARA 3.7: IRRESPECTIVE OF VISIBILITY/WEATHER CONDITIONS, RWY AND APPROACH LIGHTS IN 'SWITCHED OFF' POSITION SHALL INDICATE NON-AVAILABILITY OF SUCH RWY FOR ACFT EXPERIENCING RCF. IN SUCH CASES, PRIMARY ALTERNATE RWY, AND IF PRIMARY ALTERNATE RWY IS NOT AVAILABLE, THE SECONDARY ALTERNATE RWY, AS INDICATED BELOW, SHALL BE MADE AVAILABLE FOR SUCH ACFT:

FOR RWY 28, THE PRIMARY ALTERNATE RWY SHALL BE RWY 29L AND THE SECONDARY ALTERNATE RWY SHALL BE RWY 29R.

FOR RWY 29L, THE PRIMARY ALTERNATE RWY SHALL BE RWY 28 AND THE SECONDARY ALTERNATE RWY SHALL BE RWY 29R.

FOR RWY 29R, THE PRIMARY ALTERNATE RWY SHALL BE RWY 28 AND THE SECONDARY ALTERNATE RWY SHALL BE RWY 29L.

FOR RWY 10, THE PRIMARY ALTERNATE RWY SHALL BE RWY 11R AND THE SECONDARY ALTERNATE RWY SHALL BE RWY 11L.

FOR RWY 11R, THE PRIMARY ALTERNATE RWY SHALL BE RWY 10 AND THE SECONDARY ALTERNATE RWY SHALL BE RWY 11L.

FOR RWY 11L, THE PRIMARY ALTERNATE RWY SHALL BE RWY 10 AND THE SECONDARY

ALTERNATE RWY SHALL BE RWY 11R.

SUBPARA 4.2.1. CONTINUE ON ATS RTE, (RE-JOIN ATS RTE IF GIVEN HEADING OR FLYING OFFSET), MAINTAINING/DESCENDING TO CLEARED FLIGHT LEVEL OR FL 80 WHICHEVER IS HIGHER. AT 40 MILES TO 'DPN VOR' TAKE A TURN (AVOIDING VIP 89) TO PROCEED DIRECT TO 'SKA' VOR. IF HIGHER, DESCEND TO FL 80 IN 'SKA' HOLD.

SUBPARA 4.2.2. IF RCF TAKES PLACE WITHIN 40 NM OF 'DPN VOR', CONTINUE TO 'DPN VOR' AND AT 10 MILES TO 'DPN VOR' TAKE A TURN (AVOIDING VIP 89) TO PROCEED DIRECT TO 'SKA' VOR MAINTAINING LAST ASSIGNED LEVEL OR FL 80 WHICHEVER IS HIGHER. IF BELOW FL 80, CLIMB AND REACH FL 80 BEFORE CROSSING 25 NM OUTBOUND FROM 'DPN VOR'. IF HIGHER, DESCEND TO FL 80 IN 'SKA' HOLD.

SUBPARA 4.2.3. LEAVE 'SKA' AT FL 80 TO CARRY OUT PUBLISHED ILS/VOR DME ARC APPROACH PROCEDURE FOR ASSIGNED RWY. MAINTAIN FL080 UNTIL 20 DME DPN VOR.

SUBPARA 4.3. ARRIVING ACFT BEING RADAR VECTORED

ACFT BEING RADAR VECTORED FOR APPROACH, ON EXPERIENCING RCF, SHALL MAINTAIN LAST ASSIGNED LEVEL AND HEADING FOR 3 MINUTES AFTER DETECTING RCF OR SELECTING MODE A/C 7600, WHICHEVER IS LATER, AND THEN TAKE A CONVENIENT TURN (AVOIDING VIP 89) TO PROCEED DIRECT TO 'SKA' CLIMBING / MAINTAINING LAST ASSIGNED LEVEL, OR FL 80 WHICHEVER IS HIGHER. IF BELOW FL 80, CLIMB AND REACH FL 80 BEFORE CROSSING 25NM OUTBOUND FROM 'DPN VOR'. IF HIGHER, DESCEND TO FL 80 IN 'SKA' HOLD

4.3.1. LEAVE 'SKA' VOR AT FL80 TO CARRY OUT PUBLISHED ILS/VOR DME ARC APPROACH PROCEDURE FOR ASSIGNED RWY. MAINTAIN FL080 UNTIL 20 DME DPN VOR.

SUBPARA 5.1. DEPARTURE INTENDING TO CONTINUE TO DESTINATION

ANY DEPARTING ACFT EXPERIENCING RCF AND INTENDING TO CONTINUE TO ITS FILED PLAN DESTINATION SHALL:

5.1.1. CONTINUE ON ASSIGNED SID OR HEADING CLIMBING TO OR MAINTAINING CLEARED LEVEL OR FL80, WHICHEVER IS HIGHER.

5.1.2. THREE MINUTES AFTER SETTING MODE A/C CODE 7600 OR REACHING FL80 OR CLEARED FLIGHT LEVEL (IF HIGHER THAN FL80) WHICHEVER IS LATER:

I. IF FOLLOWING 'SID', CONTINUE ON SID TO JOIN ATS RTE AND CLIMB TO FILED FLIGHT LEVEL AND CONTINUE AS PER THE FILED FLIGHT PLAN.

II. IF FOLLOWING RADAR HEADING, TURN (AVOIDING VIP 89) TO JOIN ATS RTE BY SHORTEST RTE MAINTAINING CLEARED FLIGHT LEVEL / FL80 AS PER PARA 5.1.1. AFTER JOINING ATS RTE, CLIMB TO FILED FLIGHT LEVEL

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 63/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

AND CONTINUE AS PER THE FILED FLIGHT PLAN. DEPARTURE FOLLOWING ATS RTE V18 AND G452/L760 SHALL PASS FL160 OR ABOVE BY 50 NM DPN AND ACFT FILED FLIGHT LEVEL BELOW FL150 SHALL CONTACT JEWAR APPROACH ON FREQ 120.825 MHZ, 122.175 MHZ AND JEWAR TWR ON FREQ 118.675 MHZ, 119.125 MHZ AFTER ASCERTAING THAT ACFT IS RCF WITH DELHI ATC.
SUBPARA 5.2 DEPARTURE INTENDING TO LAND BACK AT DELHI:
ANY DEPARTING ACFT EXPERIENCING RCF AFTER DEPARTURE AND INTENDING TO LAND BACK AT IGI AIRPORT SHALL
5.2.1 CONTINUE ON ASSIGNED SID OR HEADING CLIMBING TO OR MAINTAINING CLEARED LEVEL OR FL80, WHICHEVER IS HIGHER.
5.2.2 THREE MINUTES AFTER SETTING MODE A/C CODE 7600 OR REACHING FL80 OR CLEARED FLIGHT LEVEL (IF HIGHER THAN FL80) WHICHEVER IS LATER, TAKE A TURN (AVOIDING VIP 89) TO PROCEED DIRECT TO 'SKA' VOR.
5.2.3 IF HIGHER, DESCEND TO FL80 IN 'SKA' HOLD.
5.2.4 IF REQUIRED, JETTISON FUEL WHILE IN 'SKA' HOLD, TAKING ALL NECESSARY PRECAUTIONS.
5.2.5 LEAVE 'SKA' VOR AT FL80 TO CARRY OUT PUBLISHED ILS/VOR DME ARC
APPROACH PROCEDURE FOR ASSIGNED RWY. MAINTAIN FL080 UNTIL 20 DME DPN VOR.
NOTE :-
1. IN CASE OF NON-AVAILABILITY OF SKA VOR ACFT REQUIRED TO HOLD AT SKA VOR MAY HOLD AT FOLLOWING FIX/WAY POINT:
A. R186/43 D (116.1 DPN)
B. 275054N0770030E
AMEND E-AIP ACCORDINGLY."

VIDPA1235/26 (09 JUN 26)

"LINK A3 AVBL FOR SFC MOV BY DAY ONLY. LINK FIT FOR ACFT WITH MAX WING SPAN 35M. ACFT TO CTC SMC, AIRFORCE GND ON 121.200MHZ BEFORE LANDING, TO COOR VACATION ON A3."
09 JUN 26 06:24 UNTIL 08 SEP 26 23:59 ESTIMATED

VIDPA1233/26 (08 JUN 26)

TXL F6 NOT AVBL FOR OPS. DRG THIS PERIOD ACFT OPS FM STAND 170 TO 178 SHALL BE WITH ASSISTANCE OF FLW ME ONLY.

VIDPA1122/26 (22 MAY 26)

NOISE ABATEMENT PROCEDURES NOT ADHERED DUE TO REHABILITATION AND ILS REPLACEMENT WORK AT RWY 11R/29L.

VIDPA1121/26 (22 MAY 26)

TWY T4 AND TWY S2 NOT AVBL FOR OPS.

*VIDPA1120/26 (22 MAY 26)

"RWY 11R/29L NOT AVBL FOR OPS.
DURING THIS PERIOD FLW RESTRICTIONS SHALL APPLY:
1. PORTION OF TWY Z WEST OF TWY S6 NOT AVBL FOR OPS.
2. TWY S1, S2, S5, T4, T5, T6, T7, Y1, Y2, Y4, Y5, Y6, Y7, Y8, Z2, Z3, Z4, Z5, Z6 AND Z7 NOT AVBL FOR OPS.
3. TWY S6, S7 AND S8 AVBL FOR OPS.
4. TWY CROSSINGS P6-S6, P7-S7 AND P8-S8 AVBL FOR OPS."

VIDPA1015/26 (08 MAY 26)

PORTION OF TWY M BTN TWY A AND TWY LINK 30 DOWNGRADED FOR ACFT UPTO CODE LETTER C. PORTION OF TWY LINK 30 BTN TWY K AND TWY M DOWNGRADED FOR ACFT UPTO CODE LETTER D.

VIDPA0958/26 (01 MAY 26)

HIGH POWER ENGINE RUN-UP BAY 800 NOT AVBL FOR OPS.

VIDPA0846/26 (17 APR 26)

REF EAIP INDIA VIDP AD 2.20 LOCAL AERODROME REGULATIONS.
INSERT BLW TEXT IN NOTE OF PARA 5 DETAILS OF ENGINE RUN UP AT HIGH POWER.
TWY R7 NOT AVBL FOR OPS WHILE ACFT IS BEING REPOSITIONED AT STAND 803 FOR HIGH POWER RUN-UP.
AMEND EAIP ACCORDINGLY.

VIDPG0458/26 (02 APR 26)

REF EAIP PAGE AD 2 VIDP 2-117 DATED 27 NOV 2025 REGARDING ILS OR LOC RWY 29L OF DELHI (VIDP) AIRPORT. ILS OR LOC RWY 29L PROCEDURE WITHDRAWN TEMPO DUE EQPT REPLACEMENT.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 64/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

14 MAY 26 00:00 UNTIL 12 AUG 26 23:59 ESTIMATED

VIDPG0459/26 (02 APR 26)

REF EAIP PAGE AD 2 VIDP 2-115 DATED 27 NOV 2025 REGARDING ILS RWY
29L CAT (ROMAN) II AND (ROMAN) III OF DELHI (VIDP) AIRPORT. ILS RWY
29L CAT II AND III PROCEDURE WITHDRAWN TEMPO DUE EQPT REPLACEMENT.
14 MAY 26 00:00 UNTIL 12 AUG 26 23:59 ESTIMATED

VIDPG0457/26 (02 APR 26)

"CAT (ROMAN) III ILS RWY 29L IDENT IDGM (LOC 110.900MHZ, GP
330.800MHZ,DME IDGM CH46X) NOT AVBL DUE EQUIPMENT REPLACEMENT."
14 MAY 26 00:00 UNTIL 11 AUG 26 23:59 ESTIMATED

VIDPG0456/26 (02 APR 26)

"CAT (ROMAN) III ILS RWY 11R IDENT IDMR (LOC 111.300MHZ, GP
332.300MHZ,DME IDMR CH50X) NOT AVBL DUE EQUIPMENT REPLACEMENT."
14 MAY 26 00:00 UNTIL 11 AUG 26 23:59 ESTIMATED

VIDPG0450/26 (02 APR 26)

REF EAIP PAGE AD 2 VIDP 2-131 DATED 27 NOV 2025 REGARDING ILS RWY
11R CAT (ROMAN) II AND (ROMAN) III OF DELHI (VIDP) AIRPORT. ILS RWY
11R CAT II AND III PROCEDURE WITHDRAWN TEMPO DUE EQPT REPLACEMENT.
14 MAY 26 00:00 UNTIL 12 AUG 26 23:59 ESTIMATED

VIDPG0449/26 (02 APR 26)

REF EAIP PAGE AD 2 VIDP 2-129 DATED 27 NOV 2025 REGARDING ILS OR
LOC RWY 11R OF DELHI (VIDP) AIRPORT. ILS OR LOC RWY 11R PROCEDURE
WITHDRAWN TEMPO DUE EQPT REPLACEMENT.
14 MAY 26 00:00 UNTIL 12 AUG 26 23:59 ESTIMATED

VIDPA0525/26 (05 MAR 26)

REFER PARA VIDP AD 2.20 LOCAL AD REGULATIONS IN E-AIP INDIA.
INSERT THE FOLLOWING TEXT IN SUBPARA 1. AP REGULATIONS :
ENGINE POWER MORE THAN IDLE THRUST IS NOT PERMITTED DURING
PUSHBACK AND TAXIING IN THE APRON.

VIDPG0298/26 (05 MAR 26)

REFER EAIP INDIA AD 2.24 OF VIDP THE FLW AMENDMENTS ARE
MADE IN IAP CHART OF VOR RWY 28- PAGE AD 2 VIDP 2-209 DATED 27 NOV
2025.
1) VISUAL CIRCLING MINIMA DELETED FROM AOM BOX.
2) VISUAL CIRCLING DEPICTION DELETED FROM PLAN VIEW.
AMEND ACCORDINGLY.

VIDPG0299/26 (05 MAR 26)

REFER EAIP INDIA AD 2.24 OF VIDP THE FLW AMENDMENT IS
MADE IN IAP CHART OF VOR RWY 11R- PAGE AD 2 VIDP 2-211 DATED 08 AUG
2024.
VISUAL CIRCLING MINIMA DELETED FROM AOM BOX. AMEND ACCORDINGLY.

VIDPG0300/26 (05 MAR 26)

REFER EAIP INDIA AD 2.24 OF VIDP THE FLW AMENDMENT IS
MADE IN IAP CHART OF VOR RWY 29L- PAGE AD 2 VIDP 2-213 DATED 02 NOV
2023.
VISUAL CIRCLING MINIMA DELETED FROM AOM BOX.AMEND ACCORDINGLY.

VIDPG0292/26 (05 MAR 26)

REFER EAIP INDIA AD 2.24 OF VIDP THE FOLLOWING AMDT ARE MADE IN
IAP CHART OF ILS OR LOC RWY 29R- PAGE AD 2 VIDP 2-127 DATED 16 MAY
2024.
1) VISUAL CIRCLING MINIMA DELETED FROM AOM BOX.
2) VISUAL CIRCLING DEPICTION DELETED FROM PLAN VIEW.
AMEND ACCORDINGLY.

VIDPG0297/26 (05 MAR 26)

REFER EAIP INDIA AD 2.24 OF VIDP? THE FOLLOWING AMDT ARE MADE IN
IAP CHART OF VOR RWY 10- PAGE AD 2 VIDP 2-207 DATED 27 NOV 2025.
1) VISUAL CIRCLING MINIMA DELETED FROM AOM BOX.
2) VISUAL CIRCLING DEPICTION DELETED FROM PLAN VIEW.
AMEND ACCORDINGLY.

VIDPG0296/26 (05 MAR 26)

REFER EAIP INDIA AD 2.24 OF VIDP? THE FOLLOWING AMDT ARE MADE IN
IAP CHART OF ILS OR LOC RWY 09- PAGE AD 2 VIDP 2-141 DATED 17 APR

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 65/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

2025.

- 1) VISUAL CIRCLING MINIMA DELETED FROM AOM BOX.
 - 2) VISUAL CIRCLING DEPICTION DELETED FROM PLAN VIEW.
- AMEND ACCORDINGLY.

VIDPG0294/26 (05 MAR 26)

REFER EAIP INDIA AD 2.24 OF VIDP? THE FOLLOWING AMDT ARE MADE IN IAP CHART OF ILS OR LOC RWY 27- PAGE AD 2 VIDP 2-133 DATED 08 AUG 2024.

- 1) VISUAL CIRCLING MINIMA DELETED FROM AOM BOX.
 - 2) VISUAL CIRCLING DEPICTION DELETED FROM PLAN VIEW.
- AMEND ACCORDINGLY.

VIDPG0291/26 (05 MAR 26)

REFER EAIP INDIA AD 2.24 OF VIDP THE FOLLOWING AMDT ARE MADE IN IAP CHART OF ILS OR LOC RWY 29L- PAGE AD 2 VIDP 2-117 DATED 27 NOV 2025.

- 1) VISUAL CIRCLING MINIMA DELETED FROM AOM BOX.
 - 2) VISUAL CIRCLING DEPICTION DELETED FROM PLAN VIEW.
- AMEND ACCORDINGLY.

VIDPG0295/26 (05 MAR 26)

REFER EAIP INDIA AD 2.24 OF VIDP THE FOLLOWING AMDT ARE MADE IN IAP CHART OF ILS OR LOC RWY 11L- PAGE AD 2 VIDP 2-135 DATED 17 APR 2025.

- 1) VISUAL CIRCLING MINIMA DELETED FROM AOM BOX.
 - 2) VISUAL CIRCLING DEPICTION DELETED FROM PLAN VIEW.
- AMEND ACCORDINGLY.

VIDPG0293/26 (05 MAR 26)

REFER EAIP INDIA AD 2.24 OF VIDP THE FOLLOWING AMDT ARE MADE IN IAP CHART OF ILS OR LOC RWY 11R- PAGE AD 2 VIDP 2-129 DATED 27 NOV 2025.

- 1) VISUAL CIRCLING MINIMA DELETED FROM AOM BOX.
 - 2) VISUAL CIRCLING DEPICTION DELETED FROM PLAN VIEW.
- AMEND ACCORDINGLY.

VIDPG0112/26 (21 FEB 26)

REFER AIP SUPPLEMENT 192/2025 DATED 18 SEP 2025 REGARDING RNAV1(GNSS) SIDS AND STARS INDIRA GANDHI INTERNATIONAL AIRPORT DELHI- VIDP. THE FOLLOWING AMENDEMENTS ARE MADE

1. ON THE STAR CHART AT PAGE NR 35 AT WAYPOINT DP507 AMEND ALTITUDE RESTRICTION FL140 OR ABOVE IN PLACE OF FL140 OR BELOW.
2. ON PAGE NR 36 IN TABULAR DESCRIPTION OF STAR BAVOX - 7E/7F/7G/7H ALTITUDE RESTRICTION AT SERIAL NO 40 IS AMENDED AS FL140 OR ABOVE IN PLACE OF FL140 OR BELOW.
3. ON PAGE NR 36 IN TABULAR DESCRIPTION OF STAR POSIG - 7E/7F/7G/7H ALTITUDE RESTRICTION AT SERIAL NO 30 IS AMENDED AS FL140 OR ABOVE IN PLACE OF FL140 OR BELOW.

AMEND AIP SUPPLEMENT ACCORDINGLY.

VIDPG1135/25 (18 JAN 26)

"REF AIP SUP 194/2025 REGARDING IAP CHART - ILS OR LOC RWY 10, CAT (ROMAN) II AND III. PROC AVBL FOR CAT I APCH WIE."

VIDPG1136/25 (18 JAN 26)

"REF AIP SUP 195/2025 REGARDING IAP CHART - ILS OR LOC RWY 28, CAT (ROMAN) II AND III. PROC AVBL FOR CAT I APCH WIE."

VIDPG1116/25 (18 JAN 26)

REFER AIP SUPPLEMENT 192/2025 DATED 18 SEP 2025 REGARDING RNAV1(GNSS) SIDS AND STARS INDIRA GANDHI INTERNATIONAL AIRPORT DELHI-VIDP. THE FOLLOWING AMENDEMENTS ARE MADE:

1. ON THE STAR CHART AT PAGE NR 32 AT WAYPOINT DP941 AMEND ALTITUDE RESTRICTION FL100 OR BELOW IN PLACE OF FL120 OR ABOVE.
2. ON PAGE NR 33 IN TABULAR DESCRIPTION OF STAR ATRIN-7E/7F/7G/7H ALTITUDE RESTRICTION AT SERIAL NR 30 IS AMENDED AS FL100 OR BELOW IN PLACE OF FL120 OR ABOVE.
3. ON PAGE NR 33 IN TABULAR DESCRIPTION OF STAR BUBNU-7E/7F/7G/7H ALTITUDE RESTRICTION AT SERIAL NR 50 IS AMENDED AS FL100 OR BELOW IN PLACE OF FL120 OR ABOVE.
4. ON PAGE NR 33 IN TABULAR DESCRIPTION OF STAR LKA-7E/7F/7G/7H ALTITUDE RESTRICTION AT SERIAL NR 30 IS AMENDED AS FL100 OR BELOW IN PLACE OF FL120 OR ABOVE.
5. ON PAGE NR 34 IN TABULAR DESCRIPTION OF STAR UKASO-7E/7F/7G/7H ALTITUDE RESTRICTION AT SERIAL NR 30 IS

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

AMENDED AS FL100 OR BELOW IN PLACE OF FL120 OR ABOVE.
AMEND AIP SUPPLEMENT ACCORDINGLY.

VIDPG1058/24 (05 NOV 24)

"REFER E-AIP INDIA PAGE NR AD2 VIDP3-139 DT 13 JUNE 2024.
FOLLOWING AMENDMENT IS MADE
1. IN CHART OF SID OROTI6C AND SURAM 6C RWY 29R,
DEPICTION OF TRACK TO MUNUV AS 246DEG IS DELETED.
AMEND THE E-AIP ACCORDINGLY."

VIDPA1036/22 (06 NOV 23)

PORTION OF TWY N BTN TWY CW1 AND TWY LINK 34 COMPATIBLE FOR UP TO
CODE LETTER F ACFT RESTRICTED UPTO MAX WINGSPAN 73.30 M.
AMEND TWY COMPATIBILITY CHART OF E-AIP INDIA ACCORDINGLY.

OPKC / KHI

// (COM-INFO)//

THA 00696/15 (04 MAR 26)

COM INFO:--PLS contact SHAHEEN Operation on 131.2
to provide ETA prior landing. (ISSUE 02JUL25/REF Email KHIKP04JUN25/UFN)

OPLA / LHE

** A0190/26 **

OPKCA0190/26 (18 MAY 26)

"ACFT PRKG BAYS 09,10 AND 11 CLSD DUE CIVIL WIP.
FLW ARRANGEMENTS MADE DRG NOTAM PERIOD.
- PROLONGED PRKG UNDER NO CIRCUMSTANCES BE PERMITTED.
- OPLA NOT BE DESIGNATED AS AN ALTN"

OPKCA0898/22 (28 NOV 23)

HOTEL TAXI TRACK IS OPERATIONAL. FOLLOWING INFORMATIONS ARE AS UNDER:	
-----	-----
REHABILITATED PORTION OF TWY H	NORMAL PORTION OF TWY H
-----	-----
REHABILITATED PORTIONOF TWY H AFTER NORMAL PORTION HAS DIMENSIONS AS GIVEN BELOW	NORMAL PORTION OF TWY H FM THE EDGE OF RWY 36L/18R HAS DIMENSIONS AS GIVEN BELW
-----	-----
LENGTH 1758 FEET	LENGTH 810 FEET
-----	-----
WIDTH 75.5 FEET	WIDTH 75.5 FEET
-----	-----
PCN 49/F/C/X/T	PCN 10/F/D/Y/T (AS ALREADY MENTIONED IN AIP)

A. TWY EDGE LGT AVBL. B. DAY AND NGT OPERATION IS AVBL FOR COMPATIBLE ACFT. C. TWY EDGE MARKING AVBL.	

OPIS / ISB

OPKCA0366/26 (19 JUN 26)

RWY-28L AND RWY-10R TOUCH DOWN ZONES ARE LIABLE TO BE
SLIPPERY WHEN WET DUE TO RUBBER DEPOSITS.
PILOTS TO EXER CTN WHILE LDG/TKOF

OPKCA0817/22 (28 NOV 23)

"OBSTACLE CLEARANCE ALTITUDE (OCA/H) OF ILS CAT-II RWY 28L APPROACH FOR CATEGORY D AIRCRAFT AND FOR ILS CAT-I RWY10R FOR CATEGORY C AND D AIRCRAFT HAS BEEN REVISED AS PER FOLLOWING:			
-----	-----	-----	-----
OCA/H	AB	C	D
-----	-----	-----	-----
ILS CAT-II RWY28L	1847FT (100FT)		1858FT (111FT)
-----	-----	-----	-----
OCA/HA	B	C	D
-----	-----	-----	-----
ILS CAT-I RWY10R	1933FT(200FT)	1942FT(209FT)	1952FT(219FT)
-----	-----	-----	-----

KINDLY INCORPORATE IN AIP PAKISTAN PAGES AD2.OPIS-49,
AD2.OPIS-53, AD2.OPIS-55 AND AD2.OPIS-59 ACCORDINGLY."

UTDD / DYU

UTDAA0058/26 (02 JUN 26)

TWY M SEGMENT FROM STAND A1 TO STAND A5W CLSD.

UTDAA0057/26 (02 JUN 26)

TWY F CLSD.

UTDAA0043/26 (01 JUN 26)

"CHART SID PUGUS 1A RENAMED INTO SID SX 1A.
REF AIP AD.2 UTDD-79,80."

UTDAA0047/26 (01 JUN 26)

"CHART STAR PUGUS 1E RENAMED INTO STAR SX 1E.
REF AIP AD.2 UTDD-129,130."

UTDAA0049/26 (01 JUN 26)

"CHART STAR PUGUS 1N RENAMED INTO STAR SX 1N.
REF AIP AD.2 UTDD-145,146."

UTDAA0045/26 (01 JUN 26)

"CHART SID PUGUS 1J RENAMED INTO SID SX 1J
REF AD.2 UTDD-101,102."

UTDAA0039/26 (05 MAY 26)

"STANDS B1, B1W CLSD."

UZSS / SKD

UZTTD0986/26 (01 JUN 26)

"STANDS 11, 11L, 11R CLSD."
01 JUN 26 09:25 UNTIL 01 AUG 26 18:59 ESTIMATED

UZTTD0820/26 (28 APR 26)

"CLOSED RWY REMAINS SOUTH OF RWY 09/27.AVERAGE DISTANCE
BETWEEN ACTIVE AND CLOSED RWY CENTERLINES IS 110 METERS.
PILOTS MUST EXERCISE CAUTION TO AVOID RWY CONFUSING.
REF:AIP AD2.UZSS-11,UZSS-12,UZSS-27,UZSS-28,UZSS-29,UZSS-30,
UZSS-31,UZSS-32."
28 APR 26 11:57 UNTIL 27 JUL 26 18:59 ESTIMATED

UZTTD0819/26 (28 APR 26)

"TAXIING ACFT TO STANDS 12-13 BEHING FOLLOW FOLLOW-ME
CAR, WITH EXCEPTION ACFT WITH WINGSPAN OF 36,0 METERS OR MORE."
28 APR 26 11:53 UNTIL 27 JUL 26 18:59 ESTIMATED

UZTTD0817/26 (28 APR 26)

STANDS FOR ACFT CAT A-B-C AND MODIFICATIONS 12-24 (TAX INTO NOSE
TO NORTH AND TAX OUT OF UNDER ENGINES POWER BY ASSISTANCE OF
FOLLOW-ME CAR.
28 APR 26 11:39 UNTIL 27 JUL 26 18:59 ESTIMATED

UZTTD1035/25 (02 OCT 25)

"D-ATIS SYSTEM AVBL VIA CH SITA.
REF.AIP GEN 3.5,AD2.UZSS-10."

UZTTD1021/25 (02 OCT 25)

CPDLC AVBL VIA CH SITA.
REF.AIP ENR 1.6.

UZTT / TAS

UZTTD1035/26 (12 JUN 26)

STAND C41 CLSD.

ETOQV0503/26 (08 JUN 26)

[US DOD PROCEDURAL NOTAM] INSTRUMENT APPROACH PROCEDURE LIMITED ILS C OR LOC C RWY 08R, DME &
ATC RADAR REQUIRED. MISSED APPROACH WAYPOINTS NOT IN DAFIF.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 68/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

ETOQV0504/26 (08 JUN 26)

[US DOD PROCEDURAL NOTAM] INSTRUMENT APPROACH PROCEDURE LIMITED ILS C OR LOC C RWY 26R, DME & ATC RADAR REQUIRED. MISSED APPROACH WAYPOINTS NOT IN DAFIF. MINIMUMS S-LOC 26R 1930/1600M 513 (600-1600M).

ETOQV0501/26 (08 JUN 26)

[US DOD PROCEDURAL NOTAM] INSTRUMENT APPROACH PROCEDURE LIMITED ILS C OR LOC C RWY 08L, DME & ATC RADAR REQUIRED. MISSED APPROACH WAYPOINTS NOT IN DAFIF.

UZTTD0978/26 (29 MAY 26)

"STANDS E69, E70 ARE AVLB FOR ACFTS WITH WING SPAN NO MORE THAN 34,1M AND LENGTH NO MORE THAN 44,6M."

UZTTD0977/26 (29 MAY 26)

TWY-H FROM ABEAM STAND E1 TO ABEAM STAND B-7 CLSD.

UZTTD0976/26 (29 MAY 26)

STANDS H-44 USE ONLY FOR TAXIING ACFT.

UZTTD0975/26 (29 MAY 26)

"STAND E71 IS AVLB FOR ACFT WITH WINGSPAN NO MORE THAN 34.1M, LENGTH NO MORE THAN 37.57M, ONLY IF STAND E70A IS OCCUPIED BY ACFT WITH WINGSPAN NO MORE THEN 60.3M LENGTH NO MORE THEN 63.7M."

UZTTD0973/26 (29 MAY 26)

TAXIING ACFT TO ABEAM STAND E1 AVLB WITH MAX ACFT WINGSPAN 36M AND LESS ALONG THE YELOW DASHED LINE FOLLOW FOLLOW-ME CAR.

UZTTD0972/26 (29 MAY 26)

"TAXIING INTO ACFT TO STAND B15 BY OWN POWER, TAXIING OUT ACFT BACK BY TOWING ON MAIN TWY OR TOWING FORWARD ON START-UP POINT N3."

UZTTD0938/26 (19 MAY 26)

"TAXIING INTO/OUT ACFT TO STANDS H48, H49, H50, H51,H52, H53, H54, H55, H56, H57 USE BY TOWING FROM START-UP POINT N11. MOVEMENT ACFT WITH TURNED OFF ENGINES. START-UP ENGINES ON START-UP POINT N11."

UZTTD0904/26 (14 MAY 26)

"SID DVOR/DME RWY 08L/R PUBLISHED IN CHART SID DVOR/DME RWY 26R/L, RWY 08L/R (AIP UZTT AD2.24-4.15) TO BE ASSIGNED IN CASE OF GNSS FAILURE OR LOSS. UNDER NORMAL CONDITIONS RNAV (GNSS) SID SHALL BE USED. REF: AIP UZTT AD2.24-4.15 AIRAC AMDT 03/26 EFFECTIV DATE 14 MAY 2026."

UZTTD0864/26 (07 MAY 26)

"ON PAGE AD2.UZTT-7, ADD THE FOLLOWING VALUES TO TABLE 2.13 DECLARED DISTANCES:
RWY 08L:
TWY1: TORA 3750M, TODA 3900M, ASDA 3750M
RWY 26R:
TWY5: TORA 3750M, TODA 3900M, ASDA 3750M
TWY3: TORA 1200M, TODA 1350M, ASDA 1200M
RWY 08R:
TWY7: TORA 3555M, TODA 3705M, ASDA 3555M
RWY 26L:
TWY13: TORA 1300M, TODA 1450M, ASDA 1300M
TWY14: TODA 2500M INSTESD OF 2350M.
REF: AIP AD2. UZTT-7 AIRAC AMDT 05/25
EFFECTIV DATE 02 OCT 2025."

UZTTD0863/26 (07 MAY 26)

"ON PAGE UZTT AD2.24-1.0-1, MAKE THE FOLLOWING CORRECTIONS IN THE DECLARED DISTANCES TABLE:
RWY 08L: TWY1 INSTEAD OF THR1:
RWY 26R: TWY5 INSTEAD OF THR5:
RWY 08R: TWY7 INSTEAD OF THR7:
REF: AIP UZTT AD2.24-1.0-1 AIRAC AMDT 03/26
EFFECTIV DATE 14 MAY 2026."

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 69/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

UZTTD0797/26 (24 APR 26)

"STAND B-3 IS AVLB FOR ACFT WITH WINGSPAN NO MORE THAN 36M, LENGHT NO MORE THAN 45M."

UZTTD0646/26 (30 MAR 26)

"SEGMENT TWY-B ABEAM STAND B-16, B-17 CLSD."

UZTTD0645/26 (30 MAR 26)

"TAXIING INTO ACFT TO STAND B-16, B-17 BY OWN POWER, TAXIING OUT BACK BY TOWING."

UZTTD0644/26 (30 MAR 26)

TEMPORARY STAND ESTABLISHED:
STAND B7 COORDINATES N411543.76 E0691609.60
MAX ACFT WINGSPAN 36M.
MAX ACFT LENGTH 46M.
PCN-47/F/B/X/T.

UZTTD0643/26 (30 MAR 26)

"TAXIING INTO ACFT TO STAND B7 BY OWN POWER FOLLOW FOLLOW-ME CAR, TAXIING OUT BACK BY TOWING."

UZTTD0553/26 (15 MAR 26)

"TAXIING INTO AND TAXIING OUT ACFT TO/FROM STANDS D23, D24, D25 USE BY TOWING."

UZTTD0552/26 (15 MAR 26)

TEMPORARY STANDS ESTABLISHED:
STAND D23 COORDINATES N411505.51 E0691604.89
MAX ACFT WINGSPAN 10 M.
MAX ACFT LENGTH 12 M.
PCN 60/R/A/X/T.
STAND D24 COORDINATES N411505.29 E0691604.12
MAX ACFT WINGSPAN 10 M.
MAX ACFT LENGTH 12 M.
PCN 60/R/A/X/T.
STAND D25 COORDINATES N411506.44 E0691604.28
MAX ACFT WINGSPAN 10 M.
MAX ACFT LENGTH 12 M.
PCN 60/R/A/X/T.

UZTTD0503/26 (06 MAR 26)

"AT ACFT STANDS F94, F94A, F95, F96, F97, F97A:
ENGINE START-UP ONLY AT MTWY. TAXI IN AND TAXI OUT OF ACFT BY TOWING ONLY."

UZTTD0478/26 (06 MAR 26)

STAND H-42 CLSD.

UZTTD0399/26 (23 FEB 26)

TAXIING ACFT FROM TWY-2 TO TWY-B AVLB WITH MAX ACFT WINGSPAN 60.60M THE WHITE DASHED LINE FOLLOW FOLLOW-ME CAR IF STAND B8A IS NOT OCCUPIED.

UZTTD0360/26 (17 FEB 26)

"EFFECTIVE FROM 17 FEBRUARY 2026 ON A PERMANENT BASIS, ALL BUSINESS AVIATION OPERATORS PLANNING TO PERFORM CHARTER FLIGHTS TO THE CITY OF TASHKENT (REPUBLIC OF UZBEKISTAN) SHALL INDICATE TASHKENT-VOSTOCHNY AD(HUMO)-UZTP AS THE DESTINATION AD IN FLIGHT APPLICATIONS AND IN FLIGHT PLANS INSTEAD OF TASHKENT- I.KAROMOV- UZTT."

UZTTD0246/26 (30 JAN 26)

START-UP POINT N17 REPLACED ON ABEAM STAND E1.

UZTTD0158/26 (20 JAN 26)

"OCA(H) ILS CAT II FOR ACFT ALL CAT ESTABLISHED AS:
1469 FT/(100FT).
REF:AIP
ILS CAT II OR LOC RWY08L (UZTT AD2.24-6.0),
ILS CAT II OR LOC RWY08L (UZTT AD2.24-6.16)."

UZTTD0100/26 (14 JAN 26)

TAXIING ON TWY-B TO TWY-1 AND BACK AVBL WITH MAX ACFT WINGSPAN MORE 48.06M UP TO INCLUDING 64.8M ALONG THE YELLOW DASHED LINE FOLLOW FOLLOW-ME CAR.

UZTTD0099/26 (14 JAN 26)

TAXIING ON TWY-B TO TWY-2 AND BACK AVLB WITH MAX ACFT WINGSPAN MORE 48.06M UP TO INCLUDING 64.8M ALONG THE YELLOW DASHED LINE FOLLOW FOLLOW-ME CAR IF STAND B8A IS NOT OCCUPIED.

UZTTD0061/26 (09 JAN 26)

STAND B18A CLOSED.

UZTTD1803/25 (31 DEC 25)

"RWY 08L/26R: 180 DEG TURN IS PROHIBITED, EXCEPT TURN PAD (08L/26R) FOR VIP FLIGHTS,CHECK FLIGHT I ACFT MTOW OF 24 TONS AND LESS."

UZTTD1789/25 (29 DEC 25)

AIRCRAFT CREWS EXPECT DLA ON ARR AND DEP DUE TO CONSTRUCTION WORKS AT THE AERODROME.

UZTTD1039/25 (29 OCT 25)

"D-ATIS SYSTEM AVBL VIA CH SITA.
REF.AIP GEN 3.5,AD2.UZTT-6."

UZTTD1020/25 (29 OCT 25)

CPDLC AVBL VIA CH SITA.
REF.AIP ENR 1.6.

UTAA / ASB

UUUUU0228/26 (03 JUN 26)

TWY SEGMENT BTN C1 AND C2 AVBL FOR ACFT TFC CODE LETTER C AND BLW.

UUUUU0226/26 (03 JUN 26)

"STANDS 113, 113A, 113B, 114B CLSD."

UUUUU0164/26 (11 APR 26)

TWY E1 CLSD.

UTAK / KRW

UUUUU0231/26 (15 JUN 26)

NDB 34R WZ 911 KHZ U/S DUE TO REPAIR WIP.

*UUUUU0169/26 (15 APR 26)

RWY 16L/34R CLSD.

UBBB / GYD

UBBUA0200/26 (25 JUN 26)

ACFT STAND C7 CLOSED DUE TO CONSTRUCTION WORKS

UBBUA0198/26 (19 JUN 26)

PORTION OF TWY M1 BEHIND STAND F1 CLSD DUE TO CONSTRUCTION WORKS.

UBBUA0196/26 (15 JUN 26)

"TWY E,E2,D,G,P CENTRE LINE LIGHTS U/S."

UBBUA0193/26 (07 JUN 26)

"RWY ENTRANCE LIGHTS AT INTERSECTION TWY H, TWY H2, TWY H4 AND TWY S WITH RWY 17/35 U/S."

UBBUA0190/26 (01 JUN 26)

VALIDITY OF AD CERTIFICATION CHANGED TO 01.06.2026-31.05.2029
REF AIP AD 1.5

UBBUA0108/26 (24 APR 26)

SURFACE MOVEMENT RADAR U/S.

UGTB / TBS
N I L

UDYZ / EVN

UDYZ 1225/26 (27 JUN 26)

SNOWTAM

27 JUN 2026 10:30-27 JUN 2026 18:30
06271030 08 6/6/6 NR/NR/NR NR/NR/NR DRY/DRY/DRY

MEASURED FRICTION COEFFICIENTS 0.7/0.7/0.7 SKH.

UDDDA0068/26 (16 APR 26)

"ESTABLISHMENT OF LTAA FIR-UDDD FIR BOUNDARY SIGNIFICANT POINT
FODEC 402025N 0433537E.
FOR ARRIVALS VIA FODEC TO UDYZ,FODEC FRA(A) WILL BE USED.MINIMUM
LEVEL OVER FODEC IS FL125.
FOR FLIGHT PLANNING FILE DCT OKUDA FOR RWY08 AND FODEC DCT LUMIK FOR
RWY26.
TACTICAL RADAR VECTORING MAY BE EXPECTED."

UDDDA0054/26 (24 MAR 26)

"THE THRESHOLD OF RWY 08 WILL BE TEMPORARILY DISPLACED BY 1450M
TOWARD THE RUNWAY CENTER DUE TO A DISPLACED THRESHOLD, THE DECLARED
LANDING DISTANCE AVAILABLE (LDA) IS REDUCED TO 2400M.
RWY 08 TORA-2400, TODA-2800, ASDA-2400, LDA-2400
RWY 26 TORA-2400, TODA-2850, ASDA-2400, LDA-2400
PAPI AND ILS OF RWY 08 WILL NOT BE OPERABLE.
TWY A AND MAIN TWY FROM APRON 1 TO TWY A WILL NOT BE OPERABLE.
SIMPLE APPROACH LIGHTING SYSTEMS WILL BE AVAILABLE (SINGLE SOURCE)
FOR RWY TEMPORARY THRESHOLD 08 ACCORDING TO FIGURE A7, ANNEX 14 ICAO.
CAT I AND CATII ARE OUT OF SERVICE.
A WIDE-BODY AIRCRAFT IS PERMITTED TO PERFORM BACKTRACK AT THE
RUNWAY-TAXIWAY
B, C, D INTERSECTIONS.
A BACKTRACK OF NARROW-BODY AIRCRAFT WILL BE CONDUCTED ON THE RWY.
FOR RWY 08:
DUE TO RWY 08 DISPLACED THR 400850.08N 0442325.12E
DESCENT GRADIENT 4.7 PERCENT (2.7 DEGREE)
OCA(H) 3540(740)
MAPT ZVR
FOR IAC VOR/DME 08:
ON CHART TABLE ALT ARE CHANGED DEPENDING ON FINAL APPROACH DISTANCE
ZVR DME 1NM-3820, ZVR DME 3NM-4390, ZVR DME 5NM-4960
FOR IAC RNP RWY 08 (LNAV ONLY):
ON CHART TABLE ALT ARE CHANGED DEPENDING ON FINAL APPROACH DISTANCE
DISPLACED THR 3NM-3710, DISPLACED THR 5NM-4280
ILS/DME, GLS NOT AVAILABLE)"

OIZH / ZAH
N I L

OISS / SYZ

OIIIA1333/26 (23 JUN 26)

"TWY A (BTN A1 AND A2), A1, C, C2 AND C4 CLSD"
23 JUN 26 10:46 UNTIL 23 JUL 26 10:30 ESTIMATED

OIIIA1257/26 (16 JUN 26)

SAT-WED 0330-0930
"REF AIP PAGE AD 2-9 OISS ITEM 2.18 AND REF NOTAM A0703/26,
GND SER AVBL ON FREQ 121.900 MHZ."

OIIIA1033/26 (25 MAY 26)

"REF AIP PAGE ENR 1.6-1, SHIRAZ TMA MSSR RADAR U/S AND
APCH RADAR SER IN SHIRAZ TMA NOT AVBL."
25 MAY 26 07:19 UNTIL 29 JUN 26 08:30 ESTIMATED

*OIIIA0940/26 (11 MAY 26)

RWY 11L/29R CLSD .
11 MAY 26 09:01 UNTIL 22 JUL 26 20:30 ESTIMATED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 72/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

OIIIA0938/26 (11 MAY 26)

"REF AIP PAGE ENR 1.6-5 NR 4 , TWR RADAR PRESENTATION SYSTEM U/S."
11 MAY 26 08:43 UNTIL 08 AUG 26 12:00 ESTIMATED

OIIIA0836/26 (27 APR 26)

"REF AIP PAGE AD 2 OISS APDC1,
STAND NR 103 CLSD DUE TO WIP."
27 APR 26 08:15 UNTIL 22 JUL 26 10:30 ESTIMATED

OIIIA0835/26 (27 APR 26)

DME SYZ CH125X REMOTE MONITOR IN APP U/S.
PILOTS SHALL REPORT DME OUTAGE TO OISS ATC AND
REQUEST ALTERNATIVE CLEARANCE IF REQUIRED
27 APR 26 08:13 UNTIL 22 JUL 26 10:30 ESTIMATED

OIIIA0788/26 (20 APR 26)

"GPS UNREL AND MAY BE UNAVAILABLE WI AREA
WITH THE LATERAL LIMITS OF SHIRAZ TMA
AS SPECIFIED IN IRAN AIP PAGE ENR 2.1-7, FM GND UP TO FL245,
EGPWS/GPWS MAY DISPLAY ERRONEOUS INDICATION AND MAP SHIFTING,
AS REPORTED FREQUENTLY PILOTS SHALL REPORT GPS ANOMALIES
INCLUDING DEGRADED OPERATION AND/OR LOSS OF SER,
ASAP."
20 APR 26 08:32 UNTIL 19 JUL 26 20:30 ESTIMATED

OIIIA0703/26 (25 FEB 26)

"REF AIP PAGE AD 2-8 OISS ITEM 2.18, GND SER PROVIDED BY
SHIRAZ GROUND BTN 0330-1930 (HOURS OF OPERATION)
ON FLW FREQ: 121.900 MHZ, 121.750 MHZ AND 275.800 MHZ,
AMEND AIP ACCORDINGLY."

OIAW / AWZ

OIIIA1003/26 (20 MAY 26)

"GPS UNREL AND MAY BE UNAVAILABLE WI AREA
WITH THE LATERAL LIMITS OF AHWAZ CTR AS SPECIFIED
IN IRAN AIP PAGE AD 2-7 OIAW ITEM 2.17 ATS AIRSPACE NR 1,
FM GND UP TO FL175,
EGPWS/GPWS MAY DISPLAY ERRONEOUS INDICATION AND MAP SHIFTING,
AS REPORTED FREQUENTLY PILOTS SHALL REPORT GPS ANOMALIES
INCLUDING DEGRADED OPERATION AND/OR LOSS OF SER, ASAP.
FROM GND TO FL175"
20 MAY 26 04:58 UNTIL 18 AUG 26 20:30 ESTIMATED

OIIIA0976/26 (13 MAY 26)

PAPI RWY 30 U/S AND SUBSEQUENTLY REQUIRED FLTCK
13 MAY 26 09:34 UNTIL 10 AUG 26 23:59 ESTIMATED

OIIIA0886/26 (04 MAY 26)

AMD U/S
04 MAY 26 07:35 UNTIL 31 JUL 26 10:00 ESTIMATED

OIIIA0870/26 (02 MAY 26)

NDB AWZ 415 KHZ NOT OPR DUE TO PWR.
02 MAY 26 07:41 UNTIL 31 JUL 26 10:00 ESTIMATED

OIIIA0868/26 (02 MAY 26)

"REF AIP PAGE GEN 3.5-2,
CEILOMETER TDZ RWY 30 U/S DUE TO PWR."
02 MAY 26 07:34 UNTIL 31 JUL 26 10:00 ESTIMATED

OIIIA0869/26 (02 MAY 26)

RWY 12 SALS NOT OPR DUE TO PWR.
02 MAY 26 07:37 UNTIL 31 JUL 26 10:00 ESTIMATED

OIFM / IFN

*OIIIA1325/26 (23 JUN 26)

"RWY 07R/25L CLSD DUE TO CONST WORK,
FM TWY A TO THE BEGINNING OF RWY 25L USABLE ONLY FOR TAXI"
23 JUN 26 10:09 UNTIL 01 JUL 26 10:30 ESTIMATED

OIIIA1324/26 (23 JUN 26)

TWY D AND H CLSD.
23 JUN 26 09:59 UNTIL 01 JUL 26 10:30 ESTIMATED

OIIIA1194/26 (09 JUN 26)

MILITARY /EMERGENCY UHF FREQ 243.000 MHZ U/S.
09 JUN 26 05:40 UNTIL 07 SEP 26 05:40 ESTIMATED

OIIIA1035/26 (25 MAY 26)

"REF AIP PAGE ENR 1.6-1, ESFAHAN TMA MSSR RADAR U/S AND
APCH RADAR SER IN ESFAHAN TMA NOT AVBL."
25 MAY 26 07:23 UNTIL 29 JUN 26 08:30 ESTIMATED

OIIE / IKA

OIIIA1294/26 (21 JUN 26)

21 JUN 2026 10:09-28 JUN 2026 15:30
"REF AIP PAGE GEN 3.5-10, RVR RWY 29R NOT OPR DUE TO MAINT."
21 JUN 26 10:09 UNTIL 28 JUN 26 15:30 ESTIMATED

OIIIA1230/26 (15 JUN 26)

"TWY J BTN TWY A AND APRON, AND APRON TAXI LANE
BTN STAND 112L AND STAND 110 CLSD DUE TO WIP."
14 JUN 26 05:17 UNTIL 13 JUL 26 15:30 ESTIMATED

OIIIA1229/26 (15 JUN 26)

ACFT STAND NR 110 AND STAND NR 142 CLSD DUE TO WIP.
14 JUN 26 05:15 UNTIL 13 JUL 26 15:30 ESTIMATED

OIIIA1170/26 (08 JUN 26)

TWY R6 CLSD.
08 JUN 26 09:20 UNTIL 06 SEP 26 15:30 ESTIMATED

OIIIA1052/26 (25 MAY 26)

"REF NOTAM A0983/26, PILOT MUST BE READY TO USE
DVOR/DME TRN FREQ 115.300 MHZ CH 100X IN CASE INSTRUCTED BY
MEHRABAD ATC."
25 MAY 26 09:13 UNTIL 15 AUG 26 06:00 ESTIMATED

OIIIA0990/26 (17 MAY 26)

ACFT DOCKING GUIDANCE SYSTEM STANDS
NR 104R AND 116R U/S.
17 MAY 26 14:08 UNTIL 15 AUG 26 15:30 ESTIMATED

OIIIA0991/26 (17 MAY 26)

TWY R5 AND TWY B BTN TWY R4 AND TWY R5 CLSD DUE TO WIP.
17 MAY 26 14:14 UNTIL 15 AUG 26 15:30 ESTIMATED

OIIIA0983/26 (16 MAY 26)

"DVOR/DME IKA FREQ 114.300 MHZ CH 90X U/S AND
SUBSEQUENTLY REQUIRED FLTCK.
ALSO ALL SID, STAR AND IAP BASE ON MENTIONED SYSTEM
TEMPORARILY SUSPENDED."
16 MAY 26 11:33 UNTIL 15 AUG 26 06:00 ESTIMATED

OIIIA0965/26 (12 MAY 26)

PAPI RWY 29R U/S AND SUBSEQUENTLY REQUIRED FLTCK
12 MAY 26 08:53 UNTIL 10 AUG 26 23:59 ESTIMATED

OIII / THR

*OIIIA1361/26 (25 JUN 26)

"LDG AND TKOF NOT AUTH ON RWY 11L/29R AND
USABLE ONLY FOR TAXI, RWY 11R/29L AVBL,
DLA MAY OCCUR TO ALL TFC."
25 JUN 26 05:57 UNTIL 21 SEP 26 20:30 ESTIMATED

OIIIA1034/26 (25 MAY 26)

"REF AIP PAGE ENR 1.6-1, TEHRAN TMA MSSR RADAR U/S AND
APCH RADAR SER IN TEHRAN TMA NOT AVBL."
25 MAY 26 07:21 UNTIL 29 JUN 26 08:30 ESTIMATED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 74/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

OIIIA0958/26 (12 MAY 26)

"ILS (LOC, GP, DME) RWY 29R ITRN CH44X U/S AND SUBSEQUENTLY
REQUIRED FLTCK"
12 MAY 26 08:45 UNTIL 10 AUG 26 23:59 ESTIMATED

OIIIA0830/26 (27 APR 26)

"TWO HOLES EXIST ON TWY A BTN TWY A3 AND A4 :
2M NORTH OF TWY CL, LEN: 50 CM , WID: 20 CM , DPT: 08 CM
1M NORTH OF TWY CL, LEN: 30 CM , WID: 30 CM , DPT: 05 CM."
27 APR 26 07:08 UNTIL 26 JUL 26 12:00 ESTIMATED

OIIIA0829/26 (27 APR 26)

"A HOLE EXISTS ON 1.5M RIGHT SIDE OF CL TWY A, BFR TWY A1
WITH FLW SPECIFICATIONS:
LEN:50 CM, WID:15 CM, DPT:10 CM"
27 APR 26 07:05 UNTIL 26 JUL 26 12:00 ESTIMATED

OIIIA0828/26 (27 APR 26)

"A HOLE EXISTS ON SOUTH OF RCL 11L/29R BTN TWY A3 AND TWY A4,
WITH FLW SPECIFICATION:
DIST FM RCL: 1 M,
LEN: 30 CM, WID: 20 CM, DPT: 5 CM"
27 APR 26 06:59 UNTIL 26 JUL 26 12:00 ESTIMATED

OIIIA0822/26 (26 APR 26)

"A HOLE EXISTS ON 1 M RIGHT SIDE OF CL TWY A
BTN TWY A3 AND A4 BFR STAND NR 308
WITH FLW SPECIFICATIONS:
LEN:30 CM, WID:30 CM, DPT:7 CM"
26 APR 26 16:48 UNTIL 26 JUL 26 16:46 ESTIMATED

OIIIA0821/26 (26 APR 26)

"A HOLE EXISTS ON SOUTH OF RCL 11L/29R AT INT TWY A3
WITH FLW SPECIFICATION:
-DIST FM RCL: 1 M,
LEN: 40 CM, WID: 10 CM, DPT: 10 CM"
26 APR 26 16:33 UNTIL 26 JUL 26 16:30 ESTIMATED

OIIIA0820/26 (26 APR 26)

"A HOLE EXISTS ON CL TWY A1 WITH FLW SPECIFICATIONS:
LEN:20CM, WID:5CM, DPT:4CM"
26 APR 26 16:29 UNTIL 25 JUL 26 16:30 ESTIMATED

OIIIA0819/26 (26 APR 26)

"REF AIP PAGE AD 2-10 OIII ITEM 2.18,
MEHRABAD CLEARANCE DELIVERY NOT OPR."
26 APR 26 10:25 UNTIL 26 JUL 26 10:00 ESTIMATED

OIIIA0818/26 (26 APR 26)

"REF AIP AD 2.20 ITEM 6-1-5, TWY A3, A4 AND A5 OPN
AND ONLY AVBL FOR EMERG EXIT."
26 APR 26 10:23 UNTIL 26 JUL 26 10:00 ESTIMATED

OIIIA0817/26 (26 APR 26)

"FOUR ENG ACFT HAVE TO MNTN THEIR OUTER ENGINES AT
LOW RPM DRG TAXI ON TWY B6,B8,B9 TO AVOID PRODUCING FOD."
26 APR 26 10:20 UNTIL 26 JUL 26 10:00 ESTIMATED

OIIIA0791/26 (20 APR 26)

"REF AIP PAGE AD 2 OIII IAC 1-1 AND IAC 1-1-1,
- INSTRUMENT APPROACH PROCEDURE
TEHRAN/MEHRABAD
ILS Z OR LOC Z RWY 29L
CAT A/B/C/D , AND
- INSTRUMENT APPROACH PROCEDURE TABULAR DESCRIPTION
TEHRAN/MEHRABAD
ILS Z RWY 29L
CAT A/B/C/D,
SUSPENDED."
20 APR 26 09:05 UNTIL 19 JUL 26 20:30 ESTIMATED

OITT / TBZ
N I L

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 75/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

OITR / OMH

OIIIA1312/26 (22 JUN 26)

"ALL AIRCRAFT (IFR AND VFR) DEPARTING FM/ARRIVING TO UROMIYEH AD SHALL BE EQUIPPED WITH SSR TRANSPONDER MODE S WITH ADS-B CAPABILITY OR ADS-B WITH DEDICATED 1090 MHZ ADS-B OUT CAPABILITY, EXC FOR THOSE FLT ENGAGED IN HOSP OPERATION."
22 JUN 26 11:43 UNTIL 19 SEP 26 08:30 ESTIMATED

OIIIA1074/26 (29 MAY 26)

AMD U/S
29 MAY 26 09:32 UNTIL 29 JUN 26 08:40 ESTIMATED

// (COM-INFO) //

THA 00145/24 (10 SEP 24)

COM INFO: -- ATS HOURS 0330-1830, OTHER TIME O/R (LIDO AOI) (PC-INFO)

OOMS / MCT

OOMSA0376/26 (17 JUN 26)

28 JUN 2026 05:00-28 JUN 2026 07:00
ALL TRAFFIC SUBJECT TO DELAY DUE TO VVIP MOVEMENT (MUSCAT INTL AIRPORT

*OOMSA0329/26 (26 MAY 26)

LANDING AND TAKEOFF LIMITED TO FLW RUNWAY ONLY:
RWY 08L/26R: FROM 0400 TO 1600 UTC
RWY 08R/26L: FROM 1600 TO 0400 UTC
LAST PUSHBACK 20 MIN PRIOR RWY SWITCHOVER

OOMSA0328/26 (25 MAY 26)

"-REF AIRAC AIP 03/25, USE OF PUBLISHED STARS RWY 08L/26R AND RWY 08R/26L TEMPORARILY SUSPENDED. ALL ARRIVING TRAFFIC CAN EXPECT RADAR VECTORS TO THE APPROPRIATE IAP
FOR FLIGHT PLANNING PURPOSES, ALL ARRIVING TRAFFIC TO OOMS SHALL FILE FLIGHT PLAN ROUTE TO MCT DVOR."

OOMSA0246/26 (02 MAY 26)

OOMS RWY 08L/26R ILS CAT II OPERATIONS SUSPENDED UNTIL FURTHER NOTICE.
23 APR 26 09:53 UNTIL 21 JUL 26 10:00 ESTIMATED

OMDW / DWC

ETOQV0532/26 (18 JUN 26)

[US DOD PROCEDURAL NOTAM] INSTRUMENT APPROACH PROCEDURE CHANGED ILS RWY 30, VGSI AND ILS GLIDEPATH NOT COINCIDENT. (VGSI ANGLE 3.00/TCH 98

ETOQV0534/26 (18 JUN 26)

[US DOD PROCEDURAL NOTAM] INSTRUMENT APPROACH PROCEDURE CHANGED ILS RWY 12, VGSI AND ILS GLIDEPATH NOT COINCIDENT. (VGSI ANGLE 3.00/TCH 80

ETOQV0527/26 (18 JUN 26)

[US DOD PROCEDURAL NOTAM] INSTRUMENT APPROACH PROCEDURE CHANGED RNP RWY 12, VGSI AND RNAV GLIDEPATH NOT COINCIDENT (VGSI ANGLE 3.00/TCH 80). MINIMA: LNAV/VNAV DA CAT A 470/900M 355 (300-900M), CAT BC 480/1000M 365 (400-1000M), CAT D 490/1000M 375 (400-1000M). LNAV MDA 550/1300M 435 (400-1300M), WHEN ALS INOP INCREASE CAT AB RVR/VIS TO 1500M; CAT CD RVR/VIS TO 1700M. LNAV MDA 550/1300M 435 (400-1300M), WHEN ALS INOP INCREASE CAT AB RVR/VIS TO 1500M; CAT CD RVR/VIS TO 2000M.

ETOQV0529/26 (18 JUN 26)

[US DOD PROCEDURAL NOTAM] INSTRUMENT APPROACH PROCEDURE CHANGED RNP RWY 30, VGSI AND RNAV GLIDEPATH NOT COINCIDENT (VGSI ANGLE 3.00/TCH 98). MINIMA: LNAV/VNAV DA CAT A 421/750M 250 (300-800M); CAT B 425/750M 254 (300-800M); CAT C 469/750M 298 (300-800M); CAT D 493/750M 322 (400-800M),WHEN ALS INOP INCREASE CAT AB RVR/VIS 1300M; CAT C RVR/VIS TO 1400M; CAT D RVR/VIS TO 1500M. LNAV MDA: 570/110M 399 (400-1100M), WHEN ALS INOP INCREASE CAT AB RVR/VIS TO 1500M; CAT CD RVR/VIS TO 1800M. MISSED APPROACH REQUIRES A MINIMUM CLIMB GRADIENT OF 183 FT/NM (3.0%).

*OMAEA1904/26 (07 JUN 26)

MON 1100-1400 2000-2045
RWY 12/30 CLSD DUE TO MAINT.
REF OMDW AD 2.12 RUNWAY PHYSICAL CHARACTERISTICS REMARKS.

OMAEA1591/26 (07 JUN 26)

"DUE TO CRANES ACTIVITIES
CIRCLING CAT B TO READ AS 750 (579)
REF CHART OMDW AD 2-65, CHART OMDW AD 2-66, CHART OMDW AD 2-67"

OMDB / DXB

OMAEA2179/26 (26 JUN 26)

"SECN OF TXL J BEHIND ACFT STANDS B8 AND B9 CLSD.
SECN OF TXL U BEHIND ACFT STAND B8 AND ACFT STAND B9 TEMPO RELOCATED TO THE NORTH TO ALLOW CODE F ACFT MOVEMENTS. THE CENTERLINE FOR THIS SECN WILL NOT HAVE CENTERLINE LIGHTS BUT WILL BE INSTL WITH GREEN REFLECTORS.
SECN OF CROSSOVER TWY U1 LINKING TO THE TEMPO SECN OF TXL U WILL NOT HAVE CENTERLINE LIGHTS BUT WILL BE INSTL WITH GREEN REFLECTORS.
CROSSOVER TWY U2 RELOCATED TEMPO TO THE EAST BTN ACFT STANDS B10 AND B12 LINKING TEMPO SECN OF TXL U. THE CENTERLINE FOR TEMPO CROSSOVER TWY U2 WILL NOT HAVE CENTERLINE LIGHTS BUT WILL BE INSTL WITH GREEN REFLECTORS.
CROSSOVER TWY U3 CLSD.
CROSSOVERS TWY U1 AND TWY U2 WILL BE CODE F COMPATIBLE.
TEMPO TWY SECTIONS WILL BE AVBL FOR UNRESTRICTED MOVEMENTS UP TO CODE F IN CAT I CONDITIONS.
IN CAT II/III CONDITIONS MOVEMENTS MAY BE ALLOWED UNDER FOLLOW-ME GUIDANCE.
EXISTING SECTIONS OF TXL U ARE COMPATIBLE FOR CODE E AND BELOW ONLY. THEREFORE, CODE F ACFT MOVING ON THE TEMPO RELOCATED SECN OF TXL U MUST BE VIGILANT NOT TO CONT STRAIGHT ON THE CODE E TXL U SECTIONS.
REF AIP SUP 20/2026 AREA M27 PHASE 1A."

OMAEA2173/26 (26 JUN 26)

"SECN OF TWY M BTN TWY M12A AND TWY M14A CLSD.
TWY M13, TWY M13A AND TWY M13B CLSD.
TWY M14A WEST LINK ONTO TWY M CLSD.
TWY M14B WEST LINK ONTO TWY M CLSD.
TWY M12A EAST LINK ONTO TWY M CLSD.
TWY M12B EAST LINK ONTO TWY M CLSD.
REF AIP SUP 20/2026 AREA C11 PHASE 1A AND AREA C11 PHASE 1B."

OMAEA2172/26 (26 JUN 26)

TWY K4 WEST CURVE ONTO TXL Z NOT AVBL DURING CAT II/III OPS.

OMAEA2085/26 (18 JUN 26)

"DUE TO CRANES ACTIVITIES WI OMDB AD,
SID RWY 12L MNM TURN ALTITUDE 490 FT AMSL AND MNM OBSTACLE CLIMB GRADIENT 3.4 (206 FT PER NM) UP TO 500 FT AMSL, REF OMDB 2-41.
OMNIDIRECTIONAL SID RWY 12L MNM OBSTACLE CLIMB GRADIENT 3.4 (206 FT PER NM) UP TO 500 FT AMSL, REF OMDB 2-48.
LNAV/VNAV RWY 30R TO READ AS CAT A 380(347), CAT B 390(357), CAT C 400(367), CAT D/DL 410 (377) REF CHART OMDB AD 2-70.
LNAV/VNAV RWY 30L TO READ AS CAT A 380(320), CAT B 390(330) CAT C 400(340), CAT D/DL 410 (350) REF CHART OMDB AD 2-71."

*OMAEA1891/26 (20 MAY 26)

07 JUN 2026 11:30-28 JUN 2026 13:00
07 14 21 28 1130-1300
RWY 12R/30L CLSD.

*OMAEA1886/26 (20 MAY 26)

02 03 09 10 16 17 24 25 30 1100-1400
RWY 12R/30L CLSD.

LTCC / DIY

LTAAJ2676/26 (26 JUN 26)

ILS IDBN RWY 34R U/S

LTAAJ2290/26 (04 JUN 26)

"TWY H2, TWY J, TWY W, TWY K OPN TO CIV TFC.
-ADVISE ATC INSTRUCTIONS.-"

*LTAAJ2268/26 (04 JUN 26)

RWY 16L/34R CLSD TO ALL TFC DUE TO RWY MAINT

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 77/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

*LTAAD1283/26 (04 JUN 26)

RWY 16L/34R CLSD TO TFC DUE TO RWY RENOVATION WORKS.

LTAAJ2178/26 (26 MAY 26)

RWY 16R APPROACH PAPI ANGLE IS 3.5 DEGREE

LTAAD1221/26 (26 MAY 26)

RWY 16R APPROACH PAPI ANGLE IS 3.5 DEGREE

LTAAJ2170/26 (25 MAY 26)

RWY END IDENTIFIER LIGHTS RWY 34L U/S.
RWY END IDENTIFIER LIGHTS RWY 16R U/S.

LTAAD1219/26 (25 MAY 26)

RWY END IDENTIFIER LIGHTS RWY 34L U/S.
RWY END IDENTIFIER LIGHTS RWY 16R U/S.

LTAAD1220/26 (25 MAY 26)

MIL-S POOL CLSD.

LTAAJ1838/26 (30 APR 26)

ASR UNRELIABLE BTN RADIALS 201-255 AND BTN 9-22NM AT ALL ALTITUDE.

LTAAD1007/26 (30 APR 26)

AIRFIELD SURVEILLANCE RADAR (ASR) UNRELIABLE BTN RADIALS 201-255
AND BTN 9-22NM RADIUS AT ALL ALTITUDES.

LTAAJ1810/26 (28 APR 26)

"TWYS H1, K1, F1, E1, D1, C1, B1 AND MIL-D2 CLSD TO CIV TFC.
-DUE TO MAINT-"

*LTAAJ1809/26 (28 APR 26)

RWY 16L/34R APCH LIGHTING SYSTEM AND RWY LIGHTS U/S.

*LTAAD0958/26 (28 APR 26)

RWY 16L/34R APCH LIGHTING SYSTEM AND RWY LIGHTS U/S.

LTAAD0959/26 (28 APR 26)

"TWYS C1, H1, MIL F, MIL G, MIL H CLSD TO TFC."
28 APR 26 06:54 UNTIL 28 JUL 26 14:00 ESTIMATED

LTAR / VAS

LTAAJ2589/26 (23 JUN 26)

"MOBILE VEHICLE PRESENCE EAST OF RWY 01/19 , 180M DISTANCE TO CL .
-DUE TO NEW RWY CONSTRUCTION WORK-
-ADVISE TOWER INSTRUCTIONS-"

LTAAJ2486/26 (16 JUN 26)

0800-1300
RWY 01/19 CLSD TO TRAINING FLT AND MIL FLT EXC SKED AND
AMBULANCE FLT DUE TO CONST WORKS

LTAC / ESB

LTAAJ2669/26 (26 JUN 26)

ILS GP IAKR 329.3MHZ RWY 03L U/S.

LTAAJ2659/26 (26 JUN 26)

ILS GP 330.8MHZ RWY 03R U/S.

LTAAJ2661/26 (26 JUN 26)

NDB ANK 356KHZ U/S.

LTAAJ2514/26 (18 JUN 26)

"ANKARA ESENBAGA AIRPORT
AD 2 LTAC MRVC CHART DATED 09 JUL 26, PUBLISHED VIA AIRAC AIP AMDT
NO. 07/26, IS IN EFFECT
IT IS AVAILABLE AT THE LINK BELOW

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 78/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

[HTTPS://WWW.DHMI.GOV.TR/SAYFALAR/SSD/MAIN.ASPX](https://www.dhmi.gov.tr/sayfalar/ssd/main.aspx)
REF LT 07/26 AIRAC AIP AMDT AD 2 LTAC MRVC"

LTAAJ2510/26 (18 JUN 26)

"APRON 2 ACFT STANDS 1A, 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13
AND 14 RENAMED AS 201, 202, 203, 204, 205, 206, 207, 208, 209, 210,
211, 212, 213, 214 AND 215 RESPECTIVELY.
-DUE TO IMPLEMENTATION WORKS-
-BE CAUTIOUS UNTIL AIP DATA PUBLISHED-
-ADVISE TWR INSTRUCTIONS-"

LTAAJ2458/26 (15 JUN 26)

TWY E1 CLSD TO TFC.
-ADZ TWR INSTRUCTIONS-

LTAAA2303/26 (02 JUN 26)

ANKARA ESENBOGA AD:
PLEASE ADD THE FOLLOWING INFORMATION UNDER THE HEADING 'CAT II/III
AND LVTO OPERATIONS' IN SECTION AD 2.22

RWY 03R LVTO HOLDING POSITION:
M1 TAXIWAY CAT II/III HOLDING POSITION:
400604.39N-0325918.62E

RWY 21L LVTO HOLDING POSITION:
M8 TAXIWAY CAT II/III HOLDING POSITION:
400741.73N-0330051.37E

REF AIP LTAC AD 2.22

LTAAA2300/26 (02 JUN 26)

"ANKARA ESENBOGA AERODROME
PLEASE ADD THE FOLLOWING INFORMATION UNDER THE HEADING 'DE-ICING
ANTI-ICING PROCEDURES' IN SECTION AD 2.20
'FOR THE ALTERNATIVE TAXIWAY CENTERLINE DESIGNATED AS THE 'BLUE
LINE' IN DE-ICING AREAS 1 AND 2, SEE AD 2 LTAC ADC.'

THE UPDATED AD 2 LTAC ADC HAS BEEN PUBLISHED ON THE FOLLOWING
WEBPAGE AND WILL BE INCORPORATED INTO THE AIP VIA AIRAC ON AUGUST 6,
2026.

[HTTPS://WWW.DHMI.GOV.TR/SAYFALAR/SSD/MAIN.ASPX](https://www.dhmi.gov.tr/sayfalar/ssd/main.aspx)

LTAAJ2045/26 (15 MAY 26)

"DE-ICING PRKG PSN LCA IN LINE WITH THE ACFT STANDS 101, 102 AND
103 DESIGNATED AS DE-1 AND DE-2, RENAMED AS DP-1 AND DP-2.
-BE CAUTIOUS UNTIL AIP DATA PUBLISHED-
-ADVISE TWR INSTRUCTIONS-"

LTAAJ2042/26 (15 MAY 26)

"TWY A SURFACE IS CONCRETE BTN COORDINATES 400815.27N0330031.10E
AND
400823.06N0330038.54E

PCN: 138 R/A/W/T, PCR: 1240 R/A/W/T
BE CAUTIOUS UNTIL AIP DATA PUBLISHED.
ADVISE TWR INSTRUCTIONS."

LTAAJ1753/26 (24 APR 26)

"DCL (DEPARTURE CLEARANCE) SYSTEM AVBL ON TEST. AIRCRAFT WITH THE
CAPABILITY SHALL TAKE ATC CLEARANCE FROM DCL SYSTEM, OTHERWISE MUST
CONTACT THE DELIVERY FREQ BROADCAST ON AUTOMATIC TERMINAL
INFORMATION SERVICE (ATIS) WITH THE REASON FOR 'REJECTION'."

LTAAJ1541/26 (08 APR 26)

"ANKARA ESENBOGA AD:

STAR-2 (RWY 21R/C),
STAR-8 (RWY 03R),
STAR-9 (RWY 21L),
IAC-1 (NDB Z RWY 03C),
IAC-7 (NDB Z RWY 03L),
IAC-23 (ILS Z CAT I OR LOC Z RWY 21L),
IAC-25 (ILS X CAT II RWY 03R),
IAC-26 (ILS Y CAT II RWY 21L),
IAC-27 (ILS W CAT I RWY 03R),

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 79/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

IAC-29 (ILS V CAT II RWY03R) PROCEDURES ARE SUSPENDED.

REF AIP AD 2 LTAC STAR-2, STAR-8, STAR-9, IAC-1, IAC-7, IAC-23,
IAC-25, IAC-26, IAC-27, IAC-29"
08 APR 26 07:15 UNTIL 08 JUL 26 07:08 ESTIMATED

LTBU / TEQ

LTAAB1557/26 (11 JUN 26)

"RWY 04/22 CLSD TO CIV IFR/VFR ALL TRAINING FLIGHTS, CIV VFR
GENERAL AVIATION FLIGHTS AND TRAINING ORGANIZATION FLIGHTS EXC STATE
ACFT, AMBULANCE, SAR, FIRE FIGHTING ACFT, PHOTOGRAPHY PURPOSE,
INTERNATIONAL DEP/ARR VFR TFCS AND BAYKAR ACFT.
DUE TO BAYKAR UAV ACTIVITIES
DATES AND TIMES:
MAY 04-08 11-15 18-22 25-29 0930-1400 1500-2359,
MAY 05-09 12-16 19-23 26-30 0000-0300,
JUN 01-05 08-12 15-19 22-26 29-30 0930-1400 1500-2359
JUN 02-06 09-13 16-20 23-27 30 0000-0300
JUL 01-03 06-10 13-17 20-24 27-31 0930-1400 1500-2359
JUL 01 04 07-11 14-18 21-25 28-31 0000-0300
AUG 01 0000-0300"

LTAAD0918/26 (11 JUN 26)

"RWY 04/22 CLSD TO CIV IFR/VFR ALL TRAINING FLIGHTS, CIV VFR
GENERAL AVIATION FLIGHTS AND TRAINING ORGANIZATION FLIGHTS EXC STATE
ACFT, AMBULANCE, SAR, FIRE FIGHTING ACFT, PHOTOGRAPHY PURPOSE,
INTERNATIONAL DEP/ARR VFR TFCS AND BAYKAR ACFT.
DUE TO BAYKAR UAV ACTIVITIES
DATES AND TIMES:
MAY 04-08 11-15 18-22 25-29 0930-1400 1500-2359,
MAY 05-09 12-16 19-23 26-30 0000-0300,
JUN 01-05 08-12 15-19 22-26 29-30 0930-1400 1500-2359
JUN 02-06 09-13 16-20 23-27 30 0000-0300
JUL 01-03 06-10 13-17 20-24 27-31 0930-1400 1500-2359
JUL 01 04 07-11 14-18 21-25 28-31 0000-0300
AUG 01 0000-0300"

LTAAB1332/26 (11 JUN 26)

"RWY 04/22 CLSD TO CIV IFR/VFR/IHA ALL TRAINING FLIGHTS, CIV VFR
GENERAL AVIATION FLIGHTS CLSD EXC STATE ACFT, AMBULANCE, SAR, FIRE
FIGHTING ACFT, PHOTOGRAPHY PURPOSE FLIGHTS AND BAYKAR ACFT FERRY
FLIGHT.
-DUE TO ELECTRICAL WORKS -

DATE AND TIMES

APR 07-10 13-17 20-24 27-30 0900-1030,
MAY 04-08 11-15 18 20-22 25-29 0900-1030,
JUN 01-05 08-12 15-19 22-26 29-30 0900-1030,
JUL 01-03 06-07 0900-1030"

LTAAD0771/26 (11 JUN 26)

ALL CIVIL AND MILITARY AIRCRAFT WITH 4 ENGINES THAT WILL ENTER
AND EXIT THE MILITARY APRON VIA TWY T4 AND TWY T5 ARE ADVISED TO
STOP THEIR EXTERNAL ENGINES DURING THE MANEUVERING
-DUE TO FOREIGN OBJECT DAMAGE-

LTAAD0769/26 (11 JUN 26)

LIQUID OXYGEN IS AVBL ON REQUEST 10 DAYS BEFORE THE FLIGHT.

LTAAD0770/26 (11 JUN 26)

AD OPERATING HOURS OF MILITARY UNITS AS FOLLOWS:
MON TUE WED THU FRI: 0530-1330
SATURDAY, SUNDAY, EXC OPERATION HOURS AND HOLIDAYS PPR 3 HOURS.

LTAAD0768/26 (11 JUN 26)

POSSIBILTY OF LIVE FOD (FOREIGN OBJECT DAMAGE) IN AD.

LTAAD0767/26 (11 JUN 26)

100/130 OCTANE FUEL NOT AVBL. IF NEEDED , TFC MUST CONTACT WITH
PETROL OFISI(+90 282 6824102) FOR 100/130 OCTANE FUEL AND PAYMENT
BEFORE THE FLIGHT.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 80/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

LTBR / YEI

LTAAB1571/26 (21 APR 26)

"PARKING POSITINS 11,12,13,14 CAN NOT BE USED AS ACCOMODATION.
-DUE TO PARK POSITION INADEQUACY."

LTAAD0667/26 (27 MAR 26)

MIL AD OPERATING HOURS AS FOLLOWS:
MON TUE WED THU FRI: 0520-1340
SAT SUN HOLIDAYS AND EXC OPERATING HOURS PPR 3 HOURS.

LTAAD0662/26 (27 MAR 26)

THERE COULD BE ALIVE FOREIGN OBJECT DUE TO LACK OF FENCE

LTBJ / ADB

LTAAD1482/26 (26 JUN 26)

MEN TACAN CH98X HOURS OF OPS/SERVICE:
OPERATIONAL HOURS: 0630-1430
SAT SUN AND HOLIDAYS PPR 2 HOURS.

*LTAAB2127/26 (22 MAY 26)

"TUE 2300-2359, WED 0000-0200"
RWY 16R/34L CLSD TO TAKE-OFF/LANDING TFC DUE TO CONST.
22 MAY 26 10:14 UNTIL 17 AUG 26 14:00 ESTIMATED

LTAAB2123/26 (22 MAY 26)

"DUE TO CONSTRUCTION WORKS ON RWY 16L/34R TRAFFICS SHALL USE
RWY 16R/34L FOR DEP/ARR:;
- THERE IS NO RAPID EXIT TWY ON RWY 16R/34L.
- TRAFFICS LANDING ON RWY 34L , THE LAST TWY EXITING TO RWY IS
TWY F, AND IN CASE OF MISSING EXIT FROM TWY F, ACFT SHALL BACKTRACK
THROUGH TWY P AT THR 16R, TRAFFICS SHALL COMPLY WITH TWR
INSTRUCTIONS AND EXIT RWY FROM TWY F OR APPROPRIATE TWY."
22 MAY 26 08:54 UNTIL 17 AUG 26 14:00 ESTIMATED

LTAAB2120/26 (22 MAY 26)

PRESENCE UNDECLARED CURVE MARKINGS AT THR 16R.
REF AIP LTBJ AD 2.20
22 MAY 26 08:46 UNTIL 17 AUG 26 14:00 ESTIMATED

LTAAB2121/26 (22 MAY 26)

"DURING THE CONST WORKS ON RWY 16L/34R, TRAFFICS SHALL USE
RWY 16R/34L FOR LANDING/DEPARTURE, TRAFFICS DEPARTING FROM
THR RWY 16R :

-BASED ON THE INTERSECTION DEPARTURE DISTANCE FOR TWY F DECLARED ON
REF:AIP LTBJ AD 2.13 DECLARED DISTANCES, TRAFFICS SHALL REQUEST
INTERSECTION DEPARTURE ACCORDING TO THE TECHNICAL DATA SPECIFIED BY
THE AIRLINES OR THE ACFT MANUFACTURERS WITH PERMISSION FROM THE
CONTROL TOWER

- TRAFFICS UNABLE TO MAKE INTERSECTION DEPARTURE DUE TO TECHNICAL OR
OPERATIONAL REASONS SHALL ENTER RWY 16R/34L FROM TWY F OR OTHER
APPROPRIATE TWYS IN ACCORDIANCE WITH CONTROL TWR AND TAXI TO THR 16R
AND GET DEPARTURE POSITION BY PERFORMING BACKTRACK USING THE MARKED
TURNING PAD AT THE THRESHOLD."
22 MAY 26 08:48 UNTIL 17 AUG 26 14:00 ESTIMATED

LTAAB2118/26 (22 MAY 26)

"DUE TO CONSTRUCTION WORKS ON RWY 16R/34L,
-WITH REF TO AIP TURKIYE AD2 LTBJ ADC EN AND AD 2 LTBJ 10 AD 2.20,
THE ENGINE TEST AREAS DESIGNATED AS THR 16R AND THR 34L SHALL NOT BE
USED FOR ENGINE TEST DURING THE PERIOD STATED ABOVE.
-ACFT SHALL CONDUCT ENGINE TESTS AT DE-ICING AREA LOCATED SOUTH OF
APRON 3, WITH NOSE FACING NORTH, UNDER FOLLOW-ME GUIDANCE AND ATC
INSTRUCTIONS.
-ACFT REQUESTING ENGINE RUNS SHALL CONSIDER AD PEAK TFC HOURS.
ENGINE RUNS SHALL NOT BE COMMENCED AND WITHOUT PRIOR COORDINATION
AND APPROVAL FROM RELEVANT UNITS. ACFT SHALL MAINTAIN CONTINUOUS COM
CONTACT WITH ATC MANDATORY."
22 MAY 26 08:36 UNTIL 17 AUG 26 14:00 ESTIMATED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 81/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

LTAAB2117/26 (22 MAY 26)

"TWYS J, K, L, M, N AND TWY P CLSD TO TFC.
DUE TO CONST ON RWY 16L/34R-"
22 MAY 26 08:31 UNTIL 17 AUG 26 14:00 ESTIMATED

*LTAAB2116/26 (22 MAY 26)

"RWY 16L/34R CLSD TO TAKE-OFF/LANDING TFC DUE TO CONST WORKS.

NOTE1: RWY 16L/34R BTN TWY P AND TWY H CLSD TO TAXIING.
NOTE2: THR 34R AND TWYS H-R LINE OPN TO TAXIING FOR TFC CROSSING TO
MILITARY SIDE.

DURING THE DATES AND TIMES SPECIFIED UNDER REF AIP LTBJ AD 2.12
RUNWAY PHYSICAL CHARACTERISTICS, REMARK 14 RWY 16R/34L SHALL BE USED
FOR TAKE-OFF/LANDING TFC."
22 MAY 26 08:27 UNTIL 17 AUG 26 14:00 ESTIMATED

LTAAB2109/26 (22 MAY 26)

ILS IIMR RWY 16L U/S
-DUE TO MAINT.-

LTAAB2108/26 (22 MAY 26)

ILS IMEN RWY 34R U/S
DUE TO MAINT.

LTAAB1959/26 (12 MAY 26)

"FUEL AVBL WITH FUEL TRUCKS BTN PARKING AREAS 43-68 AT APRON 3.
FUEL USING WITH HYDRANT SYSTEM AT PARKING AREAS 35,36,37,38,39,40,41
AND 42 AVBL ONLY FROM THE RIGHT WING."

LTAAD1022/26 (04 MAY 26)

TRANSITIONS FROM MAIN AND EMERGENCY RUNWAY TO MILITARY AREA SHALL
BE MADE ONLY FROM TWY R.
04 MAY 26 07:44 UNTIL 04 AUG 26 05:43 ESTIMATED

LBSF / SOF

LBSFA0731/26 (27 JUN 26)

RWY 09 MARKINGS:
- SOUTH EDGE LINE REDUCED WIDTH TILL 11TH EDGE LIGHT
- THR MARKINGS WIDTH REDUCED BY 35 PERCENT
- THR NUMBER MARKINGS SIZE REDUCED BY 70 PERCENT
- THE ARROWS FROM THE MARKINGS ON RWY 09 HAVE BEEN REMOVED
DUE TO WIP.

LBSFA0721/26 (25 JUN 26)

RWY 27 THR MARKINGS WIDTH REDUCED BY 50 PERCENT
DUE TO WIP.

LBSFA0722/26 (25 JUN 26)

RWY 09 CENTERLINE REDUCED WIDTH FROM 1ST TO 60TH EDGE LIGHT.

LBSFA0562/26 (31 MAY 26)

DE-ICING PAD LIMA CLSD DUE TO OPR REASONS.

LBSFA0561/26 (31 MAY 26)

TWY L CLSD BTN L1 AND L2 DUE TO OPR REASONS.

LBSFA0518/26 (18 MAY 26)

RNP RWY 27:
LPV 3.0 PERCENT MINIMA SUSPENDED.
LPV 2.5 PERCENT OCA (OCH) MINIMA FOR CAT A INCREASED TO 2360 (615).
REF LBSF AD 2-57.15 IAC RNP RWY 27.

LBSFA0504/26 (14 MAY 26)

"RNP RWY 09,
LPV 3.0 PERCENT OCA (OCH) MINIMA INCREASED AS FLW:
CAT A 2100 (361)
CAT B 2110 (371)
CAT C 2120 (381)
CAT D 2130 (391)
REF LBSF AD 2-57.5 IAC RNP RWY 09."

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 82/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

*LBSFA0408/26 (27 APR 26)

AD DOES NOT ACCEPT DIVERTED FLT AND IS NOT AVBL AS ALTN AD
DUE TO REDUCED CAPACITY OF APN.
27 APR 26 07:34 UNTIL 30 JUN 26 17:00 ESTIMATED

LBSFA0357/26 (10 APR 26)

TWY R CLSD DUE TO OPR REASONS.

LBSFA0342/26 (06 APR 26)

ACFT STAND 14 USABLE OBLIGATORY WITH A MARSHALLER.

LHBP / BUD

LHBPA4191/26 (26 JUN 26)

COMPASS CHECK POINT CLOSED DUE TO AIRCRAFT PARKING.
COMPASS CHECKS CAN BE MANAGED AT B5 HOLDING BAY.

LHBPA4048/26 (19 JUN 26)

TWY GB CLSD DUE TO MAINT.

LHBPA3951/26 (16 JUN 26)

THE PCN VALUE OF CONC PORTION OF TAXILANE G BEHIND STAND
R115-R117
CHANGED TO 106 R/A/W/T. REF AIP LHBP AD 2.8.

LHBPA3950/26 (16 JUN 26)

THE PCN VALUE OF ASPH PORTION OF TAXILANE G BEHIND STAND
R111-R114
CHANGED TO 51 R/B/W/T. REF AIP LHBP AD 2.8.

LHBPA2663/26 (30 APR 26)

THE COORDINATES OF PSN R280 IS 472600.01N 0191559.42E.
REFERRING TO NON-AIRAC AIP SUP 004/2026.

LHBPA2662/26 (30 APR 26)

THE COORDINATES OF PSN 45A IS 472604.25N 0191549.82E.
REFERRING TO NON-AIRAC AIP SUP 004/2026.

LHBPA2634/26 (30 APR 26)

"DEPARTURE PLANNING INFORMATION MSG (A-DPI AND C-DPI) PROVIDED TO
EUROCONTROL NETWORK MANAGER OPERATIONS CENTER (NMOC).
1.1. ADS-B DATA REQUIRED.
1.1.1. FOR ADS-B DATA USED BY THE AD OPERATOR AND EUROCONTROL,
PILOTS OF AIRCRAFT EQUIPPED WITH MODE S AND ADS-B FUNCTIONALITY MUST
BE USED, WHEN OPERATING ON THE GROUND:
A) SELECT AUTOMATIC MODE AND THE ASSIGNED MODE A, OR
B) IF AUTOMATIC MODE IS NOT AVAILABLE, SELECT ON AND THE ASSIGNED
MODE A
- FROM THE REQUEST OF PUSH-BACK.
- AFTER LANDING, UNTIL THE AIRCRAFT HAS STOPPED ON STAND.
- WHEN THE AIRCRAFT IS FULLY PARKED, THE PILOT SHALL SELECT STAND
BY.1.1.2. WHEN THE AIRCRAFT IS CAPABLE OF COMMUNICATING ITS
IDENTIFICATION (I.E. THE CALLSIGN USED IN FLIGHT), THIS MUST BE
ENTERED (VIA THE FMS OR TRANSPONDER CONTROL PANEL) AT THE TIME OF
THE PUSH-BACK REQUEST.
1.1.3. THE CREW MUST USE THE FORMAT DEFINED BY ICAO TO ENTER THE
AIRCRAFT IDENTIFICATION.
1.1.4. IN ORDER NOT TO COMPROMISE THE PERFORMANCE OF SYSTEMS BASED
ON SSR FREQUENCIES (INCLUDING AIRBORNE TCAS AND SSR RADARS),
TCAS SHOULD NOT BE SELECTED BEFORE RECEIVING CLEARANCE TO LINE UP,
AND SHOULD BE DESELECTED AFTER VACATING THE RUNWAY.)"
04 MAY 26 08:00 UNTIL 04 AUG 26 23:59 ESTIMATED

LROP / OTP

LRBBA3549/26 (26 JUN 26)

"ACFT STANDS 201-203 AVBL FOR MIL ACFT ONLY. MARSHALLING, PARKING
AND ACFT MANOEUVERING TO BE CARRIED OUT BY MIL PERSONNEL"

LRBBA3400/26 (19 JUN 26)

ON LROP THE FOLLOWING TIMES ARE CURRENTLY CONSIDERED AS
RUSH HOURS:

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 83/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

0300-0600 / 0900-1200 / 1500-1800.
EXPECT RAMP CONGESTION AND DELAY.

LRBBA3267/26 (13 JUN 26)

BACKTRACK ON RWY 08R/26L IS PERMITTED ONLY AT 26L THR TURN PAD

LRBBA3002/26 (31 MAY 26)

DVOR/DME STJ 113.200MHZ/CH 79X U/S
31 MAY 26 14:29 UNTIL 30 JUN 26 23:00 ESTIMATED

LRBBA2970/26 (29 MAY 26)

TWY G CL LGTS LEAD IN/LEAD OUT TO/FROM RWY 08R U/S

*LRBBA2701/26 (19 MAY 26)

EVERY THU 0600-0800
RWY 08R/26L CLSD

LRBBA2416/26 (08 MAY 26)

"ADVANCED TWR PROCEDURES IN FORCE:
DUE TO THE INFORMATION EXCHANGE FOR DEPARTURE FLIGHTS USING
EUROPEAN STANDARD FOR A-CDM AIRPORTS, LROP WILL SEND A-DPI
MESSAGES TO NMOC REPORTING TTOT IN ORDER TO IMPROVE TAKE-OFF
TIME ESTIMATES. THE FPL OF ACFT THAT FOR ANY REASON RETURNS TO
STAND AFTER EOBT WILL BE SUSPENDED IN THE ATM NETWORK WITH A
C-DPI MESSAGE. THE AIRCRAFT OPERATOR WILL RECIEVE A FLS MESSAGE
WITH REASON-SUSPENDED BY DEPARTURE AIRPORT- TO REVOKE THE
SUSPENSION, OPERATORS SHALL UPDATE EOBT WITH A DLA OR CHG
MESSAGE.

ACRONYMS:
A-CDM (AIRPORT COLLABORATIVE DECISION MAKING)
A-DPI (ATC DEPARTUR PLANNING INFORMATION)
ATFCM (AIR TRAFFIC FLOW CAPACITY MANAGEMENT)
C-DPI (CANCEL DEPARTURE PLANNING INFORMATION)
FLS (FLIGHT SUSPENSION)
NMOC (NETWORK MANAGER OPERATIONS CENTER)
TTOT (TARGET TAKE-OFF TIME)."
11 MAY 26 00:00 UNTIL 10 AUG 26 23:59 ESTIMATED

LRBBA2376/26 (07 MAY 26)

"SAFEGATE STANDS 103, 104, 107, 110,113 AND 114 U/S"

LRBBA2275/26 (02 MAY 26)

"DUE TO RESTRICTED AIRPORT CAPACITY, PRIOR PERMISSION REQUIRED
(PPR)

FROM AD OPERATOR IS MANDATORY FOR ALL NON-SCHEDULED FLIGHTS"

LRBBA2227/26 (29 APR 26)

NO ACFT PARKING POSITIONS AVBL BTN 1800-0500 FOR ALL NONSCHEDULED
FLIGHTS/DIVERTED FLIGHTS EXCEPT STATE/MIL ACFT AND
ACFT PARKED ON APRON 3 GENERAL AVIATION TERMINAL

LRBBA2225/26 (29 APR 26)

"DUE TO LIMITED PARKING STANDS AVBL, NONSCHEDULED FLIGHTS,
NONSCHEDULED CARGO FLIGHTS, NONSCHEDULED CARGO FLIGHTS CARRYING
MIL ARMY/MUNITIONS, WITHOUT PPR FM AD ADMINISTRATION WITH MIN 72
HR AT E-MAIL 'OPS AT CNAB.RO', NO PRKG STAND WILL BE ALLOCATED
AND NO HANDLING WILL BE PERMITTED.
EXCEPT STATE/MIL ACFT AND ACFT PARKED ON APRON 3
GENERAL AVIATION TERMINAL"

LRBBA2226/26 (29 APR 26)

"DUE TO LIMITED PARKING STANDS AVBL FOR NONSCHEDULED FLIGHTS,
BFR FILLING A FLT PLAN WITH LROP AS A DESTINATION/ALTERNATE,
MIN 72 HR PPR MUST BE OBTAINED FM AD ADMINISTRATION AT E-MAIL
'OPS AT CNAB.RO', EXCEPT STATE/MIL ACFT AND ACFT PARKED ON APRON 3
GENERAL AVIATION TERMINAL"

LRBBA2027/26 (19 APR 26)

TWY C1 CLSD ABEAM STANDS 204-206

LRBBA2026/26 (19 APR 26)

"ACFT STANDS 204, 205 AND 206 EXIT ONLY WITH PUSHBACK DUE TO
TWY C1 CLSD ABEAM STANDS 204-206 FOR ACFT STORAGE FACILITY."

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 84/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

LRBBA1898/26 (09 APR 26)

ACFT WITH WINGSPAN GREATER THAN 65M ARE NOT ALLOWED TO OPERATE
WITHOUT A SIGNED AGREEMENT BETWEEN AIRLINE AND AIRPORT AUTHORITY

LRBBA1818/26 (06 APR 26)

"GROUND STAY MORE THAN 3 HOURS FOR ALL NONSCHEDULED FLIGHTS
IS NOT PERMITTED. NO PARKING SPACE AVBL FOR LONG TERM PARKING,
NO ACFT STORAGE AVBL. EXCEPT STATE/MIL ACFT AND ACFT PARKED ON
APRON 3 GENERAL AVIATION TERMINAL."

LYBE / BEG

*LYBBA3245/26 (22 JUN 26)

28 JUN 2026 05:00-28 JUN 2026 17:00
AD FIRE AND RESCUE CAT UPGRADED TO 9.

*LYBBA3229/26 (20 JUN 26)

27 JUN 2026 05:00-27 JUN 2026 17:00
AD FIRE AND RESCUE CAT UPGRADED TO 9.

LYBBA3154/26 (17 JUN 26)

"DEPARTURE PLANNING INFORMATION MSG (A-DPI AND C-DPI)
PROVIDED TO NETWORK MANAGER OPERATIONS CENTER (NMOC).
1.1. ADS-B DATA REQUIRED
1.1.1. FOR ADS-B DATA USED BY THE AD OPERATOR AND EUROCONTROL,
PILOTS OF AIRCRAFT EQUIPPED WITH MODE S AND ADS-B FUNCTIONALITY
MUST, WHEN OPERATING ON THE GROUND:
A) SELECT AUTOMATIC MODE AND THE ASSIGNED MODE A, OR
B) IF AUTOMATIC MODE IS NOT AVAILABLE, SELECT ON AND THE ASSIGNED
MODE A
- FROM THE REQUEST OF PUSH-BACK.
- AFTER LANDING, UNTIL THE AIRCRAFT HAS STOPPED ON HIS STAND.
- WHEN THE AIRCRAFT IS FULLY PARKED, THE PILOT SHALL SELECT STBY.
1.1.2. WHEN THE AIRCRAFT IS CAPABLE OF COMMUNICATING ITS
IDENTIFICATION (I.E. THE CALLSIGN USED IN FLIGHT), THIS MUST BE
ENTERED (VIA THE FMS OR TRANSPONDER CONTROL PANEL) AT THE TIME OF
THE PUSH-BACK REQUEST.
1.1.3. THE CREW MUST USE THE FORMAT DEFINED BY ICAO TO ENTER THE
AIRCRAFT IDENTIFICATION.
1.1.4. IN ORDER NOT TO COMPROMISE THE PERFORMANCE OF SYSTEMS BASED
ON SSR FREQUENCIES (INCLUDING AIRBORNE TCAS AND SSR RADARS), TCAS
SHOULD NOT BE SELECTED BEFORE RECEIVING CLEARANCE TO LINE UP, AND
SHOULD BE DESELECTED AFTER VACATING THE RUNWAY.
REF AIP, AD 2 LYBE 1.1, LYBE AD 2.22, ITEM 4.2"

LYBBA2937/26 (06 JUN 26)

"MAXIMUM TURN AROUND TIME/PARKING TIME FOR ALL AD-HOC FLIGHTS:
COMMERCIAL, CARGO, TECHNICAL AND GENERAL AVIATION FLIGHTS
LIMITED TO 2 HOURS."

LYBBA1778/26 (26 APR 26)

PART OF TWY T BTN ACFT STAND C14 AND SB T1 LTD TO ACFT WITH MAX
WING SPAN UP TO 36M.
11 APR 26 09:19 UNTIL 01 JUL 26 21:59 ESTIMATED

LYBBA1776/26 (11 APR 26)

ACFT STAND C6 LTD TO ACFT WITH MAX WINGSPAN UP TO 28.72M.
11 APR 26 09:18 UNTIL 01 JUL 26 21:59 ESTIMATED

LYBBA1777/26 (11 APR 26)

VISUAL DOCKING GUIDANCE SYSTEM ON ACFT STAND C14 U/S.
FOLLOW ONLY MARSHALLER INSTRUCTIONS.
11 APR 26 09:18 UNTIL 01 JUL 26 21:59 ESTIMATED

LDZA / ZAG

LDZAA2160/26 (27 JUN 26)

REF AIRAC AIP SUP 01/26 - LDZA - ZAGREB/FRANJO TUDJMAN AIRPORT -
TEMPORARY SHORTENING OF RWY04/22 AND CLOSURE OF TWY A AND TWY B
DUE TO CONCRETE PAVEMENT REHABILITATION WORKS.
INFO PUBLISHED IN AIRAC AIP SUP 01/26 NO LONGER IN FORCE.
WORK COMPLETED. SUP CNL.

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 85/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

LDZAA2068/26 (27 JUN 26)

LDZA RNP RWY04
- LNAV A/B/C/D:
CHANGE OCA/H TO 750 (397) INSTEAD OF 720 (367)
- LNAV/VNAV:
CHANGE OCA/H AS FLW:
CAT A - 626 (273) INSTEAD OF 610 (257) FT
CAT B - 636 (283) INSTEAD OF 610 (257) FT
CAT C - 646 (293) INSTEAD OF 610 (257) FT
CAT D - 656 (303) INSTEAD OF 620 (267) FT
- LPV:
CHANGE OCA/H AS FLW:
CAT A - 626 (273) INSTEAD OF 610 (257) FT
CAT B - 636 (283) INSTEAD OF 610 (257) FT
CAT C - 646 (293) INSTEAD OF 610 (257) FT
CAT D - 656 (303) INSTEAD OF 620 (267) FT
REF AIP CHART:
LDZA AD 2.24.12 IAC RNP RWY04
13 JUN 26 04:00 UNTIL 13 SEP 26 22:00 ESTIMATED

*LDZAA0763/26 (14 MAR 26)

"FIREFIGHTING AND RESCUE CAT CHANGED AS FLW:
- CAT 7 AVBL H24
- CAT 8 AND 9 ALIGNED WITH CURRENT/APPROVED FLIGHT SCHEDULE AS
NEEDED OR ON REQUEST IN WRITTEN FORM NOT LATER THAN 24HR BEFORE
THE ACFT OPERATION, E-MAIL: KOORDINATORI(AT)ZAG.AERO
SEE LDZA AD 2.20.4
REF AIP LDZA AD 2-3, ITEM AD 2.6"

LOWW / VIE

LOWWA1553/26 (24 JUN 26)

REF AIP LOWW AD 2 MAP 2-1
PRKG PSN E42 DIMENSION CHANGE
NEW MAX WINGSPAN 35.99M
NEW MAX LENGTH 52.00M
PRKG PSN E43 DIMENSION CHANGE
NEW MAX LENGTH 53.00M
PRKG PSN E44 DIMENSION CHANGE
NEW MAX LENGTH 53.00M
PRKG PSN E45 DIMENSION CHANGE
NEW MAX LENGTH 53.00M

LOWWA1295/26 (06 JUN 26)

"REF AIP AUSTRIA LOWW AD 2.14
RWY 16 PALS (ICAO-STANDARD, CAT II/III), WITH LED FLG LGT, ADJUSTABLE
IN 5 STAGES, CARRIED OUT IN LED"

LOWWA1111/26 (06 JUN 26)

"LPV MINIMA SHALL BE RAISED TO THE RESPECTIVE LNAV/VNAV MINIMA.
RNP RWY 11, REF AIP AUSTRIA, LOWW AD 2 MAP 13-2-1
RNP RWY 29, REF AIP AUSTRIA, LOWW AD 2 MAP 13-2-2
RNP Z RWY 16, REF AIP AUSTRIA, LOWW AD 2 MAP 13-2-3
RNP RWY 34, REF AIP AUSTRIA, LOWW AD 2 MAP 13-2-4
NOTE: DUE TO ICAO ELECTRONIC BULLETIN 2026/13"
13 MAY 26 14:02 UNTIL 05 AUG 26 23:59 ESTIMATED

LOWWA0941/26 (06 JUN 26)

"REF AIP AUSTRIA, LOWW AD 2.22, ITEM 2.2
THE FOLLOWING TIMES ARE CURRENTLY CONSIDERED IN LOWW AS ARRIVAL RUSH
HOURS: 0600-0700 UTC, 0900-1030 UTC, 1330-1500 UTC"

LZIB / BTS

LZIBA1280/26 (16 JUN 26)

"CIVIL FLIGHTS OF UNMANNED AIRCRAFT PROHIBITED IN STEFANIK CTR:
CIRCLE RADIUS 3KM CENTRED ON 481012N 0171246E (ARP OF BRATISLAVA
M. R. STEFANIK AIRPORT) FROM GND TO 500M AGL.
DETAILS AVAILABLE ON [HTTPS://WWW.MINDOP.SK/CIVILNE-LETECTVO/GEOZONY](https://www.mindop.sk/civilne-letectvo/geozony)
(TYPE IN SMALL LETTERS).
PENETRATION IS ALLOWED FOR HUMAN LIFE RESCUE FLIGHTS, AIR AMBULANCE
FLIGHTS AND SAR FLIGHTS."
16 JUN 26 08:00 UNTIL 16 SEP 26 22:00 ESTIMATED

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 86/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

LZIBA1252/26 (12 JUN 26)

0900-SS

"LEVEL CONSTRAINTS LZIB RNAV 1 STAR RWY 22 NIT 2U, TABIN 2U AND LZIB RNAV 1 STAR RWY 31 NIT 2M, TABIN 2M FOR WPT IB641, IB651 CHANGED FROM 5500FT AMSL OR ABOVE TO 9000FT AMSL OR ABOVE DUE TO ACTIVATION OF INOVEC AREA DEDICATED TO GLIDER FLIGHTS."

LZIBA1199/26 (06 JUN 26)

0500-1700

"OCA (OCH) CHANGED FOR SPECIFIED IAP AS FOLLOWS:
- ILS Y CAT I RWY 31 ASC 4,0 PERCENT STRAIGHT-IN APPROACH:
ACFT CAT A: 635FT (201FT), ACFT CAT B: 647FT (213FT),
ACFT CAT C: 655FT (221FT), ACFT CAT D: 666FT (232FT).
- ILS Y CAT II RWY 31 ASC 4,0 PERCENT STRAIGHT-IN APPROACH:
ACFT CAT A: 547FT (113FT), ACFT CAT B: 564FT (130FT),
ACFT CAT C: 576FT (142FT), ACFT CAT D: 590FT (156FT).
REF NOTAM A1198/26."

LZIBA1052/26 (06 JUN 26)

"LPV MINIMA SHALL BE RAISED TO THE RESPECTIVE LNAV/VNAV MINIMA.
RNP RWY 22 ASC 2,5 PERCENT, REF PAGE AD 2-LZIB-7-5,
RNP RWY 31 ASC 2,5 PERCENT, REF PAGE AD 2-LZIB-7-17,
RNP RWY 31 ASC 4,0 PERCENT, REF PAGE AD 2-LZIB-7-17.
IN ACCORDANCE WITH ICAO ELECTRONIC BULLETIN 2026/13."
21 MAY 26 14:23 UNTIL 21 AUG 26 23:59 ESTIMATED

LZIBA0808/26 (06 JUN 26)

MM RWY 22 ID DOT/DASH 75 MHZ U/S.
24 APR 26 10:14 UNTIL 24 JUL 26 23:59 ESTIMATED

LKPR / PRG

LKPRA0890/26 (22 JUN 26)

VDGS ON STAND 20 U/S.

LKPRA0859/26 (15 JUN 26)

SS-SR

TWY J BLUE BTN TWY H AND STAND 17 CLSD.
POSITION PUSH 3 AND 4 ON TWY J BLUE CLSD.

LKPRA0649/26 (20 MAY 26)

STAND 17 - VDGS U/S.

*LKPRA0407/26 (12 APR 26)

"RWY 06/24 CLSD, REF AIP SUP 1/26 , VFR SUP 1/26"

LKPRA0376/26 (02 APR 26)

TWY T - CENTRE LINE LIGHTS U/S.
02 APR 26 11:59 UNTIL 02 JUL 26 16:00 ESTIMATED

LKPRA0362/26 (31 MAR 26)

STAND 22A - VDGS U/S.
31 MAR 26 06:09 UNTIL 30 JUN 26 22:00 ESTIMATED

LKPRA0273/26 (10 MAR 26)

REF AIP AD 2.22.5 ATS SURVEILLANCE SERVICES AND PROCEDURES.
CNL ITEM 2.22.5.2

LKPRA0121/26 (04 FEB 26)

"AIRPORT OPERATIONS PLAN (AOP) INTEGRATION WITH NETWORK OPERATIONS THROUGH PREDICTED DEPARTURE PLANNING INFORMATION (P-DPI) AND GENERAL ARRIVAL PLANNING INFORMATION (G-API) MESSAGES SENT TO NETWORK MANAGEMENT OPERATIONS CENTER (NMOC) IN ADDITION TO AIRPORT COLLABORATIVE DECISION MAKING (A-CDM), USED FOR AIR TRAFFIC FLOW MANAGEMENT (ATFM) PURPOSES. AIP WILL BE AMENDED ACCORDINGLY."

EPWA / WAW

EPWWA1700/26 (19 JUN 26)

POLISH AIR NAVIGATION SERVICES AGENCY PUBLISHES ON WEBSITE PANSA.PL/RCO/ INFORMATION ABOUT MEAN REAL ARRIVAL DISTANCES TO EPWA AIRPORT FOR EACH STAR PROCEDURE. THE DATA CAN BE USED AS A REFERENCE

FLIGHT DISTANCE FOR FUEL PLANNING.

EPWWA1617/26 (12 JUN 26)

"TWY E4, TWY E3, TWY N3 AND SEGMENT OF TWY E2 BTN TWY R AND TWY E4
AVBL FOR ACFT WITH WINGSPAN BELOW 36M."
12 JUN 26 11:38 UNTIL 11 SEP 26 23:59 ESTIMATED

EPWWA1409/26 (28 MAY 26)

REF AIP IFR AD 2 EPWA 1-50 - CHANGE OF INFORMATION IN POINTS:
SHOULD BE:
7.1.2.1. LVP OPERATIONS WILL BE COMMENCED WHEN RVR TDZ ARR RWY FALLS
BELOW 800M AND/OR ANY OF THE RVR FALLS BELOW 550 M AND/OR THE CLOUD
CEILING FALLS TO OR BELOW 300 FT.
7.1.2.2. LVP WILL BE TERMINATED WHEN RVR TDZ ARR RWY INCREASE TO
800M OR MORE AND/OR ALL OF THE RVR INCREASE TO 550 M OR MORE AND THE
CLOUD CEILING REACHES 300 FT OR MORE AND A CONTINUING IMPROVEMENT IS
ANTICIPATED.
INSTEAD OF:
7.1.2.1. LVP OPERATIONS WILL BE COMMENCED WHEN ANY OF THE RVR FALLS
BELOW 550 M AND/OR THE CLOUD CEILING FALLS BELOW 200 FT.
7.1.2.2. LVP WILL BE TERMINATED WHEN ALL OF THE RVR INCREASE OVER
550 M AND THE CLOUD CEILING REACHES 200 FT OR MORE AND A CONTINUING
IMPROVEMENT IS ANTICIPATED.
28 MAY 26 09:38 UNTIL 28 AUG 26 23:59 ESTIMATED

EDDS / STR

EDDZA3325/26 (27 JUN 26)

28 JUN 2026 21:00-01 JUL 2026 14:00
RWY 07: EXP TKOF FM INT I AND ADVISE TWR UPON INITIAL CTC IF
UNABLE TO COMPLY.

EDDZA3326/26 (27 JUN 26)

28 JUN 2026 21:00-01 JUL 2026 14:00
TWY I CLSD TO ICAO CODE LETTERS D-F BTN TWY S AND RWY 07/25.

EDDZA3324/26 (27 JUN 26)

28 JUN 2026 21:00-01 JUL 2026 14:00
TWY K CLSD BTN TWY S AND RWY 07/25.

*EDDZA3239/26 (23 JUN 26)

28 JUN 2026 22:30-29 JUN 2026 03:30
RWY 07/25 CLSD.

EDDZA1725/26 (07 JUN 26)

"SID CHANGED DUE TO NAVAID COVERAGE OF LBU VOR/DME:
ROTWE 5B: ADD RMK: CLIMB WITH 4.5 PCT (275 FT/NM) UNTIL PASSING 5000.
AFTER PASSING 5000 BRNAV EQPT NECESSARY.
GPS/FMS RNAV OVERLAYS REMAIN UNCHANGED.
REF AIP AD 2 EDDS 5-7-2 EFF 28 NOV 2024, 5-7-3 DATED 10 JUL 2025."
08 APR 26 12:50 UNTIL 08 JUL 26 13:00 ESTIMATED

EDDZA1597/26 (07 JUN 26)

"LUBURG VOR/DME LBU 109.20MHZ/CH29X, VOR PART USABLE ONLY UP TO
29NM ON R277."

EDDZA1595/26 (07 JUN 26)

MISSED APCH PROC CHANGED DUE TO COVERAGE OF STG DVOR/DME:
ILS OR LOC AND VOR RWY 25: DISREGARD R277 STG. USE R223 LBU ONLY.
REF AIP AD2 EDDS 4-2-1 AND 4-3-1 BOTH DATED 10 JUL 2025.

EDDZA3608/22 (09 NOV 23)

"KARLSRUHE DVOR/DME KRH 115.95/CH106Y DME NOT USABLE:

IN SECTOR 68DEG TO 315DEG CW
0 NM - 10 NM BELOW 4000 FT MSL,
10 NM - 20 NM BELOW 7200 FT MSL,
20 NM - 30 NM BELOW 10600 FT MSL,
30 NM - 40 NM BELOW 14000 FT MSL,
40 NM - 50 NM BELOW 17700 FT MSL,
50NM - 60 NM BELOW 21400 FT MSL,

IN SECTOR 315DEG TO 68DEG CW
0 NM - 10 NM BELOW 2000 FT MSL,
10 NM - 20 NM BELOW 3300 FT MSL,

Official Pilot Briefing

THA934 27JUN26 HSTWD B789 VTBS 1705 EBBR 0515+

Page 88/90
Trans ID: 5040609
Creation Time: 27.06.2026 12:51UTC

20 NM - 30 NM BELOW 4700 FT MSL,
30 NM - 40 NM BELOW 6200 FT MSL."

EDDM / MUC

EDDZA3279/26 (25 JUN 26)

TWY R ABM ACFT STAND 701 TO 703 LIMITED TO ACFT MAX ICAO CODE
LETTER E.

EDDZA3230/26 (23 JUN 26)

28 JUN 2026 20:00-14 AUG 2026 04:00
TWY A14 CLSD. TWY M CLSD BTN TWY A13 AND TWY A15.

EDDZA3226/26 (22 JUN 26)

"INCREASED RISK OF PITOT TUBE CONTAMINATION DUE TO INSECT
ACTIVITIES. TAKE APPROPRIATE MEASURES, ESPECIALLY FOR LONGER GROUND
TIMES."

EDDZA3102/26 (16 JUN 26)

TWY N3 CLSD.

EDDZA2968/26 (08 JUN 26)

ILS RWY 26L U/S.
08 JUN 26 07:00 UNTIL 31 AUG 26 23:59 ESTIMATED

EDDZA2802/26 (29 MAY 26)

RWY 26L WIP WI LOC AND GP SAFETY ZONES.

EDDZA2752/26 (28 MAY 26)

TXL E2 CLSD BTN ACFT STAND 254 AND 256.

EDDZA2753/26 (28 MAY 26)

TXL CENTER2 LTD TO ACFT ICAO CODE LETTER C BTN ACFT STAND 254 AND
256.

EDDZA2517/26 (19 MAY 26)

CHANGES TO APCH DUE TO RENEWAL OF ILS RWY 26L (IMSW):
RWY 26L: ILS AND LOC APCH TEMPO SUSPENDED.
RNP APPROACH AVAILABLE ONLY.
DURING PARALLEL OPERATIONS (ANOUNCED ON ATIS) LNAV NOT AUTHORIZED
LNAV/VNAV OR LPV TO BE USED ONLY. IF UNABLE INFORM ATC ON INITIAL
CONTACT.

EDDZA2502/26 (19 MAY 26)

"LPV APCH REOP. OCA(H) VALUES RAISED AS FOLLOWS:
LPV RWY08L: A 1748 (317), B 1793 (326), C 1802 (335), D 1868 (401)FT.
LPV RWY08R: A 1909 (423), B 1917 (431), C 1925 (439), D 1934 (448)FT.
LPV RWY26L: A 1785 (315), B 1794 (324), C 1803 (333), D 1888 (418)FT.
LPV RWY26R: A 1908 (459), B 1917 (468), C 1925 (476), D 1933 (484)FT.
DUE TO INADEQUATE PROTECTION PROVIDED IN THE MISSED APPROACH SEGMENT
FOR SOME NAVIGATION SYSTEMS AUTHORISED FOR LPV OPERATIONS."
19 MAY 26 07:48 UNTIL 18 AUG 26 23:59 ESTIMATED

EDDZA2401/26 (14 MAY 26)

TWY D5 CLSD.

EDDZA2235/26 (06 MAY 26)

"THE FLW CHANGES OCCUR TO ALL MISSED APCH PROC RWY 08R DUE TO
AIRSPACE STRUCTURE:
CLIMB WITH 3.8 PERCENT (231FT/NM) UNTIL PASSING 2800. IF UNABLE
ADVICE MUNICH RADAR DURING INTIAL CONTACT. CHANGES ARE PERMANENT.
REF AIP AD2 EDDM 4-2-2 AND 4-4-2 EFF BOTH 28 NOV 2024, 4-6-5 DATED
02 OCT 2025."
12 MAY 26 00:00 UNTIL 12 AUG 26 23:59 ESTIMATED

EDDZA6255/25 (28 JAN 26)

"CHANGES TO SID DUE TO COVERAGE OF WLD DVOR/DME: RWY 26R: GIVMI 1N:
AMEND ON HEADING 299 DEG TO INTERCEPT R119 WLD, ON R119 WLD TO READ
ON TRACK 299 DEG. CLIMB WITH 4.9 PER CENT (300 FT/NM) UNTIL PASSING
3700. AFTER PASSING 3700 BRNAV EQUIPMENT NECESSARY. REF AIP AD 2
EDDM 5-7-37 EFF 23 MAY 2019, 5-7-41 DATED 02 OCT 2025."

EDDZA6227/25 (28 JAN 26)

"MUENCHEN ILS DME (IMNE) CH32X/109.5MHZ ASSOCIATED WITH ILS RWY 08L LOC COVERAGE UP TO 17NM IN SECTOR 33DEG (LEFT) TO 35DEG (RIGHT) IN RELATION TO RCL AND DISTANCE TO LOC, MNM INTERCEPTION ALT IN THIS AREA 3500FT AMSL."

EDDL / DUS

EDDZA3319/26 (26 JUN 26)

"GERMINGHAUSEN DVOR/DME GMH 115.40MHZ/CH101X, VOR PART OUT OF SERVICE."

EDDZA3289/26 (25 JUN 26)

FUEL 100 LL NOT AVBL.
25 JUN 26 11:46 UNTIL 24 SEP 26 22:59 ESTIMATED

EDDZA3288/26 (25 JUN 26)

STEEL PLATE ON TWY P4 BEHIND STANDS C04 AND C05.
25 JUN 26 11:25 UNTIL 30 JUL 26 21:00 ESTIMATED

EDDZA3207/26 (22 JUN 26)

TWY K1 CLSD.

*EDDZA3164/26 (19 JUN 26)

22 JUN 2026 04:00-28 JUN 2026 19:59
"RWY 05L/23R AVBL ONLY DURING UNPLANNED CLOSURES OF RWY 05R/23L AND DURING THE FOLLOWING TIMES:
JUN 22 0400-0559, 0700-0959, 1200-1359, 1600-1659, 1900-1959
JUN 23 0400-0559, 0700-0759, 1600-1659, 1900-1959
JUN 24 0400-0559, 0800-0859, 1100-1359, 1500-1659, 1900-1959
JUN 25 0400-0559, 0800-0959, 1300-1659, 1900-1959
JUN 26 0400-0559, 0900-0959, 1100-1359, 1500-1659, 1900-1959
JUN 27 0400-0559, 0800-0859, 1100-1159, 1300-1359, 1900-1959
JUN 28 0400-0559, 0800-1159, 1600-1759, 1900-1959."

EDDZA2882/26 (03 JUN 26)

"STAR DOMUX 1A ADD RMK: BRNAV EQUIPMENT NECESSARY.
REF AD 2 EDDL 3-1-1 DATED 19 MAR 2026, 3-1-2 EFF 28 NOV 2024."
03 JUN 26 07:27 UNTIL 03 SEP 26 23:59 ESTIMATED

EDDZA2729/26 (27 MAY 26)

"NOERVENICH DVORTAC NVO 116.20MHZ/CH109X, DVOR PART NO USABLE OPERATIONAL COVERAGE IN SECT 070DEG TO 130DEG (CLOCKWISE) UP TO 20NM AT OR BELOW 3000FT AMSL."
27 MAY 26 15:14 UNTIL 27 AUG 26 15:00 ESTIMATED

*EDDZA2690/26 (26 MAY 26)

DAILY 2200-0330
RWY 05R/23L AVBL O/R 60MIN PRIOR.

EDDZA2662/26 (26 MAY 26)

MON-FRI 0400-1700 EXC JUN 04
"OCA(H) VALUES RAISED AS FOLLOWS:
NDB RWY 05R: ACFT CATEGORY A 680(560)FT, B-D UNCHANGED
DUE TO HIGH MOBILE CRANE WITHIN 80M RADIUS AROUND 511531N 0064433E.
ELEV 431FT, MARKED AND LIGHTED."

EDDZA2524/26 (19 MAY 26)

"LPV APCH REOPERATIVE. OCA(H) VALUES RAISED:
LPV RWY 05L: A 518 (402), B 527 (411), C 532 (416), D 539 (423)FT.
LPV RWY 05R: A 560 (440), B 572 (452), C 581 (461), D 591 (471)FT.
LPV RWY 23L: A 420 (282), B 433 (295), C 452 (314), D 479 (341)FT.
LPV RWY 23R: A 415 (292), B 428 (305), C 447 (324), D 474 (351)FT.
DUE TO INADEQUATE PROTECTION PROVIDED IN THE MISSED APCH SEGMENT FOR SOME NAVIGATION SYSTEMS AUTHORISED FOR LPV OPERATIONS."
19 MAY 26 12:55 UNTIL 18 AUG 26 23:59 ESTIMATED

EDDZA2329/26 (11 MAY 26)

ILS LOC RWY 05L:
LOC COVERAGE UP TO 15NM IN THE AREA 029DEG(L)/009DEG(R) IN RELATION TO RCL AND DIST TO LOC. MNM RECEPTION ALT IN THIS AREA 4000FT AMSL.
11 MAY 26 08:29 UNTIL 11 AUG 26 07:00 ESTIMATED

EDDZA2092/26 (29 APR 26)

ACFT STAND V63 PUSH BACK ONLY.
05 MAY 26 03:00 UNTIL 03 AUG 26 21:59 ESTIMATED

EDDZA2093/26 (29 APR 26)

TWY P4 LTD TO ACFT MAX ICAO CODE LETTER E BTN TWY M AND TWY R.
05 MAY 26 03:00 UNTIL 03 AUG 26 21:59 ESTIMATED

EDDZA2078/26 (28 APR 26)

ACFT STANDS V44A AND V45A CLSD.
28 APR 26 05:40 UNTIL 27 JUL 26 22:59 ESTIMATED

EDDZA1661/26 (02 APR 26)

COLA DVOR/DME COL 108.80MHZ/CH25X RADIAL 250 UNUSABLE FROM
ONM - 31NM BELOW 6000FT AMSL.

EDDZA5876/25 (02 MAR 26)

ACFT STAND A09 WITHOUT SAFEDOCKSYSTEM.

EDDZA4699/25 (04 OCT 25)

"RWY 05L/23R:
TDZ REVISED AND SHORTENED TO 631M.
REMOVED MARKINGS PARTIALLY VISIBLE, CAN BE IRRITATING. PAY
ATTENTION. RWY AIMING POINTS NOT ALIGNED WITH PAPI.
RWY 05L - 81.87M IN FRONT OF PAPI.
RWY 23R - 99.61M IN FRONT OF PAPI.
RWY 05L/23R: ILS GP AND PAPI GP TOUCHDOWN POINT LOCATED BEYOND AIMING
POINT MARKINGS.
RWY 05R/23L:
RWY AIMING POINTS NOT ALIGNED WITH PAPI.
RWY 05R - 15.96M IN FRONT OF PAPI.
RWY 23L - 114.18M IN FRONT OF PAPI.
RWY 05R/23L: ILS GP AND PAPI GP TOUCHDOWN POINT LOCATED BEYOND AIMING
POINT MARKINGS."

EDDZA5060/22 (02 DEC 23)

ACFT STAND V91 AND V92 LAYOUT AS SUP 25/22 FROM 08 SEP 2022.

EDDZA5561/22 (02 DEC 23)

TWY G1 RENAMED TO TWY G.

EDDZA5542/22 (02 DEC 23)

TWY W RENAMED TO TWY R.