

Official Pilot Briefing

THA415 28JUN26 HSTWC B789 VTBS 0205 WMKK 0415
THA416 28JUN26 HSTWC B789 WMKK 0520 VTBS 0730

Page 1/13
Trans ID: 5040879
Creation Time: 27.06.2026 17:53UTC

GENERAL INFORMATION

Company Fuel Guidelines

THA 00159/26 (18 JUN 26)

OM INFO:--WEF 19JUN26,
Company Fuel Guidelines:
1) Flight Outbound from VTBS:
1.1) 15 mins:
-TG319
-ETA within TEMPO ± 1 hr with adverse weather condition

1.2) 5 mins:
-BLR (ONLY WHEN SINGLE RWY OPS)
-TG317, TG407, TG409*

2) Flight Inbound to VTBS:
2.1) 20 mins:
ETA within TEMPO ± 2 hrs with adverse weather condition*

2.2) 5 mins:
ETA 22:00-24:00 (BKK local time)

3) European Flights:
3.1) Outbound flight to European: CF 3 PERCENT (Except TG916/CF5)

3.2) Inbound flight to VTBS: RCFP + 05MINS

4) Flight Level Plan for VTUK,
-Outbound from VTBS: FL250
-Inbound to VTBS: FL240

5) Planning for Arrival WADD:
To improve flight planning accuracy, for WADD arrivals,
after waypoint KOLTA, flights shall plan to DOBMA
and then follow DOBMA## STAR.

6) TG649: Flight level shall not be planned above FL380.

7) TG900: When ETA falls within TEMPO ± 2 hrs and adverse weather conditions, LTAC shall be
designated as the destination alternate.

8) Destination VTUD*:

Remove altitude restrictions and use the optimum altitude for planning.

Remark:
1) Pilot Management Department (PA)

1.1) Destinations ZBAA and ZSPD:

Flights shall be planned as Economic Tankage without company fuel, with the following
conditions:

-Widebody aircraft shall be planned with far alternates (RKSI, RJFF).

-Narrowbody aircraft shall be planned with ZBTJ as the alternate; however, ZFW shall be
restricted to ensure the carriage of at least 30 minutes of extra fuel.

1.2) Destination YPPH: ALTN YGEL (+05MINS EXTRA FUEL)*

YGEL shall be used as ALTN airport effective 25 Apr 2026 following revision of OM-A section
8.3.26 (Operations at Uncontrolled Aerodromes)

2) Everything else regarding fuel planning policy remains the same as last month.

3) Adverse weather conditions*:
RA, TS or TSRA and visibility 5000m or less

(REVISED NO.1/REF EMAIL Summary of Fuel Initiatives Meeting - 08JUN26
For Fuel Committee member/BKKPC)

// (COM-INFO) //

THA 00002/13 (31 MAY 26)

COM INFO:--All A350 and BOEING 787:
are now eligible and included in EUROCONTROL airspace CPDLC Logon list.

Official Pilot Briefing

Page 2/13

THA415 28JUN26 HSTWC B789 VTBS 0205 WMKK 0415
THA416 28JUN26 HSTWC B789 WMKK 0520 VTBS 0730

Trans ID: 5040879
Creation Time: 27.06.2026 17:53UTC

Action Required: Pilots are required to initiate CPDLC logon when entering European airspace.
(ISSUED 23MAR26/BKKPC2/UFN)

--IN CASE CANNOT BE CONTACTED BKKOC VIA TELEPHONE,
PILOTS MAY CONTACT VIA MS TEAMS CHANNEL: "OC.CENTER".
(ISSUED 30JUL24/BKKOC/UFN)

-- To improve CTOT for all flights both outbound from BKK and
inbound to BKK, pilots may contact TOCC when ready for departure to request an earlier CTOT
through any of the following channels:

- : MS Teams chat
- : LINE CLC-Pilot
- : CUT 129.325
- : Phone 02-137-1202

In addition to above contact channels, for DOMESTIC flight, pilots may also directly contact
ground staff to request earlier CTOT. (ISSUED 15FEB25/BKKOP/UFN)

--DELEGATED FUNCTIONS PHONE DIRECTORY (Direct Number)

1. OPEN BOARDING GATE : 02-137-1260
 2. BUS GATE - REMOTE BAY & DOMESTIC V.V. : 02-137-1260
 3. CREW BUS OPC-TERMINAL V.V. : 02-137-1019, 02-137-1020
 4. CONFIRM BOARDING GATE/BAY/BELT : 02-137-1263
 5. ZFW/WEIGHT & BALANCE/LOAD SHEET : 02-137-1291, 02-137-1292
 6. TG LOST & FOUND : 02-134-5454
 7. OTHER INQUIRIES/BKKOC : 02-137-1202
- (ISSUED 17JUL22/BKKOC-INFO/UFN)

--If expected divert due to weather or traffic congestion at any TG destination airports,
please kindly advise TOCC, via ACARS using OPERATIONS prompt or SITA address BKKOPTG,
the current fuel on board immediately to keep close monitoring of the flight.
(ISSUED 08MAY25/BKKOP/UFN)

--In case of pilot receives information from ground staff to delay departure due to connecting
passenger, please kindly confirm with TOCC via CUT channel.
(ISSUED 27NOV24/BKKOP/UFN)

--FOR FLIGHTS PLANNED NAVIGATING THROUGH KABUL FIR,
ONCE FINAL FL TO ENTER KABUL FIR IS AVAILABLE,
PLEASE ACARS DOWNLINK ETO/ENTRY WPT/FL TO BKKOPTG
(ISSUED 12DEC24/BKKOC/UFN)

--Please kindly consider and issue recommendation for route P500 G500 as soon as possible in
order to reduce operational risk.

1. Due to limitation of passenger oxygen chemical type (22 minutes).
If weather deviation is required, pilots shall deviate west of route only.

2. In an event of critical in-flight emergency, the aircraft should follow ICAO emergency
descent procedures, broadcast status and intentions on 125.2 MHZ and 121.5 MHZ. Thereafter,
proceed at the discretion of the PIC until clear Kabul FIR and in contact with the ATC
responsible for the airspace.
(ISSUED 31JUL24/D1/OC/UFN)

--Any flight operation by TG into the uncontrolled airspace and conflict zone,
the latest operational information " Closures and Warnings" issued by means of ICAO State
letters,
NOTAMs, AICs/AIPs, and EASA CZIB - TG are subject to strictly following the
guidance/directions
from their national authority as well as their own risk assessment.
(ISSUED 15APR24 CORR/TN003/22/OW/UFN)

--WEF 01JUN26,
SUBJ: SPECIAL SECURITY ARRANGEMENT:SSA006/2026
ATTN ALL CONCERNED

THE AVIATION SECURITY COMMITTEE (ASC) MTG ON 21MAY2026
AGREED TO ANNOUNCE SSA006/2026 AS FLWS:

AA PLS BE INFM THT THIS SSA WILL SUPERSEDE SSA005/2026
FROM 01JUN2026 UNTIL FURTHER TLX ADV

BB FR FLT DEP FRM STATION EUROPE: ARN BRU CDG CPH FRA IST LHR MUC
MXP OSL ZRH

LEVEL: LOW CMA PERFORM SSA ACCORDING TO EU REQUIREMENTS
AS FLWS:

- A1 - A/C PRE-FLIGHT SECURITY SEARCH CONDUCTED BY PIC CMA
CABIN CREW CMA ASM/SMT/DELEGATED PERSONNEL N GROUND/
STATION ENGINEER
- A18-1 5% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
CONDUCTED BY CABIN CREW

Official Pilot Briefing

Page 3/13

THA415 28JUN26 HSTWC B789 VTBS 0205 WMKK 0415
THA416 28JUN26 HSTWC B789 WMKK 0520 VTBS 0730

Trans ID: 5040879
Creation Time: 27.06.2026 17:53UTC

CC FR FLT DEP FRM STATION: DAC KHI KTI ISB LHE RGN SAI

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW

DD FR DOM FLT DEP FRM STATION: HDY HKT UBP

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW

EE FR FLT DEP FRM MAINBASE STATION: BKK

LEVEL: MEDIUM CMA SSA AS FLWS:
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES CONDUCTED
BY CABIN CREW
F2 - IDENTITY CHECK OF CREW MEMBERS BEFORE BOARDING AT
BOARDING GATE
P2 - SECONDARY CHECK AT GATE
(APPLY ONLY FLT FRM BKK TO MEL PER N SYD)

FF THE FLWG SSA SHALL BE IMPLEMENTED FR ALL ROUTE AS NORMAL PROC
P5 - INTENSIVELY PERFORM IDENTITY CHECK N VERIFICATION OF PAX
BEFORE BOARDING A/C BY
- COMPARING PAX WZ PHOTOGRAPH N PASSPORT/TVL DOCS TO
ENSURE PAX IS BONA FIDE N
- VERIFYING THE NAMES IN THE TICKETS CORRESPOND TO THOSE
ON THE IDENTITY DOCS
V1 - ALERT STAFF TO OBSERVE UNUSUAL BEHAVIOR OF PAX N ALL
PERSONNEL INVOLVED N ANY SUSPICIOUS ITEM IN THE
OPERATING AREA

GG THOSE STN NOT ON THE LIST ABOVE ARE LOW LEVEL STP
APPLY NORMAL SECURITY PROC AS MENTIONED IN OPERATION MANUAL

ADDITIONAL INSTRUCTION.

FR FLT OPS TO BLR MAA N CCU PLS IMPLEMENT THE FLW MEASURES AT THE
CHK-IN COUNTERS;
1. PROV DEDICATED CHK-IN COUNTERS FR FLT TO BLR MAA N CCU
2. DISPLAY WARNING N INFO SIGNAGE AT:
-CHK-IN COUNTERS
-B/D GATE
-FLT INFO DISPLAY SYSTEM (FIDS) AT CHK-IN COUNTERS
3. CONDUCT RANDOM X-RAY SCREENING OF SUSPICIOUS BAG AT CHK-IN
COUNTERS
4. CONDUCT RANDOM SCREENING BY USING SNIFFER DOGS IN THE CHK-IN AREA.

IN CASE OF THREAT SITU N EXTRA MEASURES ARE REQ CMA
STN MONITORING TEAM/SMT MAY RAISE UP MEASURES AS APPROPRIATE

ANY SECURITY INCIDENTS MAY OCCUR SHALL INFO MANAGEMENT CONCERNED
N BKKD1 ACCLY STP

REMARK

A18-1 5% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
A18-2 10% RANDOM SEARCH OF LIFE VEST JACKET POUCHES
WILL BE REVISED IN SPM NEXT REVISION

PLS ACK N CFM ACTUAL PERFORM TO OFC BKKD1-B
BRGDS/CAPT. CHINGCHEEP B./BKKD1 ASC CHAIRMAN

Minima for flight planning

THA 00136/26 (29 MAY 26)

COM INFO: Application of planning minima for flight planning

Due to limited space in the OFP fuel planning box, any display of "BASIC FUEL SCHEME" shall be interpreted as "BASIC FUEL SCHEME WITH VARIATION."

All THAI flights are planned using Basic Fuel Scheme with Variation, unless otherwise specified by Flight Dispatcher.

Alternate planning minima shall be applied in accordance with OMA 8.1.7.5.2.
Display format will be reviewed and updated following stakeholder discussion.

OFP - TCAR format

THA 00093/26 (18 MAY 26)

COM INFO: SFP/OFP change format according to OM-A (TCAR version)

Due to identified limitations in the current OFP template,

Official Pilot Briefing

Page 4/13

THA415 28JUN26 HSTWC B789 VTBS 0205 WMKK 0415
THA416 28JUN26 HSTWC B789 WMKK 0520 VTBS 0730

Trans ID: 5040879
Creation Time: 27.06.2026 17:53UTC

the following temporary procedures shall apply with immediate effect:

1. RVSM - Standby Altimeter

The current OFP does not provide a dedicated line for Standby Altimeter recording as required by OMA 14.4.4.

Action: Record the Standby Altimeter value adjacent to the existing record row.

This procedure is mandatory to ensure compliance with OMA 14.4.4.

2. RAIM Information

RAIM shown in the OFP is for terminal operations only.

Action: For flights requiring NPA, crew shall verify RAIM availability separately using an approved RAIM Forecast Report.

3. RCFP - MINF at DP

the displayed MINF at DP may be incorrect.

Action: Disregard the displayed value and refer to the minimum fuel at DP provided in the eOFP application to maintain information consistency.

These instructions are mandatory until corrected in the next OFP version.

FLIGHT LEG INFORMATION

VTBSWMKK

AIP SUP 43/25

THA 00372/25 (22 FEB 26)

// (SEE ATTCH) //

WMKKVTBS

AIP SUP 43/25

THA 00372/25 (22 FEB 26)

// (SEE ATTCH) //

AERODROME INFORMATION

VTBS / BKK

*VTBDC3500/26 (26 JUN 26)

28 JUN 2026 19:00-28 JUN 2026 23:00
RWY 01/19 CLSD DUE TO WIP

VTBDC3499/26 (26 JUN 26)

28 JUN 2026 19:00-28 JUN 2026 22:30
TXL CLSD DUE TO WIP DETAIL AS FLW:
-TXL T13 BEHIND ACFT STAND NR E2 E4 E6 E8 E10 401 402 403
-TXL T14 BEHIND ACFT STAND NR F1 F3 F5

VTBDC3491/26 (26 JUN 26)

BANGKOK / SUVARNABHUMI INTERNATIONAL AIRPORT PSR U/S

OB Company Safety NOTAM-BKK

THA 00161/26 (22 JUN 26)

// (SEE ATTCH) //

// (COM-INFO) //

THA 00029/26 (18 JUN 26)

COM INFO:--WEF 16FEB26 04:00LT
The operation of opening aircraft doors from outside for all arriving flight by ground staff at BKK station will be fully implemented.
(refer IOC GB/SS/005-26 date 30JAN 26/UFN)

// (COM-INFO) //

THA 00064/25 (18 JUN 26)

COM INFO:--REF AIP SUP A53/25:
RETIls U/S:
RWY 01/19: TWYs B3, B5, B7, B8, B10 and B11
RWY 02R/20L: TWYs E5, E7, E9, E12, E13, E15.

- 1) The Visual Docking Guidance System (VDGS) at the ACFT stands 101 - 114 are U/S. (14 ACFT stands).
- 2) Airlines or Ground service providers shall provide a License Mechanic performed as Marshaller to guide the aircraft from taxilane to the parking position.
- 3) The ACFT are strongly advised to strictly follow the Marshaller's signal.

(REF AIP SUP A13/25*)

--Suvarnabhumi:
DVOR/DME (SVB) (133932.5N 1004353.2E) (111.4 MHZ, CH51X) temporary suspended
from 28 November 2024 at 0001 UTC to 02 October 2026 at 0949 UTC.
(REF AIP SUP A54/24*)

--Taxiway C between Taxilane T1 and Taxilane T2, Taxiway C1 closed.
(REF AIP SUP A01/25*)

VTBDC2661/26 (07 JUN 26)

"AD 2.24 CHARTS RELATED TO AN AD,
IAC-ICAO CHANGED ALT AT IF AS FLW:
AD2-VTBS 8-9 ILS OR LOC Z RWY 19 CAT II
:READ ALT2500 (2496) INSTEAD OF ALT3000
AD2-VTBS 8-13 ILS OR LOC Z RWY 20L CAT II
:READ ALT3500 (3496) INSTEAD OF ALT4000
AD2-VTBS 8-23 RNP RWY 19 :READ ALT2500 (2496) INSTEAD OF ALT3000
AD2-VTBS 8-25 RNP RWY 20L :READ ALT3500 (3496) INSTEAD OF ALT4000
AD2-VTBS 8-27 RNP RWY 20R :READ ALT3500 (3492) INSTEAD OF ALT4000
REF AIRAC AIP AMDT AD2-VTBS-8-9, AD2-VTBS-8-13, AD2-VTBS-8-23,
AD2-VTBS-8-25, AD2-VTBS-8-27"

VTBDC2039/26 (19 APR 26)

ADVANCED VISUAL DOCKING GUIDANCE SYSTEM (A-VDGS)
ACFT STAND NR 119 308 516 AND 520 U/S DUE TO MAINT
RMK: ACFT HAVE TO FLW MARSHALLING SIGNALS STRICTLY

WMKK / KUL

WMKKA2471/26 (25 JUN 26)

28 JUN 2026 00:00-28 JUN 2026 05:00
SEPANG DVOR/DME (VSP) 114.400 MHZ (CH91X) WITHDRAWN
FOR MAINT

WMKKA2470/26 (25 JUN 26)

28 JUN 2026 00:00-28 JUN 2026 05:00
TANJUNG SEPAT DME (DTS) CH 84X WITHDRAWN
FOR MAINT

WMKKA2445/26 (22 JUN 26)

TWY L FM ACFT STAND F32 TIL ACFT STAND F34 CLSD.

THA 00371/25 (10 JUN 26)

// (COM-INFO)//

WMKK:--REF AIP SUP 54/25;
1 INTRODUCTION
1.1 This AIRAC AIP Supplement is to inform all concerned of the unserviceability of the
stopbar lights
at the intersection of Taxiways Q5 to Q7.
1.2 Runway Guard Lights are available for operational use.
1.3 Pilot to exercise caution during entering runway.

--REF AIP SUP 55/25;
1 INTRODUCTION
1.1 This AIRAC AIP Supplement is to inform all concerned of the unserviceability of the
Sequence
Flashing Lights (SFL) for RWY 14R.
1.2 Approach lighting for RWY 14R available for operational use.

--REF AIP SUP 19/26;
1) INTRODUCTION
1.1 This AIP Supplement is issued to inform all concerned that the stop bar lights at the
intersections of TWY Y1 to Y5 are serviceable
and operate alternately.

1.2 Pilot to exercise caution during entering runway.

2 VALIDITY
2.1 This AIP Supplement will remain in force until 30th June 2026.
Any updates, changes or cancellation to this supplement
will be notified through NOTAM.

WMKKA2039/26 (10 JUN 26)

28 JUN 2026 04:00-28 JUN 2026 06:00
TANJUNG SEPAT DME DTS CH84X ON TEST (CLBR

WMKKA2038/26 (10 JUN 26)

28 JUN 2026 04:00-28 JUN 2026 06:00
SEPANG DVOR/DME VSP 114.40MHZ CH91X ON TEST (CLBR

WMKKA1924/26 (10 JUN 26)

ILS GP PART RWY 32L OUT OF SER

WMKP / PEN

WMKKA2441/26 (22 JUN 26)

"REFER TO AIRAC AIP SUP 44/2024, TWY E RESUME NORMAL OPS"

WMKKA2440/26 (22 JUN 26)

DAILY 0100-0900
"UA ACT WILL TAKE PLACE WI THE FLW COORD:
051615.00N 1001615.00E - 051510.00N 1001642.00E
051458.00N 1001612.00E - 051605.00N 1001545.00E
(PANTAI ESEN,PERMATANG DAMAR LAUT,PULAU PINANG)"
F) SFC
G) 400FT AMSL

WMKKA2004/26 (22 MAY 26)

DUE TO INCORRECT PENANG INTERNATIONAL AIRPORT (WMKP)GND MOV CHART.
TO VISIT [HTTPS://AIP.CAAM.GOV.MY/AIP/WMKPCHART.PDF](https://aip.caam.gov.my/aip/wmkpchart.pdf) FOR FURTHER
DETAILS.

// (COM-INFO) //

THA 00008/25 (18 APR 26)

WMKP:--SCHEDULE BETWEEN 1800-2130 DAILY
RWY 04/22 CLOSED DUE TO WIP.
(REF AIP SUP 71/24)

VTBU / UTP

*VTBDC3302/26 (18 JUN 26)

PALS CAT 1 RWY 18 AND SALS RWY 36 U/S DUE TO MAINT

c3100/26

VTBDC3100/26 (07 JUN 26)

ILS RWY 18 U/S DUE TO MAINT

*VTBDC2844/26 (07 JUN 26)

AD CATEGORY FOR FIRE FIGHTING AND RESCUE SERVICES
DOWNGRADED TO CAT 9.

VTBDC2193/26 (07 JUN 26)

TWY EDGE LGT U/S DUE TO MAINT DETAIL AS FLW:
-TWY B
-TWY E BTN TWY B AND TWY F

VTBDC0333/23 (06 APR 24)

"IAC-ICAO-NDB RWY 36 CHANGED AS FLW:
-OCA/H : STRAIGHT-IN APPROACH
: READ 790(766)FT INSTEAD OF 750(726)FT
-OCA/H : CIRCLING APPROACH CAT A, B
: READ 1200(1141)FT INSTEAD OF 750(726)FT, 1190(1166)FT
-OCA/H : CIRCLING APPROACH CAT C, D
: READ 1450(1391)FT INSTEAD OF 1290(1266)FT, 1445(1421)FT
REF AIP VTBU AD 2.24, AD 2-VTBU-8-1"

ADDITIONAL INFORMATION

WSSS / SIN

WSSSA1979/26 (26 JUN 26)

28 JUN 2026 17:30-01 JUL 2026 22:00
JUN 28 JUL 01 1730-2200
"FLW TWY CLSD DUE WIP:
1) TWY V BTN TWY V5 AND TWY Q, INCLUDING JUNCTION OF TWY V/TWY V13
NORTHBOUND
2) TWY V13 BEHIND ACFT STAND C25"

Official Pilot Briefing

THA415 28JUN26 HSTWC B789 VTBS 0205 WMKK 0415
THA416 28JUN26 HSTWC B789 WMKK 0520 VTBS 0730

Page 7/13
Trans ID: 5040879
Creation Time: 27.06.2026 17:53UTC

WSSSA1919/26 (23 JUN 26)

28 JUN 2026 16:00-03 JUL 2026 22:00
"JUN 28-30 1600-2200, JUL 01-03 1600-2200"
TWY T9 CLSD DUE TO WIP

WSSSA1911/26 (23 JUN 26)

28 JUN 2026 16:00-03 JUL 2026 22:00
"JUN 28-30 1600-2200, JUL 01-03 1600-2200"
"TWY U BTN TWY U7 AND TWY U9, INCLUDING JUNCTION OF TWY U/TWY U8
CLSD
DUE WIP"

WSSSA1910/26 (23 JUN 26)

"JUN 26 1730-2130, JUL 03 1730-2130"
"FLW TWY CLSD DUE WIP:
1) TWY T BTN TWY R5 AND TWY U7, INCLUDING ALL THE JUNCTIONS WITHIN
2) TWY T7
3) TWY T8
4) TXL U1 BEHIND ACFT STANDS G18L TO G18R"

WSSSA1861/26 (16 JUN 26)

28 JUN 2026 20:30-28 JUN 2026 21:30
"TXL V11, INCLUDING JUNCTION OF TXL V11/TWY V9 CLSD DUE WIP"

WSSSA1860/26 (16 JUN 26)

28 JUN 2026 19:30-28 JUN 2026 20:30
JUNCTION OF TWY V/TWY V9 CLSD DUE WIP

WSSSA1859/26 (16 JUN 26)

28 JUN 2026 18:30-28 JUN 2026 19:30
"FLW TWY CLSD DUE WIP:
1. TWY V BTN TWY V8 AND TWY V9, INCLUDING JUNCTION OF TWY V/TWY V12
SB
2. TWY V12 SB BEHIND ACFT STANDS A13 TO A15"

WSSSA1858/26 (16 JUN 26)

28 JUN 2026 17:30-28 JUN 2026 18:30
"TWY V BTN TWY V12 NB AND TWY V12 SB, INCLUDING JUNCTION OF TWY
V/TWY
V8 CLSD DUE WIP"

WSSSA1573/26 (19 MAY 26)

"MAY 20 24 27 31 1730-2130, JUN 03 07 10 14 17 21 24 28 1730-2130,
JUL
01 1730-2130"
"TWY W BTN TWY V1 AND TWY N, INCLUDING JUNCTIONS OF TWY W/TWY
V4/TWY
W4 NB, TWY W/TWY W1/TWY V1 AND ALL JUNCTIONS WITHIN CLSD DUE WIP"

WSSSA1566/26 (19 MAY 26)

TXL P7 BEHIND ACFT STAND E20 CLSD

// (COM-INFO) //

THA 00241/16 (13 MAY 26)

WSSS:--REF AIP SUP 002/26,
Runway 02R/20L will not be available for civil use
from 19 February 2026, 0000UTC to 05 August 2026, 2359UTC.

WSSSA1494/26 (13 MAY 26)

ACFT TAXIING ON TWY S1 SOUTHBOUND NOT ALLOWED TO TURN RIGHT ONTO
TWY S3

WSSSA1334/26 (09 MAY 26)

TWY S2 CLSD.

WSSSA1223/26 (09 MAY 26)

RWY 02C/20C RAPID EXIT TWY INDICATOR LIGHTS (RETIL) WITHDRAWN AND
CIRCUITS ISOLATED DUE TRIAL. PILOTS TO EXER CTN WHEN VACATING RWY.

WSSSA0740/26 (09 MAY 26)

"JUN 01-30 1100-2300, JUL 01-31 1100-2300"
"FOLLOW THE GREENS OPERATIONAL TRIAL ONGOING IN CHANGI AIRPORT."

Official Pilot Briefing

Page 8/13

THA415 28JUN26 HSTWC B789 VTBS 0205 WMKK 0415
THA416 28JUN26 HSTWC B789 WMKK 0520 VTBS 0730

Trans ID: 5040879
Creation Time: 27.06.2026 17:53UTC

DURING THE TRIAL:

I. TWY CL LGT WILL BE PROGRESSIVELY TURNED ON. PILOTS ARE PROVIDED WITH DEDICATED VISUAL GUIDANCE ON ATC CLEARED TAXI ROUTE.
II. FOLLOW THE GREENS SER NOT AVBL ON RWY AND RAPID EXIT TWY. PILOTS SHALL FOLLOW ATC VERBAL TURN INSTRUCTIONS WHEN VACATING RWY
III. ATC WILL USE THE PHRASEOLOGY FOLLOW THE GREENS TOGETHER WITH A VERBAL CLEARANCE LIMIT (HOLD SHORT POINT) WHEN ISSUING A TAXI CLEARANCE TO PILOTS.
IV. PILOTS SHALL STRICTLY ADHERE TO FOLLOW THE GREENS TAXI INSTRUCTIONS AND FOLLOW THE GREEN CL LGT UNTIL THE CLEARANCE LIMIT OR WHERE RED STOPBAR IS ILLUMINATED. PILOTS SHALL KEEP A LOOKOUT FOR CONTINUOUS GREENS WHEN APPROACHING JUNCTIONS.
V. PILOTS SHALL NOT TAXI AHEAD IF THERE ARE NO GREEN CL LGT OR WHEN RED STOP BAR IS ILLUMINATED. PILOTS SHALL NOT PROCEED PAST THE VERBAL CLEARANCE LIMIT WITHOUT ATC APPROVAL EVEN WHEN NO RED STOPBAR IS ILLUMINATED.
VI. IN INSTANCES OF AMBIGUITY OR WHEN MULTIPLE GREEN LGT SEGMENTS OR BREAKS IN THE GREENS ARE OBSERVED, PILOTS SHALL STOP AND SEEK CONFIRMATION BEFORE FURTHER TAXI. ATC WILL PROVIDE ADDITIONAL VERBAL GUIDANCE.
VII. PILOTS ARE REMINDED TO EXER CTN TO ENSURE SUFFICIENT WINGTIP CLEARANCE AND SEPARATION WITH OTHER ACFT. WHEN APPROACHING ACFT STANDS, PILOTS SHALL FOLLOW THE LEAD IN LINE MARKINGS AS THE GREEN LGT MAY NOT TERMINATE IN FRONT OF THE PRKG STANDS.
VIII. FOR DEP, PILOTS SHALL ENSURE ACFT TRANSPONDER IS OPR PRIOR TO PUSHBACK CLR REQ. FOR ARR, PILOTS SHALL ENSURE ACFT TRANSPONDER IS OPR AFT LDG TIL THE ACFT REACH THE PRKG STAND.
IX. WHEN FOLLOW THE GREENS SER IS TERMINATED, ATC WILL REVERT TO VERBAL TAXI INSTRUCTIONS. PILOTS SHALL RESUME OWN NAV WITH REFERENCE TO TWY GUIDANCE SIGNS AND MARKINGS."

WIDD / BTH

WRRRA2129/26 (14 JUN 26)

"ILS/DME CH38X, DME PART U/S DUE TO TECH REASON"

WRRRA1373/26 (17 APR 26)

CHANGE INFORMATION RELATED TO INSTRUMENT APPROACH CHART -
ICAO VOR RWY 04 AS FLW :
FINAL AND MISSED APPROACH TRACK SHALL BE
READ 042 DEG MAG (041.6 DEG TRUE)
REF AIRAC AIP AMDT 160 WIDD AD 2.24-11A1
AND WIDD AD 2.24-11A2

*WRRRA1341/26 (15 APR 26)

DAILY 1010-1025 2300-2345
RWY 04/22 CLSD DUE TO RWY INSPECTION
RMK : EXC FOR HAJJ FLT

// (COM-INFO) //

THA 00444/14 (20 SEP 25)

COM INFO:--BTH Airport (WIDD) able landing for all TG aircraft type:
such as B777-300ER/A350-900/B777-200ER/787-8/787-9 and A320 and A330
Our GHA GAPURA detail below:
General Manager : Dedy Bambang
Mobile. : 0813-8423-1063
(REF TO EMAIL SMT/UFN)

VTSS / HDY

VTBDC3464/26 (25 JUN 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS) ACFT STAND NR 5 U/S

VTBDC3112/26 (08 JUN 26)

"TACAN HTY 115.70MHZ/CH104X ON TEST, DO NOT USE"

VTBDC2126/26 (16 APR 26)

TWY EDGE LGT U/S DETAIL AS FLW:
-TWY J
-TWY K
-TWY L
-TWY M

VTBDC2077/26 (09 APR 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS) ACFT STAND NR 4 U/S

Official Pilot Briefing

THA415 28JUN26 HSTWC B789 VTBS 0205 WMKK 0415
THA416 28JUN26 HSTWC B789 WMKK 0520 VTBS 0730

Page 9/13
Trans ID: 5040879
Creation Time: 27.06.2026 17:53UTC

VTBD / DMK

*VTBDC3446/26 (24 JUN 26)

24 JUN 2026 16:00-28 JUN 2026 22:00
"24 1600-2200, 26 1500-1600, 27 28 1600-2200"
RWY 03R/21L CLSD DUE TO WIP

*VTBDC3440/26 (24 JUN 26)

25 26 29 1600-2200
RWY 03L/21R CLSD DUE TO WIP

VTBDC1938/26 (19 APR 26)

RAPID EXIT TWY INDICATOR LGT RWY 21R TOWARD RAPID EXIT TWY O U/S

VTBDJ1987/26 (19 APR 26)

"TEMPO RESTRICTED AREA ACT WI 0.5NM CENTRE OF 135526.22N1003713.11E
APPROVAL SHALL BE MADE BEFORE ENTERING, EXCEPT DEP AND ARR ACFT AT
VTBD PILOT IN COMMAND SHALL STRICTLY COMPLY WITH ATC INSTRUCTION"
F) GND
G) 3000FT AGL

// (COM-INFO)//

THA 00435/14 (16 DEC 24)

COM INFO:-- DMK TG LINE MAINTENANCE WILL PROVIDE RAMP HANDLING SERVICE ON
TG FLIGHTS DIVERTED TO DMK, WHILE PIC MUST PERFORM REDUCE LINE CHECK
TO RELEASE AIRCRAFT. PRIOR TO FLIGHT DIVERSION TO DMK PLS INFORM
TOCC COMMAND CENTER (OC) VIA CUT FREQUENCY 129.325 MHZ
TO COORDINATE WITH DMK TG LINE MAINTENANCE IN ADVANCE FOR SMOOTH
HANDLING UPON ARRIVAL AT DMK
CONTACT POINTS FOR DMK LINE MAINTENANCE IN (24hrs)
AT DMK ARE AS FLW
1. TEL: 02-563-8178 (66-8178, 9999)
2. Email dmkjcb@thaiairways.com
(ISSUED 12DEC24/OP/UFN)

VTUU / UBP

VTBDC3445/26 (24 JUN 26)

STRIP RWY 05/23 WIP FM THR RWY 05 TO DIST 442M
ON BOTH SIDES OF RWY 05

VTBDC3444/26 (24 JUN 26)

STRIP RWY 05/23 WIP FM THR RWY 23 TO DIST 442M
ON BOTH SIDES OF RWY 23

*VTBDC3428/26 (23 JUN 26)

"AD OPR HR ATS AND ARO HR SER CHANGED AS FLW:
JUN 23 1320-1415, 24-JUL 07 2300-1400"

VTCC / CNX

VTBDC3516/26 (27 JUN 26)

27 JUN 2026 02:00-28 JUN 2026 16:59
TWY Q BTN TWY F AND ACFT STAND NR 20R CLSD
DUE TO TEMPO ACFT PRKG

VTBDC3490/26 (26 JUN 26)

RVR RWY 36 U/S

VTBDC3385/26 (22 JUN 26)

ACFT STAND NR 5 CLSD DUE TO WIP

VTBDC3386/26 (22 JUN 26)

ACFT STAND NR 6 CLSD DUE TO WIP

VTBDC3333/26 (19 JUN 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS) ACFT STAND NR 3 U/S

VTBDC3306/26 (18 JUN 26)

VISUAL DOCKING GUIDANCE SYSTEM (VDGS)
ACFT STAND NR 7 AND NR 8 U/S

// (COM-INFO) //

THA 00444/15 (17 JUN 26)

VTCC:--REF AIP SUP A19/25:
1 INTRODUCTION
With effect from 17 April 2025 at 1000 UTC,
the purpose of this AIP Supplement is to inform all concerned regarding the Aircraft stand
number 1 closed at Chiang Mai International Airport.
2 DETAILS
Aircraft stand number 1 closed for improvements to enhance aircraft parking compatibility.

VTBDJ4851/26 (07 JUN 26)

"05 0842-1000, 06-30 0130-1000"
UNMANNED AIRCRAFT WILL TAKE PLACE RADIUS 1NM CENTRE
184625.67N0990008.84E
F) GND
G) 300FT AGL

VTBDJ4315/26 (07 JUN 26)

TEMPO RESTRICTED AREA ACT RADIUS 0.5NM CENTRE 184626N0985806E
(EXCLUDING LDG AND TKOF RWY 18/36)
F) GND
G) 3000FT AGL

VTBDC2648/26 (17 JUN 26)

"MAY 15 0412-0800, MAY 16-JUN 30 0200-0800"
OBST MOBILE CRANE HGT 65FT AGL ERECTED AT 184623.96N0985757.21E
DIST 815M BEYOND THR RWY 18 AND 320M LEFT SIDE OF RCL

VTBDC2132/26 (17 JUN 26)

DAILY 0100-1100
OBST MOBILE CRANE HGT 82FT AGL ERECTED AT
184704.31N0985757.46E DIST 390M BFR THR
RWY 18 AND 328M LEFT SIDE OF EXTD RCL

ENROUTE INFORMATION

ASP / ASIA/PACIFIC
N I L

THA / THAILAND
N I L

VTBB / BANGKOK FIR

*VTBDJ5255/26 (26 JUN 26)

28 JUN 2026 02:00-28 JUN 2026 10:00
"ROCKET (BANGFAI) FRNG WILL TAKE PLACE RADIUS 5NM CENTRE
155346.98N1041032.21E (MUEANG DISTRICT YASOTHON PROVINCE)
RMK: COOR CTC TEL +668 1393 0595, +669 0912 1201"
F) GND
G) 19000FT AGL

*VTBDJ5239/26 (25 JUN 26)

28 JUN 2026 02:30-28 JUN 2026 05:00
"ROCKET (BANGFAI) FRNG WILL TAKE PLACE RADIUS 5NM CENTRE
165116.20N1011344.50E (LOM KAO DISTRICT PHETCHABUN PROVINCE)
RMK: COOR CTC TEL +666 4070 8746, +666 2143 0364"
F) GND
G) 19000FT AGL

VTBDC3430/26 (23 JUN 26)

"ALL ACFT VIA RTE B346, R474, W21 AND G473 ADVICE CTC
BANGKOK ACC PRI FREQ 126.500MHZ AND SRY FREQ 122.00MHZ
DUE TO RADIO FREQ INTERFERENCE"

*VTBDJ5189/26 (22 JUN 26)

28 JUN 2026 01:00-28 JUN 2026 11:00
"ROCKET (BANGFAI) FRNG WILL TAKE PLACE RADIUS 5NM CENTRE
160423.2N1033133.9E (MUEANG DISTRICT ROI ET PROVINCE)
RMK: COOR CTC TEL +668 1574 7345, +668 1739 2397"
F) GND
G) 12000FT AGL

Official Pilot Briefing

THA415 28JUN26 HSTWC B789 VTBS 0205 WMKK 0415
THA416 28JUN26 HSTWC B789 WMKK 0520 VTBS 0730

Page 11/13
Trans ID: 5040879
Creation Time: 27.06.2026 17:53UTC

VTBDC2855/26 (26 MAY 26)

"AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM THE DEMOCRATIC REPUBLIC OF THE CONGO AND THE REPUBLIC OF UGANDA
1. PURSUANT TO THE RESOLUTION OF THE NATIONAL COMMUNICABLE DISEASE COMMITTEE, EFFECTIVE FROM 27 MAY 2026 AT 1800 HOURS (LOCAL TIME) ONWARDS, PASSENGERS AND CREW MEMBERS DEPARTING FROM THE DEMOCRATIC REPUBLIC OF THE CONGO (DR CONGO) AND THE REPUBLIC OF UGANDA SHALL BE PERMITTED TO ENTER THE KINGDOM OF THAILAND ONLY VIA SUVARNABHUMI AIRPORT AND SHALL BE SUBJECT TO A MANDATORY QUARANTINE PERIOD OF TWENTY-ONE (21) DAYS, CALCULATED FROM THE DATE OF DEPARTURE FROM THE AFFECTED AREAS, IN ACCORDANCE WITH THE PRESCRIBED PUBLIC HEALTH PROCEDURES.
2. ALL AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM THE ABOVE-MENTIONED AREAS ARE REQUESTED TO COMPLY WITH AND IMPLEMENT THE PRESCRIBED MEASURES ACCORDINGLY."

// (COM-INFO) //

THA 00126/26 (14 MAY 26)

COM INFO:--REF AIP SUP A19/26;

1

INTRODUCTION

With effect from 14 May 2026 at 0001 UTC to 31 December 2026 at 0001 UTC, the purpose of this AIRAC AIP Supplement is to inform all concerned regarding Temporary suspension of SURAT THANI DVOR/DME (STN) due to relocation details are as follows.

2

THE PERIOD OF TEMPORARY SUSPENSION

STN DVOR/DME will be temporarily suspension from 14 May 2026 at 0001 UTC to 31 December 2026 at 0001 UTC.

3

FLIGHT PROCEDURE

A temporary reporting point name SAPUD (090746.24N 0990805.09E) will be established at the same coordinates of SURAT THANI DVOR/DME (STN) for ATS routes G458, W17, W24, W28, W32 and Y8 and a portion of ATS route G458 between STN and MENEX will be suspended until STN normal operations resume.

4

FLIGHT PLANNING PROCEDURES

Reference to the AIP-THAILAND part ENR 1.10 item 4.1.1.1, 4.1.1.2 a, 4.1.1.2 b, 4.1.1.3 a, 4.1.1.3 b non-RNAV2 approved aircraft. To maintain efficiency of ATS during SURAT THANI DVOR/DME (STN) relocation, non-RNAV approved aircraft that intend to operate on G458 between SAPUD and MENEX shall file flight plan, depending on ACFT capability.

5

CONTACT

Unit: Air Traffic Navigation Systems Engineering Department, Aeronautical Radio of Thailand Ltd.

Email: pariwat.ch@aerorhai.co.th

6

VALIDITY

This AIRAC AIP Supplement will remain current until 31 December 2026 at 0001 UTC. Any changes to this AIRAC AIP Supplement will be notified by NOTAM.

VTBDJ3551/26 (14 MAY 26)

DAILY 0100-0230 0600-1130

"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA 5NM EITHER SIDE OF
A LINE:151638.34N1001745.12E-145407.02N1004920.52E-
143000.00N1022800.00E-143107.26N1051100.12E
(CHAINAT, NAKHON SAWAN, LOP BURI, SURIN, SI SA KET,
UBON RATCHATHANI, BURI RAM AND NAKHON RATCHASIMA PROVINCE)
RMK: ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR VECTORED
BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC"

F) FL150

G) FL200

VTBDC2184/26 (20 APR 26)

"DUE TO VT D41A ACT FPL PROC FOR ACFT OPR FM/TO VTCC DETAIL AS FLW:

1. PERIOD MON-FRI 0000-1100

DEP/OVERFLY DEST/OVERFLY RTE

VTCC VTCT W12 IKISU W22

VTCC PONUK R207 IKISU W22 CTR A581

VTCT VTCC W22 IKISU W12

PONUK VTCC Y27 DUBEN Y28 CRIST R207 (FOR RNAV)

PONUK VTCC A581 CTR W22 IKISU R207 (FOR NON-RNAV)

2. PERIOD MON-FRI 1101-2359, SAT SUN H24

DEP/OVERFLY DEST/OVERFLY RTE

Official Pilot Briefing

THA415 28JUN26 HSTWC B789 VTBS 0205 WMKK 0415
THA416 28JUN26 HSTWC B789 WMKK 0520 VTBS 0730

Page 12/13
Trans ID: 5040879
Creation Time: 27.06.2026 17:53UTC

VTCC	VTCT	W20
VTCC	PONUK	A581
VTCT	VTCC	W20
PONUK	VTCC	A581"

VTBDJ2001/26 (05 APR 26)

"UNMANNED AIRCRAFT WILL TAKE PLACE WI AREA :
144705N1033019E - 143541N1051246E - 142051N1051232E -
141826N1030616E - 142521N1030558E - 144705N1033019E
(SI SAKET, UBON RATCHATHANI, BURIRAM AND SURIN PROVINCE
EXCLUDING PHNOM PENH FIR)
RMK : ACFT MAY FILE FPL ON AFFECTED RTE BUT EXP RADAR
VECTORED BY ATC SUBJECTED TO COORDINATION BTN CIV/MIL ATC."
F) 8000FT AMSL
G) FL170

MYS / MALAYSIA
N I L

WMFC / KUALA LUMPUR FIR

WMKKA2114/26 (10 JUN 26)

"DIRECT ROUTE OPERATIONS (DRO) AVBL WITHIN KUALA LUMPUR FIR FOR
RVSM APPROVED ACFT. OPERATORS MAY FILE EITHER IN ACCORDANCE WITH
FLIGHT PLANNING REQUIREMENTS AS SPECIFIED IN AIP ENR 1.8.6.1-
1.8.6.4 OR VIA THE FOLLOWING DRO FLT PLAN ROUTINGS AS FLW:
EASTBOUND:
1. VPL Y503 RINBA Y507, MAY BE FILED AS VPL DCT ANBIK Y507.
2. BOGUK Y507 VBA G582 VPK, MAY BE FILED AS BOGUK DCT ANBIK DCT
ADNUT G582 VPK.
3. SALAX DCT BATAR A464 ARAMA, MAY BE FILED AS SALAX DCT TOPOR
A464 ARAMA.
WESTBOUND:
1. IGARI R208 VKR Y346 PULIP, MAY BE FILED AS IGARI R208 IKUKO
DCT LASOB Y346 PULIP.
2. VPK G582 BILIK Y506 GORVU, MAY BE FILED AS VPK DCT ATIMU Y506
GORVU.
IN THE EVENT OF DRO SUSPENSION, FLT PLANNING SHALL BE IN
ACCORDANCE WITH AIP ENR 1.8.6.1-1.8.6.4
FROM SFC TO FL460"

AEROPLANE INFORMATION

AIRCRAFT CATEGORY = D
N I L

AIRCRAFT TYPE = B787

// (COM-INFO) //

THA 00143/26 (04 JUN 26)

B787:+++ (NEW) --Single Engine Taxi-in (SETI) shall not be performed on B787-8 Registration
HS-TQB* due to technical issue until further notice.
(ISSUED 04JUN06/PC/UFN)

AIRCRAFT SUBTYPE = B789
N I L

AIRCRAFT REGISTRATION = HSTWC
N I L

ADDITIONAL INFORMATION

VTSP / HKT

VTBDC3381/26 (22 JUN 26)

ACFT STAND NR 9 CLSD DUE TO WIP

VTBDC3380/26 (22 JUN 26)

ACFT STAND NR 10 CLSD DUE TO WIP

VTBDJ5144/26 (19 JUN 26)

DAILY 0100-1000
UNMANNED AIRCRAFT WILL TAKE PLACE

RADIUS 1.3NM CENTRE 080510.87N 0982201.96E.
F) GND
G) 295FT AGL

// (COM-INFO)//

THA 00094/26 (04 JUN 26)

VTSP:--REF AIP SUP A18/26:
1 INTRODUCTION
With effect from 5 May 2026 at 0101 UTC. The purpose of this AIP Supplement is to inform pilots and operators concerning the Visual Docking Guidance System (VDGS) of aircraft stand number 31 at Phuket International Airport (VTSP).
2 DETAILS
2.1 The Visual Docking Guidance System (VDGS) of aircraft stand number 31 is unserviceable.
2.2 The aircraft are strongly advised to strictly follow the Marshaller's signal.

VTBDC2995/26 (04 JUN 26)

RVR RWY 09/27 U/S

VTBDC2924/26 (04 JUN 26)

RWY CLOSURE FOR MAINT WORKS AT PHUKET INTERNATIONAL AIRPORT (VTSP) (MARCH-OCTOBER 2026)
ITEM 2. CLOSURE AREAS AND PERIODS OF RWY PREVENTIVE MAINT
AMEND AS FLW:
MONTH DATES PERIOD OF CLOSURE
MAY 31 1730-2330
JUN 01-09 23 1730-2330
JUL 07 21 1815-2330
AUG 04 1815-2330
REF AIRAC AIP SUP A14/26

VTSG / KBV

N I L

THA415 28JUN26/0205 VTBS/WMKK

N I L

THA416 28JUN26/0520 WMKK/VTBS

N I L