表 2-4 尺寸至 500mm 轴的基本偏差数值 (摘自 GB/T 1800.1-2009)

表 2-4 尺寸至 500mm 細的基本偏差 <b>级</b> 值(调自 GB/T 1800.1-2009)																
公称尺寸	† (mm)	基本偏差数值(上极限偏差 es)(μm)														
大于	至	所 有 标 准 公 差 等 级														
		a	b	c	cd	d	e	ef	f	fg	g	h	js			
	3	-270	-140	-60	-34	-20	-14	-10	-6	-4	-2	0				
3	6	-270	-140	-70	-46	-30	-20	-14	-10	-6	-4	0				
6	10	-280	-150	-80	-56	-40	-25	-18	-13	-8	-5	0				
10	14	-290	-150	<b>-95</b>	_	-50	-32		-16		-6	0	——偏差 = ±ITn/2,式 中 ITn 为标 准公差数值			
14	18	290	130	93												
18	24	-300	-160	-110	_	-65	-40		-20		-7	0				
24	30	300										U				
30	40	-310	-170	-120		-80	-50	_	-25		-9	0				
40	50	-320	-180	-130		80						U				
50	65	-340	-190	-140		-100	-60	_	-30		-10	0				
65	80	-360	-200	-150		100										
80	100	-380	-220	-170		-120	<del>-72</del>		-36	_	-12	0				
100	120	-410	-240	-180			-72					U				
120	140	-460	-260	-200	_	-145	<b>-85</b>		-43	_	-14					
140	160	-520	-280	-210								0				
160	180	-580	-310	-230												
180	200	-660	-340	-240		-170	-100	_	-50	_	-15					
200	225	-740	-380	-260	_							0				
225	250	-820	-420	-280												
250	280	-920	-480	-300		-190	-110		-56	_	-17	0				
280	315	-1050	-540	-330								U				
315	355	-1200	-600	-360		-210	-125		-62	_	-18	0				
355	400	-1350	-680	-400								U				
400	450	-1500	-760	-440		_220	-135		-68	_	-20	0				
450	500	-1650	-840	-480	_	-230	-155					U				

公称尺寸	寸 (mm)	基本偏差数值(下极限偏差 ei)(μm)																		
大于		IT5,IT6	IT7	IT8	IT4~IT7	≤IT3 >IT7	所 有 标 准 公 差 等 级													
	至	i		k		m	n	р	r	S	t	u	v	X	y	Z	za	zb	zc	
	3	-2	-4	-6	0	0	+2	+4	+6	+10	+14	_	+18	_	+20	_	+26	+32	+40	+60
3	6	-2	-4		+1	0	+4	+8	+12	+15	+19		+23		+28		+35	+42	+50	+80
6	10	-2	<b>-</b> 5	_	+1	0	+6	+10	+15	+19	+23	_	+28		+34		+42	+52	+67	+97
10	14	-3	-6		+1	0	+7	+12	+18	+23	+28	- +3	.22	_	+40		+50	+64	+90	+130
14	18												+33	+39	+45		+60	+77	+108	+150
18	24	-4	-8		+2	0	+8	+15	+22	+28	+35		+41	+47	+54	+63	+73	+98	+136	+188
24	30	4									+33	+41	+48	+55	+64	+75	+88	+118	+160	+218
30	40	<b>-</b> 5	-10		+2	0	+9	+17	+26	+34	+43	+48	+60	+68	+80	+94	+112	+148	+200	+274
40	50	_3										+54	+70	+81	+97	+114	+136	+180	+242	+325
50	65		-12	_	+2	0	+11	+20	+32	+41	+53	+66	+87	+102	+122	+144	+172	+226	+300	+405
65	80	7								+43	+59	+75	+102	+120	+146	+174	+210	+274	+360	+480
80	100	_9	-15	_	+3	0	+13	+23	+37	+51	+71	+91	+124	+146	+178	+214	+258	+335	+445	+585
100	120	-9								+54	+79	+104	+144	+172	+210	+254	+310	+400	+525	+690
120	140		-18	_	+3	0	+15	+27	+43	+63	+92	+122	+170	+202	+248	+300	+365	+470	+620	+800
140	160	-11								+65	+100	+134	+190	+228	+280	+340	+415	+535	+700	+900
160	180									+68	+108	+146	+210	+252	+310	+380	+465	+600	+780	+1000
180	200		-21	_	+4	0	+17	+31	+50	+77	+122	+166	+236	+284	+350	+425	+520	+670	+880	+1150
200	225	-13								+80	+130	+180	+258	+310	+385	+470	+575	+740	+960	+1250
225	250									+84	+140	+196	+284	+340	+425	+520	+640	+820	+1050	+1350
250	280	-16	-26		+4	0	+20	+34	+56	+94	+158	+218	+315	+385	+475	+580	+710	+920	+1200	+1550
280	315								+30	+98	+170	+240	+350	+425	+525	+650	+790	+1000	+1300	+1700
315	355	-18	-28	—	+4	0	+21	+37	+62	+108	+190	+268	+390	+475	+590	+730	+900	+1150	+1500	+1900
355	400						<b>⊤∠1</b>			+114	+208	+294	+435	+530	+660	+820	+1000	+1300	+1650	+2100
400	450	-20	-32		+5	0	+23	+40	+68	+126	+232	+330	+490	+595	+740	+920	+1100	+1450	+1850	+2400
450	500		32				+23	+40	+00	+132	+252	+360	+540	+660	+820	+1000	+1250	+1600	+2100	+2600

注: 公称尺寸小于或等于 1mm 时,基本偏差 a 和 b 均不采用。公差带 js7~js11,若 ITn 数值为奇数,则取偏差= $\pm \frac{ITn-1}{2}$ 。