

Activity Hazard Analysis (AHA)

Date:	Negligible Risk (N) – Level of risk is common.	RISK ASSESSMENT RATING (RAR)			
Job Name: Stack NVA04	Very Low (1) – Level of risk is common for trained personnel.				
Job Number: 21232	Low Risk (2) – Review procedures and mitigation methods.				
Location: Gallery 1259/1159	Medium Risk (3) – Formal written procedure / permit approved by management.	Severity of Potential Consequences			
Activity: Replace 12" Victaulic Coupling in Gallery 1259	High Level (4) – Unacceptable risk. Repeat the risk assessment process.	Extremely Low - 1	Low - 2	Medium - 3	High - 4
Likelihood of Occurrence	Extremely Low – 1	N	N	1	1
	Low - 2	N	1	2	2
	Medium - 3	1	2	3	4
	High - 4	1	3	4	4

Company Name: Poole and Kent	Superintendent: Justin Trapnell
Project Manager: Jake Medina	Foreman:
Safety Representative: Daniel Caldwell	Competent Person: Andrew Lis

#	Steps of the Job	Potential Hazards	Safety Controls	RAR
	Working in Proximity to Live Electrical Equipment	- Electrocution - Arc Flash	- Identify all power sources, and barricade off if possible - Ensure all workers are aware of live electrical sources, and maintain proper distances - Keep area clean and dry at all times - NFPA 70E/Arc Flash training	2
1	Transport materials into work area.	- Injuries from improper lifting/carrying of materials, trips falls & obstacles. - Compromised Social Distancing - Pipes placed on carts can swing unexpectedly, causing personnel or property damage	- Use proper technique when lifting/carrying materials; use 2-man crew to lift heavy items. Occasionally when doing a team lift, workers will be within 6' for an extended duration. Workers to wear face covering and aim to minimize close contact to less than 15min at a time. - Team Lift when lifting awkwardly shaped packages, or those weighing over 50 lbs. - Always be aware of surroundings & hazards. - Always wear proper PPE gear. - Provide flagger when necessary for directing lull operator and clearing access path.	1

Activity Hazard Analysis (AHA)

		-	- Provide spotter while crew moves pipes on carts, alerting both crew and pedestrians of potential hazards	
2	Prepare area for scissor/aerial lift travel.	- Increased slip, trip and fall potential. - Scissor lift tip potential - Struck by -	- Discuss slip, trip and fall potential during daily briefing. - Good Housekeeping - Area should be inspected for holes, gaps, and uneven flooring to minimize tipping of the lift - Use a spotter to communicate hazards and persons unseen to the operator	1
3	Working from heights	- Falls - Overhead hazards -	- 100% tie off to a properly load rated anchor point and usage of connection device. Using proper fall protection equipment & methods. - Inspecting and properly fitting harness and connection device. - Always be aware of surroundings/hazards and barricade off working space when necessary. - Inspect PFAS prior to use, if any damage is found (tears, load markers are exposed, burns, etc.) tag out of service and retrieve new PFAS to also be inspected prior to use. - When possible, fall restraint is encouraged.	2
4	Pipe/Hanger Assembly	- Falling objects (tools/material) - Struck by/Pinch points - Strains/ Heavy lift	- Area below to be properly barricaded - Proper hazard communication to alert other workers and trades of overhead work hazard - Spotter - Utilize mechanical means of lifting and rigging pipe and hangers into place Ensure that all toe boards are in place and well maintained before beginning elevated work	2
5	Operating Chainfall/Duct Jack/Roust-a-Bout	- Hand Injury - Falling Objects - Faulty equipment - Sprains/Strains - Finger amputation	- Wear proper cut-resistant gloves - Inspect rigging equipment - Proper attachment methods - Ensure cables are wound smoothly to reel - Ensure crew is not overexerting themselves or improperly hoisting equipment to ensure no MSD's - Ensure there are no kinks in the chain and that crew are working at a reasonable pace as to not get fingers caught	2

Activity Hazard Analysis (AHA)

--	--	--	--	--

Activity Hazard Analysis (AHA)

Equipment to be Used	Training	Inspection Requirements
Hand tools	Crew trained/certified to use hand tools	Crew inspects tools daily for any defects or damage and verify tools are in working order; Tools are discarded if defective.
Fall protection equipment	Fall protection	Inspect all connection devices and harnesses prior to each use. If found to be damaged or defective, place a "Do Not Use" tag and remove from service. Ensure body harnesses are fitted properly.
Scissor lift	Lift training	Inspect all lifts prior to each use. If found to be damaged or defective, place a "Do Not Use" tag and remove from service.
Chain fall	Proper rigging training	Crew inspects chains and pulleys prior to each use. If found to be damaged or defective, place a "Do Not Use" tag and remove from service.

Activity Hazard Analysis (AHA)

Activities Requiring a Competent or Qualified Person – Attach Proof of Competency	
Activity	Designated Competent or Qualified Person
Working in Live Data Hall Gallery	Andrew Lis

Activity Hazard Analysis (AHA)

Signatures / Verification of Review		
Name (Print)	Signature	Date


Activity Hazard Analysis (AHA)

CERTIFICATE OF COMPLETION

This is to certify that

Andrew Lis

Has participated in a safety course on Electrical Safe Work Practices – NFPA 70E – and is aware of the principles associated with the recognition of applicable hazardous energy sources, details about the type and magnitude of the hazardous energy sources, the personal protective equipment and the methods and means necessary to isolate and control these energy sources.



Vincent R. Miller, CSP
February 22, 2024

