

Work order report

Tag: 42FIT4018

Location: P141 Process Area, Lower Deck, Section 41

System: 42 Chemical injection systems

Maintenance plan: REP Repairs collector

Resp. department: Instr. land

Event: EV0000046994 Tuning of PID Controller Remarks: 2024.04.03 14:51:09: Tormod Stautland Stokka

PID Controller til 42FIT4018 tunet.

Før --> Etter

Kc (Gain): 1 --> 0.75

Ti (Integral tid): 200--> 22 sek

Testet OK.

Damping på 20 sek på SAS er fjernet pga det er 10 sek damping på instrumentet.

Comments:



Repair activity

Task finished:



Finish all steps

Tuning of PID controllers A/B on SAS for 42FIT4018.

Both pumps A/B will be performance tested and optimized.

The system will be tested for deviations, over/under damping effects and general errors.

All concerning tags referenced to the P&ID.

- -Perform step response testing, calculations and parameterization.
- -Test and implement.

Qualifications

Name	Qualification	Min. manpower	Planned time	Assignend persons
QR01		1	4 h	

42FIT4018 Flocculant 42PD007A/B >> P141

4.0 h WO0000667341 Finished:



=ORG.F.WO0000667341.MRP.001 Print date: 03.04.2024 Page 1 / 1