A

Voltage (V)

V_b

V_a

Time (ms)

Frame Clock

B

Voltage (V)

+5v

0

-5v

T_{raise}

T_{fall}

Time (ms)

Line Clock

$$\frac{T_{raise}}{T_{fall}} = \frac{5}{1} or \frac{9}{1}$$

C

Voltage (V)

2.5v

0

From Laser
20Mhz

Time (ms)

SYNC Clock

D

Voltage (V)

2.5v

0

Time (ms)

Trigger Clock