



 $RMS_{x} = 4.2[\mu rad]$ $RMS_{x} = 0.105[mm]$ $RMS_{y} = 4.6[\mu rad]$ $RMS_{y} = 0.116[mm]$