



 $RMS_x = 5.1[\mu rad]$

 $RMS_{x} = 0.128[mm]$

 $RMS_y = 3.6[\mu rad]$

 $RMS_{V} = 0.09[mm]$