



 $RMS_x = 4.2[\mu rad]$

 $RMS_{x} = 0.105[mm]$

 $RMS_y = 4.6[\mu rad]$

 $RMS_{y} = 0.116[mm]$