

Service Report

Field details

Site	Kavanagh Industries
Date of service	22-07-2026
Machine / asset	Laser cutter
Reported faults	Coil feed inspection
Affected components	Automated coil feed
Attending engineer	Trevor Blevins
Technician onsite	Supplier technicians
Service call type	Inspection

Initial assessment & findings

Visited for inspection of the new automated coil feed system.

Actions taken

1. Coil feed inspection

- **Inspection:** Reviewed electrical drawings and machine operations with supplier technicians.
- **Findings:** System present; drawings reviewed.
- **Action:** Discussed operations on site.

Conclusion & recommendations

- **Summary:** Inspection visit completed 07:00–12:00.
- **Operational test / follow-up:** Continue commissioning with supplier.