

Information

$$\frac{A\omega_n^2}{s^2 + 2\zeta\omega_n s + \omega_n^2}$$

$$\omega_d = \omega_n \sqrt{1 - \zeta^2}$$

$$\cos \theta = \zeta$$

$$t_p = \frac{\pi}{\omega_d}$$

$$y_p = A \left(1 + e^{-\zeta\pi/\sqrt{1-\zeta^2}} \right)$$

$$t_r = \frac{\pi - \theta}{\omega_d}$$

$$t_{k\%} = \frac{\ln \left(\frac{k}{100} \sqrt{1 - \zeta^2} \right)}{-\zeta\omega_n}$$

$$\%OS = 100e^{\left(\frac{-\zeta\pi}{\sqrt{1-\zeta^2}} \right)}$$

Laplace transforms of signals:

$y(t)$	$Y(s)$	Comments
$\sigma(t)$	$\frac{1}{s}$	unit step
$t\sigma(t)$	$\frac{1}{s^2}$	unit ramp
$e^{-at}\sigma(t)$	$\frac{1}{(s+a)}$	decaying exponential if $a > 0$
$t^n e^{-at}\sigma(t)$	$\frac{n!}{(s+a)^{(n+1)}}$	n^{th} order exponential
$\sin(\omega t)\sigma(t)$	$\frac{\omega}{s^2 + \omega^2}$	sinusoid
$\cos(\omega t)\sigma(t)$	$\frac{s}{s^2 + \omega^2}$	<u>cosinusoid</u>
$e^{-at}\sin(\omega t)\sigma(t)$	$\frac{\omega}{(s+a)^2 + \omega^2}$	damped sinusoid
$e^{-at}\cos(\omega t)\sigma(t)$	$\frac{s+a}{(s+a)^2 + \omega^2}$	damped <u>cosinusoid</u>