
Cube/base distance (mm)
Tool lift from start (mm)
Measured tool grasp (0/1)
Tool/cube contact proxy (N)
TCP-relative tool x (mm)
Declared target distance (mm)
Ordinary terminal Q
Relative + contract candidate
Native threshold
Recorded physical control step