
Three independent 16-point Hadamard transforms
Each: 4 row producers -> 4 column consumers
Rows
A0 A1 A2 A3 B0 B1 B2 B3 C0 C1 C2 C3
A: all 4
B: all 4
C: all 4
Cols
A0 A1 A2 A3 B0 B1 B2 B3 C0 C1 C2 C3
Slot 0
A live
C live
Slot 1
B live
Slot 0: C starts after A's final column read.
0
4
8
12
16
Illustrative units; overlap requires available resources.