

## **RESISTANCES & DIODES**



## **CAPACITORS & IC**



- 1. Place the potentiometers, minijacks and leds (without soldering). Place the panel and all the nuts on the components.
- 2. Solder the potentiometers, minijacks and leds

