

RESISTANCES & DIODES



CAPACITORS & IC



- 1. Place the potentiometers, minijacks and leds (without soldering). Place the panel and all the nuts on the components.
- 2. Solder the potentiometers, minijacks and leds

