

SAFE WORK METHOD STATEMENT (SWMS)

DOCUMENT CONTROL	
SWMS_ID	SWMS-024
SWMS_Title	Confined Space Entry
SWMS_Version	1.0
SWMS_Type	☒ Core SWMS ☐ Routine Task SWMS ☐ Non-Routine Task SWMS
Status	☐ Draft ☐ Current ☐ Superseded
Current_Version	
Authorised_By	Chris Foster
Authorised_Date	24/06/2026
Review_Date	24/07/2027
Review_Period_Months	12
Review_Trigger	☒ Initial Issue ☐ Incident ☐ Legislative Change ☐ Procedure Change ☐ Equipment Change ☐ Risk Assessment Review ☐ Scheduled Review
Linked_Core_SWMS	Isolation & LOTO SWMS-005 Hot work
Revision_Summary	Initial Issue

REVISION HISTORY

Version	Date	Change Summary	Authorised By
1.0	24/06/2026	Initial Issue	Chris Foster

EXTREME & VERY HIGH RISK HAZARDS	Risk	MAIN RISKS / PERMITS REQUIRED
1. Entering a Confined Space.	E	- Heat exhaustion, engulfment, limited access/egress. - Asphyxiation – low O₂ or contaminants. (Confined Space Entry Permit required) - Explosive atmosphere, combustible dusts (Confined Space Entry/Hot Work Permits required)
2. Work in an area which may have a contaminated or flammable atmosphere.	E	- Fire / explosion from ignition source. (Hot Work Permit required) - Asphyxiation or poisoning from contaminated atmosphere. (Confined Space Permit)
3. Work with potential for a fall from 2m or work on a roof	E	Falling worker/object ≥2m requires SWMS.
4. Hot work required. (Oxy cutting, welding, soldering, grinding, etc).	E	- Fire or explosion from ignition source. (Hot Work Permit required) - Injury caused by hot surface, grinding wheel ejected pieces, welders “flash”, etc. - Fire inside Expanded Polystyrene (EPS) wall panels (Hot Work Permit required).
5. Hand dig >200mm OR ground penetration >200mm OR mechanical earthworks OR enter a trench >1.5 M deep (excavating is Construction work)	E	- Contact utilities – electricity, water, gas, communications. (Excavation Permit required) - Trench Collapse. (Excavation Permit required)
6. Non routine electrical, high voltage or ‘live’ work or work near electrical installations.	E	- High voltage is >33kV. ‘Live’ work is when electrical equipment is worked on energised – (Management Approval Required) - Electrical cabinets or MCC identified as Red
7. Non routine work involving mechanical lifting, lowering, pushing or pulling.	E	- High mechanical force damage / injury. - High risk work licence for use of cranes, mobile plant, scaffold, dogging, etc.
8. Using high risk tools with excess noise, kickback, cutting edge, high speed/pressure, ejected material, weight, awkward posture, explosive force.	E	- Injury from use of high risk powered or hand tools. - Electrocution, burn or electric shock. - Manual task injury from weight, forces, overexertion, repetition or poor work heights.
9. Demolish / alter load bearing / integral part of a structure 6m high OR use load shifting machinery on a suspended floor OR use explosives. Includes modify handrail / floors.	E	- Being struck or crushed by parts of a structure or exposure to asbestos, lead, hazardous chemicals etc. (Demolition License and/or asbestos removal licence and Safe Work Plan required)
10. Work inside fences / barricades / enclosures where moving / rotating machinery is operating or hazards may exist.	V	- Serious bodily injury caused by contacting moving/unguarded plant or materials. - Machinery starting unexpectedly or electrocution, burn or electric shock.
11. Potential or stored energy which cannot be isolated (electrical, hydraulic, pneumatic, kinetic).	V	- Electrocution or entrapment. - Machinery entanglement / injury.
12. Work on or near a pressurized or enclosed circuit (water, pneumatic, hydraulic, hot oil, etc).	V	- Fracturing the mains or piping from contact – spills / leaks / emissions (environment). - Contacting temperature extremes.
13. Working in artificial temperature extremes or weather extremes. Hot, cold, wet, icy, lightning, high winds.	V	- Electrocution from using power tools / leads in wet conditions or lightning. - Heat stroke / Heat Exhaustion / Fatigue / Frost bite / Hypothermia / Influenza. - Slip / Trip / Fall Hazards.

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v1.0	Page 1 of 5
Doc Owner: Tuan Safety and Compliance Officer	Issue Date: 20 November-2024
Review: 20-Nov-2025	Version No: 001

SAFE WORK METHOD STATEMENT (SWMS)

14. Hazardous manual tasks or excessive noise or excessive vibration.	V	• Personal injury/illness or hearing loss.
15. Using a hazardous chemical – chemicals, heavy metals, asbestos, Lead.	V	• Exposure to hazardous chemicals. • Spills / leaks (environmental).
16. Work on or adjacent to road, rail line or water body.	V	• Being hit by passing traffic or drowning.
17. Work on or near a chemical, glue, fuel, oil or refrigerant line / system.	V	• Contact chemicals (contamination, injury, etc). • Fracturing the line from contact – fire or explosion from ignition source – spill / leak.
18. Changes to software control system.	V	• Change to way plant / equipment operates & workers not retrained.
19. Other (Specify):		

Identify task high risk workplace hazards – *Non routine work is work not documented in a Safe Operating Procedure (SOP)* or Work Instruction
 Note: If machine isolation is required, workers must be competent in the relevant isolation procedure.

LIKELIHOOD	RISK SCORE CALCULATOR				
Certain to Occur	Mod.	High	High	Extreme	Extreme
Very Likely	Mod.	Mod.	High	Very High	Extreme
Possible	Low	Mod.	High	Very High	Very High
Unlikely	Low	Mod.	Mod.	High	Very High
Rare	Low	Low	Low	Mod.	High
CONSEQUENCE	LOW	MINOR	MODERATE	FATAL	CATASTROPHIC

HIERARCHY OF CONTROLS

In order of priority:

1. Elimination – Remove the hazard completely.
2. Substitution – Replace the object/process with a less hazardous one.
3. Isolation – Isolate the hazard (i.e. separate the hazard from people).
4. Engineering – Modify a process (i.e. redesign a workstation).
5. Administration – Use procedures/systems to minimise the risk (i.e. rotation of employees, training, etc.).
6. Personal Protective Equipment (PPE) – use to try to protect the person.

Residual Risk	Action Required
Low	Ok for now. Continue to monitor.
MODERATE	Determine if remedial action/treatment is required.
HIGH	Immediate decision required by site leadership. Identify and commence remedial action with appropriate priority.
VERY HIGH	ACT NOW. Requires immediate attention by site leadership. Address the risk without delay. Requires urgent attention and clear, timely action plans to reduce the risk before proceeding.
EXTREME	ACT NOW. Requires immediate attention by site leadership. Urgently address the risk. Requires immediate resolution with focused attention until resolved.

SWMS ID: SWMS-024		SWMS Title: Confined Space	
Prepared By: Chris Foster		Date: 24/06/2026	
Business Name: Tuan Biomass Albioma			
Description of Task: Entry into a confined space for inspection, cleaning, maintenance, repair, installation, monitoring or testing activities within plant and equipment.			
Reason for analysis: ☐ New task/plant ☒ High Risk Task ☐ Change ☐ Regular review ☐ Post-Incident ☐ Contractor (to complete) Task ☐ Non-Routine Task ☐ Maintenance/Repair ☐ Other (specify):			
SWMS Team Names: 1. Chris Foster		2. David Knight	3.
4.		5.	6.
Permits Required: Confined Space ☒ Risk of Falls ☒ Excavation ☐ Hot Work ☒		PPE Requirements:              Other:	

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v1.0	Page 2 of 5
Doc Owner: Tuan Safety and Compliance Officer	Issue Date: 20 November-2024
Review: 20-Nov-2025	Version No: 001

SAFE WORK METHOD STATEMENT (SWMS)

Potential Environment Hazards	Fire/Emergency Response Equipment
Noise pollution ☒ Air pollution dust/smoke ☒ Spills to ground ☒ Soil erosion ☒ Hazards to flora & fauna ☒ Spills to water ☒	1. First Aid Kit (<i>Location</i>) <i>Smoko Room</i> 2. Communication method/details 3. Verbal, 2way radio, landline phone 4. Fire hose 5. Other: _____
Hazards Identified	
☒ Electricity ☒ Confined Space ☒ Stored Energy ☒ Extreme Temperatures ☒ Dust and or fume ☒ Hazardous Manual Tasks ☒ Psychological ☒ Traffic/Mobile Plant ☒ Ignition Sources ☒ Lighting ☒ Machinery & Equipment ☒ Person/Object Falling ☒ Pressure (air, water, gas) ☒ Object Falling ☒ Hazardous Chemicals Hot Work ☒ Other workers/people	
Other Comments	
- Entry shall comply with the Queensland Confined Spaces Code of Practice. - Standby person must remain outside the confined space for the duration of entry. - Standby person must not enter the confined space during an emergency. - Rescue must be undertaken in accordance with the documented rescue plan. - Continuous atmospheric monitoring may be required depending on the task and environment. - All workers entering the confined space must be trained and competent.	

REQUIRED CORE SWMS

List the Core SWMS that also apply to this task. Linked Core SWMS must be read and signed on through the online SWMS Register together with this SWMS.

Applies	Core SWMS	Linked SWMS_ID
☒	Isolation and LOTO	
☐	Hot Work	SWMS-005
☒	Confined Space Entry	SWMS-024
☐	Working at Heights	
☐	Crane and Lifting Operations	
☒	Working on un-isolated plant	

CRITICAL CONTROLS

The following critical controls must be in place and verified before work starts.

#	Critical Control (must be in place before work starts)	In place
1	Confined Space Permit issued and authorised	☐
2	Isolation and LOTO completed, verified and tested for zero energy	☐
3	Atmospheric testing completed and atmosphere remains safe	☐
4	Standby person present and communication maintained	☐
5	Rescue equipment available and rescue plan confirmed	☐
6	Entry point secured and unauthorised access prevented	☐

If a critical control cannot be implemented, work must stop and the SWMS must be reviewed before proceeding.

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v1.0	Page 3 of 5
Doc Owner: Tuan Safety and Compliance Officer	Issue Date: 20 November-2024
Review: 20-Nov-2025	Version No: 001

SAFE WORK METHOD STATEMENT (SWMS)

Logical Steps in order

Key Steps in Logical Order		Hazards/Risks to Workers or Public	Risk Score	Control Measures	Residual Risk Score
1	Plan and prepare work	Inadequate planning, unidentified hazards	High	Review SWMS, permit, rescue plan, worker competency verified	Med
2	Isolate plant and services	Unexpected start-up, stored energy	High	Apply LOTO, test for dead, isolate electrical, hydraulic, pneumatic, gravity and mechanical energy	Med
3	Atmospheric testing	Oxygen deficiency, toxic gas, combustible atmosphere	High	Test atmosphere before entry and continuously where required. Oxygen 19.5%-23.5%. Flammables below limits.	Med
4	Establish entry controls	Unauthorised entry, delayed rescue	High	Barricade area, maintain standby person, communication equipment available	Low
	Enter confined space	Asphyxiation, heat stress, engulfment, restricted movement	High	Permit active, monitor atmosphere, maintain communication, adequate ventilation, competent workers only	Med
	Perform work inside space	Injury from tools, manual handling, dust, noise	High	Use correct PPE, maintain housekeeping, control dust, use suitable tools and lighting	Med
	Conduct hot work (if required)	Fire or explosion	High	Hot Work Permit, remove ignition sources, continuous gas monitoring, fire protection available	Med
	Exit confined space	Personnel left inside, equipment left behind	High	Head count, remove tools, inspect area before closure	Low
	Close permit and return to service	Premature restart, exposure to hazards	High	Confirm all personnel clear, remove locks under procedure, sign off permit	Low

Add additional job steps, hazards and controls as required

AUTHORISATION		
Approved by: Chris Foster	Position: Safety and Compliance manager	Approval Date: 24/06/2026

CONTROLLED MASTER DOCUMENT	
Doc Id: SWMS – 001- 2024-v1.0	Page 4 of 5
Doc Owner: Tuan Safety and Compliance Officer	Issue Date: 20 November-2024
Review: 20-Nov-2025	Version No: 001

SAFE WORK METHOD STATEMENT (SWMS)

All relevant workers must be consulted during the development and review of this SWMS and made aware of the control measures and all required permits. Worker consultation and sign-on are recorded through the online SWMS Register.

ONLINE SWMS MANAGEMENT

Worker sign-on is completed through the online SWMS Register.

Workers are required to read and sign onto this SWMS once per review period, or sooner if the SWMS is revised, superseded, or changed due to an incident, equipment change, procedure change, legislative change, or risk assessment review.

Before each task commences, the supervisor or person in control of the work must review the SWMS through the online task review system and confirm whether anything has changed from the approved SWMS.

If no changes are identified, the task may proceed once all workers are confirmed as current against the required SWMS.

If changes are identified, the changes and additional controls must be recorded in the online Task Record before work proceeds.

Supervisor review is required where the change affects the work method, plant, equipment, location, hazards, permit requirements, or critical controls.

System of record

This Word document is the controlled master SWMS. The PDF is the worker-view copy. The HTML tablet page is used to view the SWMS and complete the task review.

Worker sign-off is stored in Worker_SWMS_Register. Daily task reviews are stored in Task_Records. Review dates and version status are controlled in SWMS_Library.

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v1.0	Page 5 of 5
Doc Owner: Tuan Safety and Compliance Officer	Issue Date: 20 November-2024
Review: 20-Nov-2025	Version No: 001