

SAFE WORK METHOD STATEMENT (SWMS)

DOCUMENT CONTROL	
SWMS_ID	SWMS-022
SWMS_Title	Conveyor Belt maintenance
SWMS_Version	1.1
SWMS_Type	☐ Core SWMS ☒ Routine Task SWMS ☐ Non-Routine Task SWMS
Status	☐ Draft ☒ Current ☐ Superseded
Authorised_By	Chris Foster
Authorised_Date	26/06/2026
Review_Date	26/07/2027
Review_Period_Months	12
Review_Trigger	☐ Initial Issue ☐ Incident ☐ Legislative Change ☐ Procedure Change ☐ Equipment Change ☐ Risk Assessment Review ☒ Scheduled Review

REVISION HISTORY

Version	Date	Change Summary	Authorised By
1.0	12/04/2025	Initial Issue	Chris Foster
	26/05/2026	Scheduled Review	Chris Foster

SWMS ID: SWMS-022		SWMS Title: Conveyor Belt maintenance	
Prepared By: Chris Foster		Date: 26/06/2026	
Business Name: Tuan Biomass Albioma			
Description of Task: Carry out inspection, maintenance, repair and replacement of conveyor belt components, including rollers, bearings, scrapers, paddles, deflectors, guards and associated equipment. Work includes isolation, removal and reinstatement of guarding, testing and recommissioning of the conveyor system.			
Reason for analysis: ☐ New task/plant ☐ High Risk Task ☐ Change ☐ Regular review ☐ Post-Incident ☐ Contractor (to complete) Task ☐ Non-Routine Task ☒ Maintenance/Repair ☐ Other (specify):			
SWMS Team Names: 1. Chris Foster		2. David Knight	
4.		5.	
Permits Required: (circle) Confined Space ☐ Isolation ☐ Hot Work ☐		PPE Requirements:            Other:	

SAFE WORK METHOD STATEMENT (SWMS)

Potential Environment Hazards	Fire/Emergency Response Equipment
☒ Noise / vibration ☒ Air pollution – dust / smoke / fume ☒ Spills to ground ☒ Spills to water / drains / waterways ☒ Soil erosion / contamination ☐ Hazards to flora & fauna ☐ Waste generation & disposal ☐ Hazardous chemicals / substances ☐ Vegetation / bushfire risk ☐ Other: _____	☒ Fire extinguisher — Location: Main shed wall ☒ Fire hose / hydrant — Location: Walking Floor, Shavings silo, inside shed ☒ First aid kit — Location: Smoko Room ☒ Spill kit — Location: Inside the North Entry door ☒ Emergency eyewash / shower — Location: Outside the workshop ☒ Emergency assembly point — Location: ☒ Communication method: ☐ Radio ☐ Phone ☐ Verbal ☒ Emergency contact No: 0439 013 224
Hazards Identified	
☒ Electricity ☐ Confined Space ☐ Stored Energy ☐ Extreme Temperatures ☒ Dust and or fume ☒ Hazardous Manual Tasks ☐ Psychological ☐ Traffic/Mobile Plant ☐ Ignition Sources ☐ Lighting ☒ Machinery & Equipment ☒ Person/Object Falling ☐ Pressure (air, water, gas) ☒ Object Falling ☐ Hazardous Chemicals ☐ Hot Work ☐ Other workers/people	
Other Comments:	

REQUIRED CORE SWMS

List the Core SWMS that also apply to this task. Linked Core SWMS must be read and signed on through the online SWMS Register together with this SWMS.

Applies	Core SWMS	Linked SWMS_ID
☒	Isolation and LOTO	SWMS-026
☐	Hot Work	SWMS-005
☐	Confined Space Entry	SWMS-024
☒	Working at Heights	SWMS-025
☐	Crane and Lifting Operations	SWMS-026
☒	Working on Un-isolated plant	SWMS-027

CRITICAL CONTROLS

The following critical controls must be in place and verified before work starts.

#	Critical Control (must be in place before work starts)
1	Conveyor fully isolated using the Lock Out Tag Out (LOTO) procedure. All energy sources isolated, personal locks applied and zero energy verified before work commences.
2	All guards and safety devices removed for maintenance must be reinstated and inspected before the conveyor is returned to service.
3	Work at height only from approved platforms or walkways. Workers must maintain three points of contact and use fall protection where required.
4	Exclusion zones established below elevated work areas to prevent exposure to falling tools, components and materials.
5	Conveyor must not be recommissioned until all personnel are clear, tools removed, guards fitted and a controlled start-up completed.
6	Replacement of heavy rollers, bearings and conveyor components must use suitable lifting equipment and be completed by competent personnel to eliminate crush and manual handling risks.

If a critical control cannot be implemented, work must stop and the SWMS must be reviewed before proceeding.

CONTROLLED MASTER DOCUMENT	
Doc Id: SWMS – 001- 2024-v2.0	Page 2 of 4
Doc Owner: Tuan Safety and Compliance Manager	Issue Date: 20 November-2024
Last Review: 24-Jun-2026	Version No: 001

SAFE WORK METHOD STATEMENT (SWMS)

Key Steps in Logical Order		Hazards/Risks to Workers or Public	Risk Score	Control Measures	Residual Risk Score
1	Work preparation and access	- Slips, trips and falls. - Falls from height while climbing to access conveyors. - Dropped tools or materials during access.	Significant	-Barricade work area below access points. -Clear sawdust debris and spillage from access ways. -Maintain three points of contact when climbing. -Do not carry tools while climbing. -Tools and materials to be raised using rope swing only.	Medium
2	Isolation of conveyor and energy sources	Unexpected start-up. Stored energy. Entanglement.	High	-Complete an isolation request form -Shut down conveyor. -Isolate all energy sources. Apply lockout/tagout. -Each worker applies personal lock. -Test for zero energy before work starts.	Medium
2	Accessing conveyor and work area	Falls from height. Slips and trips	Significant	-Access via fixed walkways and platforms only. -Walkways to be kept clear of sawdust, spillage and obstructions. -Maintain three points of contact when stepping onto walkways. -Use installed handrails at all times. -Barricade and sign areas below elevated walkways where work is occurring. -Tools secured when working adjacent to edges.	Medium
4	Removal of guards, covers and components	Pinch points. Dropped objects. Manual handling injuries.	Significant	-Confirm isolation remains in place. -Remove guards carefully. -Wear gloves if required. -Store removed covers safely.	Medium
5	Replacing belt scrapers, paddles and deflectors	Pinch points. Sharp edges. Awkward postures.	Significant	-Use correct tools. -Keep hands clear when rolling tail roller. -Wear gloves if required.	Medium
6	Replacing rollers, snub rollers and bearings	Crushing injuries. Dropped rollers.	High	-Work to done by trade -Keep hands clear of pinch points.	Medium
8	Re-installation of guards and covers	Incomplete guarding. Dropped tools.	Significant	-Reinstall all covers. -Ensure fixings are secure (min 2 bolts per cover). -Conduct final inspection. -Remove tools and materials from area.	Low
9.	Testing and recommissioning	Unexpected movement. Entanglement. Noise.	Significant	-Clear personnel from conveyor. -Communicate before de-isolation. - Remove locks per LOTO process. - Controlled test run.	Medium
10.	Housekeeping and Clean up.	Slips and trips. Plant–pedestrian interaction.	Significant	- Clean up debris and spillage. - Remove barricades when safe. - Report defects. Sign off SWMS.	Low

Add additional job steps, hazards and controls as required

All relevant workers must be consulted during the development and review of this SWMS and made aware of the control measures and all required permits. Worker consultation and sign-on are recorded through the online SWMS Register.

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v2.0

Page **3** of **4**

Doc Owner: Tuan Safety and Compliance Manager

Issue Date: 20 November-2024

Last Review: 24-Jun-2026

Version No: 001

SAFE WORK METHOD STATEMENT (SWMS)

ONLINE SWMS MANAGEMENT

Worker sign-on is completed through the online SWMS Register.

Workers are required to read and sign onto this SWMS once per review period, or sooner if the SWMS is revised, superseded, or changed due to an incident, equipment change, procedure change, legislative change, or risk assessment review.

Before each task commences, the team or person in control of the work must review the SWMS through the online task review system and confirm whether anything has changed from the approved SWMS.

If no changes are identified, the task may proceed once all workers are confirmed as current against the required SWMS.

If changes are identified, the changes and additional controls must be recorded in the online Task Record before work proceeds.

Supervisor review is required where the change affects the work method, plant, equipment, location, hazards, permit requirements, or critical controls.

System of record

This Word document is the controlled master SWMS. The PDF is the worker-view copy. The HTML tablet page is used to view the SWMS and complete the task review.

Worker sign-off is stored in Worker_SWMS_Register. Daily task reviews are stored in Task_Records. Review dates and version status are controlled in SWMS_Library.

AUTHORISATION**Approved by:** Chris Foster**Position:** Safety and Compliance Manager**Approval Date:** 25/06/2026**CONTROLLED MASTER DOCUMENT****Doc Id:** SWMS – 001- 2024-v2.0Page **4** of **4****Doc Owner:** Tuan Safety and Compliance Manager**Issue Date:** 20 November-2024**Last Review:** 24-Jun-2026**Version No:** 001