

SAFE WORK METHOD STATEMENT (SWMS)

DOCUMENT CONTROL	
SWMS_ID	SWMS-024
SWMS_Title	Confined Space Entry
SWMS_Version	1.0
SWMS_Type	☒ Core SWMS ☐ Routine Task SWMS ☐ Non-Routine Task SWMS
Status	☐ Draft ☐ Current ☐ Superseded
Authorised_By	Chris Foster
Authorised_Date	25/06/2026
Review_Date	25/07/2027
Review_Period_Months	12
Review_Trigger	☒ Initial Issue ☐ Incident ☐ Legislative Change ☐ Procedure Change ☐ Equipment Change ☐ Risk Assessment Review ☐ Scheduled Review

REVISION HISTORY

Version	Date	Change Summary	Authorised By
1.0	25/06/2026	Initial Issue	Chris Foster

SWMS ID: SWMS-024	SWMS Title: Confined Space Entry	
Prepared By: Chris Foster		Date: 24/06/2026
Business Name: Tuan Biomass Albioma		
Description of Task: Entry into a confined space for inspection, cleaning, maintenance, repair, installation, monitoring or testing activities within plant and equipment.		
Reason for analysis: ☐ New task/plant ☒ High Risk Task ☐ Change ☐ Regular review ☐ Post-Incident ☐ Contractor (to complete) Task ☐ Non-Routine Task ☐ Maintenance/Repair ☐ Other (specify):		
SWMS Team Names: 1. Chris Foster	2. David Knight	3.
4.	5.	6.
Permits Required: (circle) Confined Space ☒ Isolation ☐ Hot Work ☐ PPE Requirements:                 		
Other:		

SAFE WORK METHOD STATEMENT (SWMS)

Potential Environment Hazards	Fire/Emergency Response Equipment
☒ Noise / vibration ☒ Air pollution – dust / smoke / fume ☒ Spills to ground ☒ Spills to water / drains / waterways ☒ Soil erosion / contamination ☒ Hazards to flora & fauna ☒ Waste generation & disposal ☒ Hazardous chemicals / substances ☒ Vegetation / bushfire risk ☐ Other: _____	☒ Fire extinguisher — Location: Main shed wall ☒ Fire hose / hydrant — Location: Walking Floor, Shavings silo, inside shed ☒ First aid kit — Location: Smoko Room ☒ Spill kit — Location: Inside the North Entry door ☒ Emergency eyewash / shower — Location: Outside the workshop ☒ Emergency assembly point — Location: ☒ Communication method: ☐ Radio ☐ Phone ☐ Verbal ☒ Emergency contact No: 0439 013 224
Hazards Identified	
☒ Electricity ☒ Confined Space ☒ Stored Energy ☒ Extreme Temperatures ☒ Dust and or fume ☒ Hazardous Manual Tasks ☒ Psychological ☐ Traffic/Mobile Plant ☒ Ignition Sources ☒ Lighting ☒ Machinery & Equipment ☒ Person/Object Falling ☒ Pressure (air, water, gas) ☒ Object Falling ☒ Hazardous Chemicals ☐ Hot Work ☒ Other workers/people	
Other Comments:	

REQUIRED CORE SWMS

List the Core SWMS that also apply to this task. Linked Core SWMS must be read and signed on through the online SWMS Register together with this SWMS.

Applies	Core SWMS	Linked SWMS_ID
☒	Isolation and LOTO	SWMS-026
☐	Hot Work	SWMS-005
☒	Confined Space Entry	SWMS-024
☐	Working at Heights	SWMS-025
☐	Working Around Crane and Lifting Operations	SWMS-026
☐	Working on energised or unguarded machinery	SWMS-027

CRITICAL CONTROLS

The following critical controls must be in place and verified before work starts.

#	Critical Control (must be in place before work starts)
1	Confined Space Permit issued and authorised
2	Isolation and LOTO completed, verified and tested for zero energy
3	Atmospheric testing completed and atmosphere remains safe
4	Standby person present and communication maintained
5	Rescue equipment available and rescue plan confirmed
6	Entry point secured and unauthorised access prevented

If a critical control cannot be implemented, work must stop and the SWMS must be reviewed before proceeding.

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v2.0	Page 2 of 4
Doc Owner: Tuan Safety and Compliance Manager	Issue Date: 20 November-2024
Last Review: 24-Jun-2026	Version No: 001

SAFE WORK METHOD STATEMENT (SWMS)

Key Steps in Logical Order		Hazards/Risks to Workers or Public	Risk Score	Control Measures	Residual Risk Score
1	Plan and prepare work	Inadequate planning, unidentified hazards	High	Review SWMS, permit, rescue plan, worker competency verified	Med
2	Isolate plant and services	Unexpected start-up, stored energy	High	Apply LOTO, test for dead, isolate electrical, hydraulic, pneumatic, gravity and mechanical energy	Med
3	Atmospheric testing	Oxygen deficiency, toxic gas, combustible atmosphere	High	Test atmosphere before entry and continuously where required. Oxygen 19.5%-23.5%. Flammables below limits.	Med
4	Establish entry controls	Unauthorised entry, delayed rescue	High	Barricade area, maintain standby person, communication equipment available	Low
5	Enter confined space	Asphyxiation, heat stress, engulfment, restricted movement	High	Permit active, monitor atmosphere, maintain communication, adequate ventilation, competent workers only	Med
6	Perform work inside space	Injury from tools, manual handling, dust, noise	High	Use correct PPE, maintain housekeeping, control dust, use suitable tools and lighting	Med
7	Conduct hot work (if required)	Fire or explosion	High	Hot Work Permit, remove ignition sources, continuous gas monitoring, fire protection available	Med
8	Exit confined space	Personnel left inside, equipment left behind	High	Head count, remove tools, inspect area before closure	Low
9	Close permit and return to service	Premature restart, exposure to hazards	High	Confirm all personnel clear, remove locks under procedure, sign off permit	Low

Add additional job steps, hazards and controls as required

All relevant workers must be consulted during the development and review of this SWMS and made aware of the control measures and all required permits. Worker consultation and sign-on are recorded through the online SWMS Register.

ONLINE SWMS MANAGEMENT

Worker sign-on is completed through the online SWMS Register.

Workers are required to read and sign onto this SWMS once per review period, or sooner if the SWMS is revised, superseded, or changed due to an incident, equipment change, procedure change, legislative change, or risk assessment review.

Before each task commences, the team or person in control of the work must review the SWMS through the online task review system and confirm whether anything has changed from the approved SWMS.

If no changes are identified, the task may proceed once all workers are confirmed as current against the required SWMS.

CONTROLLED MASTER DOCUMENT			
Doc Id: SWMS – 001- 2024-v2.0		Page 3 of 4	
Doc Owner: Tuan Safety and Compliance Manager		Issue Date: 20 November-2024	
Last Review: 24-Jun-2026		Version No: 001	

SAFE WORK METHOD STATEMENT (SWMS)

If changes are identified, the changes and additional controls must be recorded in the online Task Record before work proceeds. Supervisor review is required where the change affects the work method, plant, equipment, location, hazards, permit requirements, or critical controls.

System of record

This Word document is the controlled master SWMS. The PDF is the worker-view copy. The HTML tablet page is used to view the SWMS and complete the task review.

Worker sign-off is stored in Worker_SWMS_Register. Daily task reviews are stored in Task_Records. Review dates and version status are controlled in SWMS_Library.

AUTHORISATION		
Approved by: Chris Foster	Position: Safety and Compliance Manager	Approval Date: 25/06/2026

CONTROLLED MASTER DOCUMENT	
Doc Id: SWMS – 001- 2024-v2.0	Page 4 of 4
Doc Owner: Tuan Safety and Compliance Manager	Issue Date: 20 November-2024
Last Review: 24-Jun-2026	Version No: 001