

SAFE WORK METHOD STATEMENT (SWMS)

DOCUMENT CONTROL	
SWMS_ID	SWMS-026
SWMS_Title	Isolation and Lockout/Tagout (LOTO)
SWMS_Version	1.0
SWMS_Type	☒ Core SWMS ☐ Routine Task SWMS ☐ Non-Routine Task SWMS
Status	☐ Draft ☐ Current ☐ Superseded
Authorised_By	Chris Foster
Authorised_Date	25/06/2026
Review_Date	25/07/2027
Review_Period_Months	12
Review_Trigger	☒ Initial Issue ☐ Incident ☐ Legislative Change ☐ Procedure Change ☐ Equipment Change ☐ Risk Assessment Review ☐ Scheduled Review

REVISION HISTORY

Version	Date	Change Summary	Authorised By
1.0	25/06/2026	Initial Issue	Chris Foster

SWMS ID: SWMS-026		SWMS Title: Isolation and Lockout/Tagout (LOTO)	
Prepared By: Chris Foster		Date: 24/06/2026	
Business Name: Tuan Biomass Albioma			
Description of Task: Isolation and Lockout/Tagout (LOTO) of plant, equipment, or energy sources prior to maintenance, repair, inspection, or other work where unexpected energisation or release of stored energy could cause injury. Applies to all electrical, mechanical, pneumatic, hydraulic, thermal, and gravitational energy sources.			
Reason for analysis: ☐ New task/plant ☐ High Risk Task ☐ Change ☐ Regular review ☐ Post-Incident ☐ Contractor (to complete) Task ☐ Non-Routine Task ☐ Maintenance/Repair ☐ Other (specify):			
SWMS Team Names: 1. Chris Foster		2. David Knight	
4.		5.	
Permits Required: (circle) Confined Space ☐ Isolation ☒ Hot Work ☐		PPE Requirements:                  Other:	

SAFE WORK METHOD STATEMENT (SWMS)

Potential Environment Hazards	Fire/Emergency Response Equipment
☐ Noise / vibration ☐ Air pollution – dust / smoke / fume ☐ Spills to ground ☐ Spills to water / drains / waterways ☐ Soil erosion / contamination ☐ Hazards to flora & fauna ☐ Waste generation & disposal ☐ Hazardous chemicals / substances ☐ Vegetation / bushfire risk ☐ Other: _____	☒ Fire extinguisher — Location: Main shed wall ☒ Fire hose / hydrant — Location: Walking Floor, Shavings silo, inside shed ☒ First aid kit — Location: Smoko Room ☒ Spill kit — Location: Inside the North Entry door ☒ Emergency eyewash / shower — Location: Outside the workshop ☒ Emergency assembly point — Location: ☒ Communication method: ☐ Radio ☐ Phone ☐ Verbal ☒ Emergency contact No: 0439 013 224
Hazards Identified	
☒ Electricity ☐ Confined Space ☒ Stored Energy ☐ Extreme Temperatures ☐ Dust and or fume ☐ Hazardous Manual Tasks ☐ Psychological ☐ Traffic/Mobile Plant ☐ Ignition Sources ☐ Lighting ☒ Machinery & Equipment ☐ Person/Object Falling ☒ Pressure (air, water, gas) ☐ Object Falling ☐ Hazardous Chemicals ☐ Hot Work ☐ Other workers/people	
Other Comments:	

REQUIRED CORE SWMS

List the Core SWMS that also apply to this task. Linked Core SWMS must be read and signed on through the online SWMS Register together with this SWMS.

Applies	Core SWMS	Linked SWMS_ID
☐	Isolation and LOTO	SWMS-026
☐	Hot Work	SWMS-005
☐	Confined Space Entry	SWMS-024
☐	Working at Heights	SWMS-025
☐	Crane and Lifting Operations	SWMS-026
☐	Working on Un-isolated plant	SWMS-027

CRITICAL CONTROLS

The following critical controls must be in place and verified before work starts.

#	Critical Control (must be in place before work starts)
1	An Isolation Permit has been issued and is in place before any work commences.
2	All energy sources are isolated, de-energised, and verified at zero energy state (test before touch) before work begins.
3	Each worker performing work on isolated plant has applied their own personal lock and danger tag to every isolation point.
4	Stored energy (pneumatic, hydraulic, gravitational, spring) is fully dissipated or mechanically restrained before work begins.
5	No lock or tag is to be removed by anyone other than the person who applied it, except under the authorised lost-key or emergency removal procedure.
6	Plant is confirmed safe to re-energise (all workers clear, tools removed, guards refitted) before any lock or tag is removed and energy is restored.

If a critical control cannot be implemented, work must stop and the SWMS must be reviewed before proceeding.

CONTROLLED MASTER DOCUMENT			
Doc Id: SWMS – 001- 2024-v2.0		Page 2 of 3	
Doc Owner: Tuan Safety and Compliance Manager		Issue Date: 20 November-2024	
Last Review: 24-Jun-2026		Version No: 001	

SAFE WORK METHOD STATEMENT (SWMS)

Key Steps in Logical Order		Hazards/Risks to Workers or Public	Risk Score	Control Measures	Residual Risk Score
1	Plan the isolation.	Incorrect isolation, unexpected plant start-up or exposure to hazardous energy.	High	Complete the Isolation Permit, identify all energy sources and notify affected personnel.	Low
2	Shut down the plant.	Moving equipment, stored energy or uncontrolled plant movement.	High	Follow the approved shutdown procedure and allow the plant to come to a complete stop.	Low
3	Apply lockout and isolation.	Electric shock, crushing, entanglement or release of stored energy.	High	Isolate all energy sources and apply personal locks and danger tags.	Low
4	Verify zero energy.	Residual electrical, mechanical, hydraulic or pneumatic energy.	High	Test and confirm all energy sources are isolated before work begins.	Low
5	Complete the work.	Isolation removed during work or unauthorised operation of plant.	Medium	Maintain all personal locks and keep the Isolation Permit active until work is complete.	Low
6	Remove isolation and return to service.	Unexpected plant start-up or injury during recommissioning.	High	Inspect the work area, remove locks in accordance with the procedure and return the plant to service safely.	Low

Add additional job steps, hazards and controls as required

All relevant workers must be consulted during the development and review of this SWMS and made aware of the control measures and all required permits. Worker consultation and sign-on are recorded through the online SWMS Register.

ONLINE SWMS MANAGEMENT

Worker sign-on is completed through the online SWMS Register.

Workers are required to read and sign onto this SWMS once per review period, or sooner if the SWMS is revised, superseded, or changed due to an incident, equipment change, procedure change, legislative change, or risk assessment review.

Before each task commences, the team or person in control of the work must review the SWMS through the online task review system and confirm whether anything has changed from the approved SWMS.

If no changes are identified, the task may proceed once all workers are confirmed as current against the required SWMS.

If changes are identified, the changes and additional controls must be recorded in the online Task Record before work proceeds. Supervisor review is required where the change affects the work method, plant, equipment, location, hazards, permit requirements, or critical controls.

System of record

This Word document is the controlled master SWMS. The PDF is the worker-view copy. The HTML tablet page is used to view the SWMS and complete the task review.

Worker sign-off is stored in Worker_SWMS_Register. Daily task reviews are stored in Task_Records. Review dates and version status are controlled in SWMS_Library.

AUTHORISATION

Approved by: Chris Foster	Position: Safety and Compliance Manager	Approval Date: 25/06/2026
----------------------------------	--	----------------------------------

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v2.0	Page 3 of 3
Doc Owner: Tuan Safety and Compliance Manager	Issue Date: 20 November-2024
Last Review: 24-Jun-2026	Version No: 001