

SAFE WORK METHOD STATEMENT (SWMS)

DOCUMENT CONTROL	
SWMS_ID	SWMS-026
SWMS_Title	Working Around Crane and Lifting Operations
SWMS_Version	1
SWMS_Type	☒ Core SWMS ☐ Routine Task SWMS ☐ Non-Routine Task SWMS
Status	☐ Draft ☐ Current ☐ Superseded
Authorised_By	Chris Foster
Authorised_Date	25/06/2026
Review_Date	25/07/2027
Review_Period_Months	12
Review_Trigger	☒ Initial Issue ☐ Incident ☐ Legislative Change ☐ Procedure Change ☐ Equipment Change ☐ Risk Assessment Review ☐ Scheduled Review

REVISION HISTORY

Version	Date	Change Summary	Authorised By
1.0	25/06/2026	Initial Issue	Chris Foster

SWMS ID: SWMS-026		SWMS Title: Working Around Crane and Lifting Operations	
Prepared By: Chris Foster		Date: 25/06/2026	
Business Name: Tuan Biomass Albioma			
Description of Task: Working in the vicinity of crane and lifting operations, including assisting with the removal, installation or positioning of plant, equipment and materials.			
Reason for analysis: ☐ New task/plant ☒ High Risk Task ☐ Change ☐ Regular review ☐ Post-Incident ☐ Contractor (to complete) Task ☒ Non-Routine Task ☐ Maintenance/Repair ☐ Other (specify):			
SWMS Team Names: 1. Chris Foster		2. David Knight	
3.		4.	
5.		6.	
Permits Required: (circle) Confined Space ☐ Isolation ☐ Hot Work ☐		PPE Requirements:                 Other:	

SAFE WORK METHOD STATEMENT (SWMS)

Potential Environment Hazards	Fire/Emergency Response Equipment
☐ Noise / vibration ☐ Air pollution – dust / smoke / fume ☐ Spills to ground ☐ Spills to water / drains / waterways ☐ Soil erosion / contamination ☐ Hazards to flora & fauna ☐ Waste generation & disposal ☐ Hazardous chemicals / substances ☐ Vegetation / bushfire risk ☐ Other: _____	☒ Fire extinguisher — Location: Main shed wall ☒ Fire hose / hydrant — Location: Walking Floor, Shavings silo, inside shed ☒ First aid kit — Location: Smoko Room ☒ Spill kit — Location: Inside the North Entry door ☒ Emergency eyewash / shower — Location: Outside the workshop ☒ Emergency assembly point — Location: ☒ Communication method: ☐ Radio ☐ Phone ☐ Verbal ☒ Emergency contact No: 0439 013 224
Hazards Identified	
☐ Electricity ☐ Confined Space ☒ Stored Energy ☐ Extreme Temperatures ☒ Dust and or fume ☒ Hazardous Manual Tasks ☐ Psychological ☐ Traffic/Mobile Plant ☐ Ignition Sources ☐ Lighting ☒ Machinery & Equipment ☐ Person/Object Falling ☐ Pressure (air, water, gas) ☒ Object Falling ☐ Hazardous Chemicals ☐ Hot Work ☐ Other workers/people	
Other Comments:	

REQUIRED CORE SWMS

List the Core SWMS that also apply to this task. Linked Core SWMS must be read and signed on through the online SWMS Register together with this SWMS.

Applies	Core SWMS	Linked SWMS_ID
☐	Isolation and LOTO	SWMS-026
☐	Hot Work	SWMS-005
☐	Confined Space Entry	SWMS-024
☐	Working at Heights	SWMS-025
☐	Crane and Lifting Operations	SWMS-026
☐	Working on Energised or Unguarded Plant	SWMS-027

CRITICAL CONTROLS

The following critical controls must be in place and verified before work starts.

#	Critical Control (must be in place before work starts)
1	Lift planned and communicated before work begins.
2	Exclusion zones established and maintained around lifting operations.
3	Workers remain clear of suspended loads and load paths at all times.
4	Only authorised personnel direct or communicate with the crane operator.
5	Lifting equipment and lifting points inspected and suitable for the load.
6	Load landed safely and work area made safe before personnel re-enter.

If a critical control cannot be implemented, work must stop and the SWMS must be reviewed before proceeding.

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v2.0	Page 2 of 3
Doc Owner: Tuan Safety and Compliance Manager	Issue Date: 20 November-2024
Last Review: 24-Jun-2026	Version No: 001

SAFE WORK METHOD STATEMENT (SWMS)

Key Steps in Logical Order		Hazards/Risks to Workers or Public	Risk Score	Control Measures	Residual Risk Score
1	Plan the lifting activity.	Unplanned lift, incorrect lifting method or poor coordination.	High	Review the lift plan, identify hazards and communicate roles before work begins.	Low
2	Establish the work area.	Unauthorised access, struck by plant or suspended load.	High	Set up exclusion zones, barriers and maintain clear access around the lifting area.	Low
3	Work with the lifting team.	Miscommunication resulting in unsafe movements or worker injury.	High	Follow directions from the crane operator and dogger. Use agreed communication methods and never give conflicting instructions.	Low
4	Work around suspended loads.	Struck by or crushed by a suspended or swinging load.	High	Never stand beneath suspended loads. Stay clear of the load path and pinch points. Use tag lines where required.	Low
5	Complete work during lifting operations.	Hand injuries, caught-between hazards or falling objects.	Medium	Keep hands clear of pinch points, wear required PPE and secure all tools and materials.	Low
6	Complete the lift and restore the area.	Residual hazards, unstable loads or trip hazards.	Medium	Confirm the load is safely landed, remove lifting gear when safe and tidy the work area before reopening access.	Low

Add additional job steps, hazards and controls as required

All relevant workers must be consulted during the development and review of this SWMS and made aware of the control measures and all required permits. Worker consultation and sign-on are recorded through the online SWMS Register.

ONLINE SWMS MANAGEMENT

Worker sign-on is completed through the online SWMS Register.

Workers are required to read and sign onto this SWMS once per review period, or sooner if the SWMS is revised, superseded, or changed due to an incident, equipment change, procedure change, legislative change, or risk assessment review.

Before each task commences, the team or person in control of the work must review the SWMS through the online task review system and confirm whether anything has changed from the approved SWMS.

If no changes are identified, the task may proceed once all workers are confirmed as current against the required SWMS.

If changes are identified, the changes and additional controls must be recorded in the online Task Record before work proceeds.

Supervisor review is required where the change affects the work method, plant, equipment, location, hazards, permit requirements, or critical controls.

System of record

This Word document is the controlled master SWMS. The PDF is the worker-view copy. The HTML tablet page is used to view the SWMS and complete the task review.

Worker sign-off is stored in Worker_SWMS_Register. Daily task reviews are stored in Task_Records. Review dates and version status are controlled in SWMS_Library.

AUTHORISATION

Approved by: Chris Foster

Position: Safety and Compliance Manager

Approval Date: 25/06/2026

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v2.0

Page **3** of **3**

Doc Owner: Tuan Safety and Compliance Manager

Issue Date: 20 November-2024

Last Review: 24-Jun-2026

Version No: 001