

SAFE WORK METHOD STATEMENT (SWMS)

DOCUMENT CONTROL	
SWMS_ID	SWMS-005
SWMS_Title	Hot Work
SWMS_Version	1.1
SWMS_Type	☒ Core SWMS ☐ Routine Task SWMS ☐ Non-Routine Task SWMS
Status	☐ Draft ☒ Current ☐ Superseded
Authorised_By	Chris Foster
Authorised_Date	25/06/2026
Review_Date	25/07/2027
Review_Period_Months	12
Review_Trigger	☐ Initial Issue ☐ Incident ☐ Legislative Change ☐ Procedure Change ☐ Equipment Change ☐ Risk Assessment Review ☒ Scheduled Review

REVISION HISTORY

Version	Date	Change Summary	Authorised By
1.0	14/05/2025	Initial Issue	Chris Foster
1.1	25/06/2026	Scheduled Review	Chris Foster

SWMS ID: SWMS-0005		SWMS Title: Hot Work	
Prepared By: Chris Foster		Date: 24/06/2026	
Business Name: Tuan Biomass Albioma			
Description of Task: Hot work activities including welding, grinding, oxy cutting, soldering, or any task producing sparks, heat, or open flame during maintenance, repair, or installation work on plant and equipment.			
Reason for analysis: ☐ New task/plant ☒ High Risk Task ☐ Change ☐ Regular review ☐ Post-Incident ☐ Contractor (to complete) Task ☐ Non-Routine Task ☐ Maintenance/Repair ☐ Other (specify):			
SWMS Team Names: 1. Chris Foster		2. David Knight	3.
4.		5.	6.
Permits Required: (circle) Confined Space ☐ Isolation ☐ Hot Work ☒		PPE Requirements:  Other:	

SAFE WORK METHOD STATEMENT (SWMS)

Potential Environment Hazards	Fire/Emergency Response Equipment
☒ Noise / vibration ☒ Air pollution – dust / smoke / fume ☒ Spills to ground ☒ Spills to water / drains / waterways ☒ Soil erosion / contamination ☒ Hazards to flora & fauna ☒ Waste generation & disposal ☒ Hazardous chemicals / substances ☒ Vegetation / bushfire risk ☐ Other: _____	☒ Fire extinguisher — Location: Main shed wall ☒ Fire hose / hydrant — Location: Walking Floor, Shavings silo, inside shed ☒ First aid kit — Location: Smoko Room ☒ Spill kit — Location: Inside the North Entry door ☒ Emergency eyewash / shower — Location: Outside the workshop ☒ Emergency assembly point — Location: ☒ Communication method: ☐ Radio ☐ Phone ☐ Verbal ☒ Emergency contact No: 0439 013 224
Hazards Identified	
☒ Electricity ☒ Confined Space ☐ Stored Energy ☐ Extreme Temperatures ☒ Dust and or fume ☒ Hazardous Manual Tasks ☐ Psychological ☐ Traffic/Mobile Plant ☒ Ignition Sources ☒ Lighting ☐ Machinery & Equipment ☒ Person/Object Falling ☒ Pressure (air, water, gas) ☐ Object Falling ☒ Hazardous Chemicals ☒ Hot Work ☒ Other workers/people	
Other Comments:	

REQUIRED CORE SWMS

List the Core SWMS that also apply to this task. Linked Core SWMS must be read and signed on through the online SWMS Register together with this SWMS.

Applies	Core SWMS	Linked SWMS_ID
☐	Isolation and LOTO	SWMS-026
☐	Hot Work	SWMS-005
☐	Confined Space Entry	SWMS-024
☐	Working at Heights	SWMS-025
☐	Crane and Lifting Operations	
☐	Working on isolated plant	

CRITICAL CONTROLS

The following critical controls must be in place and verified before work starts.

#	Critical Control (must be in place before work starts)
1	Hot Work Permit issued and approved before work starts
2	Combustible materials removed, protected or isolated from the work area.
3	Plant and hazardous energy sources isolated and verified safe before work begins.
4	Fire extinguishers available and a fire watch maintained during hot work and after completion.
5	Only competent workers perform hot work using the required PPE.
6	Fire watch 30 and 60 minutes after hot work is completed

If a critical control cannot be implemented, work must stop and the SWMS must be reviewed before proceeding.

Key Steps in Logical Order		Hazards/Risks to Workers or Public	Risk Score	Control Measures	Residual Risk Score
1.	Plan the work and obtain permits	Uncontrolled ignition sources, incorrect preparation	High	Hot work permit issued. Risk assessment completed. Area inspected for combustible materials.	Low
2.	Identify area/job-specific controls on the Hot Work Permit	Fire or explosion due to unrecognised hazards such as combustible dust, nearby equipment, flammable materials, or other work activities	High	MANDATORY: Person signing the permit must inspect the area and record the special requirements required the Hot Work Permit. Controls may include cleaning sawdust, removing combustible materials, listing isolated equipment, wetting area down, exclusion zone 10m around the area, plan to improve ventilation. This section of the hot work permit can not be left blank.	Low
3.	Prepare work area	Fire from sparks, dust ignition, flammable materials	High	Remove or cover combustible materials. Clean area of sawdust and dust.	Low
4.	Isolate equipment	Unexpected start-up, stored energy	High	Follow lockout/tagout procedures. Verify isolation before work begins. (Check for dead)	Low
5.	Set up equipment	Electric shock, equipment failure, gas leaks	Mod	Inspect welding leads, hoses, regulators. Use tested equipment. Ensure adequate ventilation.	Low
6.	Conduct hot work	Burns, eye injury, sparks causing fire, welding flash	High	Wear correct PPE. Maintain fire watch. Control sparks and slag. Keep fire extinguisher nearby.	Low
7.	Manage fumes and ventilation	Exposure to fumes or smoke	High	Open the inspection hatches before work starts as natural ventilation or plant as extraction systems. Use respirators where required. Atmosphere tester for confined spaces.	Low
8.	Monitor surrounding area	Fire spreading to nearby materials	High	Stand by person listed on permit during high-risk work. Monitor nearby equipment and structures.	Low
9.	Completion and inspection	Delayed ignition or smouldering materials	High	Fire watch person (minimum 60 minutes after completion) listed on the permit Inspect area before leaving.	Low

Add additional job steps, hazards and controls as required

All relevant workers must be consulted during the development and review of this SWMS and made aware of the control measures and all required permits. Worker consultation and sign-on are recorded through the online SWMS Register.

ONLINE SWMS MANAGEMENT

CONTROLLED MASTER DOCUMENT			
Doc Id: SWMS – 001- 2024-v2.0		Page 3 of 4	
Doc Owner: Tuan Safety and Compliance Manager		Issue Date: 20 November-2024	
Last Review: 24-Jun-2026		Version No: 001	

SAFE WORK METHOD STATEMENT (SWMS)

Worker sign-on is completed through the online SWMS Register.

Workers are required to read and sign onto this SWMS once per review period, or sooner if the SWMS is revised, superseded, or changed due to an incident, equipment change, procedure change, legislative change, or risk assessment review.

Before each task commences, the team or person in control of the work must review the SWMS through the online task review system and confirm whether anything has changed from the approved SWMS.

If no changes are identified, the task may proceed once all workers are confirmed as current against the required SWMS.

If changes are identified, the changes and additional controls must be recorded in the online Task Record before work proceeds.

Supervisor review is required where the change affects the work method, plant, equipment, location, hazards, permit requirements, or critical controls.

System of record

This Word document is the controlled master SWMS. The PDF is the worker-view copy. The HTML tablet page is used to view the SWMS and complete the task review.

Worker sign-off is stored in Worker_SWMS_Register. Daily task reviews are stored in Task_Records. Review dates and version status are controlled in SWMS_Library.

AUTHORISATION		
Approved by: Chris Foster	Position: Safety and Compliance Manager	Approval Date: 25/06/2026

CONTROLLED MASTER DOCUMENT**Doc Id:** SWMS – 001- 2024-v2.0Page **4** of **4****Doc Owner:** Tuan Safety and Compliance Manager**Issue Date:** 20 November-2024**Last Review:** 24-Jun-2026**Version No:** 001