

SAFE WORK METHOD STATEMENT (SWMS)

DOCUMENT CONTROL	
SWMS_ID	SWMS-006
SWMS_Title	ID Fan Clean
SWMS_Version	1.1
SWMS_Type	☐ Core SWMS ☒ Routine Task SWMS ☐ Non-Routine Task SWMS
Status	☐ Draft ☒ Current ☐ Superseded
Authorised_By	Chris Foster
Authorised_Date	25/06/2026
Review_Date	25/07/2027
Review_Period_Months	12
Review_Trigger	☐ Initial Issue ☐ Incident ☐ Legislative Change ☐ Procedure Change ☐ Equipment Change ☐ Risk Assessment Review ☒ Scheduled Review

REVISION HISTORY

Version	Date	Change Summary	Authorised By
1.0	12/04/2025	Initial Issue	Chris Foster
1.1	25/06/2026	Scheduled Review	Chris Foster

SWMS ID: SWMS-006	SWMS Title: ID Fan Clean	
Prepared By: Chris Foster		Date: 24/06/2026
Business Name: Tuan Biomass Albioma		
Description of Task: Gain entry to ID fan, clean fan blade and remove Build Up from walls.		
Reason for analysis: ☒ New task/plant ☐ High Risk Task ☐ Change ☐ Regular review ☐ Post-Incident ☐ Contractor (to complete) Task ☐ Non-Routine Task ☐ Maintenance/Repair ☐ Other (specify):		
SWMS Team Names: 1. Chris Foster	2. David Knight	3.
4.	5.	6.
Permits Required: (circle) Confined Space ☒ Isolation ☒ Hot Work ☐ PPE Requirements:            Other:		
Potential Environment Hazards		Fire/Emergency Response Equipment

SAFE WORK METHOD STATEMENT (SWMS)

☒ Noise / vibration ☒ Air pollution – dust / smoke / fume ☒ Spills to ground ☒ Spills to water / drains / waterways ☐ Soil erosion / contamination ☐ Hazards to flora & fauna ☒ Waste generation & disposal ☐ Hazardous chemicals / substances ☐ Vegetation / bushfire risk ☐ Other: _____	☒ Fire extinguisher — Location: Main shed wall ☒ Fire hose / hydrant — Location: Walking Floor, Shavings silo, inside shed ☒ First aid kit — Location: Smoko Room ☒ Spill kit — Location: Inside the North Entry door ☒ Emergency eyewash / shower — Location: Outside the workshop ☒ Emergency assembly point — Location: ☒ Communication method: ☒ Radio ☒ Phone ☒ Verbal ☒ Emergency contact No: 0439 013 224
--	---

Hazards Identified

- ☒ Electricity
 ☒ Confined Space
 ☒ Stored Energy
 ☒ Extreme Temperatures
 ☒ Dust and or fume
 ☒ Hazardous Manual Tasks
☐ Psychological
☐ Traffic/Mobile Plant
☐ Ignition Sources
☒ Lighting
☒ Machinery & Equipment
☐ Person/Object Falling
☐ Pressure (air, water, gas)
☐ Object Falling
☐ Hazardous Chemicals
☐ Hot Work
☐ Other workers/people

Other Comments:

REQUIRED CORE SWMS

List the Core SWMS that also apply to this task. Linked Core SWMS must be read and signed on through the online SWMS Register together with this SWMS.

Applies	Core SWMS	Linked SWMS_ID
☒	Isolation and LOTO	SWMS-026
☐	Hot Work	
☒	Confined Space Entry	SWMS-024
☐	Working at Heights	
☐	Crane and Lifting Operations	
☐	Working on isolated plant	

CRITICAL CONTROLS

The following critical controls must be in place and verified before work starts.

#	Critical Control (must be in place before work starts)
1	All electrical, mechanical, pneumatic and hydraulic energy sources isolated, locked and verified as zero energy.
2	Confined Space Entry Permit issued, authorised and displayed before entry.
3	Atmosphere tested, continuously monitored where required, and maintained safe by ventilation.
4	Safe access provided, an entry point maintained, and continuous communication with the standby person.
5	Competent workers enter the space, a trained standby person remains outside, and a rescue plan and equipment are immediately available.
6	

If a critical control cannot be implemented, work must stop and the SWMS must be reviewed before proceeding.

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v2.0	Page 2 of 4
Doc Owner: Tuan Safety and Compliance Manager	Issue Date: 20 November-2024
Last Review: 24-Jun-2026	Version No: 001

SAFE WORK METHOD STATEMENT (SWMS)

Key Steps in Logical Order		Hazards/Risks to Workers or Public	Risk Score	Control Measures	Residual Risk Score
1.	Confirm Isolation	Unexpected energisation or movement of equipment	High	- Lockout/tagout using isolation procedure - Test for zero energy - Apply lockout tags - Permit Issuer to verify isolation	Low
2.	Open both access hatch to the ID Fan	Strains, dropped hatch, pinch points	Moderate	- Use mechanical aid or team lift - Wear gloves - Ensure stable standing position - Keep clear of fall zone	Low
3.	Test atmosphere using calibrated 4-gas detector	Toxic gas, oxygen deficiency, explosive atmosphere	High	- Use calibrated detector for O₂, CO, H₂S, LEL - Entry only if atmosphere safe - Record results on permit	Moderate
4.	Gain access to ID fan using a ladder. Enter confined space	Falls from height, entry into hazardous atmosphere	Moderate	- Use fall protection - Maintain 3 points of contact, - - Ensure permit to work is in place	Low
5.	Use air chisel and needle gun to clean fan blades.	Flying debris, noise, vibration, foreign body in eye, Manual handling	Moderate	-Wear eye and ear protection, - use tools as per manufacturer's instructions	Low
6.	Use shovel to remove all excess build up from walls of pipe.	Foreign body in eye, Manual handling, exposure to hot material, contact injury.	Moderate	- Full face shield or sealed safety goggles - Use long-handled scraper or shovel - Scrape gently to avoid flicking material - work in pairs	Low
7.	Exit confined space and account for all tools and equipment.	Missed items creating future hazard	Moderate	-Use checklist for tools - Permit Issuer to verify clean area - Exit safely using three points of contact - Communicate exit to standby person	Low
8.	Close and secure all hatches	Pinch injuries, unsecured hatch	Low	- Use mechanical aid if needed - Keep hands clear when closing - Confirm latch and seal are secure - Notify control room when complete	Low
9.	Remove isolation locks/tags	Premature re-energisation	Moderate	- Only person who applied the lock/tag may remove it - Permit Issuer to verify - Communicate clearance to affected workers	Low

Add additional job steps, hazards and controls as required

All relevant workers must be consulted during the development and review of this SWMS and made aware of the control measures and all required permits. Worker consultation and sign-on are recorded through the online SWMS Register.

ONLINE SWMS MANAGEMENT

Worker sign-on is completed through the online SWMS Register.

CONTROLLED MASTER DOCUMENT			
Doc Id: SWMS – 001- 2024-v2.0		Page 3 of 4	
Doc Owner: Tuan Safety and Compliance Manager		Issue Date: 20 November-2024	
Last Review: 24-Jun-2026		Version No: 001	

SAFE WORK METHOD STATEMENT (SWMS)

Workers are required to read and sign onto this SWMS once per review period, or sooner if the SWMS is revised, superseded, or changed due to an incident, equipment change, procedure change, legislative change, or risk assessment review.

Before each task commences, the team or person in control of the work must review the SWMS through the online task review system and confirm whether anything has changed from the approved SWMS.

If no changes are identified, the task may proceed once all workers are confirmed as current against the required SWMS.

If changes are identified, the changes and additional controls must be recorded in the online Task Record before work proceeds.

Supervisor review is required where the change affects the work method, plant, equipment, location, hazards, permit requirements, or critical controls.

System of record

This Word document is the controlled master SWMS. The PDF is the worker-view copy. The HTML tablet page is used to view the SWMS and complete the task review.

Worker sign-off is stored in Worker_SWMS_Register. Daily task reviews are stored in Task_Records. Review dates and version status are controlled in SWMS_Library.

AUTHORISATION**Approved by:** Chris Foster**Position:** Safety and Compliance Manager**Approval Date:** 25/06/2026**CONTROLLED MASTER DOCUMENT****Doc Id:** SWMS – 001- 2024-v2.0Page **4** of **4****Doc Owner:** Tuan Safety and Compliance Manager**Issue Date:** 20 November-2024**Last Review:** 24-Jun-2026**Version No:** 001