

SAFE WORK METHOD STATEMENT (SWMS)

DOCUMENT CONTROL	
SWMS_ID	SWMS-007
SWMS_Title	Outlet Pipe Clean
SWMS_Version	1.1
SWMS_Type	☐ Core SWMS ☒ Routine Task SWMS ☐ Non-Routine Task SWMS
Status	☐ Draft ☐ Current ☐ Superseded
Authorised_By	Chris Foster
Authorised_Date	25/06/2026
Review_Date	25/07/2027
Review_Period_Months	12
Review_Trigger	☐ Initial Issue ☐ Incident ☐ Legislative Change ☐ Procedure Change ☐ Equipment Change ☐ Risk Assessment Review ☒ Scheduled Review

REVISION HISTORY

Version	Date	Change Summary	Authorised By
1.0	23/05/2024	Initial Issue	Chris Foster
1.1	25/06/2026	Scheduled Review	Chris Foster

SWMS ID: SWMS-007		SWMS Title: Outlet Pipe Clean	
Prepared By: Chris Foster		Date: 25/06/2026	
Business Name: Tuan Biomass Albioma			
Description of Task: Gain entry to Outlet pipe use shovel to remove all material build on the bend			
Reason for analysis: ☐ New task/plant ☐ High Risk Task ☐ Change ☐ Regular review ☐ Post-Incident ☐ Contractor (to complete) Task ☐ Non-Routine Task ☐ Maintenance/Repair ☐			
Other (specify):			
SWMS Team Names: 1. Chris Foster		2. David Knight	
3.		4.	
5.		6.	
Permits Required: (circle) Confined Space ☒ Isolation ☒ Hot Work ☐		PPE Requirements:            Other:	
Potential Environment Hazards		Fire/Emergency Response Equipment	

SAFE WORK METHOD STATEMENT (SWMS)

☐ Noise / vibration ☐ Air pollution – dust / smoke / fume ☐ Spills to ground ☐ Spills to water / drains / waterways ☐ Soil erosion / contamination ☐ Hazards to flora & fauna ☐ Waste generation & disposal ☐ Hazardous chemicals / substances ☐ Vegetation / bushfire risk ☐ Other: _____	☒ Fire extinguisher — Location: Main shed wall ☒ Fire hose / hydrant — Location: Walking Floor, Shavings silo, inside shed ☒ First aid kit — Location: Smoko Room ☒ Spill kit — Location: Inside the North Entry door ☒ Emergency eyewash / shower — Location: Outside the workshop ☒ Emergency assembly point — Location: ☒ Communication method: ☐ Radio ☐ Phone ☐ Verbal ☒ Emergency contact No: 0439 013 224
Hazards Identified ☒ Electricity ☒ Confined Space ☒ Stored Energy ☒ Extreme Temperatures ☒ Dust and or fume ☒ Hazardous Manual Tasks ☒ Psychological ☐ Traffic/Mobile Plant ☐ Ignition Sources ☒ Lighting ☐ Machinery & Equipment ☐ Person/Object Falling ☐ Pressure (air, water, gas) ☐ Object Falling ☐ Hazardous Chemicals ☐ Hot Work ☐ Other workers/people	
Other Comments:	

REQUIRED CORE SWMS

List the Core SWMS that also apply to this task. Linked Core SWMS must be read and signed on through the online SWMS Register together with this SWMS.

Applies	Core SWMS	Linked SWMS_ID
☒	Isolation and LOTO	SWMS-026
☐	Hot Work	SWMS-005
☒	Confined Space Entry	SWMS-024
☐	Working at Heights	SWMS-025
☐	Crane and Lifting Operations	SWMS-026
☐	Working on Un-isolated plant	SWMS-027

CRITICAL CONTROLS

The following critical controls must be in place and verified before work starts.

#	Critical Control (must be in place before work starts)
1	All electrical, mechanical, pneumatic and hydraulic energy sources isolated, locked and verified as zero energy.
2	Confined Space Entry Permit issued, authorised and displayed before entry.
3	Atmosphere tested, continuously monitored where required, and maintained safe by ventilation.
4	Safe access provided, an entry point maintained, and continuous communication with the standby person.
5	Competent workers enter the space, a trained standby person remains outside, and a rescue plan and equipment are immediately available.
6	

If a critical control cannot be implemented, work must stop and the SWMS must be reviewed before proceeding.

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v2.0	Page 2 of 4
Doc Owner: Tuan Safety and Compliance Manager	Issue Date: 20 November-2024
Last Review: 24-Jun-2026	Version No: 001

SAFE WORK METHOD STATEMENT (SWMS)

Key Steps in Logical Order		Hazards/Risks to Workers or Public	Risk Score	Control Measures	Residual Risk Score
1	Confirm Isolation	Unexpected start up	High	- Lockout/tagout using isolation procedure - Test for zero energy - Apply lockout tags - Permit Issuer to verify isolation	Low
2.	Open access hatch to the outlet pipe	Strains, dropped hatch, pinch points	Moderate	- Use mechanical aid or team lift - Wear gloves - Ensure stable standing position - Keep clear of fall zone	Low
3.	Test atmosphere using calibrated 4-gas detector	Toxic gas, oxygen deficiency, explosive atmosphere	High	- Use calibrated detector for O₂, CO, H₂S, LEL - Ventilate if required - Entry only if atmosphere safe - Record results on permit	Low
4.	Enter confined space	Asphyxiation, heat stress, entrapment	Extreme	- Confined space permit required - Trained personnel only - Continuous gas monitoring - Rescue plan in place - Comms with standby person - PPE: Gloves, long sleeves	Low
5.	Use shovel or scraper to push residue build-up on the outlet pipe, down the drop box chute	Foreign body in eye, Manual handling, exposure to hot material, contact injury	High	- Full face shield or sealed safety goggles - Use long-handled scraper or shovel - Scrape gently to avoid flicking material	Low
6.	Manually remove loose debris from the drop box bin.	Dust inhalation, slips/trips, repetitive strain	High	- Dust mask (P2 rated) - Heavy-duty gloves - Rotate task if prolonged - Ensure adequate lighting	Low
7.	Visually inspect: - Outlet pipe condition - Thermocouple Make sure chute is fully clear	Foreign body in eye, Sharp edges, falling debris, heat contact	High	- Use full face shield/goggles - Ensure pipe has cooled - Use a torch - Record condition in inspection in diary	Low
8.	Exit confined space and account for all tools and equipment.	Missed items creating future hazard	Moderate	- Use checklist for tools - Permit Issuer to verify clean area - Exit safely using three points of contact - Communicate exit to standby person	Low

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v2.0

Page **3** of **4**

Doc Owner: Tuan Safety and Compliance Manager

Issue Date: 20 November-2024

Last Review: 24-Jun-2026

Version No: 001

SAFE WORK METHOD STATEMENT (SWMS)

9.	Close and secure all hatches	Pinch injuries, unsecured hatch	Moderate	- Use mechanical aid if needed - Keep hands clear when closing - Confirm latch and seal are secure - Notify control room when complete	Low
10.	Remove isolation locks/tags	Premature re-energisation	High	- Only person who applied the lock/tag may remove it - Sign off by supervisor - Communicate clearance to affected workers - Record in isolation log	Low

Add additional job steps, hazards and controls as required

All relevant workers must be consulted during the development and review of this SWMS and made aware of the control measures and all required permits. Worker consultation and sign-on are recorded through the online SWMS Register.

ONLINE SWMS MANAGEMENT

Worker sign-on is completed through the online SWMS Register.

Workers are required to read and sign onto this SWMS once per review period, or sooner if the SWMS is revised, superseded, or changed due to an incident, equipment change, procedure change, legislative change, or risk assessment review.

Before each task commences, the team or person in control of the work must review the SWMS through the online task review system and confirm whether anything has changed from the approved SWMS.

If no changes are identified, the task may proceed once all workers are confirmed as current against the required SWMS.

If changes are identified, the changes and additional controls must be recorded in the online Task Record before work proceeds.

Supervisor review is required where the change affects the work method, plant, equipment, location, hazards, permit requirements, or critical controls.

System of record

This Word document is the controlled master SWMS. The PDF is the worker-view copy. The HTML tablet page is used to view the SWMS and complete the task review.

Worker sign-off is stored in Worker_SWMS_Register. Daily task reviews are stored in Task_Records. Review dates and version status are controlled in SWMS_Library.

AUTHORISATION

Approved by: Chris Foster	Position: Safety and Compliance Manager	Approval Date: 25/06/2026
----------------------------------	--	----------------------------------

CONTROLLED MASTER DOCUMENT

Doc Id: SWMS – 001- 2024-v2.0	Page 4 of 4
Doc Owner: Tuan Safety and Compliance Manager	Issue Date: 20 November-2024
Last Review: 24-Jun-2026	Version No: 001