MI PART NO: REV:						PO NUMBER:				TRAVELER NO./ ARM NO. /LOT#.			
865-0117-002 E						7011477				020549663			
DESCRIPTION OF MATERRIAL						MODEL OR SERIAL NO.				REC.INSP	IN PRO	CESS	
WIRE, TFLN INSD, PLATED COPPER, 28AWG, RED (ROHS)											V		
						INSPECTION P				PLAN			
	NAME OF VENDOR					SAMPLE INSP				100% INSP	FIRST ARTICLE		
E N D O R	THE WIRE CONNECTION, INC.					AQL: LEVEL				~			
	ATPET APPEND				QUANTIT								
	STREET ADDRESS				RECEIVED	INSPECTE			REJECTED				
	1240 TEXAN TRAIL SUITE 106 GRAPEVINE				16762	16762	16762		16762				
	CITY: USA STATE: TX ZIP CODE: 75061					REPORT WRITTEN BY DATE							
						Thai Thi Bao Yen 10-Nov-18		l					
ITEM QTY				DESCRIPTION			DEFECT		RESP	ON	DISP'N	DISP'N	
1 16762 Broken;			Broken;										
DEFECT CODE RES						PONSIBILITY D			DISPOSITION				
1. BURRS 10. MACHINING 1						1. VENDOR A. RETL			ETUR	RN TO VENDOR(VEN. EXP)			
2. DAMAGED 11. MARKING									RETURN TO VENDOR (MI EXP)				
3. DESCRIBE 12. Paperwork 3					3. PRODUCTION C. REWO			REWOF	PRK				
					4. TEST D. SCRA								
						5. ENGINEERING E. USE AS							
						6. MARKETING F. SALVAG							
						7. SHIPPING G. DESCR B. DESCRIBE			IBE				
9. FUNCTION 18. WRONG PART													
_	TEM QTY			ADDITIONAL INSTRUCTION						INSP.		ATE	
1	16762 SCRAP with remark: Team MRB deci					ide scrap and charge cost to engineering;			Phan Thanh Trong				
CORRECTIVE ACTION: NOT REQUIRED REQUIRED NOTIFCATION ISSUED CA REQUEST NO: DATE:													
			-										
FOLLOW UP NOTES: see detail in NCR database						 			ACCTG, USE ONLY				
									REMOVED FROM:				
										BOOK INV:			
MARLOW MRB AUTHORIZA						ATION			ISSUE DEBIT MEMO DATE. NO.				
EN	GINEERII	NG:	i i	DATE:						<u> </u>			
	AM THAN								-				

FORM #005-0033 REV A