

MI PART NO:					REV:	PO NUMBER:			TRAVELER NO./ ARM NO. /LOT#.				
SP	5935	5-04A0	С		Р	1			NCM83199				
DESCRIPTION OF MATERRIAL						MODEL OR SERIAL NO.			REC.INSP	IN PROCESS			
Cooler						SP5935-04AC			_	<u>~</u>			
							INSPECTION PLAN						
	NAME OF VENDOR						SAMPLE INSP			100% INSP	FIRST		
	II-VI VIETNAM CO., LTD.						□ AQL		I EVEI	V	ARTICLE		
v													
E	<u> </u>						QUANTITY						
N	STREET ADDRESS						RECEIV	ED ED	INSPECTED		REJECTED		
D	36 VSIP STREET 4, VIETNAM SINGAPORE INDUSTRIAL PARK, BINH HOA WARD, THUAN					10		10	10	10			
	AN TOWN, BINH DUONG PROVINCE, VIETNAM					TARK, BINITTIOA WARD, THOAN		10	10				
•	CITY: VNM STATE: ZIP CODE:						REPOR	Т	DATE				
							WRITTEN BY		08-Dec-18				
							Temoperator		00-200-10				
ITI	EM QTY DESCRIPTION							DEFECT RESPON DISP'N					
1	1 10 OUT OF PARALLELISM/HEIGHT; Chi				niều cao đô //	ao đô // Fail 0.034>0.038 đo lai CMM ;			DIMENSIONAL	ENSIONAL;			
										<u>′ </u>			
DEFECT CODE RE						PONSIBILITY	DISPOSITION						
l. I	BURF	RS	1	10. MACHINING	1	. VENDOR	A. RETUR			N TO VENDOR(VEN. EXP)			
2. I	DAM	AGED) 1	11. MARKING	2	. PURCHARSING	B.	RETUR	N TO VENDOR (MI EXP)				
3. DESCRIBE 12. Paperwork					3	. PRODUCTION	C. REWORK						
I. DIMENSIONAL 13. PLATING					4	. TEST	D. SCRAP						
						. ENGINEERING	E. USE AS IS						
6. DRAWING ERROR 15. SOLDER						6. MARKETING F. SALVAGE							
7. EXPIRE 16. SURFACE FINISH						7. SHIPPING G. DESCRIBE			IBE				
3. Flatness 17. THREADS						. DESCRIBE							
9. FUNCTION 18. WRONG PART													
TEM QTY ADDITIONAL INSTRUC				ADDITIONAL INSTRUC	TION				INSP. DATE				
CC	ORRECTIVE ACTION: NOT REQUIRED REQUIRED NOTIFCATION							ISSUED CA REQUEST NO: DATE:					
O	OLLOW UP NOTES: see detail in NCR database												
								ACCTG, USE ONLY					
								REMOVED FROM:					
								BOOK INV:					
MARLOW MRB AUTHORIZATION ISSUE DEBIT MEMO													
								DATE. NO.					

FORM #005-0033 REV A