

Cao Hoang Vu

10451 VISTA PARK ROAD • DALLAS, TEXAS 75238 • 214-340-4900 • TWX 910-860-5161 NO. P00000GZ

							O. . U					
MI PART NO:				REV:		PO NUMBER:			TRAVELER NO./ ARM NO. /LOT#.			
217-0178-001 C				С		7013119			QT1846			
DESCRIPTION OF MATERRIAL						MODEL OR SERIAL NO.			REC.INSP	IN PRO	CESS	
THERMISTOR 10K, NTC, QTI INS 1008033 (ROHS)						ST4161-03				V		
					Τ		PLAN					
	NAME OF VENDOR				SA	SAMPLE INSP			100% INSP	FIRST ARTICLE		
V E	QTI SENSING SOLUTIONS					AQL: LEVEL			<u>~</u>			
N D						QUANTIT			Υ			
	STREET ADDRESS			RE	ECEIVED INSPECTED		CTED	DEFECTIVE	REJECTED			
0	2108 CENTURY WAY BOISE			57		57		26	26			
R	CITY: USA STATE: ID ZIP CODE: 83709				RE	PORT WRITTEN BY	DATE					
					Ng	uyen Thanh Cong	25-Dec	-18				
ITEM QTY DESCRIPTION					DEFECT	RESPON		N	DISP'N			
	DEEEC	T CODE			DEC	DONEIDII ITV		•	DISPOSITION	•		
DEFECT CODE F						RESPONSIBILITY						
1. BURRS 10. MACHINING				1. VENDOR			A. RETURN TO VENDOR (VEN. EXP)					
			MARKING Banarwark			2. PURCHARSING 3. PRODUCTION		B. RETURN TO VENDOR (MI EXP) C. REWORK				
3. DESCRIBE 12. Paperwork 4. DIMENSIONAL 13. PLATING			•						SCRAP			
5. DIRTY 14. SCRATCH				5. ENGINEERING			E. USE AS IS					
6. DRAWING ERROR 15. SOLDER									SALVAGE			
7. EXPIRE 16. SURFACE FINISH				7. SHIPPING			G. DESCRIBE					
8. [3. Flatness 17. THREADS			8. DESCRIBE			H. TBD					
9. F	UNCTION	18. \	WRONG PART		9	. TBD						
ITE	M QT	΄ Δ	ADDITIONAL INSTRU	ICTION					INSP.		DATE	
CORRECTIVE ACTION: NOT REQUIRED REQUIRED NOTIFCATION ISSUI								ISSUED (CA REQUEST NO): DATE:		
EΩ	I I OW LID NO	TES: 500	dotail in NCP datab	200	,							
FOLLOW UP NOTES: see detail in NCR database									ACCTG, USE ONLY			
									REMOVED FROM:			
									BOOK INV:			
MARLOW MRB AUTHORIZATION									ISSUE DEBIT MEMO DATE. NO.			
FN	IGINEERING:		DATE:					<u> </u>	<u> </u>			

FORM #005-0033 REV A