NON-CONFORMANCE REPORT

incorporated

10451 VISTA PARK ROAD • DALLAS, TEXAS 75238 • 214-340-4900 • TWX 910-860-5161

NO. 100001VC

MI PART NO: REV: F						PO N	PO NUMBER:			TRAVELER NO./ ARM NO. /LOT#.			
541-0326-001 7 702						7020	20457			GBT-PREL20-3630			
DE	DESCRIPTION OF MATERRIAL MOI						DDEL OR SERIAL NO.			REC.INSP	INPROCESS		
TORSION SPRING DVT-5 ST4184										V			
						INSPECTION PLAN							
	NAI	NAME OF VENDOR					SAMPLE INSP			100% INSF	FIRST	FIRST ARTICLE	
٧	GLOBALTRONIC BIO-TECH PRECISION (PTE LTD).				E LTD).		AQL: LEVEL			M	ı	П	
E N						QUANTITY							
D O	STREET ADDRESS					RECEIVED INSPECTED		DEFECTIVE	REJECTED				
	5 BUROH STREET, SINGAPORE 627567						182			89	89		
R	CITY: SGP STATE: ZIP CODE:						REPORT WRITTEN BY	DATE					
							VN QA Inspector	11-Jan-	21				
ITE	ITEM QTY DESCRIPTION					DEF		DEF	ECT	RESPON	DISP'N		
1	1 89 Dimension is out of spec; Spec: 170			700->2080 N,	00->2080 N, but actual 1555->1875 N.;			DIME	ENSIONAL;				
	DEFECT CODE RESPONS						SIBILITY		DISPOSITION				
1. BURRS 10. FUNCTION 1. \					. VEN			RETURN TO VENDOR(VEN. EXP)					
				11. MACHINING		2. PURCHARSING		A1. RETURN TO VENDOR WITH					
3. DAMAGED				12. MARKING			DDUCTION	REPLACEMEN					
4. DESCRIBE				13. PAPERWORK	4. TI					N TO VENDOR WITH CREDIT			
			NAL	14. PLATING		5. ENGINEERING 6. MARKETING		B. RETURN TO VENDOR (MI EXP)					
						PPING	C. REWORK D. SCRAP						
							SCRIBE		E. USE AS IS				
9. Flatness 18. THREADS						. DEG	CKIDE		F. SALVAGE				
10. FUNCTION 19. WRONG PART								G. DESCRIBE					
IO. FONCTION 15. WRONG PART								H. SCRAP AND DESTROY PER IATF 16949					
ITE	M	Q	TY	ADDITIONAL INSTRUC	TION			11. 00		INSP.		ATE	
CO	RRE	CTIVE	ACTIO	 N:	EQUIRED	NOTI	FCATION	ISSU	ED CA	REQUEST NO	D: DATE:		
				see detail in NCR databas	_								
								A	ACCTG, USE ONLY				
									REMOVED FROM:				
										BOOK INV:			
	MARLOW MRB AUTHORIZATION								ISSUE DEBIT MEMO				
									DATE. NO.				

FORM #005-0033 REV A