MI	PART NO:			REV:	PO NUMBER:			TRAVELER	TRAVELER NO./ ARM NO. /LOT#.			
SF	25984-03AC			A				83976-183545				
DESCRIPTION OF MATERRIAL					MODEL OR SERIAL NO.			REC.INSP	IN PROCESS			
Cooler					SP5984-03AC				<u>~</u>			
							INSPECTION PLAN					
	NAME OF VENDOR						SAMPLE INSP			100% INSP	FIRST	
	II-VI VIETNAM CO., LTD.						AQL: LI		LEVEL	~	ARTICLE	
٧												
Ε							QUANTITY					
N	STREET ADDRESS					RECEIVED I		INSPECTED	DEFECTIVE	REJECTED		
D O						396		396	396	396		
R	AND TOVAR A DISTURBLE DESCRIPTION OF A VIETNAMA											
	CITY: VNM S	TY: VNM STATE: ZIP CODE:							DATE			
							WRITTEN BY		08-Jan-19			
							Le Var	Tam				
ΙT	EM	QTY	DESCRIPTION			DEFECT		RESPON	N .	DISP'N		
1		396	Plating out;			PLATING;						
	DEFEC	T CODE	_	RESI	PONSIBILI	TY	_	С	DISPOSITION			
1.	BURRS	10. MAC	10. MACHINING		1. VENDOR		A. RETURN TO VENDOR(VEN. EXP)					
2. DAMAGED		11. MAR	11. MARKING		2. PURCHARSING		B. RETURN TO VENDOR (MI EXP)					
3. DESCRIBE			12. Paperwork		3. PRODUCTION		C. REWORK					
				4. TEST		D. SCRAP						
5. DIRTY 14. SCRATCH 6. DRAWING ERROR 15. SOLDER			5. ENGINEERING 6. MARKETING			E. USE AS IS F. SALVAGE						
7. EXPIRE 16. SURFACE FINISH			7. SHIPPING			G. DESCRIBE						
8. Flatness 17. THREADS					8. DESCRIBE							
9. FUNCTION 18. WRONG PART												
ITI	EM QTY	ADDI	FIONAL INSTRUCT	ΓΙΟΝ					INSP.		DATE	
CC	CORRECTIVE ACTION: NOT REQUIRED NOTIFCATION ISSUED CA REQUEST NO: DATE:											
FC	FOLLOW UP NOTES: see detail in NCR database											
									ACCTG, USE ONLY			
									REMOVED FROM:			
В									BOOK INV:			
	MARLOW MRB AUTHORIZATION							ISSUE DEBIT MEMO				
									DA	TE. NO.		

FORM #005-0033 REV A