MI PART NO: REV:					PO NUMBER:			TRAVELER NO./ ARM NO. /LOT#.			
135-0513-001 4+					ı				84505		
DESCRIPTION OF MATERRIAL					MODEL OR SERIAL NO.		I	REC.INSP	NSP IN PROCESS		
TEC HARNESS WITH SENSOR CONNECTOR ST4161-03					ST4161-03	1-03			~		
					1	INSPECTION PLAN					
	NAME OF VENDOR					SAMPLE INSP 100% INSP FIRST					
	II-VI VIETNAM CO., LTD.					AQL: LEVEL			~	ARTICLE	
						_					
V E						QUANTITY					
N						RECEIVED) IN:	SPECTED	DEFECTIVE	REJECTED	
D	36 VSIP STREET 4, VIETNAM SINGAPORE INDUSTRIAL PARK, BINH HOA WARD, THUAN					126	12	6	2	2	
0	PAN TOWN, BINH DUONG PROVINCE, VIETNAM										
R	CITY: VNM STATE: ZIP CODE:					REPORT		TE			
						WRITTEN	BY 14	-Jan-19			
						Pham T.H					
						Thuong		T			
┢	ITEM QTY DESCRIPTION					DEFECT		RESPON DISP'N		SP'N	
1 2 Failed specific test; HI-pot Test Fail;						TESTING;					
DEFECT CODE RESPONSIBILITY						DISPOSITION					
1. BURRS 10. MACHININ			10. MACHINING		I. VENDOR	A. RETURN TO VENDOR(VEN. EXP)					
2. DAMAGED			11. MARKING	2	2. PURCHARSING	CHARSING B. RETUR			R (MI EXP)		
3. DESCRIBE			12. Paperwork	3	3. PRODUCTION	C. REWORK					
4. DIMENSIONAL			13. PLATING		1. TEST	D. SCRAP					
5. DIRTY 14. SCRATCH					5. ENGINEERING	E. USE AS IS					
					S. MARKETING	F. SALVAGE G. DESCRIBE					
				7. SHIPPING 3. DESCRIBE	H. TBD						
	FUNCTIO		18. WRONG PART		B. TBD	11. 100					
_	EM	QTY	ADDITIONAL INSTRUCT				IN	ISP.		DATE	
CC	CORRECTIVE ACTION: NOT REQUIRED REQUIRED NOTIFCATION						ISSUED CA REQUEST NO: DATE:				
			see detail in NCR database	-	_						
						ACCTG, USE ONLY					
							REMOVED FROM:				
							BOOK INV:				
	MARLOW MRB AUTHORIZATION						ISSUE DEBIT MEMO				

FORM #005-0033 REV A

DATE. NO.