

| MI PART NO: | | | | | REV: | PO NUMBER: | | | | | | TR | TRAVELER NO./ ARM NO. /LOT#. | | | |
|---|---|-----------|----------------------------------|------------|----------------|--------------------------|---------------------|--------------|--|-------------------------------|----------------|---------------|------------------------------|----------|--------|--|
| 601-0169-007 C | | | | | С | 7009589 | | | | 700 | 7009589-140817 | | | | | |
| DESCRIPTION OF MATERRIAL | | | | | | | MODEL OR SERIAL NO. | | | | | RI | REC.INSP IN F | | ROCESS | |
| SCREW, SOCKET HEAD CAP, STAINLESS, M4- | | | | | | | | | | | | | | V | | |
| 0.7X16(ROHS) | | | | | | | | | | INSPEC | TION F | DI AN | | | | |
| | NAME OF VENDOR | | | | | SAMPLE INSP | | | | | 100% INSP | | FIRST ARTICLE | | | |
| V E N D O R | | | | | | | | | | | | | | | | |
| | A2 ZINC FASTENERS, LLC. | | | | | AQL 0.65 LEVEL C=0 | | | | | | | | | | |
| | | | | | | -,- | | | | ANTIT | | | | | | |
| | STREET ADDRESS | | | | R | RECEIVED | | | | INSPECTED | | DEFECTIVE | | REJECTED | | |
| | 907 North Pierce st Alma, GA 31510 | | | | | 100 | | | | 20 | 2 | 2 | | 100 | | |
| | CITY: USA STATE: ZIP CODE: | | | | | REPORT WRITTEN BY | | | | DATE | | | | | | |
| | | | | | С | Cao Hoang Vu | | | | 10/24/2018 | 3 | | | | | |
| ITE | М | QTY | DESCRIPTION | | | | | | DEFECT | | | | RESPON | | DISP'N | |
| 1 | | 1.5 | Metal powder on plating surface; | | | | | | SURFACE FINISH; | | | | | | | |
| 2 | | 0.5 | Dimension is out of spec; | | | | | DIMENSIONAL; | | | | | | | | |
| | | | | | | | | | | | | | | | | |
| DEFECT CODE | | | | | | RESPONSIBILITY | | | _ | DISPOSITION | | | | | | |
| 1. BURRS | | | 8. Flatness | | | 1. VENDOR | | | | A. RETURN TO VENDOR(VEN. EXP) | | | | | • | |
| 2. DAMAGED | | | 9. FUNC | | 2. PURCHARSING | | | | B. RETURN TO VENDOR (MI EXP) C. REWORK | | | | | | | |
| 3. DESCRIBE 4. DIMENSIONAL | | | 10. MARKING 11. Paperwork | | | 3. PRODUCTION 4. TEST | | IN | | | | | | | | |
| 5. DIRTY | | | 12. PLATING | | | 5. ENGINEERING | | NG. | | D. SCRAP E. USE AS | | | | | | |
| 6. DRAWING ERROR 13. SCRATCI | | | | | 6. MARKETING | | | | | F. SALVAGE | | | | | | |
| 7. EXPIRE | | | 14. SOLDER | | | 7. SHIPPING | | | | G. DESCRIBE | | | | | | |
| | | CE FINISH | | | | | DESCRIBE | | | | 0. 5 = 0 | 011.22 | | | | |
| ITE | M QTY ADDITIONAL INSTRUCTION | | | TION | 1 | | | | | | INSP. | | | DATE | | |
| CORRECTIVE ACTION: NOT REQUIRED REQUIRED NOTIFCATION ISSUED CA REQUEST NO: DATE | | | | | | | | | | | | | O: DATE: | | | |
| FOL | FOLLOW UP NOTES: see detail in NCR database | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | ACC | ACCTG, USE ONLY | | | |
| Ţ, | | | | | | | | | | | REM | REMOVED FROM: | | | | |
| | | | | | | | | | | | | BOO | BOOK INV: | | | |
| | | | | MARLOW MRB | AUTHO | DRIZA | TION | | | | | Į. | ISSUE DEBIT MEMO | | | |
| | | | | | | | | | | | | DAT | E. NO. | | | |
| ENGINEERING: DATE: | | | | | | MRB | | | Chairman: D | | | DATE: | | | | |
| Chu Ky | | | | | Chu h | | | у | | | | | | | | |
| | | | | | | | | | | | | | | | | |
| Cao Hoang Vu | | | | | | Pham | | | Thong Nhat | | | | | | | |

FORM #005-0033 REV A