

MI PART NO: REV:					PO NUMBER:			TRAVELER NO./ ARM NO. /LOT#.				
52	2-1010-001			N/A	'			170208				
DESCRIPTION OF MATERRIAL MODEL OR SERIAL M								REC.INSP	IN PROCESS			
тт									▽			
•						INSPECTION PLAN						
v						SAMPLE INSP AQL: LEVEL			100% INSP	FIRST ARTICLE		
Ē							QUANTITY					
N	STREET ADDRESS					RECEIVED		INSPECTED DEFECTIVE REJECT		REJECTED		
D O R	36 VSIP STREET 4, VIETNAM SINGAPORE INDUSTRIAL PARK, BINH HOA WARD, THUAN AN TOWN, BINH DUONG PROVINCE, VIETNAM					10		10	10	10		
	CITY: VNM STATE: ZIP CODE:						RT EN BY pang Vu	DATE 19-Mar-19				
ITEM QTY DESCRIPTION			DESCRIPTION		DEFECT		RESPON	ON DISP'N				
1		10	Burr Element;		BURRS;							
DEFECT CODE					RESPONSIBILITY		DISPOSITION					
2. 3. 4. 5. 6. 7.	BURRS 10. MACHINING DAMAGED 11. MARKING DESCRIBE 12. Paperwork DIMENSIONAL 13. PLATING DIRTY 14. SCRATCH DRAWING ERROR 15. SOLDER EXPIRE 16. SURFACE FINISH Flatness 17. THREADS FUNCTION 18. WRONG PART		1. VENDOR 2. PURCHARSING 3. PRODUCTION 4. TEST 5. ENGINEERING 6. MARKETING 7. SHIPPING 8. DESCRIBE		A. RETURN TO VENDOR(VEN. EXP) B. RETURN TO VENDOR (MI EXP) C. REWORK D. SCRAP E. USE AS IS F. SALVAGE G. DESCRIBE							
	EM QTY		TONAL INSTRUCT	ION				INSP.		DATE		
CC	CORRECTIVE ACTION: NOT REQUIRED REQUIRED NOTIFCATION							ISSUED CA REQUEST NO: DATE:				
	FOLLOW UP NOTES: see detail in NCR database											
							ACCTG, USE ONLY					
								REMOVED FROM: BOOK INV:				
	MARLOW MRB AUTHORIZATION							ISSUE DEBIT MEMO				

FORM #005-0033 REV A