

n = -	D45-	- NO			DEV.	DO NUMBER.			DAVE: ==	NO / 4514 **	0 // 07//	
MI PART NO: REV:						PO NUMBER:			TRAVELER NO./ ARM NO. /LOT#.			
485-2301-001 AG									XN1803-2303W-82435			
DESCRIPTION OF MATERRIAL						MODEL OR SERIAL NO.			REC.INSP IN PR		OCESS	
Element						RC12-6				~		
							INSPECTION PLAN					
							SAMPLE INSI	P		100% INSP	FIRST	
							□ AQL:		VEL	V	ARTICLE	
v												
Ε							QUANTITY RECEIVED INSPECTED DEFECTIVE REJECTED					
N							RECEIVED	IN	SPECTED	DEFECTIVE	REJECTED	
D O	AN TOWN, BINH DUONG PROVINCE, VIETNAM						81416	81	416	81416	81416	
R	CITY: VNM STATE: ZIP CODE:					REPORT	D/	ATE	·			
							WRITTEN BY Nguyen Van	23-Nov-1	-Nov-18			
		Tho										
ITEM QTY			DESCRIPTION					DEF	ECT	RESPON	DISP'N	
1		81416	Contamination; Void solder due to element platin			plating poor wetting;		PLA	TING;			
1.	DEFECT CODE RESPONSIBILITY 1. BURRS 10. MACHINING 1. VENDOR							A. RETURN TO VENDOR(VEN. EXP)				
2. DAMAGED						2. PURCHARSING	B. RETURN TO VENDOR (MI EXP)					
3. DESCRIBE			12. Paperwork			3. PRODUCTION						
4. DIMENSIONAL						I. TEST	D. SCRAP					
5. DIRTY			14. SCRATCH OR 15. SOLDER			5. ENGINEERING E. USE A 6. MARKETING F. SALVA						
7. EXPIRE				ACE FINISH		7. SHIPPING	G. DESCRIBE					
8. Flatness						. DESCRIBE			-			
9. FUNCTION 18. WRONG PART												
ITEM QTY			ADDIT	ADDITIONAL INSTRUCTION				INSP. DATE				
CORRECTIVE ACTION: NOT REQUIRED NOTIFCATION ISSUED CA REQUEST NO: DATE:												
FC	LLOV	V UP NOT	ES: see detai	I in NCR database		۸۵	CTG LISE	ONLY				
								ACCTG, USE ONLY REMOVED FROM:				
								BOOK INV:				
	MARLOW MRB AUTHORIZATION							ISSUE DEBIT MEMO DATE. NO.				
ENGINEERING: DATE:							<u> </u>	:				
Pł	nam N	goc Tuong	9									