

MI PART NO:					REV:	PO NUMBER:			TRAVELER NO./ ARM NO. /LOT#.				
ST4184-05 12						I			81604				
DESCRIPTION OF MATERRIAL						MODEL OR SERIAL NO.			REC.INSP IN PROCESS		OCESS		
FLUID TO PLATE TEM, LEICA SSM													
							INSPECTION PLAN						
	NAME OF VENDOR							E INSP		100% INSP	FIRST		
	II-VI VIETNA	II-VI VIETNAM CO., LTD.						.:	I EVEI	~	ARTICLE		
	,									_			
V E									OLIANT	ITV			
N								QUANTITY RECEIVED INSPECTED DEFECTIVE REJECTED					
D								/ED	INSPECTED	DEFECTIVE	KEJECTED		
0		6 VSIP STREET 4, VIETNAM SINGAPORE INDUSTRIAL PARK, BINH HOA WARD, THUAN							5	5	5		
R	AN TOWN, BINH DUONG PROVINCE, VIETNAM												
	CITY: VNM STATE: ZIP CODE:						REPOR		DATE				
					WRII		ENBY	24-Nov-18					
							Ha Minh	n Dien					
ΙT	ITEM QTY DESCRIPTION			DESCRIPTION		DEFECT		RESPON		DISP'N			
										•			
DEFECT CODE RESPONSIBILITY								DISPOSITION					
1. BURRS 10. MACHINING			HINING	1	1. VENDOR		A. RETURN TO VENDOR(VEN. EXP)						
2. DAMAGED 11. MARKING			KING	2	B. RETURN TO VENDOR (MI EXP)								
3. DESCRIBE 12. Paperwork				3	C. REWORK								
4. DIMENSIONAL			3. PLAT		4. TEST		D. SCRAP						
5. DIRTY 14. SCRATCH						S. ENGINEERING	E. USE AS IS						
6. DRAWING ERROR 15. SOLDER 7. EXPIRE 16. SURFACE FINISH						i. MARKETING '. SHIPPING	F. SALVAGE G. DESCRIBE						
8. Flatness 17. THREADS					. DESCRIBE	H. SCRAP AND DESTROY PER IATF 16949							
9. FUNCTION 18. WRONG PART													
ITI	EM QT	Υ	ADDIT	IONAL INSTRUCT	TION				INSP.		DATE		
CORRECTIVE ACTION: NOT REQUIRED REQUIRED NOTIFCATION ISSUED CA REQUEST NO: DATE:										<u> </u>			
FC	FOLLOW UP NOTES: see detail in NCR database							ACCTG, USE ONLY					
								REMOVED FROM:					
									BOOK INV:				
	MARLOW MRB AUTHORIZATION							ISSUE DEBIT MEMO					
									DATE. NO.				
ENGINEERING: DATE: :													
Нι	uynh Anh Tua	ın											
									· · · · · · · · · · · · · · · · · · ·				

FORM #005-0033 REV A