
















Title <Title>									
Size A4		Document Number <Doc>						Rev <Rev>	
Date:		Monday, December 16, 2019				Sheet		3 of 10	




MPU9250:R34 ON,FB3 ON,C62 NC,C63 NC,U20 NC;
 ICM20948:R34 NC,FB3 NC,C62 ON,C63 ON,U20 ON;




IIC Address:0x76




IIC Address:0x77





Title		
<Title>		
Size	Document Number	Rev
A	<Doc>	<RevCode>
Date:	Tuesday, December 24, 2019	Sheet 4 of 10







OpenMV复位
STM32F103启动选择
检测OpenMV是否插上
3.3V输出
I2C2 SDA
5V输出，给OpenMV供电地




Title		
<Title>		
Size	Document Number	Rev
A	<Doc>	<RevCode>
Date:	Thursday, December 05, 2019	Sheet 7 of 10




D






C



B




A




Title		
<Title>		
Size	Document Number	Rev
A4	<Doc>	<Rev>
Date:	Monday, December 16, 2019	Sheet 9 of 10


D





C



B



A



Title		
<Title>		
Size	Document Number	Rev
A4	<Doc>	<Rev>
Date:	Thursday, December 05, 2019	Sheet 10 of 10