Homework Assignment - 6 & 7

Tushar Goel NUID: 001356901

Problem 1




Figure 2: A simplified model of each DC motors with permanent magnets.

(a)

Ans - (a)

The determinant Δ from the Mason's Formula:

$$\Delta = 1 - \left[\frac{K_m}{Ls + R} \frac{1}{Js + Kf} (-K_b) \right]$$

Characteristic Polynomial for the simplified DC motors can be found out as follows:

Characteristic Polynomial
$$\rightarrow 1 - \left[\frac{K_m}{Ls + R} \frac{1}{Js + Kf} (-K_b)\right] = 0$$

$$\rightarrow 1 - \left[-\left(\frac{K_m K_b}{Ls + R} \frac{1}{Js + Kf}\right)\right] = 0$$

$$\rightarrow 1 = -K_m K_b \left[\frac{1}{Ls + R} \frac{1}{Js + Kf}\right]$$

$$\rightarrow 1 = \left[\frac{-K_m K_b}{LJs^2 + LsK_f + RJs + RK_f}\right]$$

$$\rightarrow LJs^{2} + LsK_{f} + RJs + RK_{f} = -K_{m}K_{b}$$

$$\rightarrow (LJ)s^{2} + (LK_{f} + RJ)s + (RK_{f} + K_{m}K_{b}) = 0$$

Therefore,

Characteristic Polynomial
$$\rightarrow (LJ)s^2 + (LK_f + RJ)s + (RK_f + K_mK_b) = 0$$

Problem 1

(b)

Ans – (b)

The given parameters are as follows:

$$R = 2.0$$
 $L = 0.5$ $K_m = 0.1$ $K_b = 0.1$

$$J = 0.02$$
 $K_f = 0.2$ $T_d = 1$ $V(s) = 1$

(i) Let us consider a condition when T_d is not considered or $T_d = 0$:

$$\frac{\Omega(s)}{V(s)} = \frac{\frac{K_m}{Ls + R} \frac{1}{Js + Kf}}{1 + \left[\frac{K_m K_b}{Ls + R} \frac{1}{Js + Kf}\right]} \dots (i)$$

Assuming,

Armature Gain,
$$L_a(s) = \frac{K_m}{Ls + R}$$

Load Gain,
$$L_l(s) = \frac{1}{Js + Kf}$$

Now, equation (i) becomes,

$$\frac{\Omega(s)}{V(s)} = \frac{L_a(s)L_l(s)}{1 + [K_bL_a(s)L_l(s)]} \qquad \dots (ii)$$

$$\Omega(s) = \frac{L_a(s)L_l(s)}{1 + [K_bL_a(s)L_l(s)]}V(s) \qquad \dots (iii)$$

(ii) Let us consider a condition when V(s) is not considered or V(s) = 0:

$$\frac{\Omega(s)}{T_d(s)} = \frac{L_l(s)}{1 + [K_b L_a(s) L_l(s)]} \qquad \dots (iv)$$

$$\Omega(s) = \frac{L_l(s)}{1 + \left[K_h L_a(s) L_l(s) \right]} T_d(s) \dots (v)$$

Therefore, Angular Velocity Response i.e. $\Omega(s)$ can be calculated using equation (iii) and equation (v).


$$\Omega(s) = \frac{L_a(s)L_l(s)}{1 + [K_bL_a(s)L_l(s)]}V(s) + \frac{L_l(s)}{1 + [K_bL_a(s)L_l(s)]}T_d(s) \dots (vi)$$

Hence, the transform function can be constructed using given parameters and equation (vi).

$$Transform\ Function \rightarrow \Omega(s) = \frac{L_a(s)L_l(s)}{1 + \left[K_bL_a(s)L_l(s)\right]}V(s) + \frac{L_l(s)}{1 + \left[K_bL_a(s)L_l(s)\right]}T_d(s)$$

Transform Function
$$\rightarrow \Omega(s) = \frac{10}{s^2 + 14s + 41}V(s) + \frac{50s + 200}{s^2 + 14s + 41}T_d(s) \dots (vii)$$

Plot of the angular velocity response



Problem 1

(c)

Ans - (c)

Feed-Forward Control Plots:




Figure-1





Figure-2

To minimize the speed variations induced by T_d disturbances, we can apply the following possible solutions:

- \triangleright The feedforward control structure can be used as it minimizes the effect of the external disturbance T_d on the system as shown in the above figures. Therefore, improving the performance and control accuracy.
- \triangleright The closed loop system can also be used as it helps in suppressing the effect of the external disturbance T_d . Thus, making the system independent of the variations. Therefore, closed loop systems tend to equalize inputs and outputs.
- ➤ The other possible solution is the PID controller.

Problem 2

(a)



Ans – (a)

$$\dot{\xi}_I = \begin{bmatrix} v_x(t) \\ v_y(t) \\ \omega(t) \end{bmatrix}_I = \begin{bmatrix} c_\theta & -s_\theta & 0 \\ s_\theta & c_\theta & 0 \\ 0 & 0 & 1 \end{bmatrix} \begin{bmatrix} \frac{1}{2} & \frac{1}{2} & 0 \\ 0 & 0 & 1 \\ \frac{l}{2} & \frac{-l}{2} & 0 \end{bmatrix} \begin{bmatrix} r_R \omega_R(t) \\ r_L \omega_L(t) \\ 0 \end{bmatrix}$$

Given: $\theta = \frac{\pi}{4}$

$$\xi_{I}^{\cdot} = \begin{bmatrix} V_{x}(s) \\ V_{y}(s) \\ \Omega(s) \end{bmatrix}_{I} = \begin{bmatrix} \frac{1}{2\sqrt{2}} & \frac{1}{2\sqrt{2}} & -\frac{1}{\sqrt{2}} \\ \frac{1}{2\sqrt{2}} & \frac{1}{2\sqrt{2}} & \frac{1}{\sqrt{2}} \\ \frac{l}{2} & -\frac{l}{2} & 0 \end{bmatrix} \begin{bmatrix} r_{R}\Omega(s) \\ r_{L}\Omega(s) \\ 0 \end{bmatrix} \quad \dots (viii)$$

Angular Velocity Response Model from equation (vi):

$$\Omega(s) = \frac{L_a(s)L_l(s)}{1 + [K_bL_a(s)L_l(s)]}V(s) + \frac{L_l(s)}{1 + [K_bL_a(s)L_l(s)]}T_d(s)$$

For simplification, let us assume

$$G_1(s) = \frac{L_a(s)L_l(s)}{1 + [K_bL_a(s)L_l(s)]}$$

$$G_2(s) = \frac{L_l(s)}{1 + [K_b L_a(s) L_l(s)]}$$

So, the above Angular Velocity Response Model equation can be reduced as:

$$\Omega_i(s) = G_1(s)V_i(s) + G_2(s)T_{d_i}(s) \quad ...(ix)$$

From (viii) and (ix), we can deduce

$$\xi_{I} = \begin{bmatrix} V_{x}(s) \\ V_{y}(s) \\ \Omega(s) \end{bmatrix}_{I} = \begin{bmatrix} \frac{1}{2\sqrt{2}} r_{R}(G_{1}(s)V_{R}(s) + G_{2}(s)T_{d_{R}}(s)) + \frac{1}{2\sqrt{2}} r_{L}(G_{1}(s)V_{L}(s) + G_{2}(s)T_{d_{L}}(s)) \\ \frac{1}{2\sqrt{2}} r_{R}(G_{1}(s)V_{R}(s) + G_{2}(s)T_{d_{R}}(s)) + \frac{1}{2\sqrt{2}} r_{L}(G_{1}(s)V_{L}(s) + G_{2}(s)T_{d_{L}}(s)) \\ \frac{l}{2} r_{R} \left(G_{1}(s)V_{R}(s) + G_{2}(s)T_{d_{R}}(s) \right) - \frac{l}{2} r_{L}(G_{1}(s)V_{L}(s) + G_{2}(s)T_{d_{L}}(s)) \end{bmatrix}$$

In the above equation,

 $T_{d_R}(s), T_{d_L}(s) \rightarrow represents \ the \ torque \ subjected \ to \ the \ wheels$

 $V_R(s)$, $V_L(s) \rightarrow represents$ the voltages