



P O Box 4383
Brandon, MS 39047
601-992-4142
Cell 601-937-4142

April 27, 2026

Property Condition Assessment of Property at 25 Woodgreen Pl, Madison, MS

We are pleased to present our proposal for a Property Condition Assessment of the above-captioned property.

1.0 BUILDING DESCRIPTION:

The fee quoted is based on the following reported description. If actual conditions prove to be different, the fee may change.

The subject property consists of two joined buildings , with approximately 13,609 square feet of office space and built in 1993.

2.0 BASIC PROPERTY CONDITION ASSESSMENT:

Areas to be inspected:

- The structure.
- The electrical system.
- The heating system.
- The air conditioning system.
- The ventilation system.
- The plumbing system and fixtures.
- The roof surface (weather permitting), including flashings, drainage and chimneys.
- Interior components (concentrating on non-cosmetic considerations).
- The exterior wall components, from the exterior, including doors, windows and signage.
- Landscape components including walkways, driveways (excluding sewers) and retaining walls.
- Insulation spot-check.

3.0 SCOPE OF PROPERTY CONDITION ASSESSMENT:

The assessment will meet or exceed the ASTM Standard E2018-15 for Property Condition Assessments, unless indicated otherwise.

Agreement for Inspection of 25 Woodgreen Pl, Madison, MS

The report will be a professional opinion, based on the accessible, visible components and systems of the building. We evaluate the current physical condition; we do not perform a design analysis. We visually review the performance, looking for evidence of distress. It should be understood that there are limitations to such an inspection. Throughout any inspection, inferences are often drawn which cannot be confirmed by direct observation. Therefore, it should be understood that we can reduce the number of unforeseen repairs; however, we cannot eliminate them. Consequently, no guarantee or warranty can be offered or implied.

The assessment does not include the operation of equipment by the field observer.

The report will identify deficiencies based on a sampling inspection technique. For example, in a 100-foot x 20-foot brick wall, there are roughly 13,500 bricks and 12,000 feet of mortar joints. A brick-by-brick examination and report would require several hours for this building component alone. As a practical alternative, we use our professional judgment and experience to inspect areas and components most likely to show problems. This means that in some cases we will not find localized problems that were detectable. We ask that you understand and accept this.

The report will point out areas requiring improvement. It will not provide specifications or methods for performing the work. In some cases, a more detailed study is needed to decide what action, if any, is appropriate.

The intent of the visual roof inspection is to give a general classification of the condition and to recommend whether or not a more detailed inspection should be undertaken.

All accessible units will be inspected.

EXCLUDED ITEMS:

Items excluded from this proposal include, but are not limited to, fire protection equipment, fire regulation compliance, building code and municipal bylaw compliance, security systems, telecommunication systems, process and recreational equipment and appliances. If deemed necessary, any of the above could be included on an additional fee basis.

No comment is offered on mold or environmental concerns such as urea formaldehyde foam insulation, asbestos, radon gas or polychlorinated biphenyls (PCBs). A Phase I Environmental Site Assessment is not included in this proposal.

Rather than concentrating on the presence or absence of wood boring insects such as termites or carpenter ants, the intent of the inspection is to discover significant visible structural damage caused by the insects. We do, however, recommend inspection by a specialist, especially in areas considered prone to termite problems.

4.0 REPAIR COST ESTIMATES:

Cost estimates are included in this inspection.

Agreement for Inspection of *25 Woodgreen Pl, Madison, MS*

5.0 FEE:

Our fee for the above listed inspection is \$2350.00.

6.0 ADDITIONAL INSPECTION SERVICES:

If requested, a search for outstanding building code and fire code violations may be conducted through the appropriate municipal departments.

7.0 ADDITIONAL FEES:

The fee quoted above is based on one site visit. If additional site visits are required because of lack of proper access, additional fees will apply.

Additional fees are charged at our standard hourly rate (presently **\$125.00 per hour**) for any work not specified above. A four-hour minimum will apply to any billing. Consulting for expert testimony, including court appearances, time spent waiting to appear in court (in our office or elsewhere), travelling time, meetings, and research, is charged at 1.5 times our standard rate.

8.0 DELAY OR ABANDONMENT:

If the project is delayed or not completed, our firm and its agents will be paid for their time spent to that point at the rate set out above.

9.0 COMPLETION DATE:

The project is to be completed and the final report submitted within ten business days of the day the site visit is completed.

10.0 REPORT DELIVERY

The report will be delivered by email to you upon completion.

The report will not be released to anyone without your permission.

11.0 CLIENT'S RESPONSIBILITY

11.1 Building Plans, Specifications and Records

If these exist, they should be made available. Working drawings or as-built drawings are preferred. Drawings will be referenced for general information only; a review to ensure fidelity of construction, building code compliance or a design analysis will not be undertaken.

All such record should be made available and presented to the field observer at the site visit.

Agreement for Inspection of 25 Woodgreen Pl, Madison, MS

11.2 Building Access

The client is responsible for assuring that access is available to all areas of the building, including electrical rooms, mechanical rooms and main water service entrances.

In addition, notice to tenants must be provided to allow access to all units.

12.0 ACCEPTANCE:

If this proposal is accepted, please sign the following Proposal Acceptance and return one copy with the inspection fee.

Our report will not be released until the fee has been paid.

13.0 EXPIRY:

This quote is valid for thirty days from the time of writing.

Thank you for your interest in our firm. If you would like to discuss this proposal further, please feel free to contact us. We look forward to working with you.

Sincerely,

A handwritten signature in blue ink, appearing to read "Charlie Sessums".

Charlie Sessums

PROPOSAL ACCEPTANCE

Please sign and return this page via office@alphainspection.com

The Client requests the inspection of the Subject Property **subject to the following limitations and conditions:**

1. The inspection is to be performed according to the parameters set out in this Proposal.
2. The client is to arrange site access in advance of the inspection. Site access refusal of our staff or their agents will result in additional charges.
3. The report is an opinion of the current condition of the property, based on a visual inspection of the readily accessible features of the building. The report is not a guarantee, warranty or insurance policy.
4. The Client understands and agrees that the liability of our firm, its employees and agents, is limited to the Inspection Fee.
5. The written report will be available **ten business days** after the site visit.

We have read, understood and accepted the terms of this agreement:

Name: Tyler Raborn	Phone: 601-750-5259
Co. Name:	Email: tyler@raborn-realty.com
Mailing Address: 112 Langdon Dr., Madison, MS 39110	
Inspection Address: <i>25 Woodgreen Pl, Madison, MS</i>	
On-Site Contact: Shane Saxton, (601) 540-5040	
Inspection booked for: Tuesday, May 5, 2026 at 9am	
Signature: 	Date: 4/28/26

LEVEL OF SERVICE REQUIRED *(please specify):*

X ASTM Property Condition Assessment.....\$ 2350.00